

ASS. REC. BY:

REF: CS/FCI18016299/ Kq d3ⁿ²

Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

5/9/18 @ 5.23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDR 1312B

Insured:

SHD 6646G

at Workshop m/s

Sin Ming Autocare (BFG)

Tel:

6455 0600

of

176 Sin Ming Drive # 02-05

Policy No:

Claim No:

D1800 6600 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/09/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:01am @ 6/9/18

Person Contacted:

Angela

Vehicle IN /

OUT

Date/Time

Action/Instruction (✓) Estimate

SDR1312B-CS3/INC16003416/Ggbd1

DOA: 20/02/16

SHD 6646 G-x

13/9@10:07am - revert preli advice via email.

24/9 11Lp 865a Carfax (Red & 2130, 77%)

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Pin May BPG

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 846k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 11/26 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SOR1312B Yr Regn: 01.07Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MS Latio c.c. 1498Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 137086 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAA 21180003445Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 4/9/18

Rear

R/Bal. 2 mmL/Bal. 2 mmD.O.I. 10/9/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/9 File pass to Catherine

RECEIVED 24 SEP 2018

Date/Time, File Pass to?

11/9 trust

Date/Time, File Return to?

2)

☐ : Prell. Report☐ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

TOTAL

Report Format: 7pLump Sum / I.B.T. (\$) 650

110

50

10

170



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC118016299/Kqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6646G	Veh. Inspected	SDR 1312B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006600MFSH	Excess (\$)	0.00	
Assign From	CWS (KAREN TAN)	Assign Date	06/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/09/2018	Inspection Date	10/09/2018	
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006600MFSH

Date: 13/9/2018

Our Ref: CS/FCI18016299/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SDR 1312B

Please be informed that we had conducted the inspection of the abovementioned vehicle 10/09/2018 at the premises of M/s Sin Mng Autocare and have the following to report: -

Workshop Estimate Amount	: S\$ <u>2,780.00</u>
Revised Estimate Amount	: S\$ <u>829.30</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the Rear N/S portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-09-2018	Our Ref No. D18006600MFSH
Accident Date	04-09-2018	Claim Type. Third Party
Insured Vehicle	SHD6646G	Third Party Vehicle. SDR1312B
Survey Location	176 SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX	
Contact Person.	ANGELA TAN	
Contact No.	6455 0600/ 64550600	Fax No. 6455 6192
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN MING AUTOCARE BFG PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 13 September 2018 10:07 AM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006600MFSH/1
Attachments: PRELI ADVISED SDR 1312B.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SDR 1312B**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 6 September 2018 10:03 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006600MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 5 September 2018 5:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006600MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE 068877

Attention : Motor Claim Department

Estimate : E18/2456

Date : 04/09/2018

Vehicle Num. : SDR1312B

Make/Model : NISSAN LATIO-2007

Chassis/Eng# : JN1BAAC11Z0003445/HR15063571A

Accident Date : 04/09/2018

Claim No. : BFG

Reference : TP CLAIM

Policy No. : 5033707162-09

*Not wither
11 Sep 8 650L
Resurvey After Paint
2 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|----|-----|---------------------------|
| 1. | 1PC | LIST ITEMS : |
| 2. | 1PC | REAR BUMPER |
| 3. | 1PC | REAR BUMPER RETAINER L/H |
| 4. | 1PC | REAR BUMPER RETAINER R/H |
| 5. | 1PC | REAR END PANEL |
| 6. | 1PC | REAR BUMPER LOWER GARNISH |
| 6. | 1PC | BOOT LID |

List Total S\$:
30.00% Discount S\$:

Bu/In	559.00	✓
Sn	36.00	X
Sn	36.00	X
Sn	355.00	X
Sn	76.00	X
Sn	798.00	X
	1,860.00	
	558.00	
	1,302.00	

- | | | |
|----|------|----------------------|
| 1. | 6PCS | SPECIAL NETT ITEMS : |
| | | BUMPER CLIPS |

Special Nett Total S\$:

Sn	3.00	18.00	✓
		18.00	

LABOUR :
TO PANEL BEATING ON ALL AFFECTED AREAS
TO SPRAY PAINT BOOT LID, REAR BUMPER & REAR END PANEL.
TO APPLY ANTI-RUST

Labour Total S\$:

	200	500.00	
	220	900.00	
nn	60.00	X	
		1,460.00	

E. & O.E.

Total S\$: 2,780.00

for Sin Ming Autocare BFG Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18016299/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-09-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6646G	Veh. Inspected	SDR 1312B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006600MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	05/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JN1BAAC11Z0003445	Colour	METALLIC GREY	
Odometer	137084	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/60 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/60 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/60 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/09/2018	Inspection Date	10/09/2018	
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDR 1312B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / DENTED	559.00	559.00
1	REAR BUMPER RETAINER L/H	SERVICEABLE	36.00	-
1	REAR BUMPER RETAINER R/H	SERVICEABLE	36.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	355.00	-
1	REAR BUMPER LOWER GARNISH	SERVICEABLE	76.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	798.00	-
	LESS 30% DISCOUNT		-558.00	-167.70
			1,302.00	391.30
SPECIAL NETT ITEMS				
6	BUMPER CLIPS @\$3.00 (SN)	NECESSARY	18.00	18.00
			18.00	18.00
LABOUR				
	TO PANEL BEATING ON ALL AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND BOOT LID.		500.00	200.00
	TO SPRAY PAINT BOOT LID,REAR BUMPER & REAR END PANEL.		900.00	220.00
	TO APPLY ANTI-RUST.	NOT NECESSARY	60.00	-
			1,460.00	420.00
GRAND TOTAL			2,780.00	829.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				650.00

Report Ref No. CS/FCI18016299/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.