

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

09:30am
LKK Auto
6 Sep 1972
Lavita said
leave car
for Survey then
proceed for Repair

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA1224E
Chassis No : JHMGK5850JX206480
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : QUEK HENG SOON
Ins Policy No. : SD18V05081/VPC2/R00
Date of Accident : 5/9/2018

Document No. : SQT18003732 Page 1
Date : 5. Sep 2018
Customer No. : WZI007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B33113446
Date | Time : 5. Sep 2018 6:54:16 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71188) OWNER: QUEK HENG SOON OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 05/09/2018@07.55AM SURVEYED BY: <i>Adrian Ling (LKK auto)</i> 10 SEP 2018 REF NO: <i>MCT18090100/01/SN</i> TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHC1633G (TOYOTA/PRIUS/BLUE) TAXI						
91505-TM8-003	CLIPBUMPER <i>NIC</i>	14	2.00	25	✓ 21.00	1.47	22.47
33500-T5A-J02	TAILLIGHT ASSY,R. <i>? NUC NEC</i>	1	235.10	25	✗ 176.32	12.34	188.66
33550-T5A-J02	TAILLIGHT ASSYL. <i>? NUC NEC</i>	1	235.10	25	✗ 176.32	12.34	188.66
74890-T5B-911	GARNISH ASSYRR.LICENSE <i>NUC NEC</i>	1	194.70	25	✗ 146.02	10.22	156.24
75701-T5A-000	EMBLEMH <i>next NUC</i>	1	10.70	25	✗ 8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM <i>? NUC</i>	2	1.90	25	✓ 2.85	0.20	3.05
75722-T5L-T01	EMBLEMRR.	1	10.50	25	✓ 7.87	0.55	8.42
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR <i>cut</i>	1	202.70	25	✓ 152.02	10.64	162.66
71502-T5A-J60	COVER,R.RR.BUMPER <i>? NUC</i>	1	20.30	25	✗ 15.22	1.07	16.29
71507-T5A-J60	COVER,L.RR.BUMPER <i>? NUC</i>	1	20.30	25	✗ 15.22	1.07	16.29
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>? NUC</i>	1	16.60	25	✓ 12.45	0.87	13.32
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>? NUC</i>	1	16.60	25	✓ 12.45	0.87	13.32
04715-T5B-J50ZZ	FACE,RR.BUMPER <i>detached</i>	1	492.60	25	✓ 369.45	25.86	395.31
74940-TZ5-A01	BUZZER ASSYSMART ?	1	59.30	25	? 44.47	3.11	47.58
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	58.10	25	? 43.57	3.05	46.62
66100-TAR-T10ZZ	PANEL COMPRR. <i>Repair</i>	1	314.00	25	✗ 235.50	16.49	251.99
68100-TAS-Z50ZZ	TAILGATE COMP <i>Dented</i>	1	716.30	25	✓ 537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE <i>? NUC</i>	1	92.30	25	✗ 69.22	4.85	74.07
74800-T5S-K61	LOCK ASSY,TAILGATE <i>? NUC</i>	1	77.10	25	✗ 57.82	4.05	61.87
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER <i>? NUC</i>	1	11.20	25	✓ 8.40	0.59	8.99
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER <i>? NUC</i>	2	6.30	25	✓ 9.45	0.66	10.11

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA1224E
Chassis No : JHMGK5850JX206480
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : QUEK HENG SOON
Ins Policy No. : SD18V05081/VPC2/R00
Date of Accident : 5/9/2018

Document No. : SQT18003732
Date : 5. Sep 2018
Customer No. : WZI007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B33113446
Date | Time : 5. Sep 2018 6:54:16 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
Sum Item					2187.08	153.11	2,340.19
BOSUN	SUNDRIES	1	50.00		50.00	3.50	53.50
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00		140.00	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00		350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION1	1	350.00		350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	350.00		350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00		550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4500.00		4500.00	315.00	4815.00
BKRP22S	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW1	1	4800.00		4800.00	336.00	5136.00
Sum Labor					12520.00	876.40	13,396.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 14,707.08 1,029.51 15,736.59

Total (Inclusive of GST) 15,736.59

Printed on 5/9/2018 7:08:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)