

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1030/2018/PH
Date : 4-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lee Siang Kheng Bert
Address : 22 Lorong Puntong
#10-01
Singapore 576439
Telephone : HP +65 96371119
Type of Claim : Own Damage Claims
Policy No. : 2100497023
Vehicle No : **EY 0668 H**
Model Code : Audi A5 SB 1.8 TFSI
Model / Year : Nov-10
Engine No : CDH 101824
Chassis No : WAUZZZ8T2BA009373
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Sep-18
Place of Accident : 10 Begonia Walk

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 0668 H.

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓ ✓
2	To dismantle and renew front bumper, lhs front fender and both headlight. Repair bonnet. Re-organise front crash management components Reinstall all parts removed	\$ 2,700.00 1800 / 500 ✓
3	To respray front bumper, lhs front fender and bonnet. ✓	\$ 2,100.00 1650 ✓
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓ ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: \$ 5,632.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 0668 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,584.00	✓ 1267.20
2	FIXING PARTS FOR FRONT BUMPER <i>new</i>	\$ 222.00	x
3	SIDE REINFORCEMENT <i>new</i>	\$ 770.00	x
4	SUPPORT - LH / RH <i>new</i>	2 \$ 48.00	? x
5	GUIDE PIECE <i>new</i>	\$ 37.00	? 29.60
6	SECURING STRIP - LH / RH <i>new</i>	2 \$ 60.00	? x
7	CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 180.00	x
8	FOAM FILLER PIECE <i>new</i>	\$ 109.00	x
9	AIR GUIDE GRILLE - LH <i>new</i>	\$ 118.00	? x
10	TRIM FOR FOG LAMP CHROME <i>new</i>	\$ 61.00	? x
11	PULL STRAP COVER - LOWER <i>new</i>	\$ 44.00	x
12	FRONT FENDER - LH <i>Distorted</i>	\$ 930.00	✓ 744
13	ATTACHMENT PARTS FOR FENDER <i>new</i>	\$ 49.00	? x
14	BRACKET FOR FENDER - LH FRONT <i>Bent</i>	\$ 50.00	✓ 40
15	BRACKET FOR FENDER- LH REAR <i>new</i>	\$ 50.00	? x
16	BRACE <i>Bent</i>	\$ 106.00	? 84.40
17	WHEEL HOUSING LINER <i>torn</i>	\$ 163.00	✓ 130
18	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>new</i>	\$ 38.00	? x
19	HEADLIGHT FOR GAS DISCHARGE LAMP - LH / RH <i>LH smashed</i>	2 \$ 4,190.00	✓ 3352
20	CONTROL UNIT FOR HEADLIGHT <i>new</i>	2 \$ 2,036.00	x
TOTAL SPARE PARTS		\$ 10,845.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 0668 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	GAS DISCHARGE LAMP <i>Abn</i>	2 \$	787.00 <i>x</i>
22	MOUNTING FOR HEADLIGHT - LH/RH <i>2H dyd.</i>	2 \$	218.00 <i>7 87.00</i>
23	SIGNAL HORN - LH HIGH TONE <i>Abn</i>	\$	178.00 <i>7 x</i>
24	SPRING SHACKLE - LH HIGH TONE <i>Abn</i>	\$	22.00 <i>7 x</i>
25	LIFT CYLINDER FOR HEADLIGHT - LH <i>Dmgd.</i>	\$	241.00 <i>7 190.40</i>
26	REFRIGERANT PIPE <i>Abn</i>	\$	312.00 <i>7 x</i>
27	REPAIR KIT FOR QUICK RELEASE COUPLING <i>Abn</i>	\$	60.00 <i>7 x</i>
28	HALOGEN FOG LAMP <i>canb'd</i>	\$	224.00 <i>179.00</i>
29	FLAT CONTACT HOUSING <i>Abn</i>	\$	43.00 <i>7</i>
30	1 SET SINGLE WIRES EACH WITH 2 CONTACTS <i>Abn</i>	\$	33.00 <i>7</i>
31	CAR PLATE - FRONT <i>m</i>	S/N \$	25.00 <i>25</i>
32	FRONT RIM - LH <i>LT</i>	TBC	<i>911.20</i>
33	SIUNDRIES <i>Abn.</i>	\$	300.00 <i>7 22.72</i>
TOTAL SPARE PARTS		:	\$ 13,288.00
TOTAL LABOUR CHARGES		:	\$ 5,632.00
GRAND TOTAL		:	\$ 18,920.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

20,775

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 05/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant