

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 06 Sep 2018

Preliminary Advice

Vehicle No	: EY668H	Accident Date	: 02/09/2018
Make	: AUDI A5	Policy No.	: 2100497023
Assignment Date	: 06/09/2018	Excess	: S\$0.00
Date of Inspection	: 05/09/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,920.00
Revised Amount	:S\$	11,148.00
Check Items (Estimated)	:S\$	1,898.00
Total	:S\$	13,046.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	35,824.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,176.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :