CO. REG. NO: 199402370D GST NO: M2-0123250-3

## I AUTO PTE LTD

## 金興(襲)汽車私人有限公司

160 Sin Ming Drive, #02-20,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

No.: 30004

Vehicle Insured: GV 414 R

Accident Date : 03-Sep-2018

Date: 05-Sep-2018

Our Ref : 180564 (AIG ASIA) / SHUMAN

PAGE: 1

ABEILLE CHUA SI BEE (MS)

Not Wharked

ABEILLE CHUA SI BEE (MS)
Singapore

Richy 8?

ESTIMATED COST OF REPAIR FOR MITSUBISHI GRANDIS 2.4L (2007) SGS1404D \_\_\_\_\_\_\_

1 pc rear bumper

1 pc n/s rear bumper side retainer

10 pcs rear bumper clips

Bt /way 847.00 L 24.00 X

na 40.00 -@ S\$ 4.00

911.00 -182.20

Less 20% :

728.80

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

To putty and respray on affected portions.

To remove and refit reverse sensor assy.

2001 300.00

Total:

80.00 501

S\$ 1,508.80 =========

Singapore Dollars One Thousand Five Hundred and Eight and Cents Eighty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Lisa Auto Consultants hence notify the Repairer of the following:

- · To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

cknowledged by Repairer

Signature:

Date: