

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 2938 C.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		c/f		\$ 280.00
6	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. Renew rhs rear door. Re-organise rear crash management components. Reinstall all parts removed.		\$ 5,400.00	\$ 1,000.00
7	To respray rhs rear door, rhs rear fender, rhs sill panel, drain panel, roof channel, door entrances and end panelling.		\$ 3,700.00	\$ 1,650.00
8	To renew rhs rear rim and carry out wheel alignment	S/N	\$ 280.00	\$ 280.00
9	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 13,532.00</u>	<u>\$ 3,402.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2938 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	DOOR - RH REAR	TBC	\$ 1,752.00
2	OUTER DOOR SEAL - RH	\$ 139.00	\$ 111.20
3	BONDING AGENT	\$ 43.00	
4	CLEANING SOLUTION	\$ 64.00	
5	ATTACHMENT PARTS FOR REAR DOOR - RH	\$ 110.00	
6	REAR DOOR SEAL - RH	\$ 165.00	
7	DOOR CATCH	\$ 82.00	
8	COVER DOOR CATCH	\$ 14.00	
9	SECTIONAL PART - SIDE PANEL - RH	\$ 2,006.00	
10	1/4 GLASS - RH REAR	\$ 704.00	
11	PRIMER	2 \$ 38.00	
12	1/4 GLASS - RH REAR	\$ 502.00	
13	CHROME TRIM STRIP FOR 1/4 GLASS - RH	\$ 387.00	
14	1/4 GLASS CHROME TRIM CLIP	4 \$ 52.00	
15	ALUMINIUM RIM -RHS REAR	\$ 659.00	\$ 527.20
16	ARCYLIC SEALANT	\$ 180.00	
17	CAVITY WAX	\$ 140.00	
18	STONE CHIP TREATMENT	\$ 180.00	
19	METAL FILLER POWDER	\$ 280.00	
20	REAR WINDSCREEN SEALANT	\$ 200.00	
TOTAL SPARE PARTS CHARGES		\$ 5,945.00	\$ 2,390.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2938 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 2,390.40
		c/f	
21	1/4 GLASS SEALANT	S/N \$ 100.00	
22	SUNDRIES	\$ 500.00	\$ 3.36
	TOTAL SPARE PARTS CHARGES	: \$ 6,545.00	\$ 2,393.76
	TOTAL LABOUR CHARGES	: \$ 13,532.00	\$ 3,402.00
	GRAND TOTAL	: \$ 20,077.00	\$ 5,795.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 17 December 2018 11:26 AM
To: 'Boo seng yak'; jiayee.yap@premiumauto.com.sg; Carrine Leong; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SMD2938G - OD AIG - SURVEYED 14 SEP 18

Dear Mr Boo,

Confirm repair cost of \$5795.76 before excess \$600 and GST @ 4 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, 8 December 2018 3:19 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; jiayee.yap@premiumauto.com.sg; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMD2938G - OD AIAG - SURVEYED 14 SEP 18

Hi Adrian and all

Revised estimate is attached.

Please confirm repair cost of \$5795.76 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMD 2938 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1000/2018/MAS

2 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SMD 2938 G, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SMD 2938 G**, claimant, **Mr. Lo Zheng An**, please find the related document per attached.

1. A copy of the Original invoice no. 85013301 – S\$5,559.46
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMD 2938 G

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

REPUBLIC OF SINGAPORE
DRIVING LICENCE



Licence Number: S8771408Z
Name: LO ZHENG AN
Birth Date: 09 Jan 1987
Issue Date: 07 Aug 2009


001771806F

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8771408Z





Name: LO ZHENG AN
Race: CHINESE
Date of birth: 09-01-1987
Country/Place of birth: MALAYSIA



Sex: M
S8771408Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars= $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg

PASS DATE

07 Aug 2009

License No.



5847224

NRIC No. S8771408Z



Date of issue

04-01-2018

Address

APT BLK 239 LORONG 1 TOA PAYOH
#13-98
SINGAPORE 310239

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lo Zheng An
 Period of Insurance : 13 Aug 2018 To 12 Aug 2019
 Engine No. : CHZ472536
 Chassis No. : WAUZZZ8V7J107326

Vehicle No. : SMD2938G
 Policy No. : 1800102763
 Endorsement No. :
 Issued Date : 24 Aug 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreens : \$100

Named Driver and Excess (where applicable)

Lo Zheng An - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125282

PREMIUM LEASING - HES
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Janile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSCSAN



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6888 2223
Main Telefax 6471 3733
Page 1 14:50

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6888 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408829
Telephone 6388 2223
Telefax 6441 1829

Customer Service
Service Appointment 6366 2323
Hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013301 Date : 20/12/2018 Order : SMD29386 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SMD29386 (V 38488) Regn Date: 13/08/2018 Mileage: 1855 WIP No.: 22717
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V7J1073246 Engine: CHZ 472536 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER, REAR LID AND RHS REAR DOOR, CUT OUT AND WELD RHS REAR FENDER, RENEW RHS REAR DOOR, REDORGANISE REAR CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY RHS REAR DOOR, RHS REAR FENDER AND RHS SILL PANEL, TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	1650.00	1.00	1,650.00
S	BODYWORK	M: TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
Sub-Total					
7% GST					
Grand Total					

Customer



Customer Service	
Service Appointment	6366 2323
24-hour Breakdown Service	9828 1233
Email	customer.care@premiumauto.com.sa

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Regn No.: SMD29386	(V 38488)	Regn Date: 13/08/2018	Mileage: 1855	WIP No.: 22717
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V7J1073246	Engine: CHZ 472536	Dept: U
VSB No.:				
You have been assisted by :- UB-Jiayee (33)				

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V5833052C	(A) (SK) DOOR (13/09/20) Less 020%	1.00	2190.00	1,752.00
X	A8V0601025DC	RIM 16" C4E Less 020%	1.00	659.00	527.20
X	A8K0837199	CLIP Less 020%	6.00	0.70	3.36
X	A8V5839912C	SEAL Less 020%	1.00	139.00	111.20

Parts	2,393.76	Sub-Total	5,195.76
Labour	0.00		
Sublet	3,402.00	7% GST	363.70
Menus	0.00		
Lubricant	0.00	Grand Total	5,559.46

[Signature]

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Your Ref: SMD2938G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1000/2018/TF
26 Sept 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V7J1073246
Vehicle Regn No. : SMD2938G
Vehicle Mileage : 1848km
Vehicle Owner : Mr. Lo Zheng An
Certificate No : 1800102763
Policy Excess : S\$642.00 (Inclusive of GST)
Accident Date : 27 August 2018
Place : OrchardCentral
Repair Cost : \$ 5,559.46
WIP No. : 22717
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

28/8

CLAIM SUBFOLDER TRACKING

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	02 Sep 2018		06 Sep 2018 15:59	\$5,795.76	\$5,795.76	Pending for Survey Report
			Edit Adj Rpt	Edit Estimates	View Rpt	
						Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

CLAIM SUBFOLDER DETAILS			
Insured:	LO ZHENG AN,	ID: S8771408Z, Tel: +6592371273, Email: ZHENGAN87@GMAIL.COM	27/08/2018 17:0

Vehicle Reg. No.:	SMD2938G
-------------------	-----------------

Date of Loss:	27/08/2018 17:00 - :59 [14 Days From LTA Reg Date (Man Yr)]
---------------	--

Claim Type:	OD / 6247569807SG
-------------	--------------------------

Policy/Cover Note No.:	1800102763 (Comprehensive)
------------------------	----------------------------

Excess:	S\$600.00
---------	-----------

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 406699 Ubi - Tel: 67699229 / 67699230
Handling	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/09/2018]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/09/2018]

Adjuster:	LO ZHENG AN (31 / Male), NRIC: S8771408Z, Tel: +6592371273
-----------	--

[View All](#)

Compose Case Mail

ASSOCIATED MAIL RECEIVED

- ASSOCIATED MAIL RECEIVED
- AIG_SG (25/09/2018): SMD2938G / OD / 27/08/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMD2938G (6247569807SG)**
OD
Aug 27 2018 5:15PM
[LO ZHENG AN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View In Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	06/09/18 16:00	General View												1	Load JPG	☒				
2	06/09/18 16:00	General View												1	Load JPG	☒				
3	06/09/18 16:00	General View												1	Load JPG	☒				
4	06/09/18 16:00	General View												1	Load JPG	☒				
5	06/09/18 16:00	General View												1	Load JPG	☒				
6	06/09/18 16:00	General View												1	Load JPG	☒				
7	06/09/18 16:00	General View												1	Load JPG	☒				
8	06/09/18 16:00	General View												1	Load JPG	☒				
9	06/09/18 16:00	General View												1	Load JPG	☒				
10	06/09/18 16:00	General View												1	Load JPG	☒				
11	06/09/18 16:00	General View												1	Load JPG	☒				
12	06/09/18 16:00	General View												1	Load JPG	☒				
13	06/09/18 16:00	General View												1	Load JPG	☒				
14	06/09/18 16:00	General View												1	Load JPG	☒				
Documentation															1 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	06/09/18 16:28	Singapore Accident Statement												1	Load PDF					
2	06/09/18 16:29	Certificate of Insurance												1	Load PDF					
3	06/09/18 16:29	Insured's Driving License												1	Load PDF					
4	06/09/18 16:29	MARK ESTIMATE												1	Load PDF					
5	08/01/19 14:14	DISCHARGE VOUCHER												1	Load PDF					
6	08/01/19 14:14	WORKSHOP INVOICE												1	Load PDF					

Linked Accident Report Documents

View

View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/08/18 14:04	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/08/18 14:00	Accident Photo	Load JPG	☒
2	28/08/18 14:00	Accident Photo	Load JPG	☒
3	28/08/18 14:00	Accident Photo	Load JPG	☒
4	28/08/18 14:00	Accident Photo	Load JPG	☒
5	28/08/18 14:00	Accident Photo	Load JPG	☒
6	28/08/18 14:00	Accident Photo	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	28/08/18 14:00	Accident Photo	1 Load JPG	✓
8	28/08/18 14:00	Accident Photo	1 Load JPG	✓
9	28/08/18 14:00	Accident Photo	1 Load JPG	✓
10	28/08/18 14:00	Accident Photo	1 Load JPG	✓
11	28/08/18 14:00	Accident Photo	1 Load JPG	✓
12	28/08/18 14:00	Accident Photo	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/08/18 13:56	Sketch Plan	1 Load JPG	✓
2	28/08/18 13:56	Sketch Plan #2	1 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18016306/AVD3S2

Date: 08/01/2019

REFERENCE

Insured/Claimant: LO ZHENG AN Policy No: 1800102763
Date of Loss: 27/08/2018 Nature of Claim: OD Claim No: 6247569807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD2938G**
Make & Model: AUDI A3, 999cc TFSI S-TRONIC (A) Engine No: CHZ472536
Reg. Date: 13/08/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V7J1073246
Colour: Silver Odometer: 1038 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,297.00	2,393.76	5,903.24	71.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,532.00	3,402.00	10,130.00	74.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,829.00	5,795.76	16,033.24	73.45
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	21,229.00	5,195.76	16,033.24	75.53
+ GST 7.00/7.00% (S\$)	1,486.03	363.70	1,122.33	75.53
Nett Amount (S\$)	22,715.03	5,559.46	17,155.57	75.53

INSPECTION

Date of Assignment: 06/09/2018
Date Inspected: 05/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR - RH REAR	Dented	1,752.00 FS	*1,752.00 FS
2	1		*OUTER DOOR SEAL - RH	Necessary	139.00 FS	*111.20 FS
3	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
5	1		*ATTACHMENT PARTS FOR REAR DOOR - RH	Not Necessary	110.00 FS	*- FS
6	1		*REAR DOOR SEAL - RH	Not Necessary	165.00 FS	*- FS
7	1		*DOOR CATCH	Not Necessary	82.00 FS	*- FS
8	1		*COVER DOOR CATCH	Not Necessary	14.00 FS	*- FS
9	1		*SECTIONAL PART - SIDE PANEL - RH	Repair	2,006.00 FS	*- FS
10	1		*1/4 GLASS - RH REAR	Not Necessary	704.00 FS	*- FS
11	2		*PRIMER	Not Necessary	38.00 FS	*- FS
12	1		*1/4 GLASS - RH REAR	Not Necessary	502.00 FS	*- FS
13	1		*CHROME TRIM STRIP FOR 1/4 GLASS - RH	Not Necessary	387.00 FS	*- FS
14	4		*1/4 GLASS CHROME TRIM CLIP	Not Necessary	52.00 FS	*- FS
15	1		*ALUMINIUM RIM - RHS REAR	Cut	659.00 FS	*527.20 FS
16	1		*ARCYLIC SEALANT	Not Necessary	180.00 FS	*- FS
17	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
18	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*- FS
19	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
20	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
21	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*SUNDRIES	Necessary	500.00 FS	*3.36 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					8,297.00	2,393.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	New	280.00	0.00
2	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	New	600.00	0.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	0.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG.	New	1,400.00	0.00
6	TO DISMANTLE REAR BUMPER, REAR LID AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RENEW RHS REAR DOOR. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	5,400.00	1,000.00
7	TO RESPRAY RHS REAR DOOR, RHS REAR FENDER, RHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES AND END PANELLING.	New	3,700.00	1,650.00
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			13,532.00	3,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >