

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1000/2018/PH
Date : 29-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lo Zheng An
Address : Blk 239 Lorong 1 Toa Payoh
: #13-98
Singapore 310239
Telephone : (HP) +65 92371273
Type of Claim : Own Damage Claim
Policy No. : 1800102763
Vehicle No : **SMD 2938 G**
Model Code : Audi A43 1.0 TFSI
Model / Year : Aug-18
Engine No : CHZ 472536
Chassis No : WAUZZZ8V7J1073246
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Aug-18
Place of Accident : Orchard Central

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 2938 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00	X
2	To remove and transfer rhs rear door's multi-lock system and power window devices.	S/N \$ 280.00	✓
3	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	X.
4	To dislodge and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.	S/N \$ 1,400.00	X
5	To remove and reinstall rear seat,back rest,hat tray,ABCD pillar trims,luggage compartment trims,seat belts.Dislodge roof liner and disengage curtain airbag	S/N \$ 1,400.00	X.
SUB TOTAL LABOUR CHARGES		: \$ 3,960.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 2938 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dismantle rear bumper, rear lid and rhs rear door. Cut out and weld rhs rear fender. Renew rhs rear door. Re-organise rear crash management components. Reinstall all parts removed. ✓ ✓ ✓	\$ 5,400.00	1000
7	To respray rhs rear door, rhs rear fender, rhs sill panel, drain panel, roof channel, door entrances and end panelling.	\$ 3,700.00	1650
8	To renew rhs rear rim and carry out wheel alignment	S/N \$ 280.00	✓
9	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,532.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2938 G.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	DOOR - RH REAR <i>Deletd</i>	TBC		✓
2	OUTER DOOR SEAL - RH <i>new</i>	\$	139.00	✓
3	BONDING AGENT <i>?</i>	\$	43.00	✓
4	CLEANING SOLUTION <i>?</i>	\$	64.00	?
5	ATTACHMENT PARTS FOR REAR DOOR - RH <i>?</i>	\$	110.00	?
6	REAR DOOR SEAL - RH <i>not new</i>	\$	165.00	x
7	DOOR CATCH <i>new</i>	\$	82.00	+
8	COVER DOOR CATCH <i>new</i>	\$	14.00	+
9	SECTIONAL PART - SIDE PANEL - RH <i>Regis</i>	\$	2,006.00	+
10	1/4 GLASS - RH REAR <i>?</i>	\$	704.00	+
11	PRIMER <i>new</i>	2 \$	38.00	+
12	1/4 GLASS - RH REAR	\$	502.00	+
13	CHROME TRIM STRIP FOR 1/4 GLASS - RH <i>?</i>	\$	387.00	+
14	1/4 GLASS CHROME TRIM CLIP <i>new</i>	4 \$	52.00	+
15	ALUMINIUM RIM -RHS REAR <i>ct</i>	\$	659.00	✓
16	ARCYLIC SEALANT <i>?</i>	\$	180.00	x
17	CAVITY WAX	\$	140.00	x
18	STONE CHIP TREATMENT <i>new</i>	\$	180.00	+
19	METAL FILLER POWDER	\$	280.00	+
20	REAR WINDSCREEN SEALANT <i>new</i>	\$	200.00	+
TOTAL SPARE PARTS CHARGES		\$	5,945.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 2938 G

S/N		Parts Description	Damaged Parts & Prices	
			S/Nett	Remark
21		1/4 GLASS SEALANT <i>Not rec</i>	S/N \$ 100.00	X
22		SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES			:	\$ 6,545.00
TOTAL LABOUR CHARGES			:	\$ 13,532.00
GRAND TOTAL			:	\$ 20,077.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 05/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : ~~the~~ Authorised Repairs, 05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant