

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0374/2018  
DATE : 04-SEP-2018

EQ INSURANCE COMPANY LIMITED  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX S(069110)  
TEL : 62239433  
FAX : 62234190  
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR NG HIAN CHOR  
ADDRESS : 6 KERIS DRIVE  
S(456969)  
TELEPHONE NO : 92322468

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-SLJ4408L  
VEHICLE NO : EP2468C  
MODEL CODE : FRLARBZJ11UEA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2328277A  
CHASSIS NO : SJNFEAJ11U1769322  
MILEAGE : 1 KM  
DATE IN : 04/09/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 21/08/2018

**DIRECT SETTLEMENT**

**OWNER CLAIMING LOSS OF USE / RENTAL**

**CAR AT WORKSHOP / ~~CAR NOT AT WORKSHOP~~**

**KINDLY REVERT TO ME ASAP**

*05/09/2018*

**EMAIL : [zuhri@tanchong.com](mailto:zuhri@tanchong.com)**

**OFFICE : 67038916 FAX : 64697472**

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO EP2468C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	240
4	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100
6	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
7	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	/
8	ZZ/001	REPAIR SUPPORT PANEL AND RENEW FRONT BUMPER	1000.00	585
9	ZZ/002	S/PAINT SUPPORT PANEL AND FRONT BUMPER	900.00	500
10	ZZ/003	R/I REAR DVR TO ASSIST REPAIR	120.00	X
11	ZZ/004	TRANSFER TAILGATE MECHANICAL PARTS TO NEW	80.00	/
12	ZZ/005	SUPPLY AND RENEW FRONT NO. PLATE(SMART PLATE WITH CASING) LONG		
13	ZZ/006	CHECK LIGHTING	48.00	/
14	ZZ/007	REPAIR END PANEL AND RENEW TAILGATE AND REAR BUMPER	1200.00	1170
15	ZZ/008	S/PAINT REAR BUMPER (2 TONE), END PANEL, TAILGATE	1250.00	850
TOTAL LABOUR CHARGES			5926.00	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EP2468C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 EMBLEM	90892-4EA0A	87.00	<del>max</del>	
2 EMBLEM-REAR	90890-4EA0A	59.70	new	/
3 EMBLEM RAD GRIL	62890-4EA0A	73.60	new	/
4 STRIKER-TAIL GA	90570-4EA0A	31.70	X	
5 A LOCK LIFT	90502-4EA0D	116.70	?	
6 A FIN BACK DOOR TOP NO PLATE	90810-4ES0H	336.00	X	
7 WEATHER STRIP	90830-4EA0B	158.70	new	/
8 DOOR BACK	K0100-4EAAC	2936.80	PA	/
9 RUBBER-DUM	G2716-89900	60.20	new	/
10 GLASS-TAIL GATE	90300-4EA0D	930.00	new	/ photo?
11 CANOE RIVET BUMPER REAR \$6.50 EA X 02	76882-0M000	13.00	new	/
12 GROMMET BUMPER REAR \$2.50 EA X 04	63846-5V000	10.00	new	/
13 STAY ASSY-REAR RH	H5210-4EAMA	126.00	?	
14 STAY ASSY-REAR LH	H5211-4EAMA	126.00	?	
15 REINF-BUMPER RR	H5030-4EAMA	619.20	?	
16 ENERGY ABSORBER REAR BUMPER	85090-4EA0B	126.40	?	
17 BRACKET-BUMPER RH REAR	85220-4EA0A	35.90	new	/
18 BRACKET-BUMPER LH REAR	85221-4EA0A	35.90	new	/
19 RETAINER-BUMPER LH REAR	79185-4EA0A	23.80	new	/
20 RETAINER-BUMPER REAR RH	79184-4EA0A	23.80	new	/
21 CLIP BUMPER REAR \$7.40 EA X 03	85284-JD00A	22.20	new	/
22 FINISHER-REAR BUMPER TOW	85071-4EA0A	16.80	DE	/
23 FASCIA-RR BUMP	85022-4EA0H	717.00	DE	/
24 CLIP END PANEL \$1.20 EA X 02	01553-05323	2.40	new	/
25 CLIP END PANEL FINISHER \$1.20 EA X 04	01554-00181	4.80	new	/

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EP2468C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 PLATE-LUGGAGE	84992-4EA0A	63.50	?	
27 CLIP GRILLE \$1.70 EA X 04	01515-00QAB	6.80	✓	
28 GRILLE-RADIATOR	62310-4EA1A	498.30	CRA ✓	
29 CLIP BUMPER \$1.20 EA X 04	01553-05933	4.80	✓	
30 GROMMET BUMPER \$2.20 EA X 04	01281-00111			8.80 ✓
31 BRKT-BPR SIDE,RH FRONT	62222-4EA0A	20.90	?	
32 BRKT-BPR SIDE,LH FRONT	62223-4EA0A	20.90	?	
33 COVER-BUMPER FRONT TOW	622A0-4EA0A	19.30	X	
34 BUMPER SET FR	62022-4EA0H	614.60	✓	
35 CLIP ANTENNA \$3.80 EA X 02	01553-89900			7.60 ✓
36 ANTENNA-SMART KEYLESS	285E5-JK60A	53.50	?	
37 FRT LICENCE PLATE (SMART PLATE WITH CASING) LONG	FLP			60.00 ✓
38 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 ✓
39 SUNDRIES	NPN			100.00 30
40 REAR W/SCREEN SEALANT	SEALANT - 4			80.00 ✓
SUB TOTAL		7996.20	7.60	458.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1599.24	2.28	0.00
GRAND TOTAL		6396.96	5.32	458.80
OVERALL TOTAL		6861.08		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO EP2468C

-----  
TOTAL LABOUR CHARGES                    5926.00  
TOTAL SPARE PARTS CHARGES            6861.08  
-----  
GRAND TOTAL                                12787.08 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE :  
LIABILITY :  
REMARKS :

RASUL - Hp 90010068  
11/09/18 @ 1245  
0.00 8 days  
0.00

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: