

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang Mo Kio
Ind. Park 2A
568047

Insurer Reference:
Repairer Reference: MCS1102528
Date calculated: 03/09/2019 3:00 PM

Full Report
Registration: EU2927T
Printed: 03/09/2019 3:00 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Kee Mui Hong	Currency:	SGD
Claim Reference:		Date of Incident:	09/08/18
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 08
Registration:	EU2927T
VIN number:	
Odometer:	

Model Specs

REAR PARKING SYSTEM	TWO COAT METALLIC	PREPARE OFF VEHICLE
---------------------	-------------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 45.00 SGD/h

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang Mo Kio
Ind. Park 2A
568047

Insurer Reference:

Repairer Reference: MCS1102528

Date calculated: 03/09/2019 3:00 PM

Full Report

Registration: EU2927T

Printed: 03/09/2019 3:00 PM

Code	Description	WU	Price SGD
7141A5	R + R RIGHT OUTER TAILLAMP	1.0	4.50
8131B8	REMOVE AND REFIT R/R S-PANEL MOULDING	2.0	9.00
8131A9	R + R RIGHT REAR WHEELHOUSE SHELL	3.0	13.50
8111C4B	R + R RIGHT REAR BUMPER CORNER INCLUDES: REMOVE AND REFIT REAR BUMPER AND REQUIRED ATTACHED PARTS	6.0	27.00
Labour Cost			
	Panel / Mechanical Labour	Hrs 1.20	WU 12.0
	Total of Labour		54.00

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	R/R BUMPER CORNER NEW PART PAINT K1G/P	8.0	

Paint Material Per Part

Code	Description	Price SGD
2588	R/R BUMPER CORNER NEW PART PAINT K1G/P	18.90

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		8.0	
Preparation Comp. Work Plastic	2.50	25.0	112.50
Total	10 WU/h	3.30	33.0

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1G/PUR	18.90
Material-constant Plastic	28.60
Total	47.50

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01
				Price SGD
2588	R/R BUMPER CORNER	71502T7JH00ZZ		60.00
3672	R/R S-PANEL MOULDING	74410T7MH01		40.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Audatex System Using Manufacturer Times

Page 2 of 3

PRINT DATE 03/09/2019

AH LIM Motor Company
#01-09, AMK Autopoint, 10 Ang Mo Kio
Ind. Park 2A
568047

Insurer Reference:
Repairer Reference: MCS1102528
Date calculated: 03/09/2019 3:00 PM

Full Report
Registration: EU2927T
Printed: 03/09/2019 3:00 PM

Savings	0.00
Subtotal	100.00
Addition(+15.00%)	15.00
Total	115.00

Extras

Code	Description	Price SGD
1000	SPORTS RIM -REPAIR	120.00*
1001	WHEEL ALIGNMENT	80.00*
	Total Extras	200.00

Final Calculation

	SGD	SGD
Parts	100.00	
Addition(+15.00%)	15.00	
Total Parts		115.00
Labour Time Base 10 WU/h		
Total 12.0 WU X 45.00 SGD/h	54.00	
Total of Labour		54.00
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 45.00 SGD/h	148.50	
Material Cost	47.50	
Total Paint Including Material		196.00
Repair Cost Excludes GST		565.00
GST (+7.0%)		39.55
Repair Cost Included GST		604.55

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.