

**Ah Lim Motor Company**  
**10 Ang Mo Kio Industrial**  
**Park 2A**  
**#01-09 AMK Autopoint**  
**Singapore 568047**

**Claim Reference:**  
**Assessment Number: AH000914**  
**Version: AHLIM001/1**  
**Date Calculated: 04/09/2018 04:40**

**Full Report - V1**  
**Registration: EU2927T**  
**Printed: 04/09/2018 12:57**

---

### Summary Information

#### Claim

|                       |                              |                            |     |
|-----------------------|------------------------------|----------------------------|-----|
| Location:             | Singapore (SG)               | Currency:                  | SGD |
| Printed by:           | Ahlim ahlim                  | Date of Incident:          |     |
| Authorisation Status: | Interim                      | Able to Authorise Repairs: | TBA |
| Work Provider:        | AXA Insurance S'pore Pte Ltd | Repairs Authorised:        | TBA |
| Claim Reference:      |                              | Estimated Repair Time:     |     |
| Policy Number:        |                              | Quote Due Date:            |     |
| Other Reference:      |                              | Actual Repair Days:        |     |
| Third Party:          |                              | Parts Ordered Date:        |     |
| Insured Amount:       |                              | Hire Car Start:            |     |
| Under Warranty:       |                              | Hire Car End:              |     |
| Warranty Expired:     |                              | Vehicle Collected:         |     |

#### Vehicle Details

##### Vehicle

|                     |            |
|---------------------|------------|
| Manufacturer:       | HONDA      |
| Model:              | Vezel      |
| Sub Model:          | BASE MODEL |
| Model Sheet Number: | HVE 01     |
| Registration:       | EU2927T    |
| Registration Month: | November   |
| Registration Year:  | 2015       |
| VIN Number:         |            |
| Manufacture Year:   | 2015       |
| Odometer:           | Not Known  |
| Colour:             |            |
| Engine Number:      |            |
| Fuel Level:         | %          |

##### Model Specs

|                     |                   |
|---------------------|-------------------|
| REAR PARKING SYSTEM | TWO COAT METALLIC |
| PREPARE OFF VEHICLE |                   |



#### Vehicle Condition

##### Vehicle Status

|                         |                               |            |
|-------------------------|-------------------------------|------------|
| Pre-Accident Condition: | Severity of Impact:           |            |
| Steering:               | Vehicle Status on Inspection: |            |
| Brakes Pedal Travel:    | Date of Inspection:           | 04/09/2018 |
| Place of Inspection:    |                               |            |
| Pre-Accident Damage:    |                               |            |
| Tyres Condition:        |                               |            |
| Tread Depth LHF:        | Tread Depth RHF:              |            |
| Tread Depth LHR:        | Tread Depth RHR:              |            |
| Damage Areas:           | Direction of Impact:          |            |

**Claim Reference:**  
**Assessment Number: AH000914**  
**Version: AHLIM001/1**  
**Date Calculated: 04/09/2018 04:40**

**Full Report - V1**  
**Registration: EU2927T**  
**Printed: 04/09/2018 12:57**



## Addresses

## Cost Summary

|                           |            |
|---------------------------|------------|
| Total Labour              | \$427.50   |
| Total Paint/Material      | \$73.12    |
| Total Parts               | \$1,034.43 |
| Total of Additional Costs | \$80.00    |
| Excess:                   | TBA        |
| Grand Total Exc GST:      | \$1,615.05 |
| 7 % GST:                  | \$113.05   |
| Grand Total Inc GST:      | \$1,728.10 |

## Repair Information

### LABOUR

**Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR**  
**Price/Dent = \$45.00/HR**

### Repair /

| Guide Number       | Repair Details   | WU            | Cost Price (\$) |
|--------------------|--|---------------|-----------------|
| 7141A5             | R + R RIGHT OUTER TAILLAMP   | 1.0           | 4.50            |
| 8131B8             | REMOVE AND REFIT R/R S-PANEL MOULDING                              | 2.0           | 9.00            |
| 8131A9             | R + R RIGHT REAR WHEELHOUSE SHELL                                  | 3.0           | 13.50           |
| 8111C4B            | R + R RIGHT REAR BUMPER CORNER                                     | 6.0           | 27.00           |
|                    | INCLUDES: REMOVE AND REFIT REAR BUMPER AND REQUIRED ATTACHED PARTS |               |                 |
| 8571C9)            | R + R R/R SIDE PANEL TRIM  | 2.0           | 9.00            |
| 848140             | R + R REAR END PANEL TRIM  | 2.0           | 9.00            |
| 4211F4)            | R + R R/R TYRE AND BALANCE   | 4.0           | 18.00           |
| 4211A6             | R + R R/R WHEEL  | 2.0           | 9.00            |
| 3482               | REPAIR R/R SIDE PANEL  | 10.0*         | 45.00           |
| <b>LABOUR COST</b> |  |               |                 |
|                    | <b>Total Work Units</b>  | <b>32.0</b>   |                 |
|                    | <b>Corrosion Protection External Labour</b>                        | <b>0.0HRS</b> | <b>0.00</b>     |
|                    | <b>Corrosion Protection Internal Labour</b>                        | <b>0.0HRS</b> | <b>0.00</b>     |
|                    | <b>Sub Total</b>   | <b>3.2HRS</b> | <b>\$144.00</b> |
|                    | <b>Paint Labour</b>  | <b>6.3HRS</b> | <b>\$283.50</b> |
|                    | <b>Total Labour</b>  | <b>9.5HRS</b> | <b>\$427.50</b> |

### PAINT WORK

**Time Basis 10 WU = 1 HR. Price = \$45.00/HR**

| Guide Number               | Description                            | WU          | Cost Price (\$) |
|----------------------------|--|-------------|-----------------|
|                            | - TWO COAT METALLIC                    |             |                 |
|                            | - PREPARE OFF VEHICLE                  |             |                 |
| 2588                       | R/R BUMPER CORNER REPAIR PAINT PLASTIC | 10.0        |                 |
| 3482                       | R/R SIDE PANEL REPAIR PAINTING >50%    | 20.0        |                 |
| <b>LABOUR COST - PAINT</b> |  |             |                 |
|                            | <b>TIME(PAINT)</b>                     | <b>30.0</b> |                 |

# Ah Lim Motor Company

**Claim Reference:**  
**Assessment Number: AH000914**  
**Version: AHLIM001/1**  
**Date Calculated: 04/09/2018 04:40**

**Full Report - V1**  
**Registration: EU2927T**  
**Printed: 04/09/2018 12:57**

|                                    |        |                   |
|------------------------------------|--------|-------------------|
| Preparation Main Work Plastic      | 8.0    |                   |
| Preparation Main Work Metal        | 25.0   |                   |
| Preparation Work Multi Layer Paint | 0.0    |                   |
| Total Work Units (10WU/HR)         | 63.0   |                   |
| Total Paintwork Labour             | 6.3HRS | \$283.50          |
| <b>MATERIAL COST - PAINT</b>       |        | <b>Cost Price</b> |
| Repair Painting                    |        | \$23.31           |
| Repair Painting Plastic            |        | \$8.51            |
| Material-Const Main Work Plastic   |        | \$12.70           |
| Total Excluding Pearlescent Uplift |        | \$73.12           |
| Pearlescent Uplift @ 0.0%          |        | \$0.00            |
| Total Paint Material Cost          |        | \$73.12           |

## PARTS

| Price Valid: 01/06/2015 |     |                      |                          |          |                   |
|-------------------------|-----|----------------------|--------------------------|----------|-------------------|
| Guide No.               | Qty | Description          | Part Number              | Supplier | Bet. Price (\$)   |
| 2588                    | 1   | R/R BUMPER CORNER    | 71502T7JH00ZZ            |          | 0% 60.00*         |
| 2620                    | 1   | R/R OUT BUMPER BRKT  | 71593T7A000              |          | 0% 12.00*         |
| 2650                    | 8   | RR BUMPER CLAMP KIT  | 91505TM8003              |          | 0% 37.50*         |
| 3672                    | 1   | R/R S-PANEL MOULDING | 74410T7MH01              |          | 0% 40.00*         |
| 9552                    | 1   | R/R WHEEL            | 42700T8CT91              |          | 0% 750.00*        |
| f: OEM Parts            |     |                      | Sub Total                |          | \$899.50          |
| g: Original             |     |                      | Mark Up From Cost (15 %) |          | \$134.93          |
| h: Secondhand           |     |                      | <b>Total Parts</b>       |          | <b>\$1,034.43</b> |
| p: Parallel             |     |                      |                          |          |                   |
| x: Exchange             |     |                      |                          |          |                   |

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

| Description                | Betterment          | Price          |
|----------------------------|---------------------|----------------|
| WHEEL ALIGNMENT SPECIALIST | 0%                  | \$80.00        |
|                            | <b>Total Extras</b> | <b>\$80.00</b> |

## Final Calculation

|                                   |                   |
|-----------------------------------|-------------------|
| <b>Total Parts</b>                | <b>\$1,034.43</b> |
| <b>Labour</b>                     |                   |
| Total Panel/Mechanical            | \$144.00          |
| Total Paintwork                   | \$283.50          |
| <b>Total Labour</b>               | <b>\$427.50</b>   |
| <b>Additional Costs</b>           |                   |
| Corr Prot Materials External      | \$0.00            |
| Corr Prot Materials Internal      | \$0.00            |
| Cost of Specialist                | \$80.00           |
| <b>Total of Additional Costs</b>  | <b>\$80.00</b>    |
| <b>Total Paint/Material Costs</b> | <b>\$73.12</b>    |
| <b>Grand Total Excludes GST</b>   | <b>\$1,615.05</b> |
| GST @ 7 %                         | \$113.05          |
| <b>Grand Total Includes GST</b>   | <b>\$1,728.10</b> |

## Assessment Notes

**Claim Reference:**

**Assessment Number: AH000914**

**Version: AHLIM001/1**

**Date Calculated: 04/09/2018 04:40**

---

**Full Report - V1**

**Registration: EU2927T**

**Printed: 04/09/2018 12:57**