

1392100

INS. CASE OWNER:

Glancy | CC 4 / AXA1801 b210, 4ph2^{sz}

LKK: IDAC:

Surveyor:

Manus

DOI:

ASSIGNMENT 7/9/18

Date / Time:

6/9/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFE 3906K

Name of Insured:

TAN TAN LIEW.

Insured Tel No.:

HP: 91178400

Excess Sec II :SS

D.O.A: 4/9/18

Is driver the own? (YES / NO)

(YES / NO)

Nature of Accident:

Claim No.:

SEMONEY | 67856

Policy No.:

GA0200671

Make / Model:

UTROV.

Place of Accident:

SFE > SLE

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SJL 6779L



INRS: WSP: Tel: Liability: RMKS:

Lee Sheng



INRS: WSP: Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
6/9/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call Of:	Lee 7/9/18
	After call ltr to OI:	
7/9/18 3.22pm	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 20 NOV 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	days Reduction: %
Confirm by:	Email	Call
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	W/h/r SS	
Loss of Rental (LOR):	SS	(days)
Loss of Use (L.U):	SS	(S x days)
Loss of Income (LOI):	SS	(S x days)
LOR only	<input type="checkbox"/>	LOU only <input type="checkbox"/>
LOR + LOU	<input type="checkbox"/>	LOR + LO <input type="checkbox"/>
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/Independent)
Legal Cost	SS	
Total:	SS	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS	Name 1:
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$350.00

REF: AXA

ASSIGNMENT

From: Date: 7/9/18

Veh No: SJL 6379C Yr Regn: 12 OB

Estimated Cost:

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or CA /

To Inspect Vehicle No: SJL 6379L

Make: Nissan Teana C.C. 1997

at Workshop n/s: Lee Sheng
of 1 Kaki Bkt Ave 6 #01-60

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 147718 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: JN1BDUJ32Z0000620

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Harder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Harder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/60R18

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIS / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

19k.

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 4/9/18

D.O.I. 7/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12/2018 3rd. next 4535

7/9/18 2/5 # 4500 confirm with Ms Lee

CRed # 11765-33/7201

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: Site Insp (\$

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18016310/pb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 06-09-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKE 3906K	Veh. Inspected	SJL 6379L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/09/2018	Inspection Date	
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

LEE SHENG AUTO PTE LTD

1;Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : leesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. PANCHATCHARAM RAMU
 BLK 440B FERVALE LINK #09-169
 S 792440

Attention : Motor Claim Department
 Contact : 91071354

*Not Affected
 note
 2/5 # 4500/2
 7/9/18
 Whichever Affected
 LK*

Estimate : ES000744

Date : 06/09/2018
 Vehicle Num. : SJL 6379L
 Make/Model : NISSAN TEANA
 Chassis/Eng# :
 Accident Date : 04/09/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1 PC	TRUNKLID		
	1 PC	TRUNKLID CHROME GARNISH		
	1 PC	TRUNKLID CHROME LOWER GARNISH		
4.	1 PC	TRUNKLID LOGO		
5.	1 PC	TRUNKLID TENNA EMBLEM		
6.	1 PC	TRUNKLID 200XL EMBLEM		
7.	1 PC	TRUNKLID LOCK		
8.	1 PC	TRUNKLID TRIM BOARD		
9.	2 PCS	TRUNKLID HINGES		
10.	1 PC	TRUNKLID WEATHERSTRIP		
11.	2 PCS	REAR LAMPS		
12.	1 PC	REAR BUMPER		
13.	2 PCS	REAR BUMPER RETAINER		
14.	2 PCS	REAR BUMPER BRACKET		
15.	1 PC	REAR BUMPER STAY		
16.	1 PC	REAR BUMPER REINFORCEMENT		
17.	8 PCS	REAR BUMPER CLIPS		
18.	1 PC	REAR END PANEL		
19.	1 PC	REAR END PANEL TOP GARNISH		
20.	1 PC	SPARE TYRE PANEL		
21.	1 PC	SPARE TYRE PANEL INSULATOR		
22.	2 PCS	REAR BUMPER SIDE CHROME		
23.	2 PCS	REAR LAMP BRACKET		
24.	1 PC	SPARE TYRE PANEL		

*20/dec 1,243.90
 117 106.60
 178.00
 35.20
 56.20
 66.40
 108.00
 220.00
 85.00 170.00
 96.70
 429.10 858.20
 931.00
 27.20 54.40
 91.70 183.40
 167.12
 437.00
 3.50 28.00
 695.00
 109.80
 850.00
 120.00
 221.30 442.60
 85.00 170.00
 950.00*

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*P-5643.80
 less 50%
 2821.9
 plus S.N 240
 1 down - 1860
 4921.90*

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : leesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. PANCHATCHARAM RAMU
 BLK 440B FERVALE LINK #09-169
 S 792440

Estimate : ES000744

Date : 06/09/2018
 Vehicle Num. : SJL 6379L
 Make/Model : NISSAN TEANA
 Chassis/Eng# :
 Accident Date : 04/09/2018
 Claim No. :
 Reference :
 Policy No. :

Attention : Motor Claim Department
 Contact : 91071354

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1 PC	SPARE TYRE PANEL INSULATOR	180.00	180.00
26.	1 PC	SPARE TYRE PANEL TOP BOARD	220.00	220.00
27.	1 PC	SPARE TYRE PANEL TOOL TRAY	120.00	120.00
28.	2 PCS	SPARE TYRE SIDE BOARD	439.40	878.80
29.	1 PC	REAR FENDER	1136.80	1,136.80
30.	2 PCS	REAR FENDER INNER TRIM	342.40	684.80
31.	1 PC	REAR FENDER WATER SHIELD	150.00	150.00
32.	1 PC	REAR EXHAUST MUFFLER	478.00	478.00
33.	1 PC	REAR EXHAUST MOUNTING	180.00	180.00
Nett Total S\$:				12,305.92
10.00% Discount S\$:				1,230.59
				11,075.33
SPECIAL NETT ITEMS :				
1.	1 <i>pc set</i>	REVERSE SENSOR	250.00	250.00
2.	1 PC	TRUNKLID LOCK SENSOR	280.00	280.00
3.	1 PC	TRUNKLID OUTER HANDLE SENSOR	250.00	250.00
4.	1 PC	SEALANT	60.00	60.00
5.	1 PC	REAR NUMBER PLATE & BASE	50.00	50.00
Special Nett Total S\$:				890.00
LABOUR :				
KNOCKING, CUTTING, JACKING WELDING ETC				2,200.00

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. PANCHATCHARAM RAMU
BLK 440B FERVALE LINK #09-169
S 792440

Attention : Motor Claim Department
Contact : 91071354

Estimate : ES000744

Date : 06/09/2018
Vehicle Num. : SJL 6379L
Make/Model : NISSAN TEANA
Chassis/Eng# :
Accident Date : 04/09/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINTING		
		TO APPLY RUST-PROOFING ON AFFECTED AREA	1000	1,800.00
		REMOVE & REFIX REAR WINDSCREEN	60	180.00
			120	120.00
		Labour Total S\$:		4,300.00

Total S\$: 16,265.33
=====

LEE SHENG AUTO PTE LTD



S.N. 240
1dm - 1860

Service Request Details

Claim

S8M00UKJ

Reference

None 

Loss Date

September 4, 2018

Request Date

September 6, 2018

Due Date

September 13, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

6/9 @ 3.47 pm Vehicle in.

Vehicle Information

Incident Vehicle Registration #

SJL6379L

Make

TPVD NISSAN

Model

TEANA-2.0 CVT (A)

Service Address

Primary Contact/Insured

TAN TAI CHIEW
BLK 467A #05-177, ADMIRALTY DRIVE, 751467, Singapore
91178400

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

[Messages](#) [Invoices](#) [History](#) [Documents](#) [Assessment](#) [Metrics](#) [Notes](#)

[New Message](#)



<SEEK MANDATE> - S8M00UKJ [ACCIDENT INVOLVING SKE 3906K(OI) & SJL 6379L(TP) ON 04/09/2018]

Type

🔔 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate up to \$5,871.09(all-in). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 15 Oct 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/10/2018

Survey Details:

Date of loss	4-Sep-18
Date of appointment	6-Sep-18
Date of survey	7-Sep-18
Location of survey	LEE SHENG AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJL 6379L
Make and Model	NISSAN TEANA 2.0L CVT ABS D/AIRBAG 2WD
Date of registration	5/12/2008
Excess	
Market Value	\$19,000
Parf Rebate	\$14,465
Nett Loss	\$4,535

Repair details:

Initial Estimate	\$	16,265.33
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$	3,061.90
Check items (estimate)	\$	-
Labour	\$	1,860.00
Total	\$	4,921.90
Lump Sum(if applicable)	\$	4,500.00

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	4,815.00	
Loss of use		NIL	
Loss of rental (w/GST)	\$	1,048.60	(7days x \$140.00)
Loss of income		NIL	
LTA search fees	\$	7.49	
Others		NIL	
Proposed Total	\$	5,871.09	

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 30 October 2018 8:41 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 67856, vehicle number SJL6379L



10/29/18 11:05 PM

NG Stacey

Re: <SEEK MANDATE> - S8M00UKJ [ACCIDENT INVOLVING SKE
3906K(OI) & SJL 6379L(TP) ON 04/09/2018]

pls proceed



Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Tuesday, 30 October 2018 7:41 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 67856, vehicle number SJL6379L

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue
1, #02-25 | S(408933)

-----Original Message-----

From: stacey.ng@axa.com.sg [mailto:stacey.ng@axa.com.sg]
Sent: Monday, 29 October 2018 11:06 PM
To: admin-d@lkkauto.com
Subject: New message for service request 67856, vehicle number SJL6379L

AXA Insurance has sent you a message for claim number S8M00UKJ.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Hsiao Tong (LKKAuto)

From: Ms Lee (Lee Sheng Auto) <ekchen_lee@leeshengauto.com.sg>
Sent: Wednesday, 31 October 2018 12:25 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: ACCIDENT ON 04/09/2018 INVOLVING SJL6379L/SKE3906K ALONG CTE/SLE
AFTER AMK AVE 1
Attachments: SJL6379L-31102018121938.pdf

Hi Hsiao Tong.

Please find attachment claiming document for vehicle no SJL6379L.

Thanks

Miss Lee

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKE 3906K (Insd veh)	Model:	NISSAN TEANA (A
	SJL 6379L (TP veh)		
Date of Accident:	04/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$		17,403.90
Final Repair Cost	: \$		4,815.00
Loss of Use	: \$		480.00
Rental (if any)	: \$		6 days at \$80.00 per day
LTA / GIA Search Fee	: \$		days

Others:	: \$	
---------	------	--

	: \$	
Final Settlement Sum	: \$	5,295.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown

1)	LEE SHENG AUTO PTE LTD	: \$	5,295.00
----	------------------------	------	----------

NUR SHAQILAH BTE ABDOL
WAHAB

22/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18016310/Upb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG		Date : 22-11-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKE 3906K	Veh. Inspected	SJL 6379L
Policy No.	GA020062/1	Coverage (\$)	0.00
Claim No.	S8M00UKJ	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	06/09/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN TEANA (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JN1BDUJ32Z0000620	Colour	WHITE
Odometer	147718	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R18	MICHELIN	7 mm
L/H Front Tyre	215/60R18	MICHELIN	7 mm
R/H Rear Tyre	215/60R18	MICHELIN	7 mm
L/H Rear Tyre	215/60R18	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/09/2018	Inspection Date	07/09/2018
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 6379L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TRUNKLID (N) (CONSISTENT)	DENTED / BUCKLED	1,243.90	1,243.90
1	TRUNKLID CHROME GARNISH (N) (CONSISTENT)	NOT NECESSARY	106.60	-
1	TRUNKLID CHROME LOWER GARNISH (N) (CONSISTENT)	CRACKED / BENT	178.00	178.00
1	TRUNKLID LOGO (N) (CONSISTENT)	NECESSARY	35.20	35.20
1	TRUNKLID TENNA EMBLEM (N) (CONSISTENT)	NECESSARY	56.20	56.20
1	TRUNKLID 200XL EMBLEM (N) (CONSISTENT)	NECESSARY	66.40	66.40
1	TRUNKLID LOCK (N) (CONSISTENT)	TWISTED	108.00	108.00
1	TRUNKLID TRIM BOARD (N) (CONSISTENT)	NOT NECESSARY	220.00	-
2	TRUNKLID HINGES @ \$85.00 (N) (CONSISTENT)	NOT NECESSARY	170.00	-
1	TRUNKLID WEATHERSTRIP (N) (CONSISTENT)	TWISTED	96.70	96.70
2	REAR LAMPS @ \$429.10 (N) (CONSISTENT)	CRACKED	858.20	858.20
1	REAR BUMPER (N) (CONSISTENT)	DISTORTED	931.00	931.00
2	REAR BUMPER RETAINER @ \$27.20 (N) (CONSISTENT)	BENT	54.40	54.40
2	REAR BUMPER BRACKET @ \$91.70 (N) (CONSISTENT)	BENT	183.40	183.40
1	REAR BUMPER STAY (N) (CONSISTENT)	NO SUCH PARTS	167.12	-
1	REAR BUMPER REINFORCEMENT (N) (CONSISTENT)	DENTED	437.00	437.00
8	REAR BUMPER CLIPS @ \$3.50 (N) (CONSISTENT)	NECESSARY	28.00	28.00
1	REAR END PANEL (N) (CONSISTENT)	BADLY DENTED	695.00	695.00
1	REAR END PANEL TOP GARNISH (N) (CONSISTENT)	TWISTED	109.80	109.80
1	SPARE TYRE PANEL (N) (CONSISTENT)	TO REPAIR SEE LABOUR	850.00	-
1	SPARE TYRE PANEL INSULATOR (N) (CONSISTENT)	NOT NECESSARY	120.00	-
2	REAR BUMPER SIDE CHROME @ \$221.30 (N) (CONSISTENT)	CRACKED	442.60	442.60
2	REAR LAMP BRACKET @ \$85.00 (N) (CONSISTENT)	NOT NECESSARY	170.00	-
1	SPARE TYRE PANEL (N) (CONSISTENT)	TO REPAIR SEE LABOUR	950.00	-
1	SPARE TYRE PANEL INSULATOR (N) (CONSISTENT)	NOT NECESSARY	180.00	-
1	SPARE TYRE PANEL TOP BOARD (N) (CONSISTENT)	NOT NECESSARY	220.00	-
1	SPARE TYRE PANEL TOOL TRAY (N) (CONSISTENT)	TORN	120.00	120.00

Report Ref No. CC4/ASM18016310/Upp3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SPARE TYRE SIDE BOARD @ \$439.40 (N) (CONSISTENT)	NOT NECESSARY	878.80	-
1	REAR FENDER (N) (CONSISTENT)	NOT NECESSARY	1,136.80	-
2	REAR FENDER INNER TRIM @ \$342.40 (N) (CONSISTENT)	NOT NECESSARY	684.80	-
1	REAR FENDER WATER SHIELD (N) (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR EXHAUST MUFFLER (N) (CONSISTENT)	TO REPAIR SEE LABOUR	478.00	-
1	REAR EXHAUST MOUNTING (N) (CONSISTENT)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-1,230.59	-
	LESS 50% DISCOUNT		-	-2,821.90
			11,075.33	2,821.90
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	200.00
1	TRUNKLID LOCK SENSOR (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	TRUNKLID OUTER HANDLE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	SEALANT (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR NUMBER PLATE & BASE (SN) (CONSISTENT)	BENT	50.00	40.00
			890.00	240.00
	LABOUR			
	KNOCKING, CUTTING, JACKING WELDING ETC. INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL AND REAR EXHAUST MUFFLER.		2,200.00	800.00
	SPRAY PAINTING.		1,800.00	1,000.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		180.00	60.00
	REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
			4,300.00	1,860.00
GRAND TOTAL			16,265.33	4,921.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/ASM18016310/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.