

ESTIMATE TO REPAIR

VEHICLE NO. : SJK 219 K
MAKE : HONDA
MODEL : FREED HYBRID SENSING 1.5G A
YEAR : 2017
CHASSIS NO : GB71024643

SURVEYOR NAME :
DATE OF SURVEY : 07 SEP 2018
TIME OF SURVEY :

DATE : 6-Sep-18
DATE OF ACCIDENT : 4-Sep-18
THIRD PARTY REF : SDL 1380 K / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 925.00
2 pcs	Rear Bumper Bracket		\$ 30.50		\$ 61.00
2 pcs	Rear Bumper Retainer		\$ 24.90		\$ 49.80
1 pc	Rear End Panel				\$ 623.70
1 pc	Rear End Panel Garnish				\$ 115.20
1 pc	Tailgate				\$ 1,100.00
1 pc	Tailgate Lock				\$ 157.10
1 pc	Tailgate Rubber				\$ 168.00
1 pc	Tailgate Centre Emblem				\$ 32.50
1 pc	Tailgate Outer Chrome Handle				\$ 320.40
1 pc	N/S Tailgate Lamp				\$ 360.00
1 pc	N/S Taillamp				\$ 580.00
1 set	Rear Windscreen Moulding				\$ 120.00
					\$ 4,612.70
	Less 20%				\$ 922.54
					\$ 3,690.16
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
	To putty and spray painting.				\$ 1,000.00
	Towing Charges (4 - Wheels)				\$ 120.00
	To transfer tailgate fittings.				\$ 80.00
	To remove and refix rear windscreen glass.				\$ 120.00
	To anti-rust.				\$ 80.00
	Labour Charges.				\$ 800.00
TG-RA/-	TOTAL				\$ 6,170.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____