

ESTIMATE TO REPAIR

VEHICLE NO. : SJK 219 K
 MAKE : HONDA
 MODEL : FREED HYBRID SENSING 1.5G A
 YEAR : 2017
 CHASSIS NO : GB71024643

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 6-Sep-18
 DATE OF ACCIDENT : 4-Sep-18
 THIRD PARTY REF : SDL 1380 K / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 925.00
2 pcs	Rear Bumper Bracket		\$ 30.50		\$ 61.00
2 pcs	Rear Bumper Retainer		\$ 24.90		\$ 49.80
1 pc	Rear End Panel				\$ 623.70
1 pc	Rear End Panel Garnish				\$ 115.20
1 pc	Tailgate				\$ 1,100.00
1 pc	Tailgate Lock				\$ 157.10
1 pc	Tailgate Rubber				\$ 168.00
1 pc	Tailgate Centre Emblem				\$ 32.50
1 pc	Tailgate Outer Chrome Handle				\$ 320.40
1 pc	N/S Tailgate Lamp				\$ 360.00
1 pc	N/S Taillamp				\$ 580.00
1 set	Rear Windscreen Moulding				\$ 120.00
					\$ 4,612.70
	Less 20%				\$ 922.54
					\$ 3,690.16
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
	To putty and spray painting.				\$ 1,000.00
	Towing Charges (4 - Wheels)				\$ 120.00
	To transfer tailgate fittings.				\$ 80.00
	To remove and refix rear windscreen glass.				\$ 120.00
	To anti-rust.				\$ 80.00
	Labour Charges.				\$ 800.00
TG-RA/-	TOTAL				\$ 6,170.16

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0