

ASS. REC. BY:

REF: CS/FCI 18016324/ Uvdjⁿ² Special Instruction:

Surveyor:

Markus

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time: 6/9/18 @ 3:45pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 6578Y

Insured:

SHB 4822M

at Workshop m/s

Kah Motor

Tel:

81006306

of

15 Ubi Rd 4

Policy No:

Claim No:

D18006631 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

4:36pm @ 6/9/18

Person Contacted:

Any

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJR 6578Y - X
	SHB 4822M - N/A IAG 12062396 / K DoA: 6/2/2012
7/9/18-	VNI (ARY)
11/9/18-	Vehicle not In yet (ARY)
19/9/18-	Vehicle still not In yet (ARY) (waiting for liability)

REF: FCI

ASSIGNMENT

From: Date: 01-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

SJR 6578Y

Kah motor

15 Ubi Rd 4

Any
after 9am

N/S	O/S

78k

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

L7A 49373

Vehicle: IN / OUT

Veh No: SJR 6578Y Yr Regn: Y 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (CA)

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Honda Jazz

Grey

705-2

YHM 6K5850JX 205203

Good

Inorder

Inorder

Nil

F:

R:

Rear

7 mm

7 mm

5/9/18

Rear

Rear

Rear

Date / Time

Action / Instruction

3/10/18 Email preli revised to FCI

5/10/18 confirmed final by #5946.10 with Ary. (Red 8760.98, 6010)

RECEIVED 08 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 8/10- typist

Report Format :

Lump Sum / I.B.I. (\$)

CWS

5946.10

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

4x15: 60

170 + 60

50

50

55

385



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006631MFSH

Our ref: CS/FCI18016324/Uvd3

DATE: 3/10/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO.SJR 6578Y


We thank for your instruction on 6/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 1/10/2018 at the premises of M/s KAH MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$14,707.08
Revised Estimate Amount	: S\$3,051.63
"Check" Items Amount	: S\$10,228.33
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	06-09-2018	Our Ref No. D18006631MFSH
Accident Date	05-09-2018	Claim Type. Third Party
Insured Vehicle	SHB4822M	Third Party Vehicle. SJR6578Y
Survey Location	15 UBI ROAD 4	
Contact Person.	ARY CHUA WAI NGEE	
Contact No.	68465673/ 81006306	Fax No. 67480770
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 3 October 2018 12:58 PM
To: 'Claim Workflow System'
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006631MFSH/1, SJR 6578Y
Attachments: SJR 6578Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJR 6578Y
Date of survey: 1/10/2018
Number of days : 5-7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 6 September 2018 4:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006631MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 6 September 2018 3:44 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006631MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0252J

Vehicle Details

Vehicle No.:	SJR6578Y
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	L15B33112562
Chassis No.:	JHMGK5850JX205203
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,488.00
Original Registration Date:	13 Apr 2018
First Registration Date:	13 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$16,488.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2028
PARF Rebate Amount:	\$12,366.00

Intended COE Rebate Details

COE Expiry Date:	12 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,830.00
COE Rebate Amount:	\$37,007.00
Total Rebate Amount:	\$49,373.00

The information contained herein is correct as at 01 Oct 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



① ×

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years COE Renewal Toyota Wish 1.8A.



\$2000 Down Payment Monthly
From \$638 Onwards. Lowest
3.18% P.A. @ GV Cars Financing.
GV Credit Pte Ltd StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category Sort by Date Posted 20 results/page

8 vehicles

honda jazz

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda jazz		Any	Any	2017	Any	Any	Any	Available
	Honda Jazz	1.5A RS	\$71,800	\$7,930 /yr	23-Jan-2017	1,498 cc	32,956 km	Hatchback	Available
Price Slashed To Clear! Guaranteed Cheapest In The Whole Market! 5 Years Unlimited Mileage Warranty By Agent! Owner Upgrading To New 7-Seater SUV Due To Family Expansion. Built In Japan Model! High Lo...									
Posted: 29-Sep-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.5A	\$75,800	\$8,150 /yr	05-Apr-2017	1,498 cc	21,000 km	Hatchback	Available
100% Accident Free. 1 Owner Fully Serviced By KAH Motors Agent. New 6 Months Road Tax. Use Mainly For Work Only. LED Headlights And Fog Lights And Two Front Doors LED Scuff Plate. 16 Inches Gloss Blac...									
Posted: 29-Sep-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.5A RS (OPC)	\$62,800	\$6,590 /yr	24-May-2017	1,498 cc	14,930 km	Hatchback	Available
\$62.8k! Lowest Price Tagged 2017 Honda Jazz 1.5A RS OPC Version In Showroom Now! Revised OPC Version! Full Maintenance And Recorded By KM Agent! Seller Upgrading Trade In! Buy With Peace Of Mind As KM...									
Posted: 27-Sep-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.5A RS	\$71,800	\$7,880 /yr	25-Jan-2017	1,498 cc	30,000 km	Hatchback	Available
Lowest Interest Rate Starting From 2.28%! Wide Range Of Loan Packages With Low Down Payment! Kah Motor Warranty Till Jan 2022 With 2 Free Engine Oil Servicing And 1 Free Gear Oil Servicing! Great Savi...									
Posted: 26-Sep-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Pro-Jex V2D Auto Pte Ltd - Specialty Workshops								
Power up for excellent performance with PRO-JEX V2D, your one-stop automobile solution provider.									
More info about this shop									
	Honda Jazz	1.5A RS	\$72,000	\$7,870 /yr	02-Feb-2017	1,498 cc	23,000 km	Hatchback	Available
Only 10% Downpayment! Safe Purchase! Agent Warranty! Fuel Saver! Trouble Free! Good Handling And Performance, 90% Loan Can Be Arranged! High Trade In For Your Car! Buying A Beauty Pre-Owned Car With U...									
GD Motoring									
Posted: 26-Sep-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.5A RS	\$72,500	\$7,820 /yr	16-Mar-2017	1,498 cc	51,200 km	Hatchback	Available
\$0 Down Payment, Monthly At Only \$1,156. Agent Unlimited Mileage Warranty Till Mar 2023. Flexible Loan Packages Available To Choose From. Low Mileage Clocked And Low Down Payment As Well. High Trade I...									
Edmund Motor Pte Ltd									
Posted: 23-Sep-2018 Tags: 2017 Honda Jazz, 2017 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.5A RS	\$73,800	\$7,680 /yr	07-Jul-2017	1,498 cc	25,000 km	Hatchback	Available

Compare

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Let Auto
6841 3838
6 OCT 2018 @ 09:00 am
Survey & Repair

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SJR6578Y
Chassis No : JHMGK5850JX205203
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : LEE SIANG CHENG
Ins Policy No. : 10826995
Date of Accident : 5/9/2018

Document No. : SQT18003729
Date : 5. Sep 2018
Customer No. : WZF002
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B33112562
Date | Time : 5. Sep 2018 6:23:50 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71187) OWNER: LEE SIANG CHENG OWNER INSURER: AVIVA INSURANCE LTD ACC DATE: 05/09/2018@12.30PM SURVEYED BY: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHB4822M (HYUNDAI/I40/YELLOW)						
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR	1	202.70	25	152.02	10.64	162.66
71502-T5A-J60	COVER,R.RR.BUMPER	1	20.30	25	15.22	1.07	16.29
71507-T5A-J60	COVER,L.RR.BUMPER	1	20.30	25	15.22	1.07	16.29
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
04715-T5B-J50ZZ	FACE,RR.BUMPER	1	492.60	25	369.45	25.86	395.31
66100-TAR-T10ZZ	PANEL COMPRR.	1	314.00	25	235.50	16.49	251.99
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
74800-T5S-K61	LOCK ASSY,TAILGATE	1	77.10	25	57.82	4.05	61.87
74440-T5A-003	WEATHERSTRIP,TAILGATE	1	92.30	25	69.22	4.85	74.07
74890-T5B-911	GARNISH ASSYRR.LICENSE	1	194.70	25	146.02	10.22	156.24
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
33500-T5A-J02	TAILLIGHT ASSY,R.	1	235.10	25	176.32	12.34	188.66
33550-T5A-J02	TAILLIGHT ASSYL.	1	235.10	25	176.32	12.34	188.66
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SJR6578Y
Chassis No : JHMGK5850JX205203
Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)
Owner's Name : LEE SIANG CHENG
Ins Policy No. : 10826995
Date of Accident : 5/9/2018

Document No. : SQT18003729
Date : 5. Sep 2018
Customer No. : WZF002
Svc Advisor : ARY CHUA WAI NGE E
Engine No : L15B33112562
Date | Time : 5. Sep 2018 6:23:50 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
Sum Item					2187.08	153.11	2,340.19
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	11	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	120	140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	140	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11	250.00	17.50	267.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	350.00	11	350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION1	1	350.00	300	350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00	300	350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	350.00	300	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	250	450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & Align Tailgate	1	550.00	450	550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4500.00	1350	4500.00	315.00	4815.00
BKRP22S	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW	1	4800.00	1400	4800.00	336.00	5136.00
Sum Labor					12520.00	876.40	13,396.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 14,707.08 1,029.51 15,736.59

15,736.59

Total (Inclusive of GST)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 5/9/2018 6:39:46 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850JX205203
License No: SJR6578Y
Mileage: 7052
Engine No: L15B33112562

Document No: SVO18056765
Printed By: ARYCHUA
Order Date: 26. September 2018
Order Time: 7:52:36 PM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71187) OWNER: LEE SIANG CHENG OWNER INSURER: AVIVA INSURANCE LTD ACC DATE: 05/09/2018@12.30PM SURVEYED BY: MARCUS CHUA(LKKAUTO)1/10/2018@10.10am REF NO: D18006631MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHB4822M (HYUNDAI/140/YELLOW)						
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR	1	202.70	25	152.02	10.64	162.66
04715-T5B-J50ZZ	FACE,RR.BUMPER	1	492.60	25	369.45	25.86	395.31
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
73127-TY0-000	RUBBER CWINDOWSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDOWSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
	SUM PARTS:				1,216.10	85.13	1,301.23
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BOJSE	0672 BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00		120.00	8.40	128.40
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	250.00		250.00	17.50	267.50
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	300.00		300.00	21.00	321.00
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BOMISC1	0626 RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	300.00		300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00		450.00	31.50	481.50
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,350.00		1,350.00	94.50	1,444.50

IND-5



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMGK5850JX205203
License No: SJR6578Y
Mileage: 7052
Engine No: L15B33112562

Document No: SVO18056765
Printed By: ARYCHUA
Order Date: 26. September 2018
Order Time: 7:52:36 PM
Service Advisor: ARY CHUA WAI NGEE

BKRP22S	EXT-YJ	1	1,400.00	1,400.00	98.00	1,498.00
	STRAIGHTEN ALIGN RR PANEL RR R					
	FENDER & RENEW					
	DAMAGE PARTS.					
			SUM LABOUR:	4,730.00	331.10	5,061.10
			TOTAL SGD	5,946.10	416.23	6,362.33
Total Payable (SGD)						6,362.33

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016324/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4822M	Veh. Inspected	SJR 6578Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006631MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	06/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JHMGK5850JX205203	Colour	GREY	
Odometer	7052	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	7 mm	
L/H Front Tyre	185/55 R16	DUNLOP	7 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	7 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2018	Inspection Date	01/10/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 6578Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
14	CLIPBUMPER (SN)	NECESSARY	21.00	21.00
1	EMBLEMRR (SN)	NECESSARY	7.87	7.87
1	DIFFUSER ASSY,RR PR (SN)	DENTED / DEFORMED	152.02	152.02
1	COVER,R RR BUMPER (SN)	NOT NECESSARY	15.22	-
1	COVER,L RR BUMPER (SN)	NOT NECESSARY	15.22	-
1	SPACER,R RR BUMPER SIDE (SN)	NOT NECESSARY	12.45	-
1	SPACER,L RR BUMPER SIDE (SN)	NOT NECESSARY	12.45	-
1	FACE,RR BUMPER (SN)	DENTED / TORN	369.45	369.45
1	PANEL COMPRR (SN)	TO REPAIR SEE LABOUR	235.50	-
1	TAILGATE COMP (SN)	BADLY DENTED	537.22	537.22
1	LOCK ASSY,TAILGATE (SN)	NOT NECESSARY	57.82	-
1	WEATHERSTRIP TAILGATE (SN)	NOT NECESSARY	69.22	-
1	GARNISH ASSYRR LICENSE (SN)	NOT NECESSARY	146.02	-
1	EMBLEMH (SN)	NOT NECESSARY	8.02	-
2	NUTPUSH 3MM (SN)	NOT NECESSARY	2.85	-
1	TAILLIGHT ASSY,R (SN)	NOT NECESSARY	176.32	-
1	TAILLIGHT ASSYL (SN)	NOT NECESSARY	176.32	-
1	BUZZER ASSYSMART (SN)	CRACKED	44.47	44.47
1	ANTENNA ASSYLF (SN)	NOT NECESSARY	43.57	-
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	8.40	8.40
2	RUBBER WINDSHIELD DAMPER (SN)	NECESSARY	9.45	9.45
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.22	6.22
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			2,237.08	1,236.10
LABOUR				
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	BODY JOINT SEALANT.		100.00	100.00
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER		140.00	120.00

Report Ref No. CS/FCI18016324/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & RENEW REVERSE SENSORS- 4 PCS.		180.00	140.00
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.	NOT NECESSARY	350.00	-
	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION.		350.00	300.00
	REMOVE & INSTALL RR WINDSCREEN.		350.00	300.00
	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM.		350.00	300.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		450.00	250.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST & ALIGN TAILGATE.		550.00	450.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (SP).		4,500.00	1,350.00
	STRAIGHTEN ALIGN RR PANEL RR R FENDER & RENEW.INCLUSIVE OF THE REPAIR OF PANEL COMPRR.		4,800.00	1,400.00
			12,470.00	4,710.00
GRAND TOTAL			14,707.08	5,946.10
RECOMMENDED COST OF REPAIRS				5,946.10

Report Ref No. CS/FCI18016324/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.