

23/03/2018

ASS. REC. BY:

REF: CS/CT/18016325/Ttd3

Special Instruction:

Surveyor:  
Mehmen

ASSIGNMENT (Office)

From (Person):

Chang Boon Sen

of

CTI

Date/Time:

6/9/18 @ 3:15 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 9181X

Insured:

SCM 1112 A

at Workshop m/s

Koh Motor

Tel:

90721769

of

255 Alexandra Road

Policy No:

DMPCS N3032441800

Claim No:

SNM18D04259C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/09/2018

CA / REV / REP. / REV 24 HRS

(up)

5/10/18 @ 100m

H.O.D. Endorsement:

Date/Time:

4:58 pm @ 6/9/18

Person Contacted:

Mr. Ng

Vehicle IN /  OUT

Date/Time	Action/Instruction (✓) Estimate
	SJA 9181X - CS3 / AIG 14014309 / Gysd1
	SCM 1112A - X
7/9/18 -	VNI
11/9/18 -	Vehicle not In.
19/09/2018	Vehicle still not In.

DOA: 25/07/19

**ASSIGNMENT**

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS \_\_\_\_\_  
 Date \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Veh No: 539 9181V Yr Regn: 208. Jm  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Holden Jazz cc 1448  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 7696 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHM GK 5850 JX-202008  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/55R16  
 R: 185/55R16  
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: 6 mm L/Bal: 6 mm  
 D.O.A: \_\_\_\_\_ D.O.I: 5/10/18  
 Survey held at: Holden Motor  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 N/S Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Part by Part \$6195.87 (Red: 4181.34 : 40%)
	- RECEIVED 21 OCT 2018

Date/Time File Pass to:  Preli. Report  
 24/10 Typist  Final Report  
 Date/Time File Return to: \_\_\_\_\_  
 Days Of Repair: 6  
 Resurvey No. of Trip: 1  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Add Fee:  Site Insp \$  
 Interview \$  
 Tech Insp \$  
 Weekend \$  
 Report Format: TP  
 Lump Sum / (E) \$ 6195.87  
 TOTAL \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018		06 Sep 2018 15:15 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]			
Insured:	LOH RENEE, ID: 57322087D						
Main Claimant:	TAN ZE YI, ID: 58428709A						
Vehicle Reg. No.:	SJG9181X	Date of Loss:	02/09/2018 10:00 - :59				
Claim Type:	TP / SNM18D04259C02	Policy/Cover Note No.:	DMPCSN3032441800 (Comprehensive)				
Vehicle Reg. No. (Insured):	SCM1112A	Policy No. (Claimant):	10806514				
		Excess:	S\$0.00				
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:						
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]						
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]						
Driver/Custodian (Insured):	MARK KHING JOON CHIAT (45 / Male), NRIC: S7242166C, Tel: +6598633731						
Adj Asg. Remarks:	NO EST, CASE WITH SJE.						

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Lucas Lee

---

**From:** Ng Sin Hai <shng@kahmotor.onmicrosoft.com>  
**Sent:** Tuesday, 4 September, 2018 8:37 PM  
**To:** Claims Dept of CTI  
**Subject:** RE: 3rd party direct settlement SJG9181X & your insured  
SCM1112A/DOA:02/09/2018/Est \$  
**Attachments:** SJG9181X-02092018-GIA REPORT.pdf

Dear All,

Please refer to the attached pdf, we are assisting our insured vehicle SJG9181X to file a 3rd party claim against your insured vehicle SCM1112A and to request for direct settlement.

Kindly assist and expedite to check the claim liability soonest.

Thank you and have a nice day, 😊

Warmest Regards,

Ng Sin Hai  
**Kah Motor Co. Sdn. Bhd**  
*(A member of Oriental Holdings Berhad)*  
Body Repair & Paint Centre  
255 Alexandra Road  
Singapore 159937  
DID: 6471 5419  
HP: 9072 1769  
E-mail: [shng@honda.com.sg](mailto:shng@honda.com.sg)



BLUE BIRD FOR  
OUR CHILDREN



Visit our  
Facebook page

Please consider the environment before printing this email

**CONFIDENTIAL NOTE:** The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/09/2018 19:28
Date Of Accident	02/09/2018 10:00
Exact Location Of Accident	JALAN ISNIN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG9181X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN ZE YI
NRIC No	S8428709A
Email Address	ALEXZY23@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96219184
Alternative Phone No	OTHERS-96219184

### Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10806514
Cover Note Number	N.A

### Driver

Name of Driver	TAN ZE YI
NRIC No	S8428709A
Date Of Birth	03/10/1984
Occupation	INDOOR
Date Of Driving Pass	08/12/2006
Driving Experience	11 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96219184
Fax Number	
Contact Number	OTHERS-96219184
EEmail Address	ALEXZY23@GMAIL.COM

Sketch Plan

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*Handwritten mark*

**VERIFIED BY AJAX MARS  
REPORTING OFFICER**

**AIZAM BIN ATAN**

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

**Sketch Plan**

A: SSG 9181X  
B: SCM 1112A

Aizam Bin Atan

Aizam Bin Atan



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Ref No: M200050223  
 Company Ref No: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
 3 ANSON ROAD #16-00  
 SPRINGLEAF TOWER  
 SINGAPORE 079909  
 Registration No : SJG9181X  
 Chassis No : JHMGK5850JX202008  
 Model : JAZZ 1.5VTIR CVT 18YM (EURO 6)  
 Owner's Name : TAN ZE YI  
 Ins Policy No. :  
 Date of Accident : 2/9/2018

Document No. : SQT18003773 Page 1  
 Date : 7. Sep 2018  
 Customer No. : WZC008  
 Svc Advisor :  
 Engine No : L15B33110809  
 Date | Time : 7. Sep 2018 8:32:25 PM  
 Surveyor Name :  
 Survey Date :  
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-T5B-000ZZ	FACERR.BUMPER	1 <i>Rx</i>	492.60	25	369.45	25.86	395.31
71507-T5A-000	GARNISHL.RR.BUMPER	<i>an</i> 1 <i>X</i>	14.00 <i>nm</i>	25	10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER	1 <i>nb</i>	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1 <i>nb</i>	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	10 <i>nb</i>	2.00	25	15.00	1.05	16.05
66100-TAR-T10ZZ	PANEL COMPRR.	1 <i>X</i>	314.00	25	235.50	16.49	251.99
63720-T5A-300ZZ	GUTTER COMPL.RR.	1 <i>X</i>	75.30	25	56.47	3.95	60.42
75450-SAA-013	OUTLETRR AIR	1 <i>X</i>	24.70	25	18.52	1.30	19.82
84640-T5A-003ZA	LINING ASSYRR.PANEL	1 <i>X</i>	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSYL.TRUNK	1 <i>X</i>	165.60	25	124.20	8.69	132.89
90667-SWZ-003ZA	CLIPTRIM 7MM	2 <i>X</i>	2.30	25	3.45	0.24	3.69
84521-T5A-901ZA	LID ASSYSPARE TIRE	1 <i>X</i>	186.00	25	139.50	9.77	149.27
04646-TAS-320ZZ	PANEL SET,L.RR.OUTSIDE	1 <i>Rx</i>	559.30	25	419.47	29.36	448.83
04655-TAS-300ZZ	PANEL SET,RR.FLOOR	<i>an</i> 1 <i>X</i>	669.90	25	502.42	35.17	537.59
67550-T5A-N10ZZ	PANEL COMP.LRR.DOOR	1 <i>bl</i>	703.40	25	527.55	36.93	564.48
74592-T5B-003	FENDER,L.RR.INNER	<i>an</i> 1 <i>X</i>	77.50	25	58.12	4.07	62.19
91501-T2A-003	CLIPINNER FENDER	2 <i>nb</i>	0.30	25	0.45	0.03	0.48
91501-TR0-003	CLIPINNER FENDER	4 <i>nb</i>	2.30	25	6.90	0.48	7.38
74591-T5B-000	COVERL.RR.FENDER	<i>an</i> 1 <i>X</i>	21.10	25	15.82	1.11	16.93
	<b>Sum Item</b>				<b>2566.16</b>	<b>179.63</b>	<b>2,745.79</b>



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT18003773	Page	2
Registration No	: SJG9181X	Date	: 7. Sep 2018		
Chassis No	: JHMGK5850JX202008	Customer No.	: WZC008		
Model	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	Svc Advisor	:		
Owner's Name	: TAN ZE YI	Engine No	: L15B33110809		
Ins Policy No.	:	Date   Time	: 7. Sep 2018 8:32:25 PM		
Date of Accident	: 2/9/2018	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOBC	BODY UNDERSIDE COATING (N)	1	250.00		250.00	17.50	267.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00		560.00	39.20	599.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	560.00		560.00	39.20	599.20
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR1	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3000.00		3000.00	210.00	3210.00
BP06R	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL	1	2000.00		2000.00	140.00	2140.00
BOJSE	SEALANT FOR LHR DOOR	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT LHR FENDER	1	80.00		80.00	5.60	85.60
<b>Sum Labor</b>					<b>7800.00</b>	<b>546.00</b>	<b>8,346.00</b>

Survey By: Taufik 97495749  
 Date & Time: 5/10/18 @ 10am  
 Excess: WP  
 Status: \_\_\_\_\_  
 Signature: [Signature]

**Total Amount** 10,366.16 725.63 11,091.79  
**Total (Inclusive of GST)** 11,091.79

Resurvey before paint 06 days  
 sur@lkkauto.com

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Form(s), must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408551. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING  
 Chassis No: JHMGK5850JX202008  
 License No: SJG9181X  
 Mileage: 4288  
 Engine No: L15B33110809

Document No: SVO18060608  
 Printed By: SHNG  
 Order Date: 13. October 2018  
 Order Time: 11:15:30 AM  
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incid GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER:TAN ZE YI OWNER INSURER:AVIVA ACC DATE:02/09/2018 SURVEYED BY:TAUFIKH DATE:05/09/2018 REF NO: TP INSURER:CHINA TAIPING TP VEH:SCM1112A ADDITIONAL PART						
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
91505-TM8-003	CLIPBUMPER	10	2.00	25	15.00	1.05	16.05
67550-TAR-306ZZ	PANEL COMPL.RR.DOOR	1	676.10	25	507.07	35.49	542.56
91501-T2A-003	CLIPINNER FENDER	2	0.30	25	0.45	0.03	0.48
91501-TR0-003	CLIPINNER FENDER	4	2.30	25	6.90	0.48	7.38
67865-T5A-003	TAPEL.RR.DOOR SASH (A) MCW	1	15.40	25	11.55	0.81	12.36
	<b>SUM PARTS:</b>				<b>565.87</b>	<b>39.60</b>	<b>605.47</b>
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BML02I	1757 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BMF00D	0701 REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00		560.00	39.20	599.20
BOMISC1	0701 RESET SMART ENTRY SYSTEM & REMOVE NECESSARY COMPONENT.(N)	1	560.00		560.00	39.20	599.20
BMI02D	1757 REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES & ETC.(N)	1	560.00		560.00	39.20	599.20
BKRP02M	0671 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,680.00		1,680.00	117.60	1,797.60
BP06R	1610 SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL, FLOOR PANEL, RR R FENDER & RR L FENDER	1	1,800.00		1,800.00	126.00	1,926.00
BOJSE	1610	1	80.00		80.00	5.60	85.60



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer:** WZC008 / CHINA TAIPING

**Chassis No:** JHMGK5850JX202008

**License No:** SJG9181X

**Mileage:** 4288

**Engine No:** L15B33110809

**Document No:** SVO18060608

**Printed By:** SHNG

**Order Date:** 13. October 2018

**Order Time:** 11:15:30 AM

**Service Advisor:** NG SIN HAI

SEALANT FOR LHR DOOR

<b>SUM LABOUR:</b>	<b>5,630.00</b>	<b>394.10</b>	<b>6,024.10</b>
--------------------	-----------------	---------------	-----------------

<b>TOTAL SGD</b>	<b>6,195.87</b>	<b>433.70</b>	<b>6,629.57</b>
------------------	-----------------	---------------	-----------------

<b>Total Payable (SGD)</b>	<b>6,629.57</b>
----------------------------	-----------------

GST Amount is calculated from individual line(s)



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT18004489	<b>Page</b>	1
<b>Registration No</b>	: SJG9181X	<b>Date</b>	: 19. Oct 2018	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMGK5850JX202008	<b>Svc Advisor</b>	:	<b>Engine No</b>	: L15B33110809
<b>Model</b>	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	<b>Engine No</b>	: L15B33110809	<b>Date   Time</b>	: 19. Oct 2018 3:05:59 PM
<b>Owner's Name</b>	: TAN ZE YI	<b>Date   Time</b>	: 19. Oct 2018 3:05:59 PM	<b>Surveyor Name</b>	:
<b>Ins Policy No.</b>	:	<b>Surveyor Name</b>	:	<b>Survey Date</b>	:
<b>Date of Accident</b>	:	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: supplementary						
67865-T5A-003	TAPEL RR.DOOR SASH	1	15.40	25	11.55	0.81	12.36
				<b>Sum Item</b>	<b>11.55</b>	<b>0.81</b>	<b>12.36</b>

Survey By	_____						
Date & Time	_____			<b>Total Amount</b>	11.55	0.81	12.36
Excess	_____			<b>Total (Inclusive of GST)</b>			<b>12.36</b>
Status	_____						
Signature	_____						

Printed on 19/10/2018 3:07:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2018		06 Sep 2018 15:15 <a href="#">Edit Adj Rpt</a>	<b>S\$6,195.87</b> <a href="#">Edit Estimates</a>	<b>S\$6,195.87</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	<b>LOH RENEE</b> , ID: S7322087D								
Main Claimant:	<b>TAN ZE YI</b> , ID: S8428709A								
Vehicle Reg. No.:	<b>SJM9181X</b>	Date of Loss:	02/09/2018 10:00 - :59 [7 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04259C02</b>	Policy/Cover Note No.:	DMPCSN3032441800 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SCM1112A</b>	Policy No. (Claimant):	10806514						
		Excess:	S\$0.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (ALEXANDRA)</b> 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>Aviva Ltd (HQ)</b> - Tel: (65) 6827 9966								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 17/09/2018]								
Driver/Custodian (Insured):	MARK KHING JOON CHIAT (45 / Male), NRIC: S7242166C, Tel: +6598633731								
Adj Asp. Remarks:	NO EST, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SJG9181X (SNM18D04259C02)  
[SCM1112A]  
TP  
TAN ZE YI  
Sep 2 2018 10:00AM  
[LOH RENEE]  
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)					Thumbnail	Print	
1	02/09/18 19:44	<b>Accident Statement</b>				1	Load HTM		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>		
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)					Thumbnail	Print	
1	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
2	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
3	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
4	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
5	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
6	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
7	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
8	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
9	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
10	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
11	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
12	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
13	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
14	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
15	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
16	02/09/18 19:35	<b>Accident Photo</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
17	02/09/18 19:35	<b>Driving License</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
18	02/09/18 19:35	<b>Driving License</b> [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
2	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
3	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
4	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
5	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
6	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
7	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
8	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	
9	24/10/18 10:18	<b>General View</b>				1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
10	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
11	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
12	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
13	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
14	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
15	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
16	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
17	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
18	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
19	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
20	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
21	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
22	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
23	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
24	24/10/18 10:18	General View	Load JPG	<input checked="" type="checkbox"/>
25	24/10/18 10:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	24/10/18 10:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	24/10/18 10:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	24/10/18 10:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	24/10/18 10:19	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/09/18 15:14	PRS	Load PDF	
2	06/09/18 15:14	TP GIA	Load PDF	
3	06/09/18 15:15	OI GIA	Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	02/09/18 19:34	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	02/09/18 19:35	Individual Statement <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	02/09/18 19:35	Individual Statement <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
4	02/09/18 19:35	Individual Statement <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/18 10:41	SUPPLEMENTARY PART	Load PDF	

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	02/09/18 19:44	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	02/09/18 19:35	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail Print
8	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
14	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
15	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
16	02/09/18 19:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
17	02/09/18 19:35	Driving License		Load JPG <input checked="" type="checkbox"/>
18	02/09/18 19:35	Driving License		Load JPG <input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		Thumbnail Print
1	02/09/18 19:34	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	02/09/18 19:35	Individual Statement		Load JPG <input checked="" type="checkbox"/>
3	02/09/18 19:35	Individual Statement		Load JPG <input checked="" type="checkbox"/>
4	02/09/18 19:35	Individual Statement		Load JPG <input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT118016325/T1TD3Q2  
**Date:** 26/10/2018

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3032441800	
Claimant Vehicle No: SJG9181X	Insured Vehicle No: SCM1112A	
Date of Loss: 02/09/2018	Nature of Claim: TP	Claim No: SNM18D04259C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SJG9181X</b>		Engine No: L15B33110809
Make & Model: HONDA JAZZ, 1.5 (A)		Chassis No: JHMGK5850JX202008
Reg. Date: 12/01/2018 (Man. Year: 2017)		Odometer: 7696 km
Colour: Silver		
Engine Capacity: 1498 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): <b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 185/55 R16	Rear Tyre Size: 185/55 R16
Front Left Side: Dunlop 6 mm	Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm	Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,685.37	595.87	2,089.50	77.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	5,600.00	2,100.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,385.37</b>	<b>6,195.87</b>	<b>4,189.50</b>	<b>40.34</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>726.98</b>	<b>433.71</b>	<b>293.27</b>	<b>40.34</b>
<b>Nett Amount (S\$)</b>	<b>11,112.35</b>	<b>6,629.58</b>	<b>4,482.77</b>	<b>40.34</b>

#### INSPECTION

Date of Assignment: 06/09/2018		
Date Inspected: 05/10/2018	Inspected At:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair: 6.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
<b>Parts:</b> 144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJG9181X)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACERR.BUMPER	Repair	369.45 FS	*- FS
2	1		*GARNISHL.RR.BUMPER	Not Necessary	10.50 FS	*- FS
3	1		*SPACERR.RR.BUMPER	Necessary	12.45 FS	*12.45 FS
4	1		*SPACERL.RR.BUMPER	Necessary	12.45 FS	*12.45 FS
5	10		*CLIPBUMPER	Necessary	15.00 FS	*15.00 FS
6	1		*PANEL COMPRR	Not Necessary	235.50 FS	*- FS
7	1		*GUTTER COMPL.RR	Not Necessary	56.47 FS	*- FS
8	1		*OUTLETRR AIR	Not Necessary	18.52 FS	*- FS
9	1		*LINING ASSYRR.PANEL	Not Necessary	45.60 FS	*- FS
10	1		*LINING ASSYL.TRUNK	Not Necessary	124.20 FS	*- FS
11	2		*CLIPTRIM 7MM	Not Necessary	3.45 FS	*- FS
12	1		*LID ASSYSPARE TIRE	Not Necessary	139.50 FS	*- FS
13	1		*PANEL SET ,L.RR.OUTSIDE	Repair	419.47 FS	*- FS
14	1		*PANEL SET,RR.FLOOR	Not Necessary	502.42 FS	*- FS
15	1		*PANEL COMP,L.RR.DOOR	Bent	527.55 FS	*507.07 FS
16	1		*FENDER ,L.RR.INNER	Not Necessary	58.12 FS	*- FS
17	1		*CLIPINNER FENDER (2 PCS)	Necessary	0.45 FS	*0.45 FS
18	1		*CLIPINNER FENDER (4 PCS)	Necessary	6.90 FS	*6.90 FS
19	1		*COVERL.RR.FENDER	Not Necessary	15.82 FS	*- FS
20	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
21	1		*TAPEL.RR.DOOR SASH	Necessary	11.55 FS	*11.55 FS
<b>Total Parts (S\$)</b>					<b>2,685.37</b>	<b>595.87</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	180.00	180.00
2	REMOVE & RENEW REVERSE SENSORS	New	180.00	180.00
3	BODY UNDERSIDE COATING	New	250.00	0.00
4	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	560.00	560.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
6	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	New	560.00	560.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS ,RR	New	560.00	560.00
8	CUT OFF & RENEW RR PANEL .STRAIGHTEN	New	3,000.00	1,680.00
9	SPRAY PAINTING ON TAILGATE ,RR BUMPER ,RR PANEL	New	2,000.00	1,800.00
10	SEALANT FOR LHR DOOR	New	80.00	80.00
11	SEALANT LHR FENDER	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,700.00</b>	<b>5,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >