

23/03/2003

ASS. REC. BY:

REF: CS/FWD18016342/Vgd3² Special Instruction:Survivor
Mehmen

ASSIGNMENT (Office) ✓

From (Person): Josey Loh

of FWD

Date/Time: 6/9/18 @ 4:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 3992G

Insured:

at Workshop m/s

F-thoz (Bkt Batok)

Tel:

8822 8339 / 96981309

of

30 Bkt Batok Crescent

Policy No:

PNP.V 2018-00066939

Claim No:

1201800011061

Sum Insured:

Excess:

\$ 3,100.00

Make of Veh:

(Client's Record)

D.O.A. 02/09/2018

Insp: 22 Tempines St 92

H.O.D. Endorsement:

CA / (REV) / REP. / REV 24 HRS

Date/Time:

7/9/18 @ 10:21am

Person Contacted:

Suhelmi

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 3992G - CS/FWD/18016074/Avb DOA: 2/9/18
12/9/18 @ 3:37pm	revert to Josey Loh via Mehmen.
12/9/18 @ 5:45pm	Clara is informed C/A via Mehmen.
15/9/18 @ 2:23pm	informed Suhelmi C/A O EX: \$3100 by email.
25/7/18 @ 9:33am	2nd revert to Josey Loh via Mehmen. (supplementary)
25/9/18 @ 9:36am	Josey Loh informed C/A at \$8666 via Mehmen.

REF: FWD

ASSIGNMENT

From: Date: 14092018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT 3992G

at Workshop m/s: Ethos

of: Tampines

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$ 3100.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 81

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 1.31 % 3 Val.: Yes or No

CA / REP. / 24 HRS

Date: Person Contacted:

N/S	O/S

Veh No: SKT 3992G Yr Regn: 615

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: New Benz A180 G.C. 1595

Colour: Red A/C Insured / Std / NI / NA

Sp. Reading: 41883 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD1760422J376161

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: R: 225/45-R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. mm L/Bal. mm D.O.A. 2/9/18

Rear R/Bal. mm L/Bal. mm D.O.I. 14/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Tyre had been replaced @ 140 Gyps. 9 hrs.

28/9/18 Conf. cost fire / of \$ 5876.00 with AHKer (Red & 5013, 46-1.) no lump sum.

RECEIVED 04 OCT 2018

Date/Time, File Pass to?

11/03/10 to FSR

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Prel. Report☐ : Final Report

MER-00

5876

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee.

Transportation.

\$ + RS \$

Photos

Others

TOTAL

250
50
50
10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018 11:11 Sendback Est	06 Sep 2018 14:28 \$10,559.00	06 Sep 2018 16:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHOONG LEE CHOO, ID: S2617812F		
Vehicle Reg. No.:	SKT3992G	Date of Loss:	02/09/2018 13:00 - :59 [38 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800011061	Policy/Cover Note No.:	PNPV2018-00006939 (Comprehensive)
		Excess:	S\$3,100.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/09/2018]		
Driver/Custodian:	CHOW SU RIN (25 / Female), NRIC: S9240439J, Tel: +6593387521		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Sep 2018 11:10	Clim Veh Model Changed	(203891) MERCEDES-BENZ A180 R17 1.6 (A).	[R] Suhelmi Bin Suharman
2	06 Sep 2018 11:10	Clim Created	Reg No: SKT3992G, Policy No: PNPV2018-00006939, Acct Date: 2018/09/02. Claim Type: OD, Insurer: FWD Singapore Pte. Ltd. (HQ), Workshop: ETHOZ Protect Pte Ltd (Bukit Batok). Created from SAS:MOR118113671	[R] Suhelmi Bin Suharman
3	06 Sep 2018 14:28	Clim Submitted	10559.00.	[R] Ng Boon Kai
4	06 Sep 2018 16:20	Clim Registration Modified	Excess: -> 3100.00.	[I] Josey Loh
5	06 Sep 2018 16:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Appraisals Associates Pte Ltd.	[I] Josey Loh
6	06 Sep 2018 16:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/17	[I] Josey Loh
7	06 Sep 2018 16:21	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Josey Loh
8	06 Sep 2018 17:49	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	07 Sep 2018 12:50	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	17 Sep 2018 15:36	Adj Rpt Initiated		[A] SHIAU CHAN
11	17 Sep 2018 15:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/17	[A] SHIAU CHAN
12	17 Sep 2018 15:37	Adj Mandate Request	Cur.Req:8326.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	17 Sep 2018 17:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/17	[I] Clara Li Zi Rong
14	17 Sep 2018 17:45	Adj Mandate Set	Approved:8326.00.	[I] Clara Li Zi Rong
15	24 Sep 2018 17:11	Clim Supp Created (S:746264)		[R] Ng Boon Kai
16	24 Sep 2018 17:13	Clim Submitted (S:746264)	340.00.	[R] Ng Boon Kai
17	24 Sep 2018 17:13	Adj Co Assigned (S:746264)	LKK Auto Consultants Pte Ltd (HQ):	[R] Merimen Administrator
18	25 Sep 2018 09:28	Supp Combined (S:746264)		[A] SHIAU CHAN
19	25 Sep 2018 09:32	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/17	[A] SHIAU CHAN
20	25 Sep 2018 09:33	Adj Mandate Request	Cur.Req:8666.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
21	25 Sep 2018 09:36	Adj Mandate Set	Approved:8666.00.	[I] Josey Loh

Date From



Date To



Audit Type None

Go

ACTIVITY

[25/09/2018 09:34] SHIAU CHAN:
PLEASE BE INFORMED THAT THE VEHICLE STILL UNDER REPAIRING.
[07/09/2018 10:26] Nivitha Govindasamy:
Please be informed vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1909064	06/09/2018 11:10	Motor	ETHOZ Protect Pte Ltd	ETHOZ Protect Pte Ltd (Bukit Batok)	SKT3992G		xx.xx
1918439	17/09/2018 15:36	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKT3992G		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 25 Sep 2018

Preliminary Advice

Vehicle No	: SKT3992G	Accident Date	: 02/09/2018
Make	: MERCEDES-BENZ A180 R17	Policy No.	: PNPV2018-00006939
Assignment Date	: 06/09/2018	Excess	: S\$3,100.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 4.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,899.00	(ESTIMATE \$10,559.00 + SUPPLEMENTARY \$340.00)
Revised Amount	:S\$	5,743.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	2,923.00	
Total	:S\$	8,666.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	81,000.00
COE / PARF Rebate	:S\$	55,270.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,730.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 18 September 2018 2:23 PM
To: boonkai.ng@ethozgroup.com
Cc: SUR
Subject: VEHICLE SKT 3992G (DOA: 02/09/2018)

Dear Boon Kai,

As spoken with Suhelmi.

As instructed by our client, please proceed to repair the insured vehicle **SKT 3992G (Excess \$3,100/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Sep 2018 11:10	Clim Veh Model Changed	(203891) MERCEDES-BENZ A180 R17 1.6 (A).	[R] Suhelmi Bin Suharman
2	06 Sep 2018 11:10	Clim Created	Reg No: SKT3992G, Policy No: PNPV2018-00006939, Acct Date: 2018/09/02. Claim Type: OD. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: ETHOZ Protect Pte Ltd (Bukit Batok). Created from SAS:MOR118113671	[R] Suhelmi Bin Suharman
3	06 Sep 2018 14:28	Clim Submitted	10559.00.	[R] Ng Boon Kai
4	06 Sep 2018 16:20	Clim Registration Modified	Excess: -> 3100.00.	[I] Josey Loh
5	06 Sep 2018 16:21	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Appraisals Associates Pte Ltd.	[I] Josey Loh
6	06 Sep 2018 16:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/17	[I] Josey Loh
7	06 Sep 2018 16:21	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Josey Loh
8	06 Sep 2018 17:49	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	07 Sep 2018 12:50	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	17 Sep 2018 15:36	Adj Rpt Initiated		[A] SHIAU CHAN
11	17 Sep 2018 15:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/09/17	[A] SHIAU CHAN
12	17 Sep 2018 15:37	Adj Mandate Request	Cur.Reg:8326.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	17 Sep 2018 17:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/09/17	[I] Clara Li Zi Rong
14	17 Sep 2018 17:45	Adj Mandate Set	Approved:8326.00.	[I] Clara Li Zi Rong

Date From



Date To



Audit Type None

Go

ACTIVITY

[07/09/2018 10:26] Nivitha Govindasamy:

Please be informed vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1909064	06/09/2018 11:10	Motor	ETHOZ Protect Pte Ltd	ETHOZ Protect Pte Ltd (Bukit Batok)	SKT3992G		xx.xx
1918439	17/09/2018 15:36	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKT3992G		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 17 Sep 2018

Preliminary Advice

Vehicle No	: SKT3992G	Accident Date	: 02/09/2018
Make	: MERCEDES-BENZ A180 R17	Policy No.	: PNPV2018-00006939
Assignment Date	: 06/09/2018	Excess	: S\$3,100.00
Date of Inspection	: 14/09/2018	Est. Duration of Repair	: 4.00
Inspection At	: ETHOZ PROTECT PTE LTD (BUKIT BATOK) 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,559.00
Revised Amount	:S\$	5,403.00
Check Items (Estimated)	:S\$	2,923.00
Total	:S\$	8,326.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	81,000.00
COE / PARF Rebate	:S\$	55,270.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,730.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2018 09:58
Date Of Accident	02/09/2018 13:20
Exact Location Of Accident	ALONG UPPER EAST COAST RD OUTSIDE ESSO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT3992G
Insured/Policyholder	
Name Of Registered Owner	CHOONG LEE CHOO
NRIC No	S2617812F
Email Address	CHOWIVIS@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81837993
Alternative Phone No	OFFICE-81837993

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A180 (R17)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00006939
Cover Note Number	05/06/2018-04/06/2019

Driver

Name of Driver	CHOW SU RIN
NRIC No	S9240439J
Date Of Birth	14/10/1992
Occupation	INDOOR
Date Of Driving Pass	26/12/2011
Driving Experience	6 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93387521

Fax Number

Contact Number

Email Address

NOEMAIL

Address	46 EASTWOOD ROAD 02-03
Postcode	486356
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TANAH MERAH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 51 NEW UPPER CHANGI ROAD #01-1514 , POSTCODE: 461051 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4499999 - FAX NO: 62447251
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL4719Y
Vehicle Make/Model/Colour	YAMAHA YZF R15
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TAN JIAN YAN
NRIC/Passport Number	S9722938D
Contact Number	96451470
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN


IMPORTANT NOTICE



1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

SKETCH PLAN

Refer to attached.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached.

Damages to my car:

- headlamp
- Tyre rim
- front right side bender
- Bonnet (scratch)
- Screeching sound from under carriage.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

<input type="checkbox"/>	Reporting Only
<input checked="" type="checkbox"/>	Claim OD
<input type="checkbox"/>	Claim TP
<input type="checkbox"/>	Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date: 2 September 2018 (Sunday)

Time: Approx. 1.20 p.m.

Location: Along 251 Upper East Coast Rd, outside the Esso Station

Parties involved: Chow Su Rin (S9240439J) and Tan Jian Yan (S9722938D)

Vehicles involved: Red Mercedes A180 (SKT 3992G) driven by Chow Su Rin and Yamaha blue and silver motorcycle (FBL 4719Y) by Tan Jian Yan

Around 1.20p.m. I was driving out of the Esso station and turning right onto Upper East Coast Road in the direction of Siglap.

Before inching my car onto Upper East Coast Rd, I looked very carefully to my left and right several times (please see my front and rear view cameras, I took such a long time that 2 cars started queuing up behind my car).

After I determined that there were no more vehicles approaching from both sides, including my right side and the filter lane (from Bedok South Ave 1 entering Upper East Coast Rd), I slowly moved my car onto Upper East Coast Rd to prepare to turn right.

After I had crossed the two lanes but just before I could make the right turn, a motorcycle suddenly hit the front right side of my car.

The motorcyclist is a young man (21 years old) and had recently obtained his motorcycle license (2 July 2018). He was still on a probationary licence. Judging from the extent of the damage caused to both vehicles, he must have been speeding as I did not see any vehicle coming from the filter lane (although I have checked very carefully as mentioned).


I got out of the car to enquire his status and he had indicated that he was fine with only minor abrasions on his right arm (3 red spots as per photos). He showed my father his legs and body - no injury is visible (per photos).

The motorcyclist was coming out from a filter lane (Bedok South Ave 1) to a main road (Upper East Coast Rd) with four lanes. When one is entering a main road from a side road, one should slow down and take the inner lane and not swinging wide onto the outer lane. My father spent 15 minutes observing traffic coming out of the filter lane and he told me that all vehicles were moving slowly and into the inner lane.

The weather was clear and the road slightly wet.

I did not sustain any injury. The motorcyclist sustained only minor bruises (3 red small spots on his right hand) and the damage to his motorcycle is only in the top front.

Thank you.


Ms Chow Su Rin

3 Sep 2018
10.06 A.M.

Mdm Choong Lee Choo

Attached:

1. 54 photos of accident
2. 3 videos of accident
3. Sketch of accident

Bedok South Ave 1

Upper East Coast Rd

Motorcycle was coming out of a side road. Must have been speeding and swung wide into the outer lane.

Coming out of a side road, motorcycle should be ridden slowly and kept to the inner lane.

My car

flow of traffic

The diagram illustrates a road intersection. A road labeled "Upper East Coast Rd" curves from the bottom left towards the top right. A vehicle, represented by a black dot with a horizontal arrow pointing left, is positioned at the top of the road. A witness, represented by a black dot with a vertical arrow pointing up, is positioned on the left side of the road. A shaded triangular area is located between the vehicle and the witness. A horizontal line represents the road's edge, and a vertical line represents the witness's position.

Bedok South Ave 1

Motorcycle was coming out of a side road. Must have been speeding and swung wide into the outer lane.

Coming out of a side road, motorcycle should be ridden slowly and kept to the inner lane.

My car

ESSO station

flow of traffic

Bedok South Ave 1

Motorcycle was coming out of a side road. Must have been speeding and swung wide into the outer lane.

Coming out of a side road, motorcycle should be ridden slowly and kept to the inner lane.

ESSO station

My car

flow of traffic

Bedok South Ave 1

Motorcycle was coming out of a side road. Must have been speeding and swung wide into the outer lane.

Coming out of a side road, motorcycle should be ridden slowly and kept to the inner lane.

ESSO Station

flow of traffic

My car

Bedok South Ave 1

Motorcycle was coming out of a side road. Must have been speeding and swung wide into the outer lane.

Coming out of a side road, motorcycle should be ridden slowly and kept to the inner lane.

My car

ESSO station

flow of traffic

The diagram shows a road layout with a triangular speed limit sign (30 mph) and a motorcyclist's path. The path is indicated by a dashed line and a solid line. A callout box points to the dashed line, stating: "Motorcyclist Must have entered into the road". Another callout box points to the solid line, stating: "Coming from the road should". The road is labeled "Bedford" and has a dashed line indicating a lane boundary. A motorcyclist is shown entering the road from the left, and a car is shown entering from the right. The car is labeled "My car".

To Whom It May Concern

Subject: Letter of Authorisation

I, Madam Choong Lee Choo (NRIC S2617812F) have authorised Ms Chow Su Rin, NRIC S9240439J (my daughter) to drive the above vehicle which is registered under my name. In addition, I authorise Ms Chow Su Rin to make a report and file a claim against my own insurance on my behalf.

Thank You

Yours sincerely



Mdm Choong Lee Choo

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7812F

Vehicle Details

Vehicle No.: SKT3992G

Vehicle to be Exported: No

Intended Deregistration Date: 14 Sep 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: A180 (R17)

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: 27091030665703

Chassis No.: WDD1760422J376161

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$22,209.00

Original Registration Date: 05 Jun 2015

First Registration Date: 05 Jun 2015

Transfer Count: 0

Actual ARF Paid: \$13,093.00 6546

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 Jun 2025

PARF Rebate Amount: \$9,819.00

Intended COE Rebate Details

COE Expiry Date: 04 Jun 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$67,601.00

COE Rebate Amount: \$45,451.00

Total Rebate Amount: \$55,270.00

The information contained herein is correct as at 14 Sep 2018

OK



Celebrate getting ahead of your peers

#KaplanSingapore

It's My Choice



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Almost New 2015 Opel Astra! Under Utilised!

1 Owner, 22,000km, Lowest
Depreciation, Loan Repayment
As Low As \$500 Per Month
Sanctuary Motor StarAdAutoInn
An Inspiration For Car Buyersclick here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted

20 results/page

50 vehicles

Mercedes-Benz a180

Advanced Search

Submit

Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Mercedes-Benz a180		Any	Any	2015	Any	Any	Any	Available

Mercedes-Benz CLA-Class
CLA180

\$92,800

\$13,090 /yr

06-Jan-2015

1,595 cc

62,878 km

Luxury

Available

Excellent Condition Inside Out, Meticulously Taken Care Of. Options To Switch Between Sport, Econ And Manual Mode For Solid Fuel Efficiency Or Performance! Trade In Welcome! Flexible Bank Or In House ...

Benefit Auto Enterprise Pte Ltd

Posted: 14-Sep-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz



Mercedes-Benz A-Class A180

\$95,500

\$12,030 /yr

20-Nov-2015

1,595 cc

26,900 km

Hatchback

Available

Elegant White, Serviced By Agent, Accident Free, One Owner Only, Low Mileage Done, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 13-Sep-2018 Tags: 2015 Mercedes-Benz A180, Mercedes-Benz A180, Mercedes-Benz, A180, Used Mercedes-Benz

Mercedes-Benz CLA-Class
CLA180

\$95,800

\$13,360 /yr

09-Feb-2015

1,595 cc

58,000 km

Luxury

Available

Limited Time Promo Interested Rate At 2.28%, 3 Months Engine/Gearbox Warranty From Our In House Workshop, Excellent Condition, Accident Free, Bank Loan In House Loan Available, Trade In Welcome.

Posted: 13-Sep-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz



Mercedes-Benz A-Class A180

\$84,500

\$12,370 /yr

02-Jan-2015

1,595 cc

Hatchback

Available

Elegant White, Serviced By Agent, Accident Free, One Owner Only, Low Mileage Done, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 13-Sep-2018 Tags: 2015 Mercedes-Benz A180, Mercedes-Benz A180, Mercedes-Benz, A180, Used Mercedes-Benz

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Mercedes-Benz CLA-Class
CLA180

\$99,800

\$13,290 /yr

11-Jun-2015

1,595 cc

43,888 km

Luxury

Available

Fully Serviced And Maintained By C&C, Excellent Condition Plus Complimentary 1 Year Pre-Owned Vehicle Warranty! Single Owner Only, R18 Model. Still Under C&C Warranty, Loan Up To 90% See To Believe, D...

Posted: 13-Sep-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz

Mercedes-Benz CLA-Class
CLA180

\$95,800

\$12,890 /yr

05-May-2015

1,595 cc

46,880 km

Luxury

Available

Full C&C Service! Beautiful Black On Black! Up To 100% Loan Available! Call Me Now For More Info And Viewing Appointment!

Benefit Auto Enterprise Pte Ltd

Posted: 13-Sep-2018 Tags: 2015 Mercedes-Benz CLA180, Mercedes-Benz CLA180, Mercedes-Benz, CLA180, Used Mercedes-Benz

Compare

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S9240439J

Name CHOW SU RIN

Exp. Date 14 Oct 1992

Issue Date 29 Dec 2011

002029994D



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9240439J



Name

CHOW SU RIN

趙 夙 情

Race

CHINESE

Date of birth

14-10-1992

Sex

F

Country of birth

SINGAPORE

S9240439J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =<2500kg 29 Dec 2011


NP 428A



Licence No: S9240439J



NRIC NO. S9240439J



Date of issue

19-10-2007

Address

46 EASTWOOD ROAD
#02-03
SINGAPORE 486356

4118073

CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00006939 (Comprehensive - Prestige Plan)

Car plate number: SKT3992G

Owner name (As the policyholder): CHOONG LEE CHOO

Coverage start date: 05/06/2018

Coverage end date: 04/06/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

a) You; and

b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Our Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Our Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Signed on: 18/05/2018



Anshik Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.



INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2018-00006939	Date of Loss:	02/09/2018
Vehicle Reg. No.:	SKT3992G	Driveable?	
Driver Age/Info:	25 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOONG LEE CHOO		
Driver:	CHOW SU RIN		
Make/Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Vehicle Reg. Date:	05/06/2015
Vehicle Colour:	RED		
Engine No:	27091030665703	Chassis No:	WDD1760422J376161
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	ETHOZ PROTECT PTE LTD (BUKIT BATOK)		

Not Advised
2 day
Excess \$3100
14/9/18
4 day
The phan be pany

COST OF CLAIMS

	Amount
Parts	8,314.00
Miscellaneous Items	35.00
Labour	2,210.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	10,559.00
+ GST 7.00% (\$\$)	739.13
Nett Amount (\$\$)	11,298.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display the repair (part) etc.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This claim is handled by: **SUHELMI BIN SUHARMAN (VEHICLE NOT IN)**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

10399

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2018)
 Parts: 143 MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ETHOZ Protect Pte Ltd/SKT3992G/06/09/2018 14:28
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET <i>12</i>	0.00	0.00	*1,100.00 F	X
2	1		*FRONT FENDER RH <i>DD/ant</i>	0.00	0.00	*500.00 F	/
3	1		*FROTN FENDER INNER SHIELD RH <i>to.1</i>	0.00	0.00	*185.00 F	/
4	10		*FROTN FENDER INNER SHIELD CLIPS <i>ner</i>	0.00	0.00	*50.00 F	/
5	1		*FRONT HEADLAMP RH <i>one</i>	0.00	0.00	*700.00 F	/
6	1		*FRONT BUMPER <i>DD</i>	0.00	0.00	*930.00 F	/
7	10		*FRONT BUMPER CLIPS <i>ner</i>	0.00	0.00	*50.00 F	/
8	1		*FRONT BUMPER LOGO <i>ner</i>	0.00	0.00	*58.00 F	/
9	1		*FROTN BUMPER LOWER GRILLE <i>11</i>	0.00	0.00	*110.00 F	X
10	1		*FOG LAMP COVER RH <i>12/1</i>	0.00	0.00	*48.00 F	X
11	1		*FROTN BUMPER REINFORCEMENT <i>11</i>	0.00	0.00	*275.00 F	X
12	1		*FROTN BUMPER SENSOR RH <i>11</i>	0.00	0.00	*165.00 F	X
13	1		*FRONT SPORT RIM RH <i>DD/ant</i>	0.00	0.00	*1,450.00 F	X
14	1		*FRONT PANEL UPPER RH <i>nm</i>	0.00	0.00	*270.00 F	X
15	1		*FRONT SUPPORT PANEL <i>DD/ant</i>	0.00	0.00	*560.00 F	X
16	1		*FRONT ABSORBER RH <i>11</i>	0.00	0.00	*485.00 F	X
17	1		*FRONT KNUCKLE ARM ASSY WITH BEARING RH <i>11</i>	0.00	0.00	*980.00 F	X
18	1		*FRONT LOWER ARM RH <i>11</i>	0.00	0.00	*398.00 F	X

F=Franchise part.

Total Parts (S\$) **8,314.00**

ETHOZ Protect Pte Ltd/SKT3992G/06/09/2018 14:28. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

4271

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	35.00
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO FACILIATE REPAIR	New 800	900.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New 600	900.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New 20	30.00
4	TO REMOVE & REFIT A/C CONDENSOR INCLUIDNG A/C GAS	New 100	120.00
5	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGMENT	New 60	80.00
6	TO REMOVE & REFIT FROTN RH SUSPENSION	New 113	150.00
7	TO CONDUCT FRONT RH WHEEL BALANCING	New 112	30.00
Gross Labour Cost (S\$)			2,210.00

ETHOZ Protect Pte Ltd/SKT3992G/06/09/2018 14:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ETHOZ PROTECT PTE LTD

Company Registration No. 199005791M

30 Bukit Batok Crescent, SINGAPORE 658075 . Website : <http://www.orix.com.sg>

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Sep 2018)

Parts: 143 MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ETHOZ Protect Pte Ltd/SKT3992G/24/09/2018 17:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER UPPER TRIM			*180.00 F
2	1		*HORN			*160.00 F
Total Parts (S\$)						340.00

F=Franchise part.

ETHOZ Protect Pte Ltd/SKT3992G/24/09/2018 17:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Date : 27/09/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHOONG LEE CHOON

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00006939 Accident Date : 02/09/2018

Vehicle No : SKT-3992-G Make & Model : MERCEDES BENZ A180 (R17) 1800

FINAL ESTIMATED REPAIR COST DETAIL Excess : 0.00 Add Excess : 3,100.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	FRONT BUMPER UPPER TRIM	180.00	180.00
1	HORN RH	160.00	160.00
1	BONNET	1100.00	0.00
1	FRONT FENDER RH	500.00	500.00
1	FRONT FENDER INNER SHIELD RH	185.00	185.00
10	FRONT FENDER INNER SHIELD CLIPS	50.00	50.00
1	FRONT HEADLAMP RH	700.00	700.00
1	FRONT BUMPER	930.00	930.00
10	FRONT BUMPER CLIPS	50.00	50.00
1	FRONT BUMPER LOGO	58.00	58.00
1	FRONT BUMPER LOWER GRILLE	110.00	0.00
1	FOG LAMP COVER RH	48.00	48.00
1	FRONT BUMPER REINFORCEMENT	275.00	0.00
1	FRONT BUMPER SENSOR RH	165.00	0.00

P: \$421.00

S/N: \$25.00

L: \$150.00

COR: \$5876.00

Repair days: 04

Excess: \$3100/2

PAGE: 1

Date : 27/09/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHOONG LEE CHOON

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00006939 Accident Date : 02/09/2018

Vehicle No : SKT-3992-G Make & Model : MERCEDES BENZ A180 (R17) 1800

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 3,100.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	FRONT SPORT RIM RH	850.00	850.00
1	FRONT PANEL UPPER RH	270.00	0.00
1	FRONT SUPPORT PANEL	560.00	560.00
1	FRONT ABSORBER RH	485.00	0.00
1	FRONT KNUCKLE ARM ASSY WITH BEARING	980.00	0.00
1	FRONT WHEEL HUB & WHEEL BEARING (RH)	0.00	0.00
1	FRONT LOWER ARM RH	398.00	0.00
	Sub Total	8054.00	4271.00
	Add 0% On Parts	0.00	0.00
	Special Nett Item		
1	COOLANT	35.00	25.00

Date : 27/09/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHOONG LEE CHOON

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00006939 Accident Date : 02/09/2018

Vehicle No : SKT-3992-G Make & Model : MERCEDES BENZ A180 (R17) 1800

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 3,100.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	35.00	25.00
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	900.00	800.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS	900.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	20.00
	TO REMOVE & REFIT A/C CONDENSOR INCLUDING A/C GAS	120.00	100.00
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	80.00	60.00
	TO REMOVE & REFIT FRONT RH SUSPENSION	150.00	0.00
	TO CONDUCT WHEEL BALANCING	30.00	0.00



Date : 27/09/2018
To : FWD SINGAPORE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : CHOONG LEE CHOON

Insured By : FWD SINGAPORE PTE. LTD.

Certificate No : PNPV2018-00006939 Accident Date : 02/09/2018

Vehicle No : SKT-3992-G Make & Model : MERCEDES BENZ A180 (R17) 1800

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 3,100.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	2210.00	1580.00
	Sub Total	10,299.00	5,876.00
	GST 7.0 %	720.93	411.32
	Total	11,019.	6,287.32

Surveyor Name : MARCUS - LKK

Date & Time : 14/09/2018 2:00:00 PM

Ng Boon Kai

CLAIM DEPARTMENT

DID : 6654 7617

FAX :

PAGE : 4

EURO AUTOPART TRADE

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201809-10208

ATTENTION TO SALES PERSON: KAI

DATE: 24-Sep-18

P/O 164707

VEHICLE NO: SKT3992G MERS A180

30 DAYS

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		FRT FENDER RH	1	\$ 500.00	\$ 500.00
2		FRT FENDER INNER SHIELD RH	1	\$ 185.00	\$ 185.00
3		FRT FENDER INNER SHIELD CLIP	10	\$ 5.00	\$ 50.00
4		HEADLAMP RH	1	\$ 700.00	\$ 700.00
5		FRT BUMPER	1	\$ 930.00	\$ 930.00
6		FRT BUMPER CLIPS	10	\$ 5.00	\$ 50.00
7		FRT BUMPER LOGO	1	\$ 58.00	\$ 58.00
8		FOGLAMP COVER RH	1	\$ 48.00	\$ 48.00
9		SUPPORT PANEL ASSY	1	\$ 560.00	\$ 560.00
10		SPORT RIM	1	\$ 850.00	\$ 850.00
11					\$ -
12					\$ -
13					\$ -
14					\$ -
15					\$ -
16					\$ -
17					\$ -
18					\$ -
19					\$ -
20					\$ -
21					\$ -
22					\$ -
23					\$ -
24					\$ -
25					\$ -
				SUB-TOTAL	\$ 3,931.00
				GST @ 7%	\$ 275.17
				GRAND TOTAL	\$ 4,206.17

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:

NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

Euro Autopart Trade

YOUR ONE STOP AUTOPARTS SOLUTION

TAX INVOICE

To COMPANY: ETHOZ PROTECT PTE LTD

INV NO: PF201809-10212

ATTENTION TO SALES PERSON:

KAI

DATE: 24-Sep-18

P/O

164707

VEHICLE NO: SKT3992G MERS A180

30 DAYS

SEND TO: 30 BUKIT BATOK CRES

S/NO.	PART NO.	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1		FRT BUMPER UPPER TRIM	1	\$ 180.00	\$ 180.00
2		HORN RH	1	\$ 160.00	\$ 160.00
3					\$ -
4					\$ -
5					\$ -
6					\$ -
7					\$ -
8					\$ -
9					\$ -
10					\$ -
11					\$ -
12					\$ -
13					\$ -
14					\$ -
15					\$ -
16					\$ -
17					\$ -
18					\$ -
19					\$ -
20					\$ -
21					\$ -
22					\$ -
23					\$ -
24					\$ -
25					\$ -
SUB-TOTAL					\$ 340.00
GST @ 7%					\$ 23.80
GRAND TOTAL					\$ 363.80

NOTE: GOODS SOLD ARE NON RETURNABLE

RECEIVED BY:

AUTHORISED BY:



NO. 50 PLAYFAIR ROAD #03-02F

NOEL BUILDING S(367995)

BRN:53225532A / GST REG NO: M90370620L

TEL: 6635 8238 FAX: 6280 5805 HP: 9451 5113 / 9457 4513

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Sep 2018 11:11 Sendback Est	06 Sep 2018 14:28 S\$10,559.00	06 Sep 2018 16:21 Edit Adj Rpt	S\$5,876.00 Edit Estimates	S\$5,876.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	24 Sep 2018 17:11	24 Sep 2018 17:13 S\$340.00	24 Sep 2018 17:13			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHOONG LEE CHOO, ID: S2617812F		
Vehicle Reg. No.:	SKT3992G	Date of Loss:	02/09/2018 13:00 - :59 [38 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800011061	Policy/Cover Note No.:	PNPV2018-00006939 (Comprehensive)
		Excess:	S\$3,100.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/09/2018]		
Driver/Custodian:	CHOW SU RIN (25 / Female), NRIC: S9240439J, Tel: +6593387521		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (25/09/2018): Alert - Adj Mandate Approved (S\$8666.00) - SKT3992G - Claim Handler: Josey Loh
- FWD_SG (17/09/2018): Alert - Adj Mandate Approved (S\$8326.00) - SKT3992G - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SKT3992G (1201800011061)

OD

Sep 2 2018 1:00PM

[CHOONG LEE CHOO]

ETHOZ Protect Pte Ltd







































Upload Documents Upload Photos Compose New Letter

View View in Browser ▼




Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/09/18 12:03	Video - Accident [Linked Accident Report Documents]	Load MP4	
2	03/09/18 12:03	Video - Accident [Linked Accident Report Documents]	Load MP4	
3	03/09/18 12:03	Video - Accident [Linked Accident Report Documents]	Load MP4	

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	06/09/18 14:28	Repairer Estimates	Load HTM	
2	24/09/18 17:13	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:37	Adjuster Immediate Advice	Load HTM	
2	25/09/18 09:32	Adjuster Immediate Advice	Load HTM	




Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:39	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	17/09/18 15:39	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
20	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
21	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
22	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
23	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>
24	17/09/18 15:39	General View	Load JPG	<input checked="" type="checkbox"/>


Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
25	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/09/18 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/09/18 09:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	28/09/18 09:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	28/09/18 09:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	28/09/18 09:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
























Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
73	28/09/18 09:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/09/18 15:38	ESTIMATE	 Load PDF	
2	08/10/18 09:35	PARTS INVOICE	 Load PDF	
3	08/10/18 09:35	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/09/18 12:03	Video - Accident	 Load MP4	
2	03/09/18 12:03	Video - Accident	 Load MP4	
3	03/09/18 12:03	Video - Accident	 Load MP4	

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/09/18 12:05	Accident Statement	 Load HTM	

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
24	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
25	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
26	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
27	03/09/18 10:48	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
Documentation			1 per page ▼	✓
No	Finalized On	ETHOZ Protect Pte Ltd (Bukit Batok)	Thumbnail	Print
1	03/09/18 10:35	Sketch Plan	Load TIF	
2	03/09/18 10:36	INSURANCE CERT	Load TIF	
3	03/09/18 10:36	DRIVER DL	Load JPG	✓
4	03/09/18 10:36	OWNER IC	Load JPG	✓
5	03/09/18 10:36	POLICE REPORT	Load JPG	✓
6	03/09/18 10:37	AUTHORISATION LETTER	Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

10/8/2018

Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18016342/UQD3S2

Date: 08/10/2018

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18016342/UQD3S2

Date: 08/10/2018

REFERENCE

Insured/Claimant:	CHOONG LEE CHOO	Policy No:	PNPV2018-00006939	
Date of Loss:	02/09/2018	Nature of Claim:	OD	Claim No: 1201800011061

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT3992G	Engine No:	27091030665703
Make & Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Chassis No:	WDD1760422J376161
Reg. Date:	05/06/2015 (Man. Year: 2015)	Odometer:	41883 km
Colour:	Red		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$81,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,654.00	4,271.00	4,383.00	50.65
Miscellaneous Items	35.00	25.00	10.00	28.57
Labour	2,210.00	1,580.00	630.00	28.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,899.00	5,876.00	5,023.00	46.09
- Excess (S\$)	0.00	3,100.00	-3,100.00	
(S\$)	10,899.00	2,776.00	8,123.00	74.53
+ GST 7.00/7.00% (S\$)	762.93	194.32	568.61	74.53
Nett Amount (S\$)	11,661.93	2,970.32	8,691.61	74.53

INSPECTION

Date of Assignment:	06/09/2018	Present Location:	ETHOZ Protect Pte Ltd (Bukit Batok)
Date Inspected:	14/09/2018	Inspected At:	ETHOZ Protect Pte Ltd (Bukit Batok)
Estimated Period of Repair:	4.0 days		30 Bukit Batok Crescent
			Singapore 658075

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2018)
Parts:	143	MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT3992G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,100.00 F	*- F
2	1		*FRONT FENDER RH	Dented / Bent	500.00 F	*500.00 F
3	1		*FROTN FENDER INNER SHIELD RH	Torn	185.00 F	*185.00 F
4	10		*FROTN FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 F
5	1		*FRONT HEADLAMP RH	Cracked	700.00 F	*700.00 F
6	1		*FRONT BUMPER	Distorted	930.00 F	*930.00 F
7	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 F
8	1		*FRONT BUMPER LOGO	Necessary	58.00 F	*58.00 F
9	1		*FROTN BUMPER LOWER GRILLE	Not Necessary	110.00 F	*- F
10	1		*FOG LAMP COVER RH	Twisted	48.00 F	*48.00 F
11	1		*FROTN BUMPER REINFORCEMENT	Not Necessary	275.00 F	*- F
12	1		*FROTN BUMPER SENSOR RH	Not Necessary	165.00 F	*- F
13	1		*FRONT SPORT RIM RH	Dented / Bent	1,450.00 F	*850.00 F
14	1		*FRONT PANEL UPPER RH	Not Necessary	270.00 F	*- F
15	1		*FRONT SUPPORT PANEL	Bent / Twisted	560.00 F	*560.00 F
16	1		*FRONT ABSORBER RH	Not Necessary	485.00 F	*- F
17	1		*FRONT KNUCKLE ARM ASSY WITH BEARING RH	Not Necessary	980.00 F	*- F
18	1		*FRONT LOWER ARM RH	Not Necessary	398.00 F	*- F
Supplementary #1						
19	1		*FRONT BUMPER UPPER TRIM	Distorted	180.00 F	*180.00 F
20	1		*HORN	Torn	160.00 F	*160.00 F

F=Franchise part.

Total Parts (S\$)	8,654.00	4,271.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	35.00	25.00
Sub Total (\$\$)			35.00	25.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILIATE REPAIR	New	900.00	800.00
2	LABOUR TO SPRAY PAINT AFFECTED AREAS	New	900.00	600.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	20.00
4	TO REMOVE & REFIT A/C CONDENSOR INCLUDNG A/C GAS	New	120.00	100.00
5	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGMENT	New	80.00	60.00
6	TO REMOVE & REFIT FROTN RH SUSPENSION	New	150.00	0.00
7	TO CONDUCT FRONT RH WHEEL BALANCING	New	30.00	0.00
Gross Labour Cost (\$\$)			2,210.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >