

Attn = Edison Lo

Fax = 67465110

Repair For Vehicle SLR 6796 K (VOLKSWAGEN New Golf 1.4 AT)

from Simon

Description Parts	Qty	Price list
1 Front bumper	1	\$ 1,192.00 DD
2 Front bumper side retainer L/R @ \$105.00	2 1 RH-DIS	\$ 210.00
3 Front bumper grille	1	\$ 308.90 CRA
4 Front bumper reinforcement	1	\$ 680.40 DD
5 Front radiator grille	1	\$ 554.75 CRA
6 Front bumper form RH	1	\$ 56.00 XNN
7 Front headlamp RH	1	\$ 1,010.50 CRA
8 Front headlamp mount bracket RH	1	\$ 288.00 XNN
9 Front headlamp bracket RH	1	\$ 194.10 XNN
10 Front fender RH	1	\$ 620.10 XR
11 Front fender inner liner RH	1	\$ 165.00 CRA
		\$ 5,279.75
	Less 10%	\$ 527.98
		\$ 4,751.77

S/NETT ITEM

12 Front fog lamp RH	1	\$ 298.00 CRA
13 Front fog lamp mesh RH	1	\$ 158.50 CRA
14 Front fog lamp chrome ring RH	1	\$ 45.00 XNN
15 Front headlamp fibra protector RH	1 set	\$ 190.00 NEC
16 Front number plate with casing	1 set	\$ 120.00 DIS
17 Front fender under shield clips RH	1 set	\$ 40.00 NEC
18 Front radiator grille emblem	1	\$ 68.50 XNN
19 Front bumper clips	1 set	\$ 48.50 NEC
	Parts Total :	\$ 5,720.27

LABOUR CHARGES & MISC

20 Check wiring, lighting & focus headlight.	\$ 50.00 30
21 To braking & re-seal front license plate at LTA.	\$ 120.00 90
22 Remove & replace all damaged parts, repair & realign.	\$ 900.00 500
23 Spray painting front fender, bonnet, front bumper and all affected portions.	\$ 1,000.00 600
24 To diagnostic checks & reset.	\$ 280.00 X
25 Anti-rust proofing	\$ 100.00 X
	Labour Total : \$ 2,450.00

Sub Total : \$ 8,170.27

LS \$3,300

5 days

Lump sum repair adjustment

\$ 6,500.00

Estimated time required for repairs

8 days