

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Vehicle No : FBK 8421 J

Vehicle Model : Vespa

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fender	\$ CM 160.00 ✓
1	Front fork assy	\$ 2 780.00 ✓
1	Front shock absorber	\$ 11 450.00 ✓
1	Front fork cover	\$ 8VC 75.00 ✓
1	Front cowling	Deep \$ cut 328.00 ✓
1	Front cowling moulding	\$ cut 95.00 ✓
1	Front cowling inner panel	Deep \$ cut 387.00 ✓
1	Front signal -L/H	\$ SCR 75.00 ✓
1	Side mirror -L/H	\$ cut 85.00 ✓
1	Handle-bar	\$ 34 320.00 ✓
1	Hand grip (1 set)	\$ 1A 80.00 ✓
1	Handle-bar balancer	\$ SCR 42.00 ✓
1	Clutch lever	\$ SCR 38.00 ✓
1	Main stand	cut \$/B 135.00 ✓
1	Seat lower panel -L/H	\$ cut 395.00 ✓
1	Rear seat lower panel -L/H	deep \$ cut 215.00 ✓
		\$ 3,660.00
	Less 10%	\$ 366.00
		\$ 3,294.00

2275

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Vehicle No : **FBK 8421 J**

Vehicle Model : **Vespa**

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$ <i>mu</i> 28.00 <i>15</i>
1	Steering cone (1 set)	\$ <i>11</i> 120.00 <i>α</i>
		<u>\$ 148.00</u>

S/No.

Labour

1	To provide towing service.	\$ 45.00 <i>35</i>
2	To check wiring and reset headlamp focusing.	\$ 80.00 <i>α</i>
3	To provide labour.	\$ <i>17</i> 380.00 <i>250</i>
4	To respray painting.	\$ 800.00 <i>520</i>
5	To repair body frame.	\$ 350.00 <i>250</i>
		<u>\$ 1,655.00</u>

Grand Total

3117.5
\$ 5,097.00

Dollars: Five Thousand And Ninety-Seven Dollars Only.

EROFIA MOTOR TRADING PTE LTD

[Signature]
LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

not Acknowledged
2400/-
5 day
7/9/18
The photo After repair