

Not about
 now
 7/9/18
 take the average
 & dy.

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg
 GST:200712509E RCB NO:201004495R

M/S : FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER FOUR
 SINGAPORE 038986
 TEL: 6727 5721
 ATTN: Motor Claim Department

Estimate No: EST0000700
 Date: 06 Sep 2018
 Policy No: ga257635/1
 Veh Reg No: SGG466U
 Make/Model: VOLKSWAGEN JETTA 1.4
 TSI AT 1623G5
 Chassis No: WVVZZZ16ZCM004719
 Engine No: CAX901645
 Reg. Date: 26-09-2011

Your Ref No: SGG466U
 Claim Type: Third Party
 Accident Date: 05-09-2018
 TP Veh Reg No: SLM4453P

Estimate Repair Cost for Vehicle No :SGG466U

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
VOLKSWAGEN JETTA 1.4 TSI AT 1623G5				
List Price				
1 Rear Boot <i>DD/3uc</i>	1,490.000	1 PC	1,490.00	—
2 Rear Boot Hinge <i>11</i>	110.0000	2 PC	220.00	X
3 Rear Boot Lock <i>1u</i>	220.0000	1 PC	220.00	—
4 Rear Boot Lock Catch <i>11</i>	90.0000	1 PC	90.00	X
5 Rear Boot Rubber <i>1u</i>	263.8000	1 PC	263.80	—
6 Rear Boot Emblem (JETTA) <i>1u</i>	35.4000	1 PC	35.40	—
7 Rear Boot Emblem (TSI) <i>1u</i>	35.4000	1 PC	35.40	—
8 Rear Boot Centre Logo <i>1u</i>	120.0000	1 PC	120.00	—
9 Rear Boot Reflector Lamp <i>1/1scn o/1scn</i>	290.0000	2 PC	580.00	—
10 Rear Boot Inner Cover Board <i>11</i>	190.0000	1 PC	190.00	X
11 Rear Tail Lamp <i>1/1scn o/1scn</i>	380.0000	2 PC	760.00	—
12 Rear Tail Lamp Inner Side Cover <i>1/1scn</i>	54.0000	2 PC	108.00	1/2
13 Rear End Panel	980.0000	1 PC	980.00	?
14 Rear End Panel Top Garnish	235.0000	1 PC	235.00	—
15 Rear Bumper <i>Dis</i>	1,123.700	1 PC	1,123.70	—
16 Rear Bumper Side Retainer <i>1u</i>	89.5000	2 PC	179.00	—
17 Rear Bumper Reinforcement	640.0000	1 PC	640.00	?
18 Rear Bumper Lower Pad <i>1u/1u</i>	540.0000	1 PC	540.00	—
19 Rear Spare Tyre Top Cover Board <i>11</i>	240.0000	1 PC	240.00	X
20 Rear Bumper Core Inner Bracket	135.0000	2 PC	270.00	?
			8,320.30	
		Less 10%	832.03	7,488.27
Special Net				
21 Rear Number Plate <i>1u</i>	50.0000	1 PC	50.00	40
22 Rear Bumper Sensor <i>1u/1u</i>	300.0000	1 SET	300.00	200
			350.00	350.00
Labour				
23 Panel Beating	1,200.000	1 PC	1,200.00	600
24 Check Wiring	80.0000	1 PC	80.00	30
25 Rust Proofing	80.0000	1 PC	80.00	60

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER FOUR
SINGAPORE 038986

TEL: 6727 5721
ATTN: Motor Claim Department

Your Ref No: SGG466U
Claim Type: Third Party
Accident Date: 05-09-2018
TP Veh Reg No: SLM4453P

Estimate No: EST0000700
Date: 06 Sep 2018
Policy No: ga257635/1
Veh Reg No: SGG466U
Make/Model: VOLKSWAGEN JETTA 1.4
TSI AT 1623G5
Chassis No: WWZZZ16ZCM004719
Engine No: CAX901645
Reg. Date: 26-09-2011

Estimate Repair Cost for Vehicle No :SGG466U

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
26 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	80.00
27 To Spray Painting	900.0000	1 PC	900.00	900.00
			2,340.00	2,340.00
Total				SS 10,178.27

TOTAL: SINGAPORE DOLLAR TEN THOUSAND ONE HUNDRED SEVENTY EIGHT AND CENTS TWENTY SEVEN ONLY

For FOCUS AUTO PTE LTD
Focus Auto Pte Ltd
No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: