

7/9/2002

ASS. REC. BY:

REF:

CS/FCI18016355/ R11 d3/12

Special Instruction:

Surveyor:

CCWS

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

6/9/18 @ 5.53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 23717

Insured:

8HD3336X

at Workshop m/s

Cycle & Camiaye France

Tel:

65684501 / 9186 5202

of

209 Penden Gardens

Policy No:

Claim No:

D18006277MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/08/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

7/9/18 @ 10:15am

Person Contacted:

Don Bong

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 23717 - X
	8HD3336X - CSI FCI17017849 / R19bn2 DOA: 9/9/17
18/9 @ 4:49am	revert preli advise via email.
	part by part \$5192/- (red: 4135/44%)

Driver: James

REF:

8024F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 2371T

at Workshop m/s CBC

of Damage Location

Insured: FCI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition) 2pm owner only DON

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLA 2371T Yr Regn: 2016 / FGS

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: CITROEN PICASSIO 1.6 c.c. 1560

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 57169 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF73ABHZTFJ845615

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/08/18 D.O.I. 11/09/18

Survey held at CBC (PG)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 19 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

Report Format : TP

Lump Sum / (B): (\$ 5921)

170
50
50
43
313



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006277MFSH

Date: 13/9/2018

Our Ref: CS/FCI18016355/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 2371T

Please be informed that we had conducted the inspection of the abovementioned vehicle 11/09/2018 at the premises of M/s Cycle and Carriage France and have the following to report: -

Workshop Estimate Amount	: S\$ <u>9,147.00</u>
Revised Estimate Amount	: S\$ <u>4,588.00</u>
"Check" Items Amount	: S\$ <u>1,532.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-08-2018	Our Ref No. D18006277MFSH
Accident Date	20-08-2018	Claim Type. Third Party
Insured Vehicle	SHD3336X	Third Party Vehicle. SLA2371T
Survey Location	209 PANDAN GARDENS	
Contact Person.	DON BONG	
Contact No.	65684501/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE FRANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 13 September 2018 4:49 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006277MFSH/1
Attachments: PRELI ADVISED SLA 2371T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLA 2371T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 7 September 2018 10:17 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006277MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 6 September 2018 5:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006277MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 19 December 2018 11:23 AM
To: Shu Pei (LKKAUTO); lauro.songcuan@cyclecarriage.com.sg; Rasul (LKKAUTO)
Cc: Andre Chow En De; Loi Ai Ting; Cheng Jo Jo; Don Bong Kiong Hua; Admin A
Subject: RE: SLA2371T (CIT) - FINALIZE

Dear Lauro,

Confirm final figure \$5192/- before 7% gst, 5days.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Friday, 7 December 2018 2:24 PM
To: lauro.songcuan@cyclecarriage.com.sg; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: FW: SLA2371T (CIT) - FINALIZE

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CS/FCI18016355/R1td3	Rasul / Denise

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



CERTIFICATE OF INSURANCE

CITROEN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Yang Shaoguang
Period of Insurance : 25 Feb 2018 To 24 Feb 2019
Engine No. : 10JBHD3024539
Chassis No. : VF73ABHZTFJ845615

Vehicle No. : SLA2371T
Policy No. : 2100453407-02
Endorsement No. :
Issued Date : 17 Jan 2018

ABOUT THE COVER

Make/Model : CITROEN Grand C4 Picasso 1.6 Blue HDi eAT6
Engine Capacity/Tonnage : 1,560.00 CC Sum Insured : Market Value First Year of Registration : 2016
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 9 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Yang Shaoguang - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
2. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708800
3. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 600339 68894501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0504485204

CYCLE & CARRIAGE - DARREN
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

1000735848/AC4

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of Yang Shaoguang

Licence Number **S8278024F**

Name **YANG SHAOGUANG**

Birth Date **17 Dec 1982**

Issue Date **04 Nov 2011**

Barcode: 0020152700

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8278024F**

Portrait of Yang Shaoguang

Name **YANG SHAOGUANG**

杨 绍 光

Race **CHINESE**

Date of birth **17-12-1982**

Sex **M**

Country of birth **CHINA**

4878081

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg **04 Nov 2011**

FOR C&C USE

Licence No: **S8278024F**

NP 428A

4878081

Barcode

IRIS No. **S8278024F**

IRIS Image

Date of issue **29-08-2012**

Address

**APT BLK 260A SENGKANG EAST WAY
#05-488
SINGAPORE 541260**

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR YANG SHAOGUANG BLK 260A SENGKANG EAST WAY #05-488 SINGAPORE 541260 Contact No Mobile: 81802386	Cust No/Name /MR YANG SHAOGUANG Reg No/Reg Date SLA2371T / 25/02/2016 Date In/Mileage / 0 Chassis No VF73ABHZTFJ845615 Engine No 10JBHD3024539 Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT Colour/Trim 1SM / 8MF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	20/08/2018/ 19:42	QUD	247 / DonBong	13713

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REAR REINFORCEMENT, REAR TAILGATE PANEL, REPAIR REAR TAILGATE, REPAIR REAR END PANEL				1100 2400.00
E PNT88000 REMOVE AND INSTALL PARKING SENSOR ASSIST				80 100.00
E PNT88000 REMOVE AND INSTALL REAR TAILGATE PANEL TO FACILITATE REPAIR WORK				250 400.00
E PNT98000 PAINT WORK SPRAY REAR TAILGATE, TAILGATE PANEL, REAR BUMPER, REAR END PANEL AND AFFECTED PORTION				28 2100.00 840
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				50 60.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				300.00
M SUNDRY PERFORM RUST PREVENTION				80.00 X AM
M SUNDRY SUPPLY C&C LOGO				50.00 X NE
M SUNDRY SUNDRIES				30 50.00 ncl
M REAR BUMPER	1.00	858.00	0.00	DE 858.00
M BUMPER BRACKET	1.00	258.00	0.00	CR4 258.00
M BUMPER SKIRT	1.00	313.00	0.00	DE 313.00
M RECESS DOOR	1.00	50.00	0.00	DE 50.00
M BRACKET SET	1.00	101.00	0.00	11 101.00
M BRACKET SET LAT	1.00	101.00	0.00	11 101.00
M BUMPER SEAL	1.00	47.00	0.00	11 47.00
M BUMPER BRACKET	1.00	296.00	0.00	CR4 296.00
M ANGLEPLATE	1.00	43.00	0.00	11 43.00
M STIFFENER LH	1.00	59.00	0.00	50 59.00
M STIFFENER RH	1.00	59.00	0.00	50 59.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
MR YANG SHAOGUANG		Cust No/Name	/MR YANG SHAOGUANG
BLK 260A SENGKANG EAST WAY		Reg No/Reg Date	SLA2371T / 25/02/2016
#05-488		Date In/Mileage	/ 0
SINGAPORE 541260		Chassis No	VF73ABHZTFJ845615
Contact No Mobile: 81802386		Engine No	10JBHD3024539
		Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT
		Colour/Trim	1SM / 8MF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	20/08/2018/ 19:42	QUD	247 / DonBong	13713

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LOW RR PAN FIX	1.00	167.00	0.00	167.00
M SENSOR SUPPORT	1.00	123.00	0.00	123.00
M TLGT EXT PANEL	1.00	477.00	0.00	477.00
M WEATHERSTRIP PAVILLON	1.00	67.00	0.00	67.00
M BADGE C4	1.00	40.00	0.00	40.00
P BADGE PICASSO	1.00	56.00	0.00	56.00
M BADGE	1.00	66.00	0.00	66.00
M BADGE BLUE HDi	1.00	38.00	0.00	38.00
M SENSOR CTR	1.00	131.00	0.00	131.00
M SENSOR CTR	1.00	131.00	0.00	131.00
M SENSOR SIDE	1.00	153.00	0.00	153.00
M SENSOR SIDE	1.00	153.00	0.00	153.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

Rasul - Hp 90010068

SURVEYOR SIGNATURE:

DATE:

11/09/18 @ 1400h

REMARKS:

5 days

Confirm & accepted by

Parts	3,787.00
Labour	5,360.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	180.00
Total (w/o GST)	9,327.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LKK.
Rasul

VEHICLE NO : SLA 2371 T

MODEL : CIT/GC4P 1.6 BLUEHDI

WIP : 13713

Material	: \$	<u>2,492.00</u>
Labour	: \$	<u>2,700.00</u>
Sub-Total	: \$	<u>5,192.00</u>
Less 2% Disc	: \$	<u>-</u>
Less Excess	: \$	<u>-</u>
Total	: \$	<u>5,192.00</u>
GST 7%	: \$	<u>363.44</u>
Grand Total	: \$	<u>5,555.44</u>
Finalise By/Date : <u>LARRY ON 06/12/18</u>		

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS

* TP vehicle no: SHD3336X

* claim loss of RENTAL.

Car No: SLA 2271T WIP 13713

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	R/R Bumper REINF	? /Supp	✓		C9676 007180
2	11 Bumper	? /Supp	✓		C9677307680
3		? /Supp			
4		? /Supp			
5		? /Supp			
6		? /Supp			
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

DATE	TAKEN BY
24/9	SPK
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CELLETE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO B4 SUSP & U/C REMOVE	

Model: GC4 P 1.6

Surveyor: RAJUL - LKK



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

PRO-FORMA INVOICECompany Reg No. 200606327M
GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR YANG SHAOGUANG BLK 260A SENGKANG EAST WAY #05-488 SINGAPORE 541260	Cust No/Name /MR YANG SHAOGUANG Reg No/Reg Date SLA2371T / 25/02/2016 Date In/Mileage 24/09/2018/ 58111 Chassis/Package VF73ABHZTFJ845615 /FS515N Engine No 10JBHD3024539 Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 CONFORT Colour/Trim 1SM / 8MF
Contact No Mobile: 81802386	



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	06/12/2018/ 16:49	TLD	884 / Lauro Songcuan	13713	0
Description of Goods / Services				Qty	Unit Price	Disc%
						Amount

E PNT88000	RENEW DAMAGED PARTS ON REAR BUMPER FACE, REAR REINFORCEMENT, REAR TAILGATE GARNISH, REPAIR REPAIR REAR END PANEL						1100.00 ✓
E PNT88000	REMOVE AND INSTALL PARKING SENSOR ASSIST						80.00 ✓
E PNT88000	REMOVE AND INSTALL REAR TAILGATE PANEL TO FACILITATE REPAIR						250.00 ✓
E PNT98000	SPRAY PAINT REAR TAILGATE, TAILGATE GARNISH, REAR BUMPER, REAR END PANEL AND AFFECTED PORTIONS						840.00 ✓
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM						50.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						300.00 ✓
M SUNDRY	SUPPLY C&C LOGO						50.00 ✓
M SUNDRY	SUNDRIES						30.00 ✓
X REAR BUMPER ✓		1.00	858.00	0.00			858.00 ✓
X BUMPER BRACKET ✓		1.00	258.00	0.00			258.00 ✓
X BUMPER SKIRT ✓		1.00	313.00	0.00			313.00 ✓
X BUMPER BRACKET ✓		1.00	296.00	0.00			296.00 ✓
X LOW RR PAN FIX ✓		1.00	167.00	0.00			167.00 ✓
X SENSOR SUPPORT ✓		1.00	123.00	0.00			123.00 ✓
X TLGT EXT PANEL ✓		1.00	477.00	0.00			477.00 ✓
Z TEXT	TP FIRST CAPITAL CLAIM AGAINST SHD3336X DOA: 20.08.2018 SURVEYOR: RASUL 11.09.2018						

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	2,492.00				
Labour	2,620.00				
Standard Menu	0.00	7% GST on	5192.00	Nett	5,192.00
Specialist Job	0.00				363.44
Diagnostics Job	0.00			Total Payable	5,555.44
Sundry/Others	80.00			Paid	0.00
Total(w/o GST)	5,192.00			Total Due	5,555.44

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016355/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3336X	Veh. Inspected	SLA 2371T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006277MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	06/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN PICASSO 1.6	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF73ABHZTFJ845615	Colour	GREY	
Odometer	57169	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2018	Inspection Date	11/09/2018	
Survey held at	CYCLE & CARRIAGE FRANCE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 2371T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	858.00	858.00
1	BUMPER BRACKET (SN)	CRACKED	258.00	258.00
1	BUMPER SKIRT (SN)	DEFORMED	313.00	313.00
1	RECESS DOOR (SN)	NOT NECESSARY	50.00	-
1	BRACKET SET (SN)	NOT NECESSARY	101.00	-
1	BRACKET SET LAT (SN)	NOT NECESSARY	101.00	-
1	BUMPER SEAL (SN)	NOT NECESSARY	47.00	-
1	BUMPER BRACKET (SN)	CRACKED	296.00	296.00
1	ANGLEPLATE (SN)	SERVICEABLE	43.00	-
1	STIFFENER LH (SN)	SERVICEABLE	59.00	-
1	STIFFENER RH (SN)	SERVICEABLE	59.00	-
1	LOW RR PAN FIX (SN)	NECESSARY	167.00	167.00
1	SENSOR SUPPORT (SN)	NECESSARY	123.00	123.00
1	TLGT EXT PANEL (SN)	CUT	477.00	477.00
1	WEATHERSTRIP PAVILLON (SN)	NOT NECESSARY	67.00	-
1	BADGE C4 (SN)	NOT NECESSARY	40.00	-
1	BADGE PICASSO (SN)	NOT NECESSARY	56.00	-
1	BADGE (SN)	NOT NECESSARY	66.00	-
1	BADGE BLUE HDI (SN)	NOT NECESSARY	38.00	-
1	SENSOR CTR (SN)	NOT NECESSARY	131.00	-
1	SENSOR CTR (SN)	NOT NECESSARY	131.00	-
1	SENSOR SIDE (SN)	NOT NECESSARY	153.00	-
1	SENSOR SIDE (SN)	NOT NECESSARY	153.00	-
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	C&C LOGO (SN)	NECESSARY	50.00	50.00
			3,887.00	2,572.00
LABOUR				
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REAR REINFORCEMENT, REAR TAILGATE PANEL, REPAIR REAR TAILGATE, REPAIR REAR END PANEL.			2,400.00	1,100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND INSTALL PARKING SENSOR ASSIST.		100.00	80.00
	REMOVE AND INSTALL REAR TAILGATE PANEL TO FACILITATE REPAIR WORK.		400.00	250.00
	PAINT WORK SPRAY REAR TAILGATE, TAILGATE PANEL, REAR BUMPER, REAR END PANEL AND AFFECTED PORTION.		2,100.00	840.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		60.00	50.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PRO TEST USING HI SCAN PRO TEST.		300.00	300.00
	PERFORM RUST PREVENTION.	NOT NECESSARY	80.00	-
			5,440.00	2,620.00
	GRAND TOTAL		9,327.00	5,192.00
	RECOMMENDED COST OF REPAIRS			5,192.00

Report Ref No. CS/FCI18016355/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.