

## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Monday, 28 January, 2019 4:12 PM  
**To:** Quintec  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** RE: Vehicle No GBG9731D  
**Attachments:** 20190128\_152133.jpg; 20190128153116534.pdf

Dear Agnes,

We refer to your below email and the contents were noted.

As spoken earlier, we will look into the matter.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

-----Original Message-----

From: Quintec [mailto:quintec@singnet.com.sg]

Sent: Monday, 28 January, 2019 3:34 PM

To: Vic (LKKAuto)

Subject: Vehicle No GBG9731D

Dear Vic

As spoken, I do not think that the dent on SLH2306X was caused by my Company lorry, GBG9731D. The dent on my vehicle lorry, as shown on the jpg photo, the height of the dent does not correspond to the dent as shown on the PDF photo for Honda Vezzel, SLH2306X.

Please investigate further & let me know if you need any clarification

Thanks

Regards

Agnes

Quintec Technology Pte Ltd

Tel : 6546 7877

Fax : 6546 7477