

ASE. REC. BY:

REF:

CS/FCI 18016358/Klv d3

n2

Special Instruction:

Surveyor:

AWS

Kalvin

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

7/9/18 9.16am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HC 6049K

Insured:

SHA 0859P

at Workshop m/s:

Premier Automotive

Tel:

6544 6671

of

23 changi south Ave 2 # 03-02

Policy No:

Claim No:

D18006614 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/09/2018

CA / REV / REP. / REV 24 HRS

(PS)

H.O.D. Endorsement:

Date/Time:

9.30am 7/9/18

Person Contacted:

Gary

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6049K - CS / III 0022808 / R7.1
	DoA: 3/11/2010
10/9/18	Email preli revised to FCI

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 6049K Yr Regn: 10JL, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Optima C.C. 1685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 581070 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAH.A414ME5463900

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt orBrake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 5/9/8 D.O.I. 7/9/8Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fray

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/6/18 Chk up \$3200 / 3P2 (Red 4180.10, 5610) 45

RECEIVED 03 OCT 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 3/10 - typistReport Format: CWSLump Sum / I.B.I: (\$) 3200/2Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150
50
50
50
300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18016358/K1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Date : 07-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 0859P	Veh. Inspected	SHC 6049K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006614MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	07/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/09/2018	Inspection Date	07/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006614MFSH

Our ref: CS/FCI18016358/K1vd3

DATE: 10/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6049K


We thank you for your instruction on 7/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 7/9/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,995.90
Revised Estimate Amount	: S\$2,466.60
"Check" Items Amount	: S\$1,116.00
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
n/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kalvin Ang
Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

MOTOR SURVEY ASSIGNMENT

Date	05-09-2018	Our Ref No. D18006614MFSH
Accident Date	05-09-2018	Claim Type. Third Party
Insured Vehicle	SHA0859P	Third Party Vehicle. SHC6049K
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GARY SHI	
Contact No.	62148880/ 65446671	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE; WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 10 September 2018 11:06 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006614MFSH/1, SHC 6049K
Attachments: SHC 6049K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 6049K
Date of survey: 7/9/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 7 September 2018 9:20 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006614MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 7 September 2018 9:16 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006614MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	10 Jul 2014 / 09:15:42	Receipt No.:	AACCK001-AX239-140710-000017
Asset Type:	Vehicle	Transaction Amount:	\$65,919.00
Asset ID:	SHC6049K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140710091542338934		

Vehicle No.:	SHC6049K
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:	Air-Con (Taxi)
-----------------------	----------------

Vehicle Attachment 2:	-
-----------------------	---

Vehicle Attachment 3:	-
-----------------------	---

Vehicle Scheme:	Taxi (Company)
-----------------	----------------

First Registration Date:	10 Jul 2014
--------------------------	-------------

Original Registration Date:	10 Jul 2014
-----------------------------	-------------

Vehicle Make:	KIA
---------------	-----

Vehicle Model:	OPTIMA 1.7(A) DIESEL
----------------	----------------------

Chassis No.:	KNAGM414ME5463900
--------------	-------------------

Engine No.:	D4FDDH308354
-------------	--------------

Motor No.:	-
------------	---

Trailer Chassis No.:	-
----------------------	---

Propellant:	Diesel
-------------	--------

Passenger Capacity:	4
---------------------	---

Engine Capacity:	1685
------------------	------

Power Rating:	-
---------------	---

Unladen Weight:	1584
-----------------	------

Maximum Laden Weight:	2050
-----------------------	------

Primary Color:	Silver
----------------	--------

Secondary Color:	-
------------------	---

Manufacturing Year:	2013
---------------------	------

Open Market Value:	\$20,007.00
--------------------	-------------

Minimum PARF Benefit:	\$7,506.00
-----------------------	------------

PARF Eligibility:	Y
-------------------	---

No. of Transfer:	0
------------------	---

Effective Ownership Date/Time:	10 Jul 2014 09:15:42
--------------------------------	----------------------

COE No.:	2014071001001216E
----------	-------------------

COE Expiry Date:	09 Jul 2022
------------------	-------------

COE Bid Category:	-
-------------------	---

Actual QP/PQP Paid Amount:	\$53,269.00
----------------------------	-------------

Lifespan Expiry Date:	09 Jul 2022
-----------------------	-------------

Owner ID Type:	Company
----------------	---------

CASH SALE/WORK ORDER No:AK 0960



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717
TEL : 6743 1987 (3 LINES) FAX : 6743 0013
Reg No: 200415052W

寶號
Messrs: PREMIER TAXI Date, 5/9/2018
車號
Vehicle No: S14E6049K 車型
Model No: OPTIMA
由
From: MAGAZINE ROAD
到
To: OMEGA
其他
Remark: ENTERING
時間
Time:

0	8	00	08	30	09	10
---	---	----	----	----	----	----

ELP. 1.50 \$750
AMOUNT: \$

--

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

經手人
Authorised by: 3294 收貨人
Received by: 9

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6049 K

1 pc	n/s head lamp	X <i>see</i>	\$ 1,028.00
1 pc	Front bumper emblem	<i>see</i>	\$ 44.00
1 pc	Front bumper	<i>Reh</i>	\$ 531.00
1 pc	Front bumper tow hook cover	X <i>see</i>	\$ 14.00
2 pcs	Front bumper n/s & o/s side retainer @\$16.00	<i>Nb on o/s X see</i>	\$ 32.00
1 pc	Front bumper n/s protector	X <i>see</i>	\$ 51.00
1 pc	Front bumper n/s fog lamp cover	X <i>see</i>	\$ 66.00
1 pc	Front n/s fender	<i>Reh</i>	\$ 384.00
1 pc	Front n/s fender inner shield	<i>Eon</i>	\$ 120.00
1 pc	Front n/s lower arm	<i>Reh</i>	\$ 439.00
1 pc	Front n/s shock absorber	<i>Reh</i>	\$ 330.00
1 pc	Front n/s ball joint	X <i>see</i>	\$ 59.00
1 pc	Front n/s tie rod end	<i>Reh</i>	\$ 61.00
1 pc	Front n/s knuckle bearing	X <i>see</i>	\$ 157.00
1 pc	Front n/s stabilizer link	<i>Reh</i>	\$ 86.00
1 pc	Front n/s knuckle arm	X <i>see</i>	\$ 547.00
1 pc	Front n/s rim	X <i>see</i>	\$ 246.00
1 pc	Front n/s wheel cover	<i>Graded</i>	\$ 116.00
			\$ 4,311.00
Less 10%			\$ 431.10
			\$ 3,879.90

S/NETT

1 set	Front n/s fender inner shield clips	<i>see</i>	\$ 28.00
1 set	Front bumper clips	<i>see</i>	\$ 48.00
1 pc	Front n/s fender sticker	X <i>see</i>	\$ 30.00
1 pc	Tyre	X <i>see</i>	\$ 200.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6049 K

Towing Fee	\$ 50.00 ✓
Sundry <i>new</i>	\$ 50.00 20
To check wheel alignment	\$ 80.00 60
To dismantle and replace front n/s undercarriage	\$ 250.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>X 21</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$ 650.00 <i>400</i>
To putty and spray painting on front bumper, front n/s fender	\$ 400.00 <i>360</i>
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 20
	<u>\$ 5,995.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

1380.10

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Ka Lun Ukley

7/9/18 1005hrs

3 Days

45

Allen Ben photo

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be reviewed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Sep-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6049 K

1 pc	Cross member	✓	Bad	\$	789.00
1 pc	Insulator Assy- Strut	✓	Bad	\$	105.00
1 pc	Engine under cover - n/s	✓	Good	\$	144.00
				\$	1,038.00
				Less 10%	\$ 103.80
					<u>\$ 934.20</u>

To dismantle and replace the cross member, dismantle and
refit front n/s undercarriage to facilitate repairs

~~100~~
\$ 450.00
\$ 1,384.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18016358/K1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 859P	Veh. Inspected	SHC 6049K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006614MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	07/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5463900	Colour	SILVER	
Odometer	581070	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2018	Inspection Date	07/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6049K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S HEAD LAMP	SERVICEABLE	1,028.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	14.00	-
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	N/S CRACKED / O/S	32.00	16.00
1	FRONT BUMPER N/S PROTECTOR	SERVICEABLE	51.00	-
1	FRONT BUMPER N/S FOG LAMP COVER	SERVICEABLE	66.00	-
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	CRACKED	120.00	120.00
1	FRONT N/S LOWER ARM	BENT	439.00	439.00
1	FRONT N/S SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT N/S BALL JOINT	SERVICEABLE	59.00	-
1	FRONT N/S TIE ROD END	BENT	61.00	61.00
1	FRONT N/S KNUCKLE BEARING	SERVICEABLE	157.00	-
1	FRONT N/S STABILIZER LINK	BENT	86.00	86.00
1	FRONT N/S KNUCKLE ARM	SERVICEABLE	547.00	-
1	FRONT N/S RIM	SERVICEABLE	246.00	-
1	FRONT N/S WHEEL COVER	GRAZED	116.00	116.00
1	CROSS MEMBER (ADDITIONAL)	BENT	789.00	789.00
1	INSULATOR ASSY-STRUT (ADDITIONAL)	BENT	105.00	105.00
1	ENGINE UNDER COVER-N/S (ADDITIONAL)	CRACKED	144.00	144.00
	LESS 10% DISCOUNT		-534.90	-316.50
			4,814.10	2,848.50
SPECIAL NETT ITEMS				
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	TYRE (SN)	SERVICEABLE	200.00	-

Report Ref No. CS/FC118016358/K1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			356.00	96.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO CHECK WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE AND REPLACE FRONT N/S UNDERCARRIAGE.		250.00	100.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME. ETC.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	20.00
	TO DISMANTLE AND REPLACE THE CROSS MEMBER, DISMANTLE AND REFIT FRONT N/S UNDERCARRIAGE TO FACILITATE REPAIRS. (ADDITIONAL).		450.00	100.00
			2,210.00	1,090.00
	GRAND TOTAL		7,380.10	4,034.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/FCI18016358/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.