

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

5-Sep-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6049 K

1 pc	Cross member	/ Bent	\$	789.00
1 pc	Insulator Assy- Strut	/ Bent	\$	105.00
1 pc	Engine under cover - n/s	/ C/A	\$	144.00
			\$	1,038.00
		Less 10%	\$	103.80
			\$	934.20

To dismantle and replace the cross member, dismantle and
refit front n/s undercarriage to facilitate repairs

\$ ~~100~~
450.00

\$ 1,384.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

