

**CHUNNI MOTOR WORK PTE LTD**

*Survey by LKK*

LONPAC

**REPAIR ESTIMATE**

VEHICLE NO: SHC 1341Z

DATE : 6.09.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FENDER SUB-ASSY, FRONT LH <i>Dental</i>			\$ 945.30 ✓
FRONT FENDER SHIELD, LH <i>deformed</i>			\$ 196.60 ✓
FRONT FENDER SHIELD CLIP <i>Nec</i>			\$ 3.80 ✓
FRONT FENDER HYBRID EMBLEM, LH <i>Nec</i>			\$ 53.50 ✓
PANEL SUB-ASSY, FRONT DOOR, LH <i>Dental</i>			\$ 1,238.50 ✓
FRONT DOOR TRIMBOARD, LH <i>crack</i>			\$ 725.00 ✓
FRONT DOOR WHETHER STRIP, LH <i>Nec</i>			\$ 226.80 ✓
MOTOR ASSY, POWER WINDOW REGULATOR, FRT. LH <i>NH</i>			\$ 768.90 X
REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH <i>st</i>			\$ 228.40 ✓
MIRROR ASSY, OUTER REAR VIEW, LH <i>crack</i>			\$ 1,374.00 ✓
COVER, OUTER MIRROR, LH <i>new</i>			\$ 141.90 X
MIRROR OUTER, LH <i>new</i>			\$ 212.80 X
ROCKER PANEL OUTER, LH <i>cut</i>			\$ 559.20 ✓
FRONT PILLAR UPPER COVER, LH <i>NH</i>			\$ 96.00 X
FRONT WHEEL RIM (LH) <i>cut</i>			\$ 1,555.10 ✓
FRONT WHEEL HUB BEARING (LH) <i>Dem</i>			\$ 560.10 ✓
FRONT SHOCK ABSORBER (LH) <i>distorted</i>			\$ 401.80 ✓
FRONT SUSPENSION LOWER ARM (LH) <i>distorted</i>			\$ 637.50 ✓
FRONT DRIVE SHAFT (LH) <i>distorted</i>			\$ 1,186.20 X ✓
RACK & PINION ASSY <i>Dem</i>			\$ 1,621.30 X ✓
LINK ASSY, FRONT STABILIZER, LH <i>distorted</i>			\$ 199.00 ✓
KNUCKLE, STEERING, LH <i>distorted</i>			\$ 562.30 ✓
END SUB-ASSY, TIE ROD, LH <i>distorted</i>			\$ 158.10 ✓
<b>SUB TOTAL</b>			\$ 13,652.10
<b>LESS 20%</b>			\$ 2,730.42
<b>DISCOUNTED TOTAL</b>			\$ 10,921.68
<b>FRONT DOOR COMFORT LOGO <i>Nec</i></b>			\$ 75.00 NETT ✓
<b>FRONT TYRE (LH) <i>NH</i></b>			\$ 216.00 NETT X
<b>NETT TOTAL</b>			\$ 291.00

*@ nhub*

*@ 75*

SHC 1341Z

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR BUMPER <i>new</i>			\$ 458.60	X
REAR BUMPER CLIPS <i>new</i>			\$ 22.00	✓
REAR FENDER, LH <i>Distorted</i>			\$ 817.50	✓
REAR FENDER SHEILD (LH) <i>new</i>			\$ 134.20	X
PANEL SUB-ASSY, REAR DOOR, LH <i>Distorted</i>			\$ 1,227.00	✓
REAR DOOR RUBBER SEAL, LH <i>SVC</i>			\$ 257.90	X
REAR TYRE RIM, LH <i>Scheduled</i>			\$ 1,555.00	✓
REAR WHEEL BEARING ING & HUB, LH			\$ 560.10	✓
REAR CROSS MEMBER <i>2 distorted</i>			\$ 2,179.40	✓
REAR SHOCK ABSORBER, LH <i>2 distorted</i>			\$ 118.30	✓
REAR SHOCK ABSORBER MOUNTING, L <i>new</i>			\$ 125.30	✓
REAR LOWER ARM, LH <i>2 distorted</i>			\$ 345.70	✓
REAR UPPER ARM, LH <i>2 distorted</i>			\$ 348.80	✓
REAR KNUCKLE ARM, LH <i>2 distorted</i>			\$ 810.60	✓
REAR STABILIZER BAR <i>2 distorted</i>			\$ 311.50	✓
REAR STABILIZER LINK, LH <i>2 distorted</i>			\$ 151.60	✓
REAR TRAILING ARM, LH <i>2 distorted</i>			\$ 314.20	✓
REAR ASSIST ARM, LH <i>2 distorted</i>			\$ 342.20	✓
<b>SUB TOTAL</b>			\$ 10,079.90	
<b>LESS 20%</b>			\$ 2,015.98	
<b>DISCOUNTED TOTAL</b>			\$ 8,063.92	
REAR DOOR COMFORT & APPS STICKER <i>new</i>			\$ 80.00	NETT ✓
REAR TYRE, LH <i>new</i>			\$ 216.00	NETT X
			\$ 296.00	
<b>LABOUR CHARGE</b>				
Panel Beating			\$ 1,500.00	800/-
Spray Painting Charge <i>10/09/2018 @ 1300m</i>			\$ 4,700.00	1000/-
Wiring Charge <i>not Antenna</i>			\$ 50.00	new
Tuff Kote <i>L/Sant 12 days</i>			\$ 100.00	40/-
Towing Charge			\$ 50.00	new
Remove/Refix Cushion & Upholstery Rear <i>rya</i>			\$ 150.00	80/-
Remove/Refix Reverse Sensor			\$ 120.00	new
Remove/Refix Undercarriage (FRT) <i>LKK Auto</i>			\$ 200.00	150/-
Remove/Refix Undercarriage (RR)			\$ 200.00	150/-
Remove/Refix Fuel Tank			\$ 150.00	new
Transfer of Door			\$ 120.00	120/-
Four Wheel Alignment			\$ 120.00	60/-
<b>TOTAL LABOUR</b>			\$ 4,580.00	
<b>ESTIMATE TOTAL</b>			\$ 24,152.60	

LKK Auto Consultants  
 The Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

*10/09/2018 @ 1300m*  
*not Antenna*  
*L/Sant 12 days*  
*rya*  
*LKK Auto*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.