

22/03/2002

ASS. REC. BY:

REF: CS3/CTI18016374/Rld3/

Special Instruction:

Surveyor:

Merimen

ASSIGNMENT (Office)

From (Person): chong Boon Sen

of

CTI

Date/Time: 7/9/18 @ 1.52pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 1041U

Insured:

XD 1941Y

at Workshop m/s

Hsy Maintenance

Tel:

9451 6228

of

10 Admiralty St. Northlink Building # 01-78

Policy No:

DMCVSN1755321700

Claim No:

SNM18D03666C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/07/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

404pm @ 7/9/18

Person Contacted:

Mr. Lison

Vehicle IN/OUT

Date/Time	Action/Instruction (x) Estimate
	YP 1041U - X
	XD 1941Y - NA / AIC 08025670 / r
10/9/18 -	vehicle still not in (Mr. Lison)
19/9/18 -	vehicle still not in yet (Mr. Lison)
9/10/18 -	was yet in yet
	No GIA.

DOA: 18/9/2018

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP 10414at Workshop m/s HSY maintenanceof 7, Brown L66 ST #01-19Insured: CTI / PRS

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YP 10414 Yr Regn: Jan / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI FCB C.C. 2998Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 160786 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FCB 21 EA 10585Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Mil / S/Rim / STD A/Rim orTyre Size: F: 195/85 R15R: 1 -BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. _____ D.O.I. 24/10/18Survey held at HSY maintenanceDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Dismantle: 24/10/2018- Estimated repair range \$6,500 - \$8,00029/10/2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 7

1)

☐ : Final ReportResurvey No. of Trip: 1Survey Fee: 150

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

150

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format : PRS

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2018		07 Sep 2018 13:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S SRISHTI ENGINEERING PTE. LTD., Co. Reg. No.: 201304229M		
Main Claimant:	ZERO SPOT LAUNDRY SERVICE PTE LTD, Co. Reg. No.: 199707580W		
Vehicle Reg. No.:	YB1041U	Date of Loss:	24/07/2018 10:00 - :59
Claim Type:	TP / SNM18D03666C02	Policy/Cover Note No.:	DMCVSN1755321700 (Comprehensive)
Vehicle Reg. No. (Insured):	XD1941Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hsy Maintenance Workshop (HQ) 10 ADMIRALTY STREET NORTHLINK BUILDING, #01-78, 757695 Woodlands - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/09/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	YP1041U
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1 :	With Power Tailgate
Vehicle Scheme :	Normal
Vehicle Make :	MAZDA
Vehicle Model :	CANTER FEB21ER3SDEB
Chassis No. :	FEB21EA10585
Propellant :	Diesel
Engine No. :	4P10B88175
Engine Capacity :	2998 cc
Maximum Power Output :	-
Maximum Laden Weight :	5000 kg
Unladen Weight :	3620 kg
Year Of Manufacture :	2015
Original Registration Date :	27 Jan 2016
Lifespan Expiry Date :	26 Jan 2036
COE Category :	C - Goods Vehicle & Bus
PQP Paid :	\$20,867.00
COE Expiry Date :	26 Jan 2026
Road Tax Expiry Date :	26 Jan 2019
Inspection Due Date :	26 Jan 2019
Intended Transfer Date :	24 Oct 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7580W
Vehicle Details	
Vehicle No.:	YP1041U
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B88175
Chassis No.:	FEB21EA10585
Maximum Power Output:	-
Open Market Value:	\$30,061.00
Original Registration Date:	27 Jan 2016
First Registration Date:	27 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$1,504.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$20,867.00
COE Rebate Amount:	\$15,139.00
Total Rebate Amount:	\$15,139.00

The information contained herein is correct as at 24 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Sep 2018		07 Sep 2018 13:52 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S SRISHTI ENGINEERING PTE. LTD., Co. Reg. No.: 201304229M								
Main Claimant:	ZERO SPOT LAUNDRY SERVICE PTE LTD, Co. Reg. No.: 199707580W								
Vehicle Reg. No.:	YP1041U	Date of Loss:	24/07/2018 10:00 - :59 [29 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03666C02	Policy/Cover Note No.:	DMCVSN1755321700 (Comprehensive)						
Vehicle Reg. No. (Insured):	XD1941Y	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Hsy Maintenance Workshop (HQ) 10 ADMIRALTY STREET NORTHLINK BUILDING, #01-78, 757695 Woodlands - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/09/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YP1041U (SNM18D03666C02)
[XD1941Y]
TP
ZERO SPOT LAUNDRY SERVICE PTE LTD
Jul 24 2018 10:00AM
[M/S SRISHTI ENGINEERING PTE. LTD.]
Hsy Maintenance Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	25/07/18 15:19	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	25/07/18 15:17	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
2	25/07/18 15:17	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 15:17	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
4	25/07/18 15:17	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
5	25/07/18 15:17	CHASSIS NUMBER <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/10/18 12:56	General View		Load PDF	
2	27/10/18 12:59	Photographs of Damaged Parts		Load PDF	




Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	25/07/18 11:41	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF	
2	25/07/18 11:43	CERTIFICATE OF INSURANCE <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 11:43	DRIVER'S NRIC & DRIVING LICENCE <small>[Linked Accident Report Documents]</small>		Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	07/09/18 13:51	PRS		Load PDF	
2	07/09/18 13:52	OI GIA		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	25/07/18 15:19	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	25/07/18 15:17	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	25/07/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	25/07/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	25/07/18 15:17	CHASSIS NUMBER		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	25/07/18 11:41	Sketch Plan	 Load TIF	
2	25/07/18 11:43	CERTIFICATE OF INSURANCE	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/18 11:43	DRIVER'S NRIC & DRIVING LICENCE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18016374/R1CD3E2

Date: 02/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1755321700
Claimant Vehicle No :	YP1041U	Insured Vehicle No :	XD1941Y
Date of Loss:	24/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03666C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP1041U			
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)		Engine No:	4P10B88175
Reg. Date:	27/01/2016 (Man. Year: 2015)		Chassis No:	FEB21EA10585
Colour:	White		Odometer:	160786 km
Engine Capacity:	2998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/09/2018	
Date Inspected:	22/10/2018 Inspected At:	Hsy Maintenance Workshop (HQ) 10 ADMIRALTY STREET NORTHLINK BUILDING, #01-78 Singapore 757695
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,500.00 -\$8,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Nov 2018)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1041U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >