



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2018 OPEL GRANDLAND X 1.2A (SBY8030E)
Date of Loss	28 August 2018
Time of Loss	10.45
Loss Description	SBY8030E (INSD) > SGM7369P (TP) > SGC1035U
Comment	

Workshop Details

Total Rebate Amount	58471
Nett Loss Amount	\$76,529.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	146



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SBY8030E

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

02/04/2018



Mileage

9286

Age of Vehicle

0

Driver Details

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2018

2018

Make

OPEL

OPEL

Model

GRANDLAND X 1.2A

GRANDLAND X 1

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

NG SUET PENG

Date of Birth

20 November 1950

dd/mm/yyyy



Age

68

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	W0VZRHNY0JS046076	W0VZRHNY0JS0
Engine No	10XTA40923936	10XTA40923936
Engine Capacity		1199
Sum Insured	0	0
Market Value	0	135000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	34 JALAN LEBAT DAUN, 808805, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	
Marital status	Unknown	
Identification #	S0890673D	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

07/09/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1200

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

235/50R19

Rear Tyre Size

235/50R19

Front left side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT BONNET			Damaged	2358		10		2122.2	Reviewing	
		2	1			FRT BONNET RUBBER SEAL RH			Necessary	168		10		151.2	Reviewing	
		3	1			FRT BONNET RUBBER SEAL LH			Necessary	168		10		151.2	Reviewing	
		4	1			FRT BONNET INSULATOR			Damaged	873		10		785.7	Reviewing	
		5	10			FRT BONNET INSULATOR CLIP			Necessary	6.5		10		58.5	Reviewing	
		6	1			FRT BONNET LOCK LEVER - SECONDARY			Damaged	108		10		97.2	Reviewing	
		7	1			FRT BONNET LOCK - PRIMARY			Serviceable	0	0	0	0	0	Deny	
		8	1			FRT BONNET LOCK CABLE			Serviceable	0	0	0	0	0	Deny	
		9	1			FRT BONNET HINGE LH			Serviceable	0	0	0	0	0	Deny	
		10	1			FRT BONNET HINGE RH			Serviceable	0	0	0	0	0	Deny	
		11	1			FRT FENDER RH			Buckled	768		10		691.2	Reviewing	
		12	1			FRT FENDER SIGNAL LAMP RH			Serviceable	0	0	0	0	0	Deny	
		13	1			FRT FENDER BRACKET RH			Serviceable	0	0	0	0	0	Deny	
		14	1			FRT FENDER INNERSHIELD RH			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		15	1			FRT FENDER WHEELARCH GARNISH RH			Serviceable	0	0	0	0	0	Deny	
		16	10			FRT FENDER WHEELARCH CLIP			Serviceable	0	0	0	0	0	Deny	
		17	10			FRT FENDER INNERSHIELD CLIP			Serviceable	0	0	0	0	0	Deny	
		18	1			FRT BUMPER			Damaged	1588		10		1429.2	Reviewing	
		19	1			FRT BUMPER LOW GARNISH (SILVER)			Serviceable	0	0	0	0	0	Deny	
		20	1			FRT BUMPER WHEELARCH GARNISH RH			Deformed	158		10		142.2	Reviewing	
		21	1			FRT BUMPER GRILLE RH			Deformed	222		10		199.8	Reviewing	
		22	1			FRT BUMPER GRILLE CHROME MLDG RH			Missing	303		10		272.7	Reviewing	
		23	1			FRT BUMPER GRILLE EXTENSION MLDG RH			Deformed	212		10		190.8	Reviewing	
		24	1			FRT BUMPER TOW COVER			Missing	90		10		81	Reviewing	
		25	1			FRT BUMPER LOWER CENTRE GRILLE			Cracked	478		10		430.2	Reviewing	
		26	1			FRT BUMPER LOWER CENTRE GRILLE CENTRE COVER			Cracked	126		10		113.4	Reviewing	
		27	10			FRT BUMPER CLIP			Necessary	3		10		27	Reviewing	
		28	1			FRT BUMPER SIDE RETAINER LH - GUIDE			Damaged	190		10		171	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		29	1			FRT BUMPER SIDE RETAINER RH - GUIDE			Damaged	190		10		171	Reviewing	
		30	1			FRT BUMPER SPONGE UPP			Damaged	358		10		322.2	Reviewing	
		31	1			FRT BUMPER REINFORCEMENT UPP - CRASH LIMITER			Bent	864		10		777.6	Reviewing	
		32	1			FRT BUMPER REINFORCEMENT LOW - FRT END			Serviceable	0	0	0	0	0	Deny	
		33	1			FRT BUMPER REINFORCEMENT LOW STAY			Serviceable	0	0	0	0	0	Deny	
		34	1			FRT BUMPER REINFORCEMENT LOW STAY			Serviceable	0	0	0	0	0	Deny	
		35	1			FRT BUMPER UNDER DUST COVER			Serviceable	0	0	0	0	0	Deny	
		36	1			FRT BUMPER FOG LAMP COVER RH			Deformed	168		10		151.2	Reviewing	
		37	1			FRT BUMPER FOG LAMP RH			Serviceable	0	0	0	0	0	Deny	
		38	2			FRT BUMPER PARKING SENSOR - INNER			Damaged	284		10		511.2	Reviewing	
		39	2			FRT BUMPER PARKING SENSOR - OUTER			Serviceable	0	0	0	0	0	Deny	
		40	1			FRT BUMPER PARKING SENSOR WIRE HARNESS			Damaged	308		10		277.2	Reviewing	
		41	1			FRT RADIATOR GRILLE BASE			Cracked	460		10		414	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		42	1			FRT RADIATOR GRILLE CHROME MLDG RH			Cut	270		10		243	Reviewing	
		43	1			FRT RADIATOR GRILLE CHROME MLDG LH			Cut	270		10		243	Reviewing	
		44	1			FRT RADIATOR GRILLE LOGO			Necessary	264		10		237.6	Reviewing	
		45	1			FRT RADIATOR GRILLE LOGO BASE - ADAPTOR			Cracked	200		10		180	Reviewing	
		46	1			FRT FORWARD CAMERA			Damaged	671		10		603.9	Reviewing	
		47	1			FRT RADAR MODULE			Serviceable	0	0	0	0	0	Deny	
		48	1			FRT RADAR MODULE BRACKET			Bent	116		10		104.4	Reviewing	
		49	1			RH HEADLAMP			Cracked	4312		10		3880.8	Reviewing	
		50	1			RH HEADLAMP HID CONTROL UNIT			Serviceable	0	0	0	0	0	Deny	
		51	1			LH HEADLAMP			Cracked	4312		10		3880.8	Reviewing	
		52	1			LH HEADLAMP HID CONTROL UNIT			Serviceable	0	0	0	0	0	Deny	
		53	1			A/C LABEL			Necessary	22		10		19.8	Reviewing	
		54	1			START / STOP LABEL			Necessary	28		10		25.2	Reviewing	
		55	1			FRT RADIATOR SUPORT PANEL TOP GARNISH			Cracked	346		10		311.4	Reviewing	
		56	1			FRT RADIATOR SUPORT PANEL TOP CENTRE - XMEMBER			Cracked	366		10		329.4	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		57	1			FRT RADIATOR SUPORT PANEL LOW CENTRE			Serviceable	0	0	0	0	0	Deny	
		58	1			FRT RADIATOR SUPORT PANEL RH			Serviceable	0	0	0	0	0	Deny	
		59	1			FRT RADIATOR SUPORT PANEL LH			Serviceable	0	0	0	0	0	Deny	
		60	1			A/C CONDENSER			Dented	1257		10		1131.3	Reviewing	
		61	1			A/C CONDENSER SUPORT BRACKET			Damaged	263		10		236.7	Reviewing	
		62	1			A/C CONDENSER AIRGUIDE RH			Deformed	68		10		61.2	Reviewing	
		63	1			A/C CONDENSER AIRGUIDELH			Deformed	68		10		61.2	Reviewing	
		64	1			A/C PIPE (CONDENSER TO COMPRESSOR)			Serviceable	0	0	0	0	0	Deny	
		65	1			A/C PIPE (COMPRESSOR TO COOLING COIL)			Bent	372		10		334.8	Reviewing	
		66	1			ALTERNATOR 120AMP			Serviceable	0	0	0	0	0	Deny	
		67	1			ALTERNATOR BELT			Serviceable	0	0	0	0	0	Deny	
		68	1			TURBO INTAKECOOLER			Damaged	1213		10		1091.7	Reviewing	
		69	1			TUBO INTAKECOOLER AIR DUCT			Cracked	284		10		255.6	Reviewing	
		70	1			TUBO INTAKECOOLER COVER			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		71	1			TURBO INTAKECOOLER TOP BRACKET			Serviceable	0	0	0	0	0	Deny	
		72	1			TURBO INTAKECOOLER CENTRE BRACKET			Serviceable	0	0	0	0	0	Deny	
		73	1			TURBO INTAKECOOLER LOW BRACKET			Serviceable	0	0	0	0	0	Deny	
		74	1			AIR HOSE (INTAKECOOLER TO THROTTLE BODY) - OUTLET			Cut	276		10		248.4	Reviewing	
		75	1			AIR HOSE (INTAKECOOLER TO THROTTLE BODY) - OUTLET			Serviceable	0	0	0	0	0	Deny	
		76	1			AIR HOSE (TURBO TO INTAKECOOLER) - INLET			Cut	410		10		369	Reviewing	
		77	1			AIR HOSE (TURBO TO INTAKECOOLER) - INLET			Serviceable	0	0	0	0	0	Deny	
		78	1			TURBO HEATSHIELD - LH			Serviceable	0	0	0	0	0	Deny	
		79	1			TURBO HEATSHIELD - RH			Dented	104		10		93.6	Reviewing	
		80	1			FRT INTAKE RESONATOR BOX			Serviceable	0	0	0	0	0	Deny	
		81	1			RADIATOR			Dented	1346		10		1211.4	Reviewing	
		82	1			RADIATOR TOP BRACKET			Cracked	36		10		32.4	Reviewing	
		83	1			RADIATOR LOW BRACKET			Serviceable	0	0	0	0	0	Deny	
		84	1			RADIATOR TOP HOSE, INLET			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		85	1			RADIATOR LOW HOSE, OUTLET			Serviceable	0	0	0	0	0	Deny	
		86	1			RADIATOR FAN ASSY, MOTOR, BLADE, COWLING			Cracked	764		10		687.6	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	2600	0	0	Reviewing		
		2		CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER LH, FRT FENDER RH, FRT DOOR RH	2200	0	0	Reviewing		
		3		TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	120	0	0	Reviewing		
		4		TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	600	0	0	Reviewing		
		5		TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	80	0	0	Reviewing		
		6		TO CONDUCT RESET OF ENGINE LIGHT ON	350	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 8 DAYS	Reviewing			
☐		2	RADIATOR SPARE TANK PIPE (DISC 10%)	Reviewing	191.7	DAMAGED (SUPPLEMENTARY)	
☐		3	FRT NUMBER PLATE	Reviewing	65	BENT	
☐		4	RADIATOR COOLANT	Reviewing	80	NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$30,699.80			Claim Amount	\$30,699.80			

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$25,613.10	\$25,613.10
Labour	\$5,950.00	\$5,950.00
Miscellaneous	\$336.70	\$336.70
Excess	-\$1,200.00	-\$1,200.00

Submit for Review