

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MS16 / CC3 / MSC / 15016419 / Urbanc

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 960 42at Workshop m/s PL

of \_\_\_\_\_


Insured: SLK B 6121 DPolicy No. 29094830 ADVClaims No. 569891

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 781

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLK 960 42 Regn: 2, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota corolla A/H 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 60886 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REH104563064

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/9/18 D.O.I. 10/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S PL, RPLS.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11A 57796 have had28/9/18 1/5 9200 confirmed with AM.\$23971.05, 73%.

RECEIVED 08 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) S + RS, SI☐ : Interview (\$ \_\_\_\_\_) Photos☐ : Tech. Invs (\$ \_\_\_\_\_) Others☐ : Weekend (\$ \_\_\_\_\_) TOTALReport Format: TPLump Sum / I.B.I. (\$ 9200.00 )

Survey Fee:

Transportation:

25010260

**Janice Lee (LKKAUTO)**

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Tuesday, September 11, 2018 3:54 PM  
**To:** 'Jasmine Lok Kheng Kwei'; Iryani Amin  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 08/09/2018, SLK 9604Z (TP VEHICLE), SKB 6121D (OI VEHICLE)  
**Attachments:** SLK 9604Z GIA.pdf

Dear Jasmine/ Iryani,

Please be informed that we had inspected the vehicle **SLK 9604Z** at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 41788.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/09/2018 15:38
Date Of Accident	08/09/2018 11:35
Exact Location Of Accident	GHIM MOH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK9604Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIANG YUSHENG
NRIC No	S7461391H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91869258
Alternative Phone No	OTHERS-91869258

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097282431 CLASSIC
Cover Note Number	

### Driver

Name of Driver	LIANG YUSHENG
NRIC No	S7461391H
Date Of Birth	07/07/1974
Occupation	OUTDOOR
Date Of Driving Pass	04/10/2002
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91869258
Fax Number	
Contact Number	OTHERS-91869258
Email Address	NOEMAIL

Address	BLK 360 #04-103 YUNG AN ROAD
Postcode	610360
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB6121D
Vehicle Make/Model/Colour	VOLKSWAGEN GOLF 1.4 TSI AT 5G13HZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 8 SEP 2018



Driver's Signature

(If driver is not the policyholder)

Date & Time:

**IDAC KAKI BUKIT (VAC)**

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305


Email: [yackb@singnet.com.sg](mailto:yackb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 8/9/18 at 11.35am, I was driving my vehicle along Gohim Moh Road. Suddenly vehicle B driving out from BIKRI carpark and hit on my LH side portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: - 8 SEP 2018

GUARMC SketchPlanForm\_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

EDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 1391H

**Vehicle Details**

Vehicle No.: SLK9604Z

Vehicle to be Exported: No

Intended Deregistration Date: 10 Sep 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 CVT

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: 1ZRY348588

Chassis No.: MR053REH104563064

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$19,995.00

Original Registration Date: 08 Feb 2017

First Registration Date: 08 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$19,995.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Feb 2027

PARF Rebate Amount: \$14,996.00

**Intended COE Rebate Details**

COE Expiry Date: 07 Feb 2027

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,889.00

COE Rebate Amount: \$42,800.00

**Total Rebate Amount: \$57,796.00**

The information contained herein is correct as at 10 Sep 2018

OK



riverbed

Start monitoring your applications in 15 minutes

Try SteelCentral Applinternals for free

FREE TRIAL

Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Mercedes S-Class S350L Moonroof.

Excellent Condition, Perfect  
Body, Loved & Maintained,  
Serviced, Paint Restored.  
Direct Owner StarAd**PRIME MOTOR & LEASING**

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles  
to choose from, ranging from  
all European to Japanese Makes.

Browse by Category

« Back ( 1 2 ) Next »







Sort by Date Posted

20 results/page

32 vehicles

Toyota Corolla

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Toyota Corolla		Any	Any	2017	Any	Any	Any	Available
	Toyota Corolla	Axio Hybrid 1.5A G	\$78,800	\$8,280 /yr	27-Nov-2017	1,496 cc	-	Sedan	Available
<b>Fuel Type:</b> Petrol-Electric Elegant Black, One Owner Only, Low Fuel Consumption With Hybrid, With Warranty, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Availa...									
Prime Motor & Leasing Posted: 10-Sep-2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota									
	Toyota Corolla	Altis 1.6A Elegance	\$79,800	\$8,290 /yr	09-Feb-2017	1,598 cc	35,000 km	Sedan	Available
10-15% Down Payment Only! Sporty Black, 1 Owner, Low Mileage Done, 5 Years Borneo Warranty, Serviced By Borneo Motor, Accident Free, Original Paintwork, Like New Condition! View To Believe. In House F...									
Horizon Motoring Posted: 10-Sep-2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota									
	Toyota Corolla	Axio 1.5A X	\$68,800	\$7,760 /yr	23-Mar-2017	1,496 cc	23,000 km	Sedan	Available
Guaranty 100% Loan Approval. Posted: 09-Sep-2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota									
	Toyota Corolla	Axio 1.5A G	\$77,800	\$8,560 /yr	25-Apr-2017	1,496 cc	12,204 km	Sedan	Available
Still Under Warranty, Accident Free, Original Paintwork, Sports Rims, DVD Player With Reverse Camera, Bluetooth, Leather Seats. Reliable And Economic, Low Fuel Consumption, Auto Aircon, Keyless Entry/... Posted: 08-Sep-2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota									
Car Buying Car Selling Car Ownership Car Aftermarket On The Move Lifestyle									
	Toyota Corolla	Altis 1.6A Elegance (OPC)	\$67,777	\$6,860 /yr	09-Feb-2017	1,598 cc	19,930 km	Sedan	Available
(High Specification Elegance Model!) 1st Owner Car. Low Mileage Unit. Vehicle Fully Maintain By Agent (Borneo Motors) With Full Servicing History Since Day One. Agent Warranty Till 08 Feb 2020. Normal... Sincere Motoring Pte Ltd Posted: 08-Sep-2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota									
	Toyota Corolla	Altis 1.6A Elegance	\$84,800	\$8,950 /yr	19-Jan-2017	1,598 cc	40,000 km	Sedan	Available
Nissan Certified Pre-Owned Unit. 10owner, Borneo 5 Years Warranty, Elegance Unit Push Start, Electric Seat, HID Lamp With LED, Original 17" Sport Rims Etc. 100% Finance Scheme With Affordable Installment... Hua Yang Credit Pte Ltd Posted: 08-Sep-2018 Tags: 2017 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota									

 Buy Tyres Online!  
 Latest Special Offers from Tyrespac!

PREMIUM AD

Compare



# COMPUTERISED 4 WHEEL ALIGNMENT

## HUNTER DSP700

Company: FASTECH AUTO PTE LTD  
 VIN: SLK 9604 Z  
 Date: 10.9.18 14:20



SLK 9604 Z

TOYOTA ALTIS 2014-

### Front : Left

Actual	Before	Specified Range
-1°31'	-1°31'	-0°59' 0°31'
2°31'	2°31'	5°08' 6°38'
0°17'	0°17'	0°00' 0°11'
14°30'	14°30'	
12°59'	12°59'	

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

### Front : Right

Actual	Before	Specified Range
-0°39'	-0°39'	-0°59' 0°31'
2°29'	2°29'	5°08' 6°38'
0°13'	0°13'	0°00' 0°11'
11°25'	11°24'	
10°45'	10°45'	

### Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
-0°52'	-0°52'	-0°45' 0°45'
0°02'	0°02'	-0°45' 0°45'
3°05'	3°06'	
0°30'	0°31'	0°00' 0°22'

### Rear : Left

Actual	Before	Specified Range
-1°46'	-1°46'	-1°58' -0°58'
0°05'	0°05'	-0°01' 0°16'

Camber  
 Toe

### Rear : Right

Actual	Before	Specified Range
-1°40'	-1°40'	-1°58' -0°58'
0°05'	0°04'	-0°01' 0°16'

### Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
-0°06'	-0°06'	-0°30' 0°30'
0°09'	0°09'	-0°01' 0°31'
0°00'	0°00'	

FASTECH AUTO PTE LTD

1 Kakit Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

not added  
nbc  
L/S \$9200  
10/9/18  
6 day.

VEHICLE NO: SLK 9604Z

QTY	PARTICULAR		
1 PCS	FRONT BUMPER	511.22	705 \$781.10
2 PCS	FRONT BUMPER SIDE HOLDERS	\$89.95	321 \$179.90
1 SET	FRONT BUMPER CLIPS		222 \$50.00
1 PCS	FRONT BUMPER FOG LAMP COVER N/S	58.11	321 \$126.50
1 PCS	FRONT BUMPER FOG LAMP N/S		222 \$361.50
1 PCS	FRONT FENDER N/S	858.05	705/321 \$981.10
1 PCS	FRONT FENDER INNER SHIELD N/S	141.50	201 \$266.50
2 PCS	FRONT FENDER 'VTI' EMBLEMS	@\$58.50 45.17x2=90.34	222 \$117.00
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S		222 \$50.00
1 PCS	FRONT FENDER INNER PANEL N/S		222 \$611.20
1 PCS	HEADLAMP ASSY N/S	2750.10	222 \$2,800.10
1 PCS	HEADLAMP PANEL N/S		321 \$241.10
1 PCS	BONNET	1140.40	705/321 \$1,426.95
2 PCS	BONNET HINGES	@\$115.00 76.60x2=153.20	321 \$230.00
1 PCS	BONNET RUBBER BEADING		222 \$46.60
1 PCS	BONNET INSULATOR		222 \$291.10
1 SET	BONNET INSULATOR CLIPS		222 \$50.00
1 PCS	FRONT DOOR N/S	1221.70	705/321 \$1,866.10
1 PCS	FRONT DOOR INNER LOCK N/S		222 \$425.10
1 PCS	FRONT DOOR INNER TRIM BOARD N/S		222/321 \$899.10
1 PCS	FRONT DOOR GLASS REGULATOR N/S		222 \$366.50
1 PCS	FRONT DOOR GLASS REGULATOR MOTOR N/S		222 \$480.10
1 PCS	FRONT DOOR 'A' PILLAR OUTER		222 \$899.10
1 PCS	ROCKER PANEL N/S		222 \$695.50
1 PCS	FRONT BUMPER SPONGE	102.38	705 \$148.10
1 PCS	FRONT BUMPER REINFORCEMENT	386.60	222 \$561.60
1 PCS	FRONT BUMPER CENTER LOWER GRILLE	105.30	222 \$201.10
1 PCS	FRONT GRILLE	264	222 \$499.50
1 PCS	AIR RESONATOR BOX		222 \$280.50
1 PCS	FRONT SUPPORT PANEL		222 \$1,160.90
1 PCS	FRONT LOWER ARM N/S	455.10	321 \$688.10
1 PCS	FRONT SHOCK ABSORBER N/S	316.97	321 \$495.50
1 PCS	FRONT KNUCKLE ARM N/S	521.20	321 \$692.30
1 PCS	FRONT KNUCKLE ARM BEARING N/S	165.50	222 \$350.00
1 PCS	FRONT DRIVESHAFT N/S		222 \$1,688.10
1 PCS	FRONT STEERING ASSY		222 \$2,880.10
1 PCS	FRONT CROSS MEMBER		222 \$1,695.30

257

1 PCS	FRONT WHEEL HOUSING PANEL N/S		25%	1	\$1,015.30	X
1 PCS	HEADLAMP LOWER BRACKET N/S	45.50		one	\$122.50	✓
					\$26,721.05	
	S.NETT					
1 SET	FRONT DOOR VISOR			me	\$120.00	50
1 PCS	FRONT TYRE N/S			sun	\$200.00	X
1 PCS	FRONT SPORT RIM N/S '17 INCH'			10/3rd	\$1,000.00	400
	LABOUR CHARGES:					
	TOWING CHARGE				\$150.00	50
	TO CHECK WIRING				\$100.00	30
	TO TRANSFER FRONT DOOR MECHANISM				\$100.00	60
	TO REFILL AIR CON GAS			11	\$150.00	X
	TO MOUNT VEHICLE ON CAR O-LINER			11	\$380.00	X
	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE				\$380.00	120
	TO CONDUCT WHEEL ALIGNMENT				\$150.00	60
	TO SPRAY RUSF PROOFING				\$120.00	80
	LABOUR FOR PANEL BEATING & REPLACING PART				\$1,800.00	800
	TO PUTTY & SPRAY PAINTING				\$1,800.00	1200
	TOTAL				\$33,171.05	
						2850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11631.37  
4723.57

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18016419/URBN2

Date: 09/10/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29094830AVW
Claimant Vehicle No :	SLK9604Z	Insured Vehicle No :	SKB6121D
Date of Loss:	08/09/2018	Nature of Claim:	TP
		Claim No:	569891

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLK9604Z	Engine No:	1ZRY348588
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104563064
Reg. Date:	08/02/2017 (Man. Year: 2016)	Odometer:	60886 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,041.05	9,173.57	18,867.48	67.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	2,400.00	2,730.00	53.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,171.05	11,573.57	21,597.48	65.11
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	33,171.05	9,200.00	23,971.05	72.26
+ GST 7.00/7.00% (S\$)	2,321.97	644.00	1,677.97	72.26
Nett Amount (S\$)	35,493.02	9,844.00	25,649.02	72.26

## INSPECTION

Date of Assignment:	12/09/2018	
Date Inspected:	10/09/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2018)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK9604Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	781.10 F	*511.22 FL
2	2	*FRONT BUMPER SIDE HOLDERS	Bent	179.90 F	*179.90 FL
3	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1	*FRONT BUMPER FOG LAMP COVER N/S	Grazed	126.50 F	*58.17 FL
5	1	*FRONT BUMPER FOG LAMP N/S	Cracked	361.50 F	*361.50 FL
6	1	*FRONT FENDER N/S	Dented/Bent	981.10 F	*858.05 FL
7	1	*FRONT FENDER INNER SHIELD N/S	Torn	266.50 F	*141.50 FL
8	2	*FRONT FENDER VVTI EMBLEMS	Necessary	117.00 F	*90.34 FL
9	1	*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
10	1	*FRONT FENDER INNER PANEL N/S	Repair	611.20 F	*- FL
11	1	*HEADLAMP ASSY N/S	Cracked	2,800.10 F	*2,750.10 FL
12	1	*HEADLAMP PANEL N/S	Buckled	241.10 F	*241.10 FL
13	1	*BONNET	Dented/Bent	1,426.95 F	*1,140.40 FL
14	2	*BONNET HINGES	Bent	230.00 F	*153.20 FL
15	1	*BONNET RUBBER BEADING	Necessary	46.60 F	*46.60 FL
16	1	*BONNET INSULATOR	Not Necessary	291.10 F	*- FL
17	1	*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
18	1	*FRONT DOOR N/S	Dented/Bent	1,866.10 F	*1,221.70 FL
19	1	*FRONT DOOR INNER LOCK N/S	Not Necessary	425.10 F	*- FL
20	1	*FRONT DOOR INNER TRIM BOARD N/S	Deformed/Torn	899.10 F	*899.10 FL
21	1	*FRONT DOOR GLASS REGULATOR N/S	Not Necessary	366.50 F	*- FL
22	1	*FRONT DOOR GLASS REGULATOR MOTOR N/S	Not Necessary	480.10 F	*- FL
23	1	*FRONT DOOR A PILLAR OUTER	Repair	899.10 F	*- FL
24	1	*ROCKER PANEL N/S	Repair	695.50 F	*- FL
25	1	*FRONT BUMPER SPONGE	Torn	148.10 F	*102.38 FL
26	1	*FRONT BUMPER REINFORCEMENT	Dented	561.60 F	*386.60 FL
27	1	*FRONT BUMPER CENTER LOWER GRILLE	Twisted	201.10 F	*105.30 FL
28	1	*FRONT GRILLE	Cracked	499.50 F	*499.50 FL
29	1	*AIR RESONATOR BOX	Cracked	280.50 F	*280.50 FL
30	1	*FRONT SUPPORT PANEL	Repair	1,160.90 F	*- FL
31	1	*FRONT LOWER ARM N/S	Bent	688.10 F	*455.10 FL
32	1	*FRONT SHOCK ABSORBER N/S	Bent	495.50 F	*316.97 FL
33	1	*FRONT KNUCKLE ARM N/S	Bent	692.30 F	*521.20 FL
34	1	*FRONT KNUCKLE ARM BEARING N/S	Necessary	350.00 F	*165.50 FL
35	1	*FRONT DRIVESHAFT N/S	Not Necessary	1,688.10 F	*- FL
36	1	*FRONT STEERING ASSY	Not Necessary	2,880.10 F	*- FL
37	1	*FRONT CROSS MEMBER	Not Necessary	1,695.30 F	*- FL
38	1	*FRONT WHEEL HOUSING PANEL N/S	Repair	1,015.30 F	*- FL
39	1	*HEADLAMP LOWER BRACKET N/S	Cracked	122.50 F	*45.50 FL
40	1	*SET FRONT DOOR VISOR	Necessary	120.00 FS	*50.00 FS
41	1	*FRONT TYRE N/S	Serviceable	200.00 FS	*- FS
42	1	*FRONT SPORT RIM N/S 17 INCH	Dented/Bent	1,000.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 28,041.05 12,081.43

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	2,907.86
Total Parts (S\$)					28,041.05	9,173.57

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING CHARGE	New	150.00	50.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO TRANSFER FRONT DOOR MECHANISM	New	100.00	60.00
4	TO REFILL AIR CON GAS	New	150.00	-
5	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	-
6	TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE	New	380.00	120.00
7	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
8	TO SPRAY RUSF PROOFING	New	120.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACING PART	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			5,130.00	2,400.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;