

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 761K**AAD1809-037**

Not Authorized
Resurvey By paint *8640h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 761K

VF1ABL15AUC283336

RENAULT

LATITUDE

5.9.2018

AIG**PART****LIST**

1	FENDER PANEL REAR RH	\$	<i>11</i> 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	<i>12</i> 671.45
1	WHEELARCH REAR RH	\$	<i>12</i> 543.47
1	ROCKER PANEL INNER GARNISH RH	\$	<i>12</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>11</i> 1,024.79
1	ROCKER PANEL CENTER RH	\$	<i>11</i> 990.25
1	BUMPER COVER REAR	\$	<i>11</i> 1,108.46
1	BUMPER LOWER REAR	\$	<i>12</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>12</i> 113.47
1	BUMEP R BRACKET SIDE RH REAR	\$	<i>12</i> 135.97
1	BUMEP R RETAINER RH REAR	\$	<i>12</i> 44.99
1	BUMPER REFLECTOR RH	\$	<i>12</i> 43.61
1	BUMEP R BRACKET SIDE LH REAR	\$	<i>11</i> 135.97
1	BUMPER RETAINER LH REAR	\$	<i>12</i> 44.99
1	BUMPER REFLECTOR RH	\$	<i>12</i> 43.61
1	BUMPER BEAM REAR	\$	<i>11</i> 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	<i>11</i> 225.95
1	BUMPER BEAM BRACKET RH REAR	\$	<i>11</i> 225.95

\$ 10,664.94

10% **\$ 1,066.49**

\$ 9,598.45

Special Nett

1	REAR DOOR STICKER '6555 3333'	\$	<i>11</i> 80.00 <i>X</i>
1	DOOR CHECK BOLT	\$	<i>12</i> 22.69 <i>X</i>
1	DOOR GUIDE SCREW	\$	<i>12</i> 10.85 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1809-037**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 761K

1	DOOR HINGE BOLT	\$	<i>SL</i> 10.85	}	<i>X</i>
1	DOOR HINGE NUT RH	\$	<i>SL</i> 14.60		
1	DOOR CHECK BOLT	\$	<i>SL</i> 22.69		
1	DOOR CHECK NUT	\$	<i>SL</i> 3.75		
1	DOOR LOCK SCREW L70Y	\$	<i>SL</i> 6.12		
1	DOOR CATCH SCREW L70Y	\$	<i>SL</i> 10.06		
1SET	PARKING AID	\$	<i>SL</i> 700.00		
1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00		
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00		
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00		
1SET	BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00		
1SET	BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00		
1SET	BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00		
1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00		
1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00		

TOTAL	\$	1,128.63
--------------	-----------	-----------------

TOTAL PARTS	\$	10,727.08
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>2001</i> 3,000.00	
Putty and spray painting of the affected portion.	\$	3,000.00	<i>4401</i>
To rust-proofing of the affected areas.	\$	<i>na</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>7</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1809-037**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 761K

To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Towing Fees.	\$	nn 120.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X

TOTAL \$ 9,130.00**Over All Total \$ 19,857.08****LUMP SUM (REPAIR DAY)****10 DAYS**
2 days**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: