

ASS. REC. BY:

REF:

CS/FCI18016424/KlvD3

n2

Special Instruction:

Surveyor
CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time: 7/11/18 @ 7:09pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6869K

Insured:

SHC 0955J

at Workshop m/s

Premier Automotive

Tel:

6544 6682

of

23 Changi South Ave 2 #03-02

Policy No:

Claim No:

D18006662MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/09/2018

CA / REV / REP. / REV 24 HRS

CDS

11/09/2018

H.O.D. Endorsement:

Date/Time

9:57am @ 10/11/18

Person Contacted:

Goh wee dek

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6869K - CC4 / II 16000103 / fwb3q2 DOA: 04/01/16
	SFK 955J - CS / FCI 14064628 / M1tbu2 DOA: 7/13/14
12/9/18	Email preli. revised to FCI

Signature

Kaluh

REF: FCI

ASSIGNMENT

From: Date: 11/09/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 6869K
at Workshop n/s Premier Automotive
of 23 Changi South Ave 2 # 03-02

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS (DS)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHC 6869K

Yr Regn:

2 Sep 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA optima

c.c 1685

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp Reading

3 41355

T/Radio: Insured / Std / NI / NA

Eng/No:

KNAHA44AF5621882

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

2

Rear

R/Bal.

mm

R/Bal.

2

mm

L/Bal.

mm

L/Bal.

2

mm

D.O.A.

6/9/18

D.O.I.

11/9/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/9/18	Subst 43 \$1250 / 2 hrs. (Red 3274-30, 7290 40)

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/8 - typist

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

CWS

Lump Sum / I.B.I. (\$

1250/2

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

135
50
50
24
259



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18016424/K1vd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 10-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 955J	Veh. Inspected	SHC 6869K
Policy No.		Coverage (\$)	0.00
Claim No.	D18006662MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	10/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/09/2018	Inspection Date	11/09/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	07-09-2018	Our Ref No. D18006662MFSH
Accident Date	06-09-2018	Claim Type. Third Party
Insured Vehicle	SHC0955J	Third Party Vehicle. SHC6869K
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 12 September 2018 11:51 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006662MFSH/1, SHC 6869K
Attachments: SHC 6869K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 6869K
Date of survey: 11/9/2018
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 10 September 2018 10:03 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006662MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 7 September 2018 7:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006662MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006662MFSH

Our ref: CS/FCI18016424/K1vd3

DATE: 12/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6869K


We thank you for your instruction on 7/9/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/9/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,524.30
Revised Estimate Amount	: S\$1,469.80
"Check" Items Amount	: S\$810.90
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kalvin Ang
Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	02 Sep 2015 / 08:03:54	Receipt No.:	AACCK001-AX239-150902-000020
Asset Type:	Vehicle	Transaction Amount:	\$69,132.00
Asset ID:	SHC6869K	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01:02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150902080354482162		

Vehicle No.:	SHC6869K
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	02 Sep 2015
Original Registration Date:	02 Sep 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5621882
Engine No.:	D4FDEH313430
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,156.00
Minimum PARF Benefit:	\$12,971.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	02 Sep 2015 08:03:54
COE No.:	2015090201003473D
COE Expiry Date:	01 Sep 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$47,373.00
Lifespan Expiry Date:	01 Sep 2023

Sketch Plan Pg. 4

 PREMIER TAXIS	HIRERY RELIEF / SUPER RELIEF
VEHICLE NO.	SHC 6869 P
CONTACT NO.	9172 7837.
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1045846C



Name
TAY SEOW TENG

鄭紹廷

Race
CHINESE

Date of birth
23-09-1944

Country of birth
SINGAPORE

Sex
M

S1045846C

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S1045846C**

Name
TAY SEOW TENG

Birth Date: **23 Sep 1944**

Issue Date: **29 Oct 2009**



NRIC No: **S1045846C**



Date of issue
26-10-2009

Address
**APT BLK 27 MARINE CRESCENT
#21-07
SINGAPORE 440027**

4467651

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 10 Feb 1965

NP 428A



Licence No: S1045846C

Land Transport Authority



VOCATIONAL LICENCE

Licence No: **S1045846C**

Name: **TAY SEOW TENG**

Issue Date: **4/4/2011**

Please visit www.lta.gov.sg to check the status of this vocational licence

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141517
CO. REG:200707743D GST REG:200707743D

7-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6869 K

1 pc	Bootlid emblem	X	\$	27.00
1 pc	Bootlid CRDi	X	\$	29.00
1 pc	Boot lid lower garnish	X	\$	290.00
1 pc	Rear bumper	Redundant	\$	696.00
1 pc	Rear bumper lower cover	cl	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X	\$	58.00
1 pc	Rear bumper inner sponge	✓	\$	114.00
1 pc	Rear bumper reinforcement	X	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	X	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X	\$	36.00

\$ 2,207.00

Less 10%

\$ 220.70

\$ 1,986.30

S/NETT

1 set	Rear bumper clips	X	\$	48.00
1 set	Bootlid lower garnish clips	X	\$	60.00
1 set	Bootlid stickers	X	\$	100.00
1 set	Reverse sensor	X	\$	280.00

Signature:

Date:

Sundry

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel

To apply rustproofing on the repaired and replaced panels.

\$ 50.00 X 1

\$ 120.00 30

\$ 180.00 X 1

\$ 750.00 200

\$ 800.00 150

\$ 150.00 X 1

\$ 4,524.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18016424/K1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-09-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 955J	Veh. Inspected	SHC 6869K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18006662MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	07/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5621882	Colour	SILVER	
Odometer	341355	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2018	Inspection Date	11/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6869K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID EMBLEM	NOT NECESSARY	27.00	-
1	BOOTLID CRDI	NOT NECESSARY	29.00	-
1	BOOT LID LOWER GARNISH	SERVICEABLE	290.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-220.70	-101.60
			1,986.30	914.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			538.00	248.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENTDAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL.		750.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON BOOTLID,BOOTLID LOWER GARNISH,REAR BUMPER,END PANEL.	NOT NECESSARY	800.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	-
			2,000.00	410.00
GRAND TOTAL			4,524.30	1,572.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/FCI18016424/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.