

Sumatra - 5/9

195/2010

INS. CASE OWNER: SAUHA

CC 3/AIG1801

6025, N/A 3/2

LKK:
IDAC:

Surveyor: NAZ

ASSIGNMENT
DOI: 3/1/18

Date / Time: 3/1/18

Registered in Merimen: 10/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLC b2bom.

Name of Insured:

MARY LINA BEAUTY A SUMINANT
SPECIALIST

Insured Tel No.:

HP:

D.O.A:

4/1/18 PIC

Claim No.:

254457568759

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II :SS

Is driver the owner? (YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

If NO, Driver Name / Age:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

Driver Tel No.:

400 6746



INSRS:
WSP:
Tel:
Liability:
RMKS:

SMKT



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
13/1/18	Non-Reporting ltr (1st):	13/08/18 / 05/09/2019
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	Email ☐ Call ☐
Repair Cost:	SS	11,396.19	9 days	Reduction:	50 %
FINAL SETTLEMENT		Date/Time:	Confirm with:	Confirm by:	Email ☐ Call ☐
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:			
Repair Cost:	SS	—			
Loss of Rental (LOR):	SS	—	(	x	days)
Loss of Use (LOU):	SS	—	(	x	days)
Loss of Income (LOI):	SS	—	(	x	days)
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LO ☐	[Tick only one]		
GIA/LTA Search	SS	—			
Medical:	SS	—			
Disbursement:	SS	(e.g. Tow/ Independent)			
Legal Cost	SS	—			
Total:	SS	Global Sum SS:		17/1/19	
FINAL PAYMENT		Date/Time:	Confirm with:	Confirm by:	Email ☐ Call ☐
Payee 1:	SS	Name 1:		—	
Payee 2: (Strike if N.A.)	SS	Name 2:		—	
Payee 3: (Strike if N.A.)	SS	Name 3:		—	

WP REPORT
REPUTATED
NO SETTLEMENT
OIO PAY DIRECTLY TO TP

1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP REPORT \$320.00
3) Survey fee:
4) AR fee → \$254

REF:

REF:

ALG

TAX/09/18/2018

Surveyor: ALG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 6219 G Yr Regn: 5 OCT 2015

Type M, Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIMO C.C. 1798

Colour: BEAN A/C: Insured / Std / NI / I

Sp. Reading BATT, FLAT T/Radio: Insured / Std / NI / I

Eng/No: _____

C/No: JTDKN36U305766085

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Op / Jammed / Leaked / Burnt or

Brake: In Op / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ACHILHS (F), FALKEN (R)

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 4/9/18 D.O.I. 7/9/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time _____ Action / Instruction _____

Plp \$11,396.19
CRP: \$16,146.84 (50%)

ALG PTP

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____

☐ : Interview (\$ _____) Photos _____

☐ : Tech. Invs (\$ _____) Others _____

☐ : Weekend (\$ _____) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18016425/Nub3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 10-09-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 6360M	Veh. Inspected	SHD 6219G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/09/2018	Inspection Date	07/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Section A - Accident Details

Registration Number	SHD6219G
Case Reference Number	TAX/09/18/2010
Registration Date	05/10/15
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHIN SING PIAN
Type of Accident	Others
Accident Date and Time	04/09/18 11:30 PM
Accident Reported Date and Time	05/09/18 8:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097820
Special Instruction to ARC, if any	
Prepared Date and Time	04/12/18 1:28 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,028.00	\$1,000.00
Total Spray Cost	\$4,986.00	\$1,980.00
Total Spare Part Cost	\$18,513.75	\$7,901.19
Total Other Cost	\$2,025.00	\$515.00
TOTAL COST	\$27,552.75	\$11,396.19 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	9.0
Prepared / Adjusted By	Kim Ming Chin	Naz (LKK) / AIG
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0487	Invoice Number	
Quotation Date	24.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$400.00 ✓
TO REPAIR REAR PORTION	\$1,352.00	\$600.00 ✓
Total Labour	\$2,028.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$360.00	\$0.00
RESPRAY WHEEL CAP	\$360.00	\$50.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$80.00 ✓
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 ✓
TO RESPRAY DOOR HANDLE	\$180.00	\$30.00 ✓
TO RESPRAY VIEW MIRROR	\$180.00	\$30.00 ✓
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00 ✓
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$50.00 ✓
TO REPSRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$80.00 ✓
TO RESPRAY TAIL GATE	\$378.00	\$200.00 ✓
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$80.00 ✓
TO RESPRAY REAR PANEL	\$180.00	\$80.00 ✓
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00 ✓
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$4,986.00	\$1,980.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$20.00 ✓
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$20.00 ✓

TO REMOVE AND REFIX WING MIRROR	\$120.00	\$20.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00 <i>PN Nec</i>	\$125.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$240.00	\$50.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$30.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$2,025.00	\$515.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	25.00	\$0.00	Replace	Repair <i>X R</i>
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$0.00	Replace	Repair <i>X R</i>
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00 ✓	Replace	Replace ✓ <i>NEL</i>
			DOOR OUTER HANDLE FRT/RH	0.00	\$370.80	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	10.00	\$0.00	Replace	Not Given <i>X SVL</i>
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$0.00	Replace	Repair <i>X R</i>
		52161-16010	BUMPER CLIPS	0.00	\$1.61	25.00	\$0.00	Replace	Not Given <i>X NN</i>
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$0.00	Replace	Repair <i>X R</i>
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93 ✓	Replace	Replace ✓ <i>NEL</i>
		53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		53851-47040	FENDER LINER PAD, FR WHEEL RH	0.00	\$49.30	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		42611-47140(Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given <i>X SVL</i>
			CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58 ✓	Replace	Replace ✓ <i>SVL</i>
		879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	25.00	\$80.55 ✓	Replace	Replace ✓ <i>SVL</i>
		67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88 ✓	Replace	Replace ✓ <i>DD</i>
		85710-47120	DOOR REGULATOR MOTOR REAR RH	0.00	\$947.80	10.00	\$0.00	Replace	Not Given <i>X SVL</i>
		69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	0.00	\$224.80	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
6505632	BODY RH	68770-52031	HINGE LOWER RHR, DOOR	0.00	\$52.00	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
6505630	BODY RH	68750-20121	HINGE UPPER RHR, DOOR	0.00	\$81.70	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	25.00	\$0.00	Replace	Not Given <i>X SVL</i>
		61604-47090	FENDER RR/RH	1.00	\$766.80	25.00	\$575.10 ✓	Replace	Replace ✓ <i>DD</i>
			STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80 ✓	Replace	Replace ✓ <i>NEL</i>
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60 ✓	Replace	Replace ✓ <i>NEL</i>
		62710-47130	QUARTER GLASS RR/RH	1.00	\$846.50	25.00	\$634.88 ✓	Replace	Replace ✓ <i>NEL</i>
			SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00 ✓	Replace	Replace ✓ <i>NEL</i>

	65637-47021	FENDER LINER RR/RH	0.00	\$141.30	25.00	\$0.00	Replace	Not Given	X	SVC
	65631-47041	SILL MEMBER PLATE RR/RH	0.00	\$57.50	25.00	\$0.00	Replace	Not Given	X	SVC
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	25.00	\$0.00	Replace	Not Given	X	SVC
	52562-47010	TAIL LAMP BRACKET, RH	1.00	\$30.70	25.00	\$23.03	Replace	Replace	/	NEC
	81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	/	CRK
	62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	25.00	\$0.00	Replace	Not Given	X	SVC
	42611-47140	WHEEL DISC	0.00	\$1,484.20	25.00	\$0.00	Replace	Not Given	X	SVC
6503707		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
	42602-47060	CAP SUB-ASSY, WHEEL	1.00	\$174.10	25.00	\$130.58	Replace	Replace	/	MIS
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	/	CRK
	52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	/	NEC
	52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace	/	DD
supp	52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	/	BT
supp	52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	/	BT
	89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	10.00	\$0.00	Replace	Not Given	X	SVC
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	/	NEC
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/	NEC
	76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace	/	CRK
	76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	/	CRK
	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	25.00	\$0.00	Replace	Not Given	X	SVC
	52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	/	CRK
supp	52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	/	CRK
	58308-47011	UNDER COVER SUBASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	Replace	/	CRK
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	/	DD
	75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	/	NEC
	75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	/	NEC
	75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	/	NEC
		SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	/	NEC
	69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	25.00	\$0.00	Replace	Not Given	X	SVC
	67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	/	DBP
	69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	25.00	\$0.00	Replace	Not Given	X	SVC
	69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	25.00	\$0.00	Replace	Not Given	X	SVC
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$0.00	Replace	Repair	X	CR
	75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	/	NEC
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	/	NEC
	75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	/	NEC
	75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	/	NEC
		STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/	NEC
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/	NEC
	58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace	/	DD
supp	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace	/	CRK

supp	64716-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace	CRK
	58336-12090	REINFORCEMENT, RR	2.00	\$34.60	25.00	\$51.90	Replace	Replace	PD
		SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	NEL
	58311-47071	SPARE TYRE PANEL	1.00	\$667.70	25.00	\$500.78	Replace	Replace	DD
	64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	25.00	\$0.00	Replace	Not Given	JVC
supp	58416-47030B3	BOX RR FLOOR, BOARD	1.00	\$679.60	25.00	\$509.70	Replace	Replace	Local missing
	58415-47030	BOARD, RR FLOOR	0.00	\$392.30	25.00	\$0.00	Replace	Not Given	JVC
	76085-47910	SPOILER REAR	0.00	\$953.70	25.00	\$0.00	Replace	Not Given	JVC
supp	52563-47010	TAIL LAMP BRACKET, LH	1.00	\$30.70	25.00	\$23.03	Replace	Replace	CRK
	81561-47170	TAIL LAMP LH	0.00	\$548.40	10.00	\$0.00	Replace	Not Given	JVC
Total				\$23,647.60		\$7,901.19			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

32,943.69

7901.19
+ 1000.00
+ 2495.00

11,396.19

CONFIRMED PART BY PART REPAIR R11,396.19 / 9 DAYS.

NAR LKK
JUL

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/09/18/2010	Date of Collection	1 1
Vehicle No	SHD 6219 G	Date of Request	11/09/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	3 2

S/N	Part Number	Part Description	Quantity	Unit Price
		ARM SUB ASSY, REAR BUMPER RH	1pc	/ BT
		ARM SUB ASSY, REAR BUMPER LH	1pc	/ BT
		REAR BUMPER RETAINER RH	1pc	/ CRA
		REAR PANEL COVER, DECK TRIM HOLE	1pc	/ CRA
		END PANEL COVER, DECK TRIM REAR	1pc	/ CRA
		BOX, REAR FLOOR BOARD	1pc	? CRA about 100

<<<Please submit photographs for damaged parts>>>

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMART Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission

pg 1/2

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/09/18/2010	Date of Collection	1 / 1
Vehicle No	SHD 6219 G	Date of Request	11/09/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (if any)	82

S/N	Part Number	Part Description	Quantity	Unit Price
		TAIL LAMP LOWER BRACKET	1/1	/ CRA
		TO REQUEST ADDITIONAL REPAIR PARTS		/

<<<Please submit photographs for damaged parts>>>

I, (Name) _____
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
 Signature of person making this declaration
 [to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

P77/2

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHD 6219G Ref. No. TAX 9 / 18 / 2010

Make / Model : TOYOTA PRIUS Reg. Date : 05/10/2015

Name of Driver : CHIN SING PIAN

Date/Time of Accident : 04/09/2018 23:30

Surveyor is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097820

Special Instruction to ARC, if any :

The damages on the Taxi are as indicated in the following diagram :



Signed : Date :

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305766085 Mileage :

Date Prepared : 06/09/2018 17:00 Repair Completed date/time:

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 2,028.00	\$
Total Spray Painting Charges :	\$ 4,986.00	\$
Total Material Charges :	\$ 18,503.23	\$
Other Charges :	\$ 2,025.00	\$
TOTAL :	\$ 27,542.23	\$ 0.00

No. of Repair Days : [12]

Signature :

Prepared by: MING
06/09/2018 17:00

Adjusted by:

[9]

QN No. _____ Invoice No. _____ Invoice Date _____
 Signed : _____ Date : _____

Section D - Details of Repair Estimates

Ref. No. _____ TAX 9 / 18 / 2010

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	678.00	400
TO REPAIR REAR PORTION	1352.00	600
Total Labour	\$ 2,028.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200
TO RESPRAY FRONT FENDER RH	378.00	200
TO RESPRAY RIM	360.00	X n n
RESPRAY WHEEL CAP	360.00	50
TO RESPRAY ROCKER PANEL MOULDING	180.00	80
TO RESPRAY FRONT DOOR RH	378.00	200
TO RESPRAY DOOR HANDLE	180.00	30
TO RESPRAY VIEW MIRROR	180.00	30
TO RESPRAY RH REAR DOOR	378.00	200
TO RESPRAY REAR FENDER RH	378.00	200
TO RESPRAY TROUGH BACK DOOR RH	180.00	50
TO REPSRAY REAR BUMPER	378.00	200
TO RESPRAY BUMPER BEAM	180.00	80
TO RESPRAY TAIL GATE	378.00	200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80
TO RESPRAY REAR PANEL	180.00	80
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100
TO RESPRAY REAR SPOILER	180.00	X n n
Total Spray Painting & Panel Beating	\$ 4,986.00	\$ -

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20
TO WASH AND VACUUM	60.00	X nn
TO TRANSFER REAR TAILGATE MECHANISM	120.00	20
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	20
TO REMOVE AND REFIX WING MIRROR	120.00	20
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	nn
TO TRANSFER DOOR MECHANISM	240.00	50
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	/ net
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	X 50
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40
TO REPLACE SUNDRY PARTS	100.00	X nn
Total Other Costs	\$ 2,025.00	\$ -

Part 4 - Spare Parts / Material Usage

Reservation No : _____

Page ()

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
52119-47930	BUMPER FRT	1	482.00	25%	361.50	/	X R
	BUMPER CLIPS	10	12.08	25%	1.61	/	X R
52115-47040	BUMPER SUPPORT F/RH	1	76.40	25%	57.30	/	X SUC
53801-47050	FENDER FRT/RH	1	723.40	25%	542.55	/	X R
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.93	/	/ nec
53875-47030	FENDER LINER FRT/RH	1	171.70	25%	128.78	/	X SUC
53851-47040	FENDER LINER PAD, FR WHEEL, RH	1	49.30	25%	36.98	/	X SUC
42611-47140(Frt)	WHEEL DISC. FRONT	1	1484.20	25%	1113.15	/	X SUC
	TYRE	1	126.74	0%	126.74	/	X R
42602-47060	CAP SUB-ASSY, WHEEL	1	174.10	25%	130.57	/	/ SCR
75851-47900	MOULDING BODY, RH	1	673.60	25%	505.20	/	X R
67001-47070	DOOR FRT/RH	1	894.40	25%	670.80	/	X R
	STICKER DECAL SMRT (DOOR)	1	60.00	0%	60.00	/	/ nec
69210-74030	DOOR OUTER HANDLE FRT/RH	1	370.80	25%	278.10	/	
87910-47330	MIRROR ASSY, RH	1	1307.10	25%	980.33	/	X SUC
81730-52090	MIRROR LAMP RH	1	65.30	10%	58.77	/	X SUC
879157-4010	COVER, OUTER MIRROR, RH	1	107.40	25%	80.55	/	/ SCR
67003-47080	DOOR RR/RH	1	954.50	25%	715.88	/	/ DD
85710-47120	DOOR REGULATOR MOTOR REAR RH	1	947.80	10%	853.02	/	?
69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	25%	168.60	/	?
68770-52031	HINGE LOWER RHR, DOOR	1	52.00	25%	39.00	/	?
68750-20121	HINGE UPPER RHR, DOOR	1	81.70	25%	61.28	/	?
68630-47031	CHECK ASSY, RR DOOR,	1	150.30	25%	112.73	/	?
61604-47090	FENDER RR/RH	1	766.80	25%	575.10	/	/ DD
	STICKER DECAL SMRT	1	7.80	0%	7.80	/	/ nec
	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	/ nec
62710-47130	QUARTER GLASS RR/RH	1	846.50	25%	634.88	/	/ nec
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	/ nec
65637-47021	FENDER LINER RR/RH	1	141.30	25%	105.98	/	X SUC
65631-47041	SILL MEMBER PLATE RR/RH	1	57.50	25%	43.13	/	X SUC

61621-47030	TROUGH, BACK DOOR	1	110.90	25%	83.18	/	?
52562-47010	TAIL LAMP BRACKET, RH	1	30.70	25%	23.03	/	/nll
81551-47180	TAIL LAMP RH	1	557.80	10%	502.02	/	/CEA
62940-16060	DUCT ASSY, QUARTER	1	70.40	25%	52.80	/	?
42611-47140	WHEEL DISC	1	1484.20	25%	1113.15	/	Xnn
	TYRE	1	126.74	0%	126.74	/	Xnn
42602-47060	CAP SUB-ASSY, WHEEL	1	174.10	25%	130.57	/	/MIS
52159-47905	BUMPER REAR	1	458.60	25%	343.95	/	/CRA
52161-16010	BUMPER CLIPS	10	1.61	25%	12.07	/	/nll
52023-12240	BUMPER REINFORCEMENT REAR	1	205.70	25%	154.27	/	/DT
52016-47030	ARM SUB-ASSY, RR BUMPER LH	1	139.60	25%	104.70	/	?
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1	139.60	25%	104.70	/	?
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10%	141.66	/	?
	SENSOR REVERSE	1	180.00	0%	180.00	/	/nll
	PIXEL STICKER	2	60.00	0%	120.00	/	/nll
76088-47020	BUMPER LIP COVER RR/LH	1	72.20	25%	54.15	/	/CEA
76891-47020	BUMPER LIP REAR	1	228.90	25%	171.67	/	/CEA
76087-47020	BUMPER LIP COVER RR/RH	1	118.10	25%	88.58	/	XSVL
52576-47020	BUMPER SIDE RETAINER RR/LH	1	94.80	25%	71.10	/	/CEA
52575-47020	BUMPER SIDE RETAINER RR/RH	1	94.80	25%	71.10	/	XSVL
58308-47011	UNDER COVER SUBASSY, RR FLOOR	1	514.50	25%	385.87	/	/CEA
67005-47241	TAILGATE ASY	1	1007.90	25%	755.92	/	/DD
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25%	22.05	/	/nll
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25%	22.05	/	/nll
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25%	22.05	/	/nll
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	/nll
69350-47030	TAILGATE DOOR LOCK	1	444.10	25%	333.07	/	?
67881-47022	TAILGATE DOOR WEATHER STRIP	1	353.40	25%	265.05	/	/DLS
69415-47020	TAILGATE LOCK, COVER	1	15.70	25%	11.77	/	?
69431-47010	STRIKER, BACK DOOR	1	48.90	25%	36.67	/	?
76801-47070-B0	TAILGATE OUTSIDE GARNISH	1	504.90	25%	378.67	/	XR
75310-47020	EMBLEM REAR	1	60.30	25%	45.22	/	/nll
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.92	/	/nll
75442-47030	NAME PLATE (PRIUS)	1	60.80	25%	45.60	/	/nll
75443-47030	NAME PLATE (TOYOTA)	1	51.90	25%	38.92	/	/nll
	STICKER DECAL SMRT	1	7.80	0%	7.80	/	/nll

	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	ALC
58307-47060	END PANEL	1	602.10	25%	451.57	/	DD
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1	46.10	25%	34.57	/	?
64716-47031B0	END PANEL COVER, DECK TRIM, RR	1	121.10	25%	90.82	/	?
58336-12090	REINFORCEMENT, RR	2	34.60	25%	51.90	/	DD
4006314	SEALANT SIKAFLEX	1	37.00	0%	37.00	/	ALC
58311-47071	SPARE TYRE PANEL	1	667.70	25%	500.77	/	DD
64993-47020	BOX, DECK FLOOR, RR	1	649.70	25%	487.28	/	?
58416-47030B3	BOX RR FLOOR, BOARD	1	679.60	25%	509.70	/	?
58415-47030	BOARD, RR FLOOR	1	392.30	25%	294.23	/	?
76085-47910	SPOILER REAR	1	953.70	25%	715.28	/	X SVL
52563-47010	TAIL LAMP BRACKET, LH	1	30.70	25%	23.02	/	X SVL
81561-47170	TAIL LAMP LH	1	548.40	10%	493.56	/	X SVL
TOTAL MATERIALS					\$	18,503.23	

NAZ LKK
 7/19/18 1045
 PIP
 7 DAYS
 BEFORE PAINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

View Received Message

This mail is associated with :

***SHD6219G (7544575687SG)**
[SLC6360M]

TP

SMRT TAXIS PTE LTD

Sep 4 2018 11:00PM

[MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/09/2018 11:41 AM.
To LKK_HQ
Subject No OI GIA Report

Hi

Pls be advice that no OI GIA report received
Pls find OI details below for your further actions.

OI name : MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD

Address :
26 Tai Seng Street
#07-02
Singapore 534057

Thank you.

Regards,
chan yoke shi

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18016425/Nub3 & CC6/AIG18016247/Ujb3

13 September, 2018

MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD

26 Tai Seng Street

#07-02

Singapore 534057

Dear Sirs,

**ACCIDENT INVOLVING SLC 6360M AND SHD 6219G AND SH 2163H ON 04/09/2018
ALONG / AT CTE TOWARDS SLE (NEAR WHAMPOA)**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Thin Thin

Claims

Tel : 6841 2360

Fax: 6741 4108

Email : thinthin@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18016425/Nhb3

05 September 2019

By Registered Mail
First Reminder

MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD

26 Tai Seng Street

#07-02

Singapore 534057

Dear Sir,

**ACCIDENT INVOLVING SLC 6360M AND SHD 6219G AND SH 2163H ON 04/09/2018
ALONG / AT CTE TOWARDS SLE (NEAR WHAMPOA)**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 13/09/2018

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen **(14)** days from date of this letter **(by 21/09/2019)**.

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan

Claims

Tel : 6841 2096

Fax: 6741 4108

Email : vicalpeh@lkkauto.com

c.c *Claims Manager*
 AIG Asia Pacific Insurance Pte. Ltd
 (Motor Claims Dept)



Singapore Post Limited
(Reg. No. 198201523M)
10 Eunos Road 8
408-30 Singapore Post Centre
Singapore 408600

Tel: 1905
Fax: 6342 5114
To check delivery status or to raise an enquiry
on your registered article(s), please visit
www.singpost.com

(SUN 4 12)

POSTING RECEIPT FOR REGISTERED ARTICLE(S)

NOTES:

- Separate forms are to be used for Insured and Non-Insured Registered Article.
- Please provide all information required and produce this receipt for all enquiries.
- Please tick where applicable. It shall be assumed no Advice of Receipt (A/R) is required or delivery by air is requested if relevant * is left blank.
- Please indicate the return address on the item(s) to ensure prompt return in event of non-delivery to the addressee(s).
- Please post item(s) at the post office counter according to the sequence stated below.

1. Name & Address of Addressee		AR: ☒ Y ☐ N		BY: ☐ AIR ☐ SUR	
DENGA TENG		Insurance: ☐ Y ☐ N		For Official Use Only (Item numbers are printed in order of posting at counter)	
BLK 26 BT. BATOK EAST AVE 2		Contents:			
# 20-05					
SINGAPORE 659920 (SLS 4678M)					
2. Name & Address of Addressee		Insurance: ☒ Y ☐ N		BY: ☐ AIR ☐ SUR	
MARY CHIA BEAUTY & SUMMING SPECIALIST PRECIOUS		Insurance: ☐ Y ☐ N			
26 Tai Seng Street					
#07-02					
Singapore 534057 (SLS 6360M)					
Sender's Agreement		Contents:			

I have read, understood and agreed to the terms and conditions of posting overleaf. I accept the maximum liability payable for Registered Mail Service and certify that all information provided by me is true and the item(s) does not contain any hazardous or prohibited item(s).

Name & Signature

Date

P116

09/2014



MPR-03119249005891



MacPherson Road
Singapore Post Limited
10 Eunos Road 8
Singapore Post Centre
Singapore 408600
GST Reg. No.: M2-0105651-9
Customer Service Hotline: 1605

Date/Time 6/9/2019 10:01

No. Description Amount(\$\$)

1	Accept Registered Article Item	0.00
	1. Ref: RC2825647975G Ctry: SG	
	Transaction No.: 8024192490048	
	2. Ref: RC2825648065G Ctry: SG	
	Transaction No.: 8024192490049	
2	Sale of Postage Label (Domestic)	2.54
	Quantity: 1	
	Unit price: 2.54	
	Total GST: 0.17	
	Ref.: RC2825647975G	
	Insurance: 0.00	
	Postage paid: 2.54	
	Transaction No.: 8024192490050	
3	Sale of Postage Label (Domestic)	2.54
	Quantity: 1	
	Unit price: 2.54	
	Total GST: 0.17	
	Ref.: RC2825648065G	
	Insurance: 0.00	
	Postage paid: 2.54	
	Transaction No.: 8024192490050	
	Total GST	0.34
	Total Amount	5.08
	Cash	5.08

Enjoy up to 3% cashback on eligible online and retail spend with the Spree Credit Card. No minimum spend required. T&Cs apply. Sign up now at singpost.com/spreecard

Thank you for giving us the opportunity to serve you. Please visit www.singpost.com for detailed Terms and Conditions.

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 12 September, 2019 3:56 PM
To: Syed-Yusoff, Saliha
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref:7544575687SG - ACCIDENT INVOLVING VEHICLES SLC 6360M AND SHD 6219G ON 04/09/2018 - LKK REF CC3/AIG18016425/Nhb3

Dear Saliha,

We refer to the subject matter and to our telephone conversation earlier.

As spoken, the matter had been repudiated.

Kindly assist to reopen/send back report in merimen for our further action and grant rights for us to view the repudiation letter.

Thank you.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and is for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018 Edit Reg		07 Sep 2018 00:00 Edit Adj Rpt	S\$11,396.19 Edit Estimates	S\$11,396.19 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD, Co. Reg. No.: 199403356Z								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHD6219G	Date of Loss:	04/09/2018 23:00 - :59 [34 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7544575687SG	Policy/Cover Note No.:	2100509471						
Vehicle Reg. No. (Insured):	SLC6360M	Policy No. (Claimant):	D-18090213MFSH						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 19/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (12/09/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD6219G (7544575687SG)**
[SLC6360M]

TP

SMRT TAXIS PTE LTD

Sep 4 2018 11:00PM

[MARY CHIA BEAUTY & SLIMMING SPECIALIST PTE LTD]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/01/19 09:59	General View	Load JPG	☒
2	10/01/19 09:59	General View	Load JPG	☒
3	10/01/19 09:59	General View	Load JPG	☒
4	10/01/19 09:59	General View	Load JPG	☒
5	10/01/19 09:59	General View	Load JPG	☒
6	10/01/19 09:59	General View	Load JPG	☒
7	10/01/19 09:59	General View	Load JPG	☒
8	10/01/19 09:59	General View	Load JPG	☒
9	10/01/19 09:59	General View	Load JPG	☒
10	10/01/19 09:59	General View	Load JPG	☒
11	10/01/19 09:59	General View	Load JPG	☒
12	10/01/19 09:59	General View	Load JPG	☒
13	10/01/19 09:59	General View	Load JPG	☒
14	10/01/19 09:59	General View	Load JPG	☒
15	10/01/19 09:59	General View	Load JPG	☒
16	10/01/19 09:59	General View	Load JPG	☒
17	10/01/19 09:59	General View	Load JPG	☒
18	10/01/19 09:59	General View	Load JPG	☒
19	10/01/19 09:59	General View	Load JPG	☒
20	10/01/19 09:59	General View	Load JPG	☒
21	10/01/19 09:59	General View	Load JPG	☒
22	10/01/19 09:59	General View	Load JPG	☒
23	10/01/19 09:59	General View	Load JPG	☒
24	10/01/19 09:59	General View	Load JPG	☒
25	10/01/19 09:59	General View	Load JPG	☒
26	10/01/19 09:59	General View	Load JPG	☒
27	10/01/19 09:59	General View	Load JPG	☒
28	10/01/19 09:59	General View	Load JPG	☒
29	10/01/19 09:59	General View	Load JPG	☒
30	10/01/19 09:59	General View	Load JPG	☒
31	10/01/19 09:59	General View	Load JPG	☒
32	10/01/19 09:59	General View	Load JPG	☒
33	10/01/19 09:59	General View	Load JPG	☒
34	10/01/19 09:59	General View	Load JPG	☒
35	10/01/19 09:59	General View	Load JPG	☒
36	10/01/19 09:59	General View	Load JPG	☒
37	10/01/19 09:59	General View	Load JPG	☒
38	10/01/19 09:59	General View	Load JPG	☒
39	10/01/19 09:59	General View	Load JPG	☒
40	10/01/19 09:59	General View	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	10/01/19 09:59	General View	 Load JPG	☒
42	10/01/19 09:59	General View	 Load JPG	☒
43	10/01/19 09:59	General View	 Load JPG	☒
44	10/01/19 09:59	General View	 Load JPG	☒
45	10/01/19 09:59	General View	 Load JPG	☒
46	10/01/19 09:59	General View	 Load JPG	☒
47	10/01/19 09:59	General View	 Load JPG	☒
48	10/01/19 09:59	General View	 Load JPG	☒
49	10/01/19 09:59	General View	 Load JPG	☒
50	10/01/19 09:59	General View	 Load JPG	☒
51	10/01/19 10:00	General View	 Load JPG	☒
52	10/01/19 10:00	General View	 Load JPG	☒
53	10/01/19 10:00	General View	 Load JPG	☒
54	10/01/19 10:00	General View	 Load JPG	☒
55	10/01/19 10:00	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/09/18 17:50	TP ESTIMATE- MARKED	 Load PDF	
2	10/09/18 17:50	TP GIA REPORT	 Load PDF	
3	13/09/18 19:19	Non reporting letter	 Load PDF	
4	05/09/19 10:45	First Reminder Letter	 Load PDF	
5	21/10/19 09:05	EMAIL	 Load PDF	
6	21/10/19 09:05	REGISTERED MAIL FEE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18016425/NHB3S2
Date: 21/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100509471
Claimant Vehicle No: SHD6219G Insured Vehicle No: SLC6360M
Date of Loss: 04/09/2018 Nature of Claim: TP Claim No: 7544575687SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6219G Engine No: 2ZR6527481
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Chassis No: JTDKN36U305766085
Reg. Date: 05/10/2015 (Man. Year: 2015) Odometer: 0 km
Colour: Maroon
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Achilles 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Achilles 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	24,029.69	8,026.19	16,003.50	66.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,914.00	3,370.00	5,544.00	62.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	32,943.69	11,396.19	21,547.50	65.41

INSPECTION

Date of Assignment: 07/09/2018
Date Inspected: 07/09/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 9.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
2	1		*CAP SUB-ASSY, WHEEL (DISC 25%)	Scratched	174.10 F	*130.58 F
3	1		*COVER, OUTER MIRROR, RH (DISC 25%)	Scratched	107.40 F	*80.55 F
4	1		*DOOR RR/RH (DISC 25%)	Dented	954.50 F	*715.88 F
5	1		*FENDER RR/RH (DISC 25%)	Dented	766.80 F	*575.10 F
6	1		*QUARTER GLASS RR/RH (DISC 25%)	Necessary	846.50 F	*634.88 F
7	1		*TAIL LAMP BRACKET, RH (DISC 25%)	Necessary	30.70 F	*23.03 F
8	1		*CAP SUB-ASSY, WHEEL (DISC 25%)	Missing	174.10 F	*130.58 F
9	1		*BUMPER REAR (DISC 25%)	Cracked	458.60 F	*343.95 F
10	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	16.10 F	*12.08 F
11	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
12	1		*ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
13	1		*ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
14	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Cracked	72.20 F	*54.15 F
15	1		*BUMPER LIP REAR (DISC 25%)	Cracked	228.90 F	*171.68 F
16	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Cracked	94.80 F	*71.10 F
17	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Cracked	94.80 F	*71.10 F
18	1		*UNDER COVER SUBASSY, RR FLOOR (DISC 25%)	Cracked	514.50 F	*385.88 F
19	1		*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
20	1		*TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	Necessary	29.40 F	*22.05 F
21	1		*TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	Necessary	29.40 F	*22.05 F
22	1		*MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
23	1		*TAIL GATE DOOR WEATHER STRIP (DISC 25%)	Deformed	353.40 F	*265.05 F
24	1		*EMBLEM REAR (DISC 25%)	Necessary	60.30 F	*45.23 F
25	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
26	1		*NAME PLATE (PRIUS) (DISC 25%)	Necessary	60.80 F	*45.60 F
27	1		*NAME PLATE (TOYOTA) (DISC 25%)	Necessary	51.90 F	*38.93 F
28	1		*END PANEL (DISC 25%)	Dented	602.10 F	*451.58 F
29	1		*END PANEL COVER, DECK TRIM HOLLE (DISC 25%)	Cracked	46.10 F	*34.58 F
30	1		*END PANEL COVER, DECK TRIM, RR (DISC 25%)	Cracked	121.10 F	*90.83 F
31	2		*REINFORCEMENT, RR (DISC 25%)	Dented	69.20 F	*51.90 F
32	1		*SPARE TYRE PANEL (DISC 25%)	Dented	667.70 F	*500.78 F
33	1		*BOX RR FLOOR, BOARD (DISC 25%)	Lock Missing	679.60 F	*509.70 F
34	1		*TAIL LAMP BRACKET, LH (DISC 25%)	Cracked	30.70 F	*23.03 F
35	1		*TAIL LAMP RH (DISC 10%)	Cracked	557.80 F	*502.02 F
36	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
37	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
38	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
39	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
40	1		*SENSOR REVERSE (SN)	Necessary	180.00 F	*180.00 F
41	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
42	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
43	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
44	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
45	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
46	1		*DOOR OUTER HANDLE FRT/RH	Serviceable	370.80 F	*- F
47	1		*MIRROR ASSY, RH	Serviceable	1,307.10 F	*- F
48	1		*MIRROR LAMP RH	Serviceable	65.30 F	*- F
49	1		*BUMPER SUPPORT F/RH	Serviceable	76.40 F	*- F
50	1		*FENDER LINER FRT/RH	Serviceable	171.70 F	*- F
51	1		*FENDER LINER PAD, FR WHEEL. RH	Serviceable	49.30 F	*- F
52	1		*WHEEL DISC. FRONT	Serviceable	1,484.20 F	*- F
53	1		*TYRE	Serviceable	126.74 F	*- F
54	1		*DOOR REGULATOR MOTOR REAR RH	Serviceable	947.80 F	*- F
55	1		*DOOR REGULATOR SUB-ASSY, FRT/REAR RH	Serviceable	224.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*HINGE LOWER RHR, DOOR	Serviceable	52.00 F	*- F
57	1		*HINGE UPPER RHR, DOOR	Serviceable	81.70 F	*- F
58	1		*CHECK ASSY, RR DOOR,	Serviceable	150.30 F	*- F
59	1		*FENDER LINER RR/RH	Serviceable	141.30 F	*- F
60	1		*SILL MEMBER PLATE RR/RH	Serviceable	57.50 F	*- F
61	1		*TROUGH, BACK DOOR	Serviceable	110.90 F	*- F
62	1		*DUCT ASSY, QUARTER	Serviceable	70.40 F	*- F
63	1		*WHEEL DISC	Serviceable	1,484.20 F	*- F
64	1		*TYRE	Serviceable	126.74 F	*- F
65	1		*ANTENNA ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
66	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
67	1		*TAILGATE DOOR LOCK	Serviceable	444.10 F	*- F
68	1		*TAILGATE LOCK, COVER	Serviceable	15.70 F	*- F
69	1		*STRIKER, BACK DOOR	Serviceable	48.90 F	*- F
70	1		*BOX, DECK FLOOR, RR	Serviceable	649.70 F	*- F
71	1		*BOARD, RR FLOOR	Serviceable	392.30 F	*- F
72	1		*SPOILER REAR	Serviceable	953.70 F	*- F
73	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F
74	1		*BUMPER CLIPS	Not Necessary	1.61 F	*- F
75	1		*MOULDING BODY, RH	Repair	673.60 F	*- F
76	1		*DOOR FRT/RH	Repair	894.40 F	*- F
77	1		*BUMPER FRT	Repair	482.00 F	*- F
78	1		*FENDER FRT/RH	Repair	723.40 F	*- F
79	1		*TAILGATE OUTSIDE GARNISH	Repair	504.90 F	*- F
80	1		*SOLAR FILM (SN)	Necessary	125.00 F	*125.00 F
F=Franchise part.						
					Total Parts (S\$)	24,029.69 8,026.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,028.00	1,000.00
2	SPRAY PAINT.	New	4,986.00	1,980.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	20.00
5	TO WASH AND VACUUM.	New	60.00	0.00
6	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	20.00
7	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	100.00
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	20.00
9	TO REMOVE AND REFIX WING MIRROR.	New	120.00	20.00
10	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	0.00
11	TO TRANSFER DOOR MECHANISM.	New	240.00	50.00
12	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	240.00	50.00
13	TO REMOVE & REFIT REAR QUARTER GLASS RH.	New	120.00	30.00
14	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	20.00
15	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	40.00
16	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
Gross Labour Cost (S\$)			8,914.00	3,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >