

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHD 6219G Ref. No. TAX 9 / 18 / 2010

Make / Model : TOYOTA PRIUS Reg. Date : 05/10/2015

Name of Driver : CHIN SING PIAN

Date/Time of Accident : 04/09/2018 23:30

Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)

Taxi is Towed Back ? YES / NO


Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097820

Special Instruction to ARC, if any :

Signed : Date :

The damages on the Taxi are as indicated in the following diagram :



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U305766085 Mileage :

Date Prepared : 06/09/2018 17:00 Repair Completed date/time:

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 2,028.00	\$
Total Spray Painting Charges :	\$ 4,986.00	\$
Total Material Charges :	\$ 18,503.23	\$
Other Charges :	\$ 2,025.00	\$
TOTAL :	\$ 27,542.23	\$ 0.00

No. of Repair Days : [12]

Signature : Prepared by: MING
06/09/2018 17:00

Adjusted by: [7]

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. _____ Invoice No. _____ Invoice Date _____

Signed : _____ Date : _____

Section D - Details of Repair Estimates

Ref. No. TAX 9 / 18 / 2010

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	678.00	400
TO REPAIR REAR PORTION	1352.00	600
Total Labour	\$ 2,028.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200
TO RESPRAY FRONT FENDER RH	378.00	200
TO RESPRAY RIM	360.00	X n n
RESPRAY WHEEL CAP	360.00	50
TO RESPRAY ROCKER PANEL MOULDING	180.00	80
TO RESPRAY FRONT DOOR RH	378.00	200
TO RESPRAY DOOR HANDLE	180.00	30
TO RESPRAY VIEW MIRROR	180.00	30
TO RESPRAY RH REAR DOOR	378.00	200
TO RESPRAY REAR FENDER RH	378.00	200
TO RESPRAY TROUGH BACK DOOR RH	180.00	50
TO REPSRAY REAR BUMPER	378.00	200
TO RESPRAY BUMPER BEAM	180.00	80
TO RESPRAY TAIL GATE	378.00	200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80
TO RESPRAY REAR PANEL	180.00	80
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100
TO RESPRAY REAR SPOILER	180.00	X n n
Total Spray Painting & Panel Beating	\$ 4,986.00	\$ -

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20
TO WASH AND VACUUM	60.00	X nn
TO TRANSFER REAR TAILGATE MECHANISM	120.00	20
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	100
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	20
TO REMOVE AND REFIX WING MIRROR	120.00	20
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	7 nn
TO TRANSFER DOOR MECHANISM	240.00	50
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	/ nec
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	X 50
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40
TO REPLACE SUNDRY PARTS	100.00	X nn
Total Other Costs	\$ 2,025.00	\$ -

Part 4 - Spare Parts / Material Usage

Reservation No : _____

Page ()

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (I)	Not given (x) Repair (R) Replace (I)
52119-47930	BUMPER FRT	1	482.00	25%	361.50	/	X R
	BUMPER CLIPS	10	12.08	25%	1.61	/	X R
52115-47040	BUMPER SUPPORT F/RH	1	76.40	25%	57.30	/	X SUC
53801-47050	FENDER FRT/RH	1	723.40	25%	542.55	/	X R
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.93	/	/ REC
53875-47030	FENDER LINER FRT/RH	1	171.70	25%	128.78	/	X SUC
53851-47040	FENDER LINER PAD, FR WHEEL. RH	1	49.30	25%	36.98	/	X SUC
42611-47140(Frt)	WHEEL DISC. FRONT	1	1484.20	25%	1113.15	/	X SUC
	TYRE	1	126.74	0%	126.74	/	X R
42602-47060	CAP SUB-ASSY, WHEEL	1	174.10	25%	130.57	/	/ SCR
75851-47900	MOULDING BODY, RH	1	673.60	25%	505.20	/	X R
67001-47070	DOOR FRT/RH	1	894.40	25%	670.80	/	X R
	STICKER DECAL SMRT (DOOR)	1	60.00	0%	60.00	/	/ REC
69210-74030	DOOR OUTER HANDLE FRT/RH	1	370.80	25%	278.10	/	
87910-47330	MIRROR ASSY, RH	1	1307.10	25%	980.33	/	X SUC
81730-52090	MIRROR LAMP RH	1	65.30	10%	58.77	/	X SUC
879157-4010	COVER, OUTER MIRROR, RH	1	107.40	25%	80.55	/	/ SCR
67003-47080	DOOR RR/RH	1	954.50	25%	715.88	/	/ DD
85710-47120	DOOR REGULATOR MOTOR REAR RH	1	947.80	10%	853.02	/	?
69801-52070	DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	25%	168.60	/	?
68770-52031	HINGE LOWER RHR, DOOR	1	52.00	25%	39.00	/	?
68750-20121	HINGE UPPER RHR, DOOR	1	81.70	25%	61.28	/	?
68630-47031	CHECK ASSY, RR DOOR,	1	150.30	25%	112.73	/	?
61604-47090	FENDER RR/RH	1	766.80	25%	575.10	/	/ DD
	STICKER DECAL SMRT	1	7.80	0%	7.80	/	/ REC
	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	/ REC
62710-47130	QUARTER GLASS RR/RH	1	846.50	25%	634.88	/	/ REC
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	/ REC
65637-47021	FENDER LINER RR/RH	1	141.30	25%	105.98	/	X SUC
65631-47041	SILL MEMBER PLATE RR/RH	1	57.50	25%	43.13	/	X SUC

61621-47030	TROUGH, BACK DOOR	1	110.90	25%	83.18	/	?
52562-47010	TAIL LAMP BRACKET, RH	1	30.70	25%	23.03	/	ALL
81551-47180	TAIL LAMP RH	1	557.80	10%	502.02	/	CEA
62940-16060	DUCT ASSY, QUARTER	1	70.40	25%	52.80	/	?
42611-47140	WHEEL DISC	1	1484.20	25%	1113.15	/	Xnn
	TYRE	1	126.74	0%	126.74	/	Xnn
42602-47060	CAP SUB-ASSY, WHEEL	1	174.10	25%	130.57	/	MIS
52159-47905	BUMPER REAR	1	458.60	25%	343.95	/	CRA
52161-16010	BUMPER CLIPS	10	1.61	25%	12.07	/	ALL
52023-12240	BUMPER REINFORCEMENT REAR	1	205.70	25%	154.27	/	DT
52016-47030	ARM SUB-ASSY, RR BUMPER LH	1	139.60	25%	104.70	/	?
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1	139.60	25%	104.70	/	?
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10%	141.66	/	?
	SENSOR REVERSE	1	180.00	0%	180.00	/	ALL
	PIXEL STICKER	2	60.00	0%	120.00	/	ALL
76088-47020	BUMPER LIP COVER RR/LH	1	72.20	25%	54.15	/	CEA
76891-47020	BUMPER LIP REAR	1	228.90	25%	171.67	/	CEA
76087-47020	BUMPER LIP COVER RR/RH	1	118.10	25%	88.58	/	XSVZ
52576-47020	BUMPER SIDE RETAINER RR/LH	1	94.80	25%	71.10	/	CEA
52575-47020	BUMPER SIDE RETAINER RR/RH	1	94.80	25%	71.10	/	XSVZ
58308-47011	UNDER COVER SUBASSY, RR FLOOR	1	514.50	25%	385.87	/	CRA
67005-47241	TAILGATE ASY	1	1007.90	25%	755.92	/	DD
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25%	22.05	/	ALL
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25%	22.05	/	ALL
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25%	22.05	/	ALL
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	ALL
69350-47030	TAILGATE DOOR LOCK	1	444.10	25%	333.07	/	?
67881-47022	TAILGATE DOOR WEATHER STRIP	1	353.40	25%	265.05	/	DL
69415-47020	TAILGATE LOCK, COVER	1	15.70	25%	11.77	/	?
69431-47010	STRIKER, BACK DOOR	1	48.90	25%	36.67	/	?
76801-47070-B0	TAILGATE OUTSIDE GARNISH	1	504.90	25%	378.67	/	XR
75310-47020	EMBLEM REAR	1	60.30	25%	45.22	/	ALL
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.92	/	ALL
75442-47030	NAME PLATE (PRIUS)	1	60.80	25%	45.60	/	ALL
75443-47030	NAME PLATE (TOYOTA)	1	51.90	25%	38.92	/	ALL
	STICKER DECAL SMRT	1	7.80	0%	7.80	/	ALL

	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	neu
58307-47060	END PANEL	1	602.10	25%	451.57	/	DD
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1	46.10	25%	34.57	/	?
64716-47031B0	END PANEL COVER, DECK TRIM, RR	1	121.10	25%	90.82	/	?
58336-12090	REINFORCEMENT, RR	2	34.60	25%	51.90	/	DD
4006314	SEALANT SIKAFLEX	1	37.00	0%	37.00	/	neu
58311-47071	SPARE TYRE PANEL	1	667.70	25%	500.77	/	DD
64993-47020	BOX, DECK FLOOR, RR	1	649.70	25%	487.28	/	?
58416-47030B3	BOX RR FLOOR, BOARD	1	679.60	25%	509.70	/	?
58415-47030	BOARD, RR FLOOR	1	392.30	25%	294.23	/	?
76085-47910	SPOILER REAR	1	953.70	25%	715.28	/	XSVL
52563-47010	TAIL LAMP BRACKET, LH	1	30.70	25%	23.02	/	XSVL
81561-47170	TAIL LAMP LH	1	548.40	10%	493.56	/	XSVL
TOTAL MATERIALS					\$	18,503.23	

NA2 LKK
 7/19/18 104
 PIP
 7 Days
 BEFORE PRINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: