

1/5/2018

INS. CASE OWNER:

CC 6 UP 1801

LKK:
IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

10/1/18

Date / Time:

10/1/18

Registered in Merimen:

10/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUH 4799T

Name of Insured:

UP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

9/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MO MUNG HOE

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

3175444456

Policy No.:

94444444

Make / Model:

HONDA

Place of Accident:

VISHNU RINH RO / CP UP BIK 615

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

WMM

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

14/1/18

PBL 14/1/18 - Y

SUH 4799T - Y

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation to Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Cal

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2386.10

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

10.00

(\$ 20 x 5 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

2493.55

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

S\$

2493.55

Name 1:

Ban Hock Him Co. Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

#320.00

COPY SENT

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FQ1933R

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19567

L7A 7620

no second hand parts.

note new parts replacement.

confirm Repair sum \$2230 with Raymond.

(Ref # 1693 / 437)

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18016427/Upb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 10-09-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 4799T	Veh. Inspected	FQ 1933R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/08/2018	Inspection Date	10/09/2018	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 15.000288A

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 32975

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

*Not Allowed
Repair Sum \$2230
10/9/18
Sdy.*

DATE : 06/09/2018
CLAIM NO. : 11184
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FQ1933R
MAKE/MODEL : BMW /

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX REAR(HEPCO&BECKER) GOBI TC42 SILVER	REPLACE	1.00	\$546.00	546.00
2	BRACKET FAIRING	REPLACE	1.00	\$508.00	508.00
3	COVER CYLINDER HEAD	REPLACE	1.00	\$441.00	441.00
4	EMBLEM	REPLACE	2.00	\$45.00	90.00
5	FOOTREST FRONT(PIVOT PEGZ) SET	REPLACE	1.00	\$360.00	360.00
6	GASKET CYLINDER HEAD P/N: 42940	REPLACE	2.00	\$85.00	170.00
7	GASKET INNER CYLINDER HEAD	REPLACE	2.00	\$19.00	38.00
8	GUARD HANDLE RH	REPLACE	1.00	\$126.00	126.00
9	HANDLE GUARD (BARBUSTERS) SET	REPLACE	1.00	\$336.00	336.00
10	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$385.00	385.00
11	PEDAL BRAKE	REPLACE	1.00	\$328.00	328.00
12	POWDER COAT BRACKET (MISC) P/N: 48368	REPLACE	1.00	\$95.00	95.00
13	RUBBER MOUNT P/N: 42941	REPLACE	4.00	\$12.00	48.00



S/N	Description	Action	Qty	Unit Price	Amount
14	STICKER FUEL TANK	REPLACE	2.00	\$120.00	240.00
15	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00
16	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$70.00	70.00
SUB TOTAL					\$3,793.00
GST @ 7 %					\$265.51
GRAND TOTAL					\$4,058.51

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1862
102
1675-80

24 8-80



CERT NO.: 2000-1-0383
ISO 9001:2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 33378

Supplementary 1 To QTN: 32975

DATE : 21/12/2018

CLAIM NO. : 11184

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FQ1933R
MAKE/MODEL : BMW /

S/N	Description	Action	Qty	Unit Price	Amount
1	SPRAY PAINT FUEL TANK	Spray	1.00	\$130.00	130.00
SUB TOTAL					\$130.00
GST @ 7 %					\$9.10
GRAND TOTAL					\$139.10

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



3927.



CERT NO.: 2502-1-2383
ISO 9001 : 2015

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32975

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 06/09/2018
CLAIM NO. : 11184
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FQ1933R
MAKE/MODEL : BMW /

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOX REAR(HEPCO&BECKER) GOBI TC42 SILVER	REPLACE	1.00	\$546.00	491.40
				Disc %: 10.00	
2	BRACKET FAIRING	REPLACE	1.00	\$508.00	457.20
				Disc %: 10.00	
3	EMBLEM	REPLACE	2.00	\$45.00	81.00
				Disc %: 10.00	
4	GASKET CYLINDER HEAD P/N: 42940	REPLACE	2.00	\$85.00	153.00
				Disc %: 10.00	
5	GASKET INNER CYLINDER HEAD	REPLACE	2.00	\$19.00	34.20
				Disc %: 10.00	
6	GUARD HANDLE RH	REPLACE	1.00	\$126.00	113.40
				Disc %: 10.00	
7	HANDLE GUARD (BARBUSTERS) SET	REPLACE	1.00	\$336.00	302.40
				Disc %: 10.00	
8	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$300.00	300.00
9	POWDER COAT BRACKET (MISC) P/N: 48368	REPLACE	1.00	\$95.00	95.00
10	RUBBER MOUNT P/N: 42941	REPLACE	4.00	\$12.00	43.20
				Disc %: 10.00	
11	SPRAY PAINT FUEL TANK	Repair	1.00	\$130.00	130.00
12	STICKER FUEL TANK	REPLACE	2.00	\$120.00	240.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001 : 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
13	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - FOR COLLECTION OF ACCIDENT BIKE.	Supply/Install	1.00	\$45.00	45.00

SUB TOTAL

\$2,485.80

GST @ 7 %

\$174.01

GRAND TOTAL

\$2,659.81

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

CERT NO: 20002-1-0383
ISO 9001 : 2015

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 25 September 2018 3:12 PM
To: 'Raymond'
Cc: Vivian Lau (LKKAUTO); Admin A
Subject: RE: Accident Involving FQ1933R & SLH4799T on 08/08/2018 *LKK REF:

Without Prejudice

Hi Sirs,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond <raymond@bhh.com.sg>
Sent: Tuesday, 25 September 2018 2:17 PM
To: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: Accident Involving FQ1933R & SLH4799T on 08/08/2018

Dear Hsiao Tong,

As requested by our client, please advise your insured liability for direct settlement.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



From: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>

Sent: Thursday, 20 September, 2018 10:14 AM

To: Raymond <raymond@bhh.com.sg>

Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Subject: RE: Accident Involving FQ1933R & SLH4799T on 08/08/2018

WITHOUT PREJUDICE

Dear Raymond,

Thank you for the email.

Dear Hsiao Tong,

Kindly assist CC6/LCR18016427/Upb3

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond [<mailto:raymond@bhh.com.sg>]

Sent: Thursday, 20 September, 2018 10:10 AM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Accident Involving FQ1933R & SLH4799T on 08/08/2018

Dear Vivian,

Please advise your insured liability for direct settlement.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



BAN HOCK HIN
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

www.bhh.com.sg

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | L



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018 Edit Reg		10 Sep 2018 00:00 Edit Adj Rpt	S\$2,230.00 Edit Estimates	S\$2,230.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K, Tel: +6588888888		
Main Claimant:	VANGA S/O GANASAN, ID: S8931956J		
Vehicle Reg. No.:	FQ1933R	Date of Loss:	08/08/2018 00:00 - :59 [242 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3179941449SG	Policy/Cover Note No.:	0999994821 (Comprehensive)
Vehicle Reg. No. (Insured):	SLH4799T	Policy No. (Claimant):	PNMC201700001527
		Excess:	
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Jeffrey-SK] Jeffreysaykiat.Ng@aig.com		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/09/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (12/09/2018): Conflicting DOA

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FQ1933R (3179941449SG)**
[SLH4799T]

TP

VANGA S/O GANASAN

Aug 8 2018 12:00AM

[LCRF PTE LTD]

Ban Hock Hin Co. Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail		Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown														Edit			
Photos/Images															3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)														Thumbnail		Print	
1	10/09/18 18:19		Chassis Number														Load JPG			
2	10/09/18 18:19		General View														Load JPG			
3	10/09/18 18:19		General View														Load JPG			
4	10/09/18 18:19		General View														Load JPG			
5	10/09/18 18:19		General View														Load JPG			
6	10/09/18 18:19		General View														Load JPG			
7	10/09/18 18:19		General View														Load JPG			
8	10/09/18 18:19		General View														Load JPG			
9	10/09/18 18:19		General View														Load JPG			
10	10/09/18 18:19		General View														Load JPG			
11	10/09/18 18:19		General View														Load JPG			
12	10/09/18 18:19		General View														Load JPG			
13	10/09/18 18:19		General View														Load JPG			
14	10/09/18 18:19		General View														Load JPG			
15	10/09/18 18:19		General View														Load JPG			
16	10/09/18 18:19		General View														Load JPG			
17	10/09/18 18:19		General View														Load JPG			
18	10/09/18 18:19		General View														Load JPG			
19	10/09/18 18:19		General View														Load JPG			
20	10/09/18 18:19		General View														Load JPG			
21	10/09/18 18:19		General View														Load JPG			
22	10/09/18 18:19		General View														Load JPG			
23	10/09/18 18:19		General View														Load JPG			
24	10/09/18 18:19		General View														Load JPG			
25	10/09/18 18:19		General View														Load JPG			
26	10/09/18 18:19		General View														Load JPG			
27	10/09/18 18:19		General View														Load JPG			
28	10/09/18 18:19		General View														Load JPG			
29	10/09/18 18:19		General View														Load JPG			
30	10/09/18 18:19		General View														Load JPG			
31	10/09/18 18:19		General View														Load JPG			
32	10/09/18 18:19		General View														Load JPG			

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	10/09/18 18:19	General View	 Load JPG	✓
34	10/09/18 18:19	General View	 Load JPG	✓
35	10/09/18 18:19	General View	 Load JPG	✓
36	10/09/18 18:19	General View	 Load JPG	✓
37	10/09/18 18:19	General View	 Load JPG	✓
38	10/09/18 18:19	General View	 Load JPG	✓
39	10/09/18 18:19	General View	 Load JPG	✓
40	10/09/18 18:19	General View	 Load JPG	✓
41	10/09/18 18:20	Odometer Reading	 Load JPG	✓
42	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
43	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
44	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
45	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
46	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
47	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
48	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
49	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
50	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
51	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
52	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
53	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
54	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
55	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
56	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
57	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
58	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
59	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
60	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
61	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
62	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
63	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
64	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
65	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
66	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
67	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
68	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
69	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
70	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
71	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
72	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
73	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
74	21/12/18 16:41	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 20:23	TP ESTIMATE- MARKED	 Load PDF	
2	11/09/18 20:23	TP GIA REPORT	 Load PDF	
3	28/02/19 14:40	AUTHORISATION TO ACT	 Load PDF	
4	28/02/19 14:40	LETTER TO OI	 Load PDF	

Letters/Correspondences			1 per page ▾	
No	Finalized On		Thumbnail	Print
5	28/02/19 14:40	LKK Auto Consultants Pte Ltd (HQ) LTA SEARCH	Load PDF	
6	28/02/19 14:40	RELEASE VOUCHER	Load PDF	
7	28/02/19 14:40	WORKSHOP INVOICE	Load PDF	
No	Finalized On		Thumbnail	Print
1	12/09/18 11:15	AIG Asia Pacific Insurance Pte. Ltd. (SG) OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH4799T (Insd veh)	Model:	BMW R1100GS 1.1
	FQ1933R (TP veh)		
Date of Accident:	08/08/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	4,197.61
Final Repair Cost	:	\$	2,386.10
Loss of Use	:	\$	100.00
Rental (if any)	:	\$	5.00 days at \$20.00 per day
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	2,493.55
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Ban Hock Hin Co. Pte Ltd	:	\$ 2,493.55
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

28 Feb
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18016427/UPB3S2

Date: 28/02/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994821
Claimant Vehicle No :	FQ1933R	Insured Vehicle No :	SLH4799T
Date of Loss:	08/08/2018	Nature of Claim:	TP
		Claim No:	3179941449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FQ1933R	Engine No:	112EB09986939
Make & Model:	BMW R1100GS, 1.1	Chassis No:	WB10409B8WZB85735
Reg. Date:	26/05/1998 (Man. Year: 1998)	Odometer:	314377 km
Colour:	Yellow		
Engine Capacity:	1085 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/80 R19	Rear Tyre Size:	150/70 R17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,338.00	2,010.80	1,327.20	39.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	585.00	475.00	110.00	18.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,923.00	2,485.80	1,437.20	36.64
Approved Total (Overridden) (S\$)		2,230.00		
(S\$)	3,923.00	2,230.00	1,693.00	43.16
+ GST 7.00/7.00% (S\$)	274.61	156.10	118.51	43.16
Nett Amount (S\$)	4,197.61	2,386.10	1,811.51	43.16
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,493.55		

INSPECTION

Date of Assignment:	10/09/2018		
Date Inspected:	10/09/2018	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOX REAR (HECO&BECKER) GOBI TC42 SILVER	Cut	546.00 F	*546.00 FL
2	1		*BRACKET FAIRING	Bent	508.00 F	*508.00 FL
3	1		*COVER CYLINDER HEAD	Repair	441.00 F	*- FL
4	2		*EMBLEM	Necessary	90.00 F	*90.00 FL
5	1		*SET FOOTREST FRONT (PIVOT PEGZ)	Serviceable	360.00 F	*- FL
6	2		*GASKET CYLINDER HEAD	Necessary	170.00 F	*170.00 FL
7	2		*GASKET INNER CYLINDER HEAD	Necessary	38.00 F	*38.00 FL
8	1		*GUARD HANDLE RH	Cut	126.00 F	*126.00 FL
9	1		*SET HANDLE GUARD (BARBUSTERS)	Cut	336.00 F	*336.00 FL
10	1		*PEDAL BRAKE	Not Necessary	328.00 F	*- FL
11	4		*RUBBER MOUNT	Necessary	48.00 F	*48.00 FL
12	1		*POWDER COAT BRACKET (MISC)	Damaged	95.00 FS	*95.00 FS
13	2		*STICKER FUEL TANK	Necessary	240.00 FS	*240.00 FS
14	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT (SCRATCHED)	Not Consistent With The Impact	12.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,338.00	2,197.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	186.20
Total Parts (\$\$)	3,338.00	2,010.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR: FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	New	385.00	300.00
2	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED: FOR COLLECTION OF ACCIDENT BIKE.	New	70.00	45.00
3	SPRAY PAINT FUEL TANK.	New	130.00	130.00
Gross Labour Cost (S\$)			585.00	475.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >