

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	ENGINE UNDERSHIELD REAR <i>Not new</i>	\$ 550.00	? } <input checked="" type="checkbox"/>
22	UNDERBODY TRIM FRT LH <i>Not new</i>	\$ 128.00	? } <input checked="" type="checkbox"/>
23	UNDERBODY TRIM LH <i>Not new</i>	\$ 273.00	? } <input checked="" type="checkbox"/>
24	UNDERBODY TRIM LH <i>Not new</i>	\$ 168.00	? } <input checked="" type="checkbox"/>
25	REAR SILENCER LH <i>Not new</i>	\$ 1,157.00	+ <input checked="" type="checkbox"/>
26	DUAL CLIPS <i>Not new</i>	2 \$ 93.00	+ <input checked="" type="checkbox"/>
27	TRIM FOR EXHAUST TAIL PIPE CHROME <i>Not new</i>	\$ 497.00	+ <input checked="" type="checkbox"/>
28	CLAMP <i>Not new</i>	\$ 70.00	+ <input checked="" type="checkbox"/>
29	ALUMINIUM RIM FRONT/ REAR LH <i>lit</i>	2 \$ 1,451.00	+ <input checked="" type="checkbox"/> <i>lit</i>
30	RUBBER VALVE <i>Not new</i>	8 \$ 23.00	+ <input checked="" type="checkbox"/>
31	RADIAL TYRE FRONT / REAR LH <i>Involved</i>	2 \$ 1,539.00	740 (sw) 50% depreciation 370
32	FRONT WISHBONE LINK FRT LH <i>Not new</i>	\$ 476.00	? } <input checked="" type="checkbox"/>
33	SUSPENSION GUIDE <i>Not new</i>	\$ 863.00	? } <input checked="" type="checkbox"/>
34	UPPER GUIDE FRT / REAR <i>Not new</i>	2 \$ 952.00	? } <input checked="" type="checkbox"/>
35	ATTACHMENTS PARTS <i>Not new</i>	\$ 105.00	? } <input checked="" type="checkbox"/>
36	WHEEL BEARING HOUSING <i>Not new</i>	\$ 995.00	? } <input checked="" type="checkbox"/>
37	SWIVEL JOINT <i>Not new</i>	\$ 166.00	? } <input checked="" type="checkbox"/>
38	SUSPENSION FORKS LH <i>Not new</i>	\$ 203.00	? } <input checked="" type="checkbox"/>
39	COUPLING ROD <i>Not new</i>	\$ 124.00	? } <input checked="" type="checkbox"/>
40	GAS SHOCK ABSORBER <i>Not new</i>	\$ 455.00	? } <input checked="" type="checkbox"/>
SUB-TOTAL SPARE PARTS		\$ 10,288.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	AXLE GUIDE LH <i>Neu</i>	\$ 802.00	?
42	WISHBONE UPPER LH <i>Neu</i>	\$ 524.00	?
43	REAR WHEEL BEARING HOUSING <i>Neu</i>	\$ 871.00	?
44	REAR WHEEL BEARING HOUSING ASSEMBLY <i>Neu</i>	\$ 394.00	?
45	TRACK ROD <i>Neu</i>	\$ 104.00	?
46	REAR GAS SHOCK ABSORBER <i>Neu</i>	\$ 448.00	?
47	SUNDRIES <i>Neu</i>	\$ 1,200.00	?
TOTAL SPARE PARTS		\$ 22,722.00	
TOTAL LABOUR CHARGES		\$ 11,224.00	
GRAND TOTAL		\$ 33,946.00	

36,709

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

36112.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 10/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1045/2018/GW 18-Sep-18 Glory 1 of 1 SKK 7409 X Audi A6 C7 2.0 TFSI Mu
--	---	--

Quantity	Description	Unit Price	Amount
Parts			
1	Engine Undershield Front <i>top</i>	\$ 550.00	✓ 440
2	Engine Undershield Rear <i>top</i>	\$ 550.00	✓ 440
3	Wheel Spoiler LHS <i>cracked</i>	\$ 232.00	✓ 161.00
4	Wheel Spoiler RHS <i>cracked</i>	\$ 232.00	✓ 161.00
5	Radiator Grille <i>cracked</i>	\$ 1,174.00	✓ 939.00
6	Front No Plate <i>new</i>	\$ 25.00	✓ 25
		\$ 2,763.00	
LABORS			
TOTAL		\$ 2,763.00	

For Premium Automobiles Pte Ltd

Adrian Ling


 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1045/2018/GW
Date : 10-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

8 days - ok - jb - 3 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Cher Hung Mong
Address : 31 Jalan Lokam
Singapore 537874
Telephone : HP +65 691783730
Type of Claim : OWN DAMAGE CLAIM
Policy No. : 2100349916-05
Vehicle No : **SKK 7409 X**
Model Code : Audi A6 C7 2.0 TFSI M u
Model / Year : Aug-13
Engine No : CDN 358816
Chassis No : WAUZZZ4FG2EN017804
Mileage : 119718 KM
Date In : 5-Sep-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Sep-18
Place of Accident : Seranggon Ave 1 Infront of St.Gabriel Sec Sch

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 7409 X

S/N	Nature of Jobs	Estimated Charges
1	Towing charges.	<i>waived.</i>
2	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and parking aid.	S/N \$ 480.00 \$ 480.00
3	To remove and transfer rear parking aid and rear kick sensor.	S/N \$ 360.00
4	To dismantle lhs front suspension. Inspect for damages and renew accordingly.	S/N \$ 1,800.00
5	To dismantle lhs rear suspension. Inspect for damages and renew accordingly.	S/N \$ 1,800.00
SUB LABOUR CHARGES		<u>\$ 4,440.00</u> <u>\$ 480.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 7409 X

S/N	Nature of Jobs		Estimated Charges		
				\$	480.00
6	To dismantle and renew front bumper, lhs side member trim and rear bumper. Reorganise front and rear crash management components. Reinstall all parts removed. (Added \$250.00 for side member trim and both engine sump guard)	c/f	\$ 2,800.00	\$	750.00
7	To respray front bumper, lhs side member trim and rear bumper.		\$ 2,800.00	\$	1,100.00
8	To remove and renew lhs rear exhaust silencer. Align to position.	S/N	\$ 480.00		
9	To renew lhs front and rear rims and tyres. To carry out wheel alignment .	S/N	\$ 320.00	\$	320.00
10	To carry out diagnostic checks	S/N	\$ 384.00	\$	192.00
TOTAL LABOUR CHARGES			\$ 11,224.00	\$	2,842.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			1,860.80
1	FRONT BUMPER	\$ 2,326.00	
2	FRONT BUMPER FIXING PARTS	\$ 236.00	
3	CLOSING ELEMENTS	\$ 163.00	
4	FRONT BUMPER SPOILER	\$ 216.00	
5	FRONT SPOILER FIXING PARTS	\$ 43.00	
6	FRONT AIR GUIDE GRILLE LH	\$ 134.00	
7	END CAP LH	\$ 34.00	
8	FRONT WHEEL HOUSING LINERS LH	\$ 246.00	
9	HOUSING LINERS ATTACHMENTS	\$ 68.00	
10	FRONT WHEEL SPOILER FRT LH	\$ 202.00	
11	STONE CHIP GUARD FRT LH	\$ 63.00	
12	ADHESIVE TAPE	\$ 49.00	
13	BRACKET FOR TRIM FRT LH	\$ 14.00	
14	SIDE MEMBER TRIM	\$ 752.00	\$ 601.60
15	ATTACHMENTS PARTS	\$ 105.00	\$ 83.36
16	REAR BUMPER	\$ 2,205.00	
17	REAR BUMPER FIXING PARTS	\$ 236.00	
18	REAR BUMPER SPOILER	\$ 301.00	
19	REAR BUMPER SECURING STRIPS	\$ 148.00	
20	ENGINE UNDERSHIELD FRT	\$ 550.00	
	SUB-TOTAL SPARE PARTS	\$ 8,091.00	\$ 2,545.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 2,545.76
21	ENGINE UNDERSHIELD REAR		\$ 550.00	
22	UNDERBODY TRIM FRT LH		\$ 128.00	
23	UNDERBODY TRIM LH		\$ 273.00	
24	UNDERBODY TRIM LH		\$ 168.00	
25	REAR SILENCER LH		\$ 1,157.00	
26	DUAL CLIPS	2	\$ 93.00	
27	TRIM FOR EXHAUST TAIL PIPE CHROME		\$ 497.00	
28	CLAMP		\$ 70.00	
29	ALUMINIUM RIM FRONT/ REAR LH	2	\$ 1,451.00	
30	RUBBER VALVE	8	\$ 23.00	
31	RADIAL TYRE FRONT / REAR LH	2	\$ 1,539.00	\$ 370.00
32	FRONT WISHBONE LINK FRT LH		\$ 476.00	
33	SUSPENSION GUIDE		\$ 863.00	
34	UPPER GUIDE FRT / REAR	2	\$ 952.00	
35	ATTACHMENTS PARTS		\$ 105.00	
36	WHEEL BEARING HOUSING		\$ 995.00	
37	SWIVEL JOINT		\$ 166.00	
38	SUSPENSION FORKS LH		\$ 203.00	
39	COUPLING ROD		\$ 124.00	
40	GAS SHOCK ABSORBER		\$ 455.00	
	SUB-TOTAL SPARE PARTS		\$ 10,288.00	\$ 2,915.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 2,915.76
41	AXLE GUIDE LH		\$ 802.00	
42	WISHBONE UPPER LH		\$ 524.00	
43	REAR WHEEL BEARING HOUSING		\$ 871.00	
44	REAR WHEEL BEARING HOUSING ASSEMBLY		\$ 394.00	
45	TRACK ROD		\$ 104.00	
46	REAR GAS SHOCK ABSORBER		\$ 448.00	
47	<i>Added parts - see attached</i>		\$ 2,736.00	\$ 2,166.60
48	SUNDRIES		\$ 1,200.00	
	TOTAL SPARE PARTS	:	\$ 25,458.00	\$ 5,082.36
	TOTAL LABOUR CHARGES	:	\$ 11,224.00	\$ 2,842.00
	GRAND TOTAL	:	\$ 36,682.00	\$ 7,924.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/1045/2018/GW
 18-Sep-18
 Johnny Boo
 one
 SKK7409X
 AUDI A6

Quantity	Description	Unit Price	Amount
Parts			
1	Engine Undershield Front	\$ 550.00	\$ 440.00
2	Engine undershield Rear	\$ 550.00	\$ 440.00
3	Wheel spoiler LHS/RHS	\$ 464.00	\$ 322.40
4	Radiator grille	\$ 1,174.00	\$ 939.20
5	Front No plate	\$ 25.00	\$ 25.00
	S/N		
		\$ 2,763.00	\$ 2,166.60
LABORS			
TOTAL		\$ 2,763.00	\$ 2,166.60

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 19 December 2018 11:40 AM
To: 'Boo seng yak'; Carrine Leong; jiyee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SKK7409X - OD AIG - SURVEYED 10 SEP 18

Dear Mr Boo,

Confirm repair cost of \$7,924.36 before excess \$800 and GST @ 8 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 3 December 2018 9:13 AM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKK7409X - OD AIG - SURVEYED 10 SEP 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$7924.36 @ 8 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKK 7409 X

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1045/2018/MAS

18 Jan 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SKK 7409 X, Audi A6 C7 2.0 TFSI Mu

With reference to the above-mentioned vehicle, no. **SKK 7409 X**, claimant, **Ms. Yu Pek Ling**, please find the related document per attached.

1. A copy of the Original invoice no. 85013360 – S\$7,623.07
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKK 7409 X

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 1 10:07

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408689
Telephone 6384 2923

Customer Service
Service Appointment 6366 2223
24 hour Breakdown Service 9628 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013360 Date : 08/01/2019 Order : SKK7409X Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKK7409X (V 21317) Regn Date: 27/00/2013 Mileage: 122647 WIP No.: 23698
Model: A6 C7 2.0 TFSI MU 4G207H (MY 1 Chassis: WAUZZZ4G2EN017804 Engine: CDN 358816 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND LHS SIDE MEMBER TRIM. REMOVE AND REINSTALL SIDE MEMBER TRIM AND ENGINE GUARDS. REORGANISE FRONT AND REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS SIDE MEMBER TRIM	1100.00	1.00	1,100.00

Sub-Total	
7% GST	
Grand Total	



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408699
Telephone: 6388 2223

Customer Service
Service Appointment: 6366 2323
24-hour Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 10:07

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013360 Date : 08/01/2019 Order : SKK7409X Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKK7409X (V 21317) Regn Date: 27/08/2013 Mileage: 122647 WIP No.: 23698
Model: A6 C7 2.0 TFSI MU 4G207H (MY 1 Chassis: WAUZZZ4G2EN017804 Engine: CDN 358816 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

	Details	Qty	Unit Price	Amount
S	BODYWORK M: TO RENEW LHS FRONT AND REAR TYRES. TO CARRY OUT WHEEL ALIGNMENT	320.00	1.00	320.00
S	BODYWORK M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Q	CON M: Less 50% Contribution of tire to be paid by owner \$740.00 x 50% = -\$370.00	-370.00	1.00	-370.00
X	IP225/55R17P7 PIRELLI CINTURATO P7	2.00	370.00	740.00
X	A4G00536S1 T94 GRILLE Less 020%	1.00	1174.00	939.20
X	A4G0053887C SPOILER Less 020%	1.00	201.50	161.20
X	A4G0053888C SPOILER Less 020%	1.00	201.50	161.20
X	A4G0063822J PAN Less 020%	1.00	550.00	440.00
X	A4G0063821F PAN Less 020%	1.00	550.00	440.00
X	A4G00538556 GRU 006446/(V) (SK) TRIM(1 Less 020%	1.00	752.00	601.60
X	A4G0007065A GRU COVER Less 020%	1.00	2325.00	1,860.00
X	A4G0098909A SECUR. SET Less 020%	1.00	13.70	10.96
X	A4G0098909 SECUR. SET Less 020%	1.00	90.50	72.40

Parts	5,427.36	Sub-Total	7,124.36
Labour	0.00	7% GST	498.71
Sublet	2,867.00	Grand Total	7,623.07
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKK 7409 X

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1045/2018/GW
22 September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI Mu
Vehicle Chassis No. : WAUZZZ4G2EN017804
Vehicle Regn No. : **SKK 7409 X**
Vehicle Mileage : 119718 KM
Vehicle Owner : Ms. Yu Pek Ling
Certificate No : 2100349916-05
Policy Excess : **S\$856.00(Inclusive GST)**
Accident Date : 04/09/2018
Place : **Serangoon Ave 1 Infront Of St. Gabriel Sec School**
Repair Cost : \$ 7,623.07
WIP No. : **23698**
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018		10 Sep 2018 14:36 Edit Adj Rpt	S\$7,924.36 Edit Estimates	S\$7,924.36 View Rpt		Pending for Survey Report Cancel Case

Main
Reference
Claim Details
Documents
Show All

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	YU PEK LING, ID: S2181389C, Tel: +6591783730			
Vehicle Reg. No.:	SKK7409X	Date of Loss:	04/09/2018 22:00 - :59 [60 Months and 8 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 1559503773SG	Policy/Cover Note No.:	2100349916-05 (Comprehensive)	
		Excess:	S\$800.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/09/2018]			
Driver/Custodian:	CHER HUNG MONG (59 / Male), NRIC: S1318484D, Tel: +6591783730			

- ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)
- AIG_SG (19/09/2018): Alert - Adj Mandate Approved (S\$10584.00) - SKK7409X - Claim Handler: Loo, Tong ...
 - AIG_SG (11/09/2018): Alert - Adj Mandate Approved (S\$7821.00) - SKK7409X - Claim Handler: Loo, Tong S...
 - AIG_SG (11/09/2018): SKK7409X / OD / 04/09/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKK7409X (1559503773SG)**
OD
Sep 4 2018 10:05PM
[YU PEK LING]
Premium Automobiles Pte Ltd

View

1 per page

Assessment Reports			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	11/09/18 10:18	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>
2	18/09/18 14:25	Adjuster Immediate Advice	Load HTM	<input checked="" type="checkbox"/>

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
20	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
21	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
22	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
23	11/09/18 09:07	General View	Load JPG	<input checked="" type="checkbox"/>
24	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	18/09/18 14:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	18/09/18 14:07	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/18 09:15	Singapore Accident Statement		Load PDF <input checked="" type="checkbox"/>
2	11/09/18 09:16	Certificate of Insurance		Load PDF <input checked="" type="checkbox"/>
3	11/09/18 09:16	Driver's Driving License		Load PDF <input checked="" type="checkbox"/>
4	11/09/18 09:16	MARK ESTIMATE		Load PDF <input checked="" type="checkbox"/>
5	18/09/18 14:16	1ST MARK ESTIMATE		Load PDF <input checked="" type="checkbox"/>
6	24/01/19 11:21	DISCHARGE VOUCHER		Load PDF <input checked="" type="checkbox"/>
7	24/01/19 11:21	SUPPLEMENTARY		Load PDF <input checked="" type="checkbox"/>
8	24/01/19 11:21	WORKSHOP INVOICE		Load PDF <input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/18 19:48	Accident Statement		Load HTM <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	05/09/18 19:47	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/18 18:39	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	05/09/18 18:39	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120Our File No: CC3/AIG18016430/AVBS2
Date: 24/01/2019

REFERENCE

Insured/Claimant: YU PEK LING Policy No: 2100349916-05
Date of Loss: 04/09/2018 Nature of Claim: OD Claim No: 1559503773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKK7409X Engine No: CDN358816
Make & Model: AUDI A6, 2.0 TFSI MU (A) Chassis No: WAUZZZ4G2EN017804
Reg. Date: 27/08/2013 (Man. Year: 2013) Odometer: 119718 km
Colour: Black
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,888.60	5,082.36	19,806.24	79.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,224.00	2,842.00	8,382.00	74.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,112.60	7,924.36	28,188.24	78.06
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	35,312.60	7,124.36	28,188.24	79.82
+ GST 7.00/7.00% (S\$)	2,471.88	498.71	1,973.17	79.82
Nett Amount (S\$)	37,784.48	7,623.07	30,161.41	79.82

INSPECTION

Date of Assignment: 10/09/2018
Date Inspected: 10/09/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,326.00 FS	*1,860.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	236.00 FS	*- FS
3	1		*CLOSING ELEMENTS	Not Necessary	163.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Not Necessary	216.00 FS	*- FS
5	1		*FRONT SPOILER FIXING PARTS	Not Necessary	43.00 FS	*- FS
6	1		*FRONT AIR GUIDE GRILLE LH	Not Necessary	134.00 FS	*- FS
7	1		*END CAP LH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINERS LH	Not Necessary	246.00 FS	*- FS
9	1		*HOUSING LINERS ATTACHMENTS	Not Necessary	68.00 FS	*- FS
10	1		*FRONT WHEEL SPOILER FRT LH	Not Necessary	202.00 FS	*- FS
11	1		*STONE CHIP GUARD FRT LH	Not Necessary	63.00 FS	*- FS
12	1		*ADHESIVE TAPE	Not Necessary	49.00 FS	*- FS
13	1		*BRACKET FOR TRIM FRT LH	Not Necessary	14.00 FS	*- FS
14	1		*SIDE MEMBER TRIM	Deformed	752.00 FS	*601.60 FS
15	1		*ATTACHMENTS PARTS	Necessary	105.00 FS	*83.36 FS
16	1		*REAR BUMPER	Not Necessary	2,205.00 FS	*- FS
17	1		*REAR BUMPER FIXING PARTS	Not Necessary	236.00 FS	*- FS
18	1		*REAR BUMPER SPOILER	Not Necessary	301.00 FS	*- FS
19	1		*REAR BUMPER SECURING STRIPS	Not Necessary	148.00 FS	*- FS
20	1		*ENGINE UNDERSHIELD FRT	Not Necessary	550.00 FS	*- FS
21	1		*ENGINE UNDERSHIELD REAR	Not Necessary	550.00 FS	*- FS
22	1		*UNDERBODY TRIM FRT LH	Not Necessary	128.00 FS	*- FS
23	1		*UNDERBODY TRIM LH	Not Necessary	273.00 FS	*- FS
24	1		*UNDERBODY TRIM LH	Not Necessary	168.00 FS	*- FS
25	1		*REAR SILENCER LH	Not Necessary	1,157.00 FS	*- FS
26	2		*DUAL CLIPS	Not Necessary	93.00 FS	*- FS
27	1		*TRIM FOR EXHAUST TAIL PIPE CHROME	Not Necessary	497.00 FS	*- FS
28	1		*CLAMP	Not Necessary	70.00 FS	*- FS
29	2		*ALUMINIUM RIM FRONT / REAR LH	Not Necessary	1,451.00 FS	*- FS
30	8		*RUBBER VALVE	Not Necessary	23.00 FS	*- FS
31	2		*RADIAL TYRE FRONT / REAR LH (@ \$740.00 DISC 50%)	Punctured	1,539.00 FS	*370.00 FS
32	1		*FRONT WISHBONE LINK FRT LH	Not Necessary	476.00 FS	*- FS
33	1		*SUSPENSION GUIDE	Not Necessary	863.00 FS	*- FS
34	2		*UPPER GUIDE FRT / REAR	Not Necessary	952.00 FS	*- FS
35	1		*ATTACHMENTS PARTS	Not Necessary	105.00 FS	*- FS
36	1		*WHEEL BEARING HOUSING	Not Necessary	995.00 FS	*- FS
37	1		*SWIVEL JOINT	Not Necessary	166.00 FS	*- FS
38	1		*SUSPENSION FORKS LH	Not Necessary	203.00 FS	*- FS
39	1		*COUPLING ROD	Not Necessary	124.00 FS	*- FS
40	1		*GAS SHOCK ABSORBER	Not Necessary	455.00 FS	*- FS
41	1		*AXLE GUIDE LH	Not Necessary	802.00 FS	*- FS
42	1		*WISHBONE UPPER LH	Not Necessary	524.00 FS	*- FS
43	1		*REAR WHEEL BEARING HOUSING	Not Necessary	871.00 FS	*- FS
44	1		*REAR WHEEL BEARING HOUSING ASSEMBLY	Not Necessary	394.00 FS	*- FS
45	1		*TRACK ROD	Not Necessary	104.00 FS	*- FS
46	1		*REAR GAS SHOCK ABSORBER	Not Necessary	448.00 FS	*- FS
47	1		*SUNDRIES	Not Necessary	1,200.00 FS	*- FS
48	1		*ENGINE UNDERSHIELD FRONT	Torn	440.00 FS	*440.00 FS
49	1		*ENGINE UNDERSHIELD REAR	Torn	440.00 FS	*440.00 FS
50	1		*WHEEL SPOILER LHS	Cracked	161.20 FS	*161.20 FS
51	1		*WHEEL SPOILER RHS	Cracked	161.20 FS	*161.20 FS

Report was unsubmitted during this print-out.

1/24/2019

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RADIATOR GRILLE	Cracked	939.20 FS	*939.20 FS
53	1		*FRONT NO PLATE	Necessary	25.00 FS	*25.00 FS
F=Franchise part. S=SpcNett.				Total Parts (S\$)	24,888.60	5,082.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES. (NPA)	New	0.00	0.00
2	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND PARKING AID.	New	480.00	480.00
3	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR KICK SENSOR.	New	360.00	0.00
4	TO DISMANTLE LHS FRONT SUSPENSION. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	New	1,800.00	0.00
5	TO DISMANTLE LHS REAR SUSPENSION. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	New	1,800.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS SIDE MEMBER TRIM AND REAR BUMPER. REORGANISE FRONT AND REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,800.00	750.00
7	TO RESPRAY FRONT BUMPER, LHS SIDE MEMBER TRIM AND REAR BUMPER.	New	2,800.00	1,100.00
8	TO REMOVE AND RENEW LHS REAR EXHAUST SILENCER, ALIGN TO POSITION.	New	480.00	0.00
9	TO RENEW LHS FRONT AND REAR RIMS AND TYRES. TO CARRY OUT WHEEL ALIGNMENT.	New	320.00	320.00
10	TO CARRY DIAGNOSTIC CHECKS.	New	384.00	192.00
Gross Labour Cost (S\$)			11,224.00	2,842.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >