

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6210D

MAKE :

MODEL : HYUNDAI #40

DATE : 5.05.2017

TEL : 6542 5119

FAX : 6542 6039 INDIA

To Be Survey By LKK (Ma)

Qty	Partis Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 294.35
	Radiator Grille H Emblem			\$ 113.65
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Bracket Top (L/R/H)			\$ 44.80
	Front Bumper Bracket (L/R/H)			\$ 49.20
	Front Bumper Retainer Mounting			\$ 18.40
	Front Bumper Clips 10 pcs			\$ 22.00
	Headlamp Support Top Cover			\$ 398.00
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (L/R/H)			\$ 2,776.00
	Radiator			\$ 1,388.00
	Radiator Fan Blade, Cowling, Motor Assy			\$ 850.20
	Radiator Bracket (R/H/DH)			\$ 792.95
	Radiator Guard			\$ 13.00
	Hom Unit (L/R/H)			\$ 70.00
	Hom Wire			\$ 173.50
	Aircon Condenser			\$ 156.50
	Inter Cooler			\$ 1,137.35
	Inter Cooler Mounting (2 PCS)			\$ 921.90
	Sub Total			\$ 10,155.80
	Less 20%			\$ 2,031.16
	Discounted Total			\$ 8,124.64
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
	Labour Charge			\$ 1,000.00
	Panel Beating			\$ 200.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 150.00
	Remove/Refix Aircon & Refill Gas			\$ 1,400.00
	TOTAL LABOUR			\$ 1,400.00

11/18 Plc provided. Close

107

LK

500
200.00
50.00
150.00

Nett 25.00
Nett 30.00

25.90

156.50

70.00

792.95

398.00

44.80

142.20

113.65