

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/1045/2018/GW  
**Date** : 10-Sep-18

**Vehicle IN workshop. Kindly arrange for survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Cher Hung Mong  
**Address** : 31 Jalan Lokam  
Singapore 537874  
**Telephone** : HP +65 691783730  
**Type of Claim** : OWN DAMAGE CLAIM  
**Policy No.** : 2100349916-05  
**Vehicle No** : **SKK 7409 X**  
**Model Code** : Audi A6 C7 2.0 TFSI M u  
**Model / Year** : Aug-13  
**Engine No** : CDN 358816  
**Chassis No** : WAUZZZ4FG2EN017804  
**Mileage** : 119718 KM  
**Date In** : 05-Sep-18  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 04-Sep-18  
**Place of Accident** : Seranggon Ave 1 Infront of St.Gabriel Sec Sch

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKK 7409 X

S/N	Nature of Jobs	Estimated Charges	
1	Towing charges.	<i>waived.</i>	✓
2	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and parking aid.	S/N \$ 480.00	✓
3	To remove and transfer rear parking aid and rear kick sensor.	S/N \$ 360.00	✗
4	To dismantle lhs front suspension. Inspect for damages and renew accordingly.	S/N \$ 1,800.00	?
5	To dismantle lhs rear suspension. Inspect for damages and renew accordingly.	S/N \$ 1,800.00	?
<b>SUB LABOUR CHARGES</b>		<b>\$ 4,440.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKK 7409 X

S/N	Nature of Jobs	Estimated Charges
6	To dismantle and renew front bumper, lhs side member trim and rear bumper. Reorganise front and rear crash management components. Reinstall all parts removed. ✓ ✓	\$ <del>2,800.00</del> 500
7	To respray front bumper, lhs side member trim and rear bumper. ✓	\$ <del>2,800.00</del> 1100
8	To remove and renew lhs rear exhaust silencer. Align to position.	S/N \$ 480.00 X
9	To renew lhs front and rear rims and tyres. To carry out wheel alignment .	S/N \$ 320.00 ✓
10	To carry out diagnostic checks	S/N \$ <del>384.00</del> 192
<b>TOTAL LABOUR CHARGES</b>		<b><u>\$ 11,224.00</u></b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
 Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>selhd</i>	\$ 2,326.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 236.00	+
3	CLOSING ELEMENTS ?	\$ 163.00	?
4	FRONT BUMPER SPOILER ?	\$ 216.00	?
5	FRONT SPOILER FIXING PARTS ?	\$ 43.00	?
6	FRONT AIR GUIDE GRILLE LH <i>new</i>	\$ 134.00	+
7	END CAP LH <i>new</i>	\$ 34.00	+
8	FRONT WHEEL HOUSING LINERS LH <i>not ?</i>	\$ 246.00	?
9	HOUSING LINERS ATTACHMENTS ?	\$ 68.00	?
10	FRONT WHEEL SPOILER FRT LH ?	\$ 202.00	?
11	STONE CHIP GUARD FRT LH ?	\$ 63.00	?
12	ADHESIVE TAPE ?	\$ 49.00	?
13	BRACKET FOR TRIM FRT LH <i>new</i>	\$ 14.00	+
14	SIDE MEMBER TRIM <i>selhd</i>	\$ 752.00	✓
15	ATTACHMENTS PARTS ?	\$ 105.00	?
16	REAR BUMPER <i>new</i>	\$ 2,205.00	+
17	REAR BUMPER FIXING PARTS <i>new</i>	\$ 236.00	+
18	REAR BUMPER SPOILER ?	\$ 301.00	?
19	REAR BUMPER SECURING STRIPS ?	\$ 148.00	?
20	ENGINE UNDERSHIELD FRT ?	\$ 550.00	?
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 8,091.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
 Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	ENGINE UNDERSHIELD REAR ?	\$ 550.00	?
22	UNDERBODY TRIM FRT LH ?	\$ 128.00	?
23	UNDERBODY TRIM LH ?	\$ 273.00	?
24	UNDERBODY TRIM LH ?	\$ 168.00	?
25	REAR SILENCER LH <i>Mean</i>	\$ 1,157.00	+
26	DUAL CLIPS <i>Mean</i>	2 \$ 93.00	+
27	TRIM FOR EXHAUST TAIL PIPE CHROME <i>Mean</i>	\$ 497.00	+
28	CLAMP <i>Mean</i>	\$ 70.00	+
29	ALUMINIUM RIM FRONT/ REAR LH <i>lit</i>	2 \$ 1,451.00	✓
30	RUBBER VALVE <i>Mean</i>	8 \$ 23.00	+
31	RADIAL TYRE FRONT / REAR LH <i>Punctured</i>	2 \$ <del>1,539.00</del>	700 (sn) 50% depreciation
32	FRONT WISHBONE LINK FRT LH ?	\$ 476.00	?
33	SUSPENSION GUIDE ?	\$ 863.00	?
34	UPPER GUIDE FRT / REAR ?	2 \$ 952.00	?
35	ATTACHMENTS PARTS ?	\$ 105.00	?
36	WHEEL BEARING HOUSING ?	\$ 995.00	?
37	SWIVEL JOINT ?	\$ 166.00	?
38	SUSPENSION FORKS LH ?	\$ 203.00	?
39	COUPLING ROD ?	\$ 124.00	?
40	GAS SHOCK ABSORBER ?	\$ 455.00	?
<b>SUB-TOTAL SPARE PARTS</b>		<b>\$ 10,288.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKK 7409 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	AXLE GUIDE LH ?	\$ 802.00	?
42	WISHBONE UPPER LH ?	\$ 524.00	?
43	REAR WHEEL BEARING HOUSING ?	\$ 871.00	?
44	REAR WHEEL BEARING HOUSING ASSEMBLY ?	\$ 394.00	?
45	TRACK ROD ?	\$ 104.00	?
46	REAR GAS SHOCK ABSORBER ?	\$ 448.00	?
47	SUNDRIES ?	\$ 1,200.00	?
<b>TOTAL SPARE PARTS</b>		<b>\$ 22,722.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 11,224.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 33,946.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian Lim*  
Surveyed Date : *10/09/18*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Not Authorised, 08 Days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant