

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	SLN 664 T	Nos Norhani
Parts (a) Cost / List Price Items	\$ 20,160.25	Pusing Bypains
Plus/Less25%_	\$ 5,040.06	7 17
Total of Cost / List	\$ 15,120.19	
(b) Nett Price Items Less		LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation
Total of Nett Item (c) Special Nett Items	\$ 45.00	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Total Parts Cost	\$ 15,165.19	Acknowledged by Repairer
Labour	\$ 2,950.00	Signature: Date:
Total	\$ 18,115.19	

Nar	me of Surveyor		Kennern
Cor	mpany	:	LKK
Sur	vey conducted on		17/9/18 at
	marks By Surveyor		
(a)	The repair of this vehicle is author	orized	/ is not authorized until further notice.
(b)	Recommended Days of Repair	:	day(s)
(c)	Resurvey	*	Required / Not Required
(d)	Excess	:\$_	
(e)	Signature of surveyor		Se Date: 17/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : Make & Model :

Chassis No

SLN 664 T

TOYOTA PRIUS

JTDKB3FU403556230

Submit By

Year Manufacture

Engine No.

Carmen Lim

2017

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	Ry	1	\$45.00	S.N	
2	Front number plate garnish	cm	1	\$129.00		
3	Bonnet	By	1	\$812.40		
4	Bonnet lock		1	\$130.00		7
5	Bonnet hinge LH	DIT	1	\$57.80		
6	Bonnet hinge RH		1	\$57.80		?
7	Front support panel centre		1	\$338.50		7
8	Front support panel LH		1	\$213.50		7
9	Front support panel RH		1	\$213.50		7
10	Headlamp panel LH		1	\$89.20		7
11	Headlamp panel RH		1	\$89.20		7
12	Support panel lower		1	\$387.95		7
13	Front support panel top garnish	In	1	\$285.40		X
14	Front support panel top garnish clip	nn	10	\$35.00		
15	Air duct		1	\$195.40		7
16	Air duct - inlet		1	\$109.75		7
17	Brace panel		1	\$105.20		7
18	Condenser	Sh	1	\$1,544.70		`X
19	Radiator	Su	1	\$1,841.80		X
20	Radiator fan motor RH	sn	1	\$455.70		X
21	Radiator fan motor LH	52	1	\$491.79		X
22	Radiator fan blade LH	sh	1	\$197.80		X
23	Radiator fan blade RH	in	1	\$219.80		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : Make & Model:

Chassis No :

SLN 664 T

TOYOTA PRIUS JTDKB3FU403556230

Submit By

Year Manufacture : Engine No.

Carmen Lim

2017

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan cowling	Sin	1	\$287.67		×
25	Headlamp LH	ngin	1	\$2,531.60		
26	Headlamp RH		1	\$2,531.60		7
27	Front bumper	Bu	1	\$450.80		
28	Front bumper clip	m	10	\$40.00		
29	Front bumper reinforcement - upper	3	1	\$711.50		
30	Front bumper reinforcement - lower		1	\$245.30		7
31	Front bumper side retainer RH	Pi	1	\$107.20		
32	Front bumper side retainer LH	0,1	1	\$107.20		
33	Front bumper upper grille	Dir	1	\$321.90		_
34	Front bumper lower grille	ent	1	\$148.60		_
35	Front bumper emblem	nx	1	\$87.10		_
36	Front bumper tow cover RH	P2	1	\$25.70		X
37	Front bumper tow cover LH	Sn	1	\$25.70		×
38	Front bumper sponge - upper		1	\$89.81		7
39	Front bumper sponge - lower		1	\$135.70		7
40	Fog lamp LH	Sn.	1	\$910.70		×
41	Fog lamp RH	Su	1	\$910.70		X
42	Engine under cover		1	\$198.30		?
43	Engine under cover clip		10	\$35.00		7
44	RH front fender	R	1	\$868.70		X
45	RH front fender undershield	Sh	1	\$185.64		<
46	RH front fender undershield clip	na	10	\$25.00		×

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Ve	hic	е	No.	

Make & Model: Chassis No

SLN 664 T

TOYOTA PRIUS JTDKB3FU403556230

Submit By

Year Manufacture :

Carmen Lim

2017

Engine No. Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RHF fender wording "HYBRID"	1	\$44.17		
48	LH front fender	1	\$868.70		×
49	LH front fender undershield	1	\$195.60		×
50	LH front fender undershield clip	10	\$25.00		X
51	LHF fender wording "HYBRID"	. 1	\$44.17		
52		1			
53		1			
54		1			
55		1			
56		1			
57		1			
58		1			
59		6			
60		1			
61		1			
62		1			
63		1			
64		1			
65		1			
66		1			
67		1			
68		1			
69		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	: _	SLN 664 T	Submit By	:	Carmen Lim	
Make & Model	: _	TOYOTA PRIUS	JS Year of Manufacture		2017	
S/No		Labour Description		Fsimate	h Adjusted	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT	1 1100	7 1100
	REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL,		
	LHF FENDER,RHF FENDER) 500 - 700	\$1,400.00	?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL,		0
	LHF FENDER,RHF FENDER)	\$1,200.00	8001
3	To check wiring & focus headlamp	\$50.00	201
4	To remove & refit radiator, condenser to assist work load,		
	to top up A/C gas.	\$150.00	?
5	To tuff coat (30)	\$150.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.