

AAA-LKK
Monday @ 17/9/18.

K&P.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 664 T

Parts	(a) Cost / List Price Items	\$	20,160.25
	Plus/Less 25%	\$	5,040.06
	Total of Cost / List	\$	15,120.19
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	15,165.19
Labour		\$	2,950.00
Total		\$	18,115.19

The above total will be subjected to 7% G.S.T.

Finalised.

8175.04

7031.76

6093.78

45

6138.78

1370

7458.78

Not Authorized
Resurvey By paint

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

✓ ok

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

17/9/18

at 11:30

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 05-4 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Sc

Date: 17/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLN 664 T
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU403556230

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>R</i>	1	\$45.00	✓ S.N	✓
2	Front number plate garnish <i>CM</i>	1	\$129.00	✓	✓
3	Bonnet <i>R</i>	1	\$812.40	✓	✓
4	Bonnet lock <i>R</i>	1	\$130.00		X
5	Bonnet hinge LH <i>DIT</i>	1	\$57.80	✓	✓
6	Bonnet hinge RH <i>R</i>	1	\$57.80		X
7	Front support panel centre <i>R</i>	1	\$338.50		X
8	Front support panel LH <i>R</i>	1	\$213.50		X
9	Front support panel RH <i>R</i>	1	\$213.50		X
10	Headlamp panel LH <i>R</i>	1	\$89.20		X
11	Headlamp panel RH <i>R</i>	1	\$89.20		X
12	Support panel lower <i>R</i>	1	\$387.95		X
13	Front support panel top garnish <i>Sh</i>	1	\$285.40		X
14	Front support panel top garnish clip <i>nn</i>	10	\$35.00		X
15	Air duct <i>Sh</i>	1	\$195.40		X
16	Air duct - inlet <i>Sh</i>	1	\$109.75		X
17	Brace panel <i>R</i>	1	\$105.20		X
18	Condenser <i>Sh</i>	1	\$1,544.70		X
19	Radiator <i>Sh</i>	1	\$1,841.80		X
20	Radiator fan motor RH <i>Sh</i>	1	\$455.70		X
21	Radiator fan motor LH <i>Sh</i>	1	\$491.79		X
22	Radiator fan blade LH <i>Sh</i>	1	\$197.80		X
23	Radiator fan blade RH <i>Sh</i>	1	\$219.80		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

999.10
45 (S.N)

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 664 T

TOYOTA PRIUS

JTDKB3FU403556230

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan cowling <i>Sn</i>	1	\$287.67		X
25	Headlamp LH <i>Mt M</i>	1	\$2,531.60 ✓		✓
26	Headlamp RH <i>Mt M</i>	1	\$2,531.60 ✓		✓
27	Front bumper <i>Bu</i>	1	\$450.80 ✓		✓
28	Front bumper clip <i>mc</i>	10	\$40.00 ✓		✓
29	Front bumper reinforcement - upper <i>Bu</i>	1	\$711.50 ✓		✓
30	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		R
31	Front bumper side retainer RH <i>Dis</i>	1	\$107.20 ✓		✓
32	Front bumper side retainer LH <i>Dis</i>	1	\$107.20 ✓		✓
33	Front bumper upper grille <i>Dis</i>	1	\$321.90 ✓		✓
34	Front bumper lower grille <i>cmf</i>	1	\$148.60 ✓		✓
35	Front bumper emblem <i>RA</i>	1	\$87.10 ✓		✓
36	Front bumper tow cover RH <i>Sn</i>	1	\$25.70		X
37	Front bumper tow cover LH <i>Sn</i>	1	\$25.70		X
38	Front bumper sponge - upper <i>Sn</i>	1	\$89.81		R
39	Front bumper sponge - lower <i>Sn</i>	1	\$135.70		R
40	Fog lamp LH <i>Sn</i>	1	\$910.70		X
41	Fog lamp RH <i>Sn</i>	1	\$910.70		X
42	Engine under cover <i>Sn</i>	1	\$198.30		R
43	Engine under cover clip <i>Sn</i>	10	\$35.00		R
44	RH front fender <i>R</i>	1	\$868.70		X
45	RH front fender undershield <i>Sn</i>	1	\$185.64		✓
46	RH front fender undershield clip <i>Sn</i>	10	\$25.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

7037.50

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 664 T

TOYOTA PRIUS
JTDKB3FU403556230

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim**2017****Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	RHF fender wording "HYBRID" <i>na</i>	1	\$44.17 ✓		✓
48	LH front fender <i>B</i>	1	\$868.70		X
49	LH front fender undershield <i>na</i>	1	\$195.60		X
50	LH front fender undershield clip <i>na</i>	10	\$25.00		X
51	LHF fender wording "HYBRID" <i>na</i>	1	\$44.17 ✓		✓
52		1			
53		1			
54		1			
55		1			
56		1			
57		1			
58		1			
59		6			
60		1			
61		1			
62		1			
63		1			
64		1			
65		1			
66		1			
67		1			
68		1			
69		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

88.34



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempart.com.sg

Vehicle No. : SLN 664 T Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.