SG MOTOR ENTERPRISE

4001, Ang Mo Klo Industrial Park 1 #01-21 SINGAPORE 569622 Tel: 6452 4898 Fax: 6452 4868 Email: sg_motor_enterprise@yahoo.com.sg

DATE: 12 August 2015

To : LKK

By Fax: 6256 4315

2 Days

Attn: Guo Qiang Tel: 82880262

VEHICLE NO : FBF 4177S

ACCIDENT DATE: 31 July 2015

RS 125

	Description	Qty	Quotation \$
1	Side LH Fairing / Cut	1	350.00
2	Handle Bar / 6	1	185 00
3	Clutch Leve : Cut	1	18500 48
4	RS Sticker / McC	1	200.00 50 (SN)
		Sub-Total ·	860.00 583
		Less 10%	86.00
		Sub-Total	774.00 524.7
	Nett items		
1	Respray paint matt black		250.00 120
2	Labour to remove & replace parts, align etc		200.00 60
		Sub-Total	450.00
		Nett Total	1,224.00 754.7
	NB: This estimate was made from a visual	7	20%: 600

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly,

Kindly revert upon completion

hank you

SG MOTOR ENTERPRISE

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

185. 48° = 583° * 583° × 90 % 524.7 * 50 . . + 50 * L/s-\$600 120 0 + 60° = 180° * 524.7 + 180 -= 754.7 * 80. 0.0