



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
6 Benoi Place Singapore 629927  
Tel: 6861 0908 Fax: 6515 2948

Date: 08.09.2018

AXA Insurance Singapore Pte Ltd  
8 Shenton Way #27-01/02  
AXA Tower  
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2829Y TOYOTA VELLFIRE HYBRID (2012)

## To Supply

1 ) 1pc	Rear bumper	\$	1,050.00 <del>DE</del>
2 ) 1set	Rear bumper clip	\$	30.00 <del>me</del>
3 ) 1pc	Rear bumper right retainer	\$	? 130.00 <del>me</del>
4 ) 1pc	Rear bumper right reflector	\$	90.00 <del>CR</del>
5 ) 1pc	Right reverse sensor	\$	290.00 <del>cut</del>
6 ) 1pc	Right reverse sensor cover	\$	25.00 <del>me</del>

Sub total parts	\$	1,615.00
Less: 25% discount	\$	(403.75)
	\$	1,211.25

## L/charges

1 ) To remove & refit right reverse sensor. Check wiring.	\$	40.00
2 ) To remove rear bumper. To knock end panel. Replace rear bumper. Align & adjust rear bumper.	\$	<del>350.00</del> 300
3 ) To putty, respray painting rear bumper & end panel. To polish.	\$	<del>400.00</del> 300

Sub total L/charges	\$	790.00
Estimated Grand total	\$	2,001.25

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
Hp 90010068  
3 days  
P/P  
16/09/18 @ 1740  
Resurvey BP paint