

REF:

ASSIGNMENT

TIDR:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s:

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bail or Market Value:

IDAC Accident Report:

Consistent? - Yes or No

GIA / PR Seen:

Consistent? - Yes or No

Est. Repairs:

5

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLP 7242X

Yr Reg: 2017 June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q2

cc. 999

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

3048

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAF2226AG1HA 0221/8

Gen. Cond: Good / Fair / Poor / BurntSteering: Indolent / Jammed / Leaked / Burnt orBrake: Indolent / Jammed / Leaked / Burnt orMod: Nil / SRim / STD A/Rim or

Tyre Size:

F: 215/55R17

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

13/04/18

Survey held at:

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP mslg

RECEIVED 1 MAY 2018

Date/Time: File Place for



Preli. Report



Final Report

11/5/18

Date/Time: File Return for

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp: 15



Interview: 15



Tech. Insp: 15



Workshop: 15

Survey Fee:

Transportation:

F: 150

F: 150

F: 150

F: 150

100
10

210

Report Furnish

Lump Sum / L.I.P. /

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 20 February 2020 4:23 PM
To: Carrine Leong
Cc: 'Boo seng yak'; jiajee.yap@premiumauto.com.sg; SUR; 'Premiumauto Claims'
Subject: RE: FINAL REVISION - SLP7242X - TP MSIG - SURVEYED 13 SEP 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$11,709.60 before GST and 5 repair days.

Kindly send the relevant documents to MSIG Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Wednesday, 19 February 2020 5:27 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; jiajee.yap@premiumauto.com.sg; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; 'Premiumauto Claims' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLP7242X - TP MSIG - SURVEYED 13 SEP 18

Hi Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you 31 Dec 2019.

We sincerely appreciate your early closure.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1046/2018/PH
Date	:	10-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SJO 8291 R

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name	:	Ms Anila Mawar Rahaedja
Address	:	8 Scotts Road
	:	#13-02
	:	Singapore 228238
Telephone	:	HP +65 91592581
Type of Claim	:	Third party claims
Policy No.	:	
Vehicle No	:	SLP 7242 X
Model Code	:	Audi Q2 1.0 TFSI
Model / Year	:	Jun-17
Engine No	:	CHZ 300978
Chassis No	:	WAUZZZGA6HA022118
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Sep-18
Place of Accident	:	ECP

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7242 X.

29

S/N	Nature of Jobs		Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 ✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00 ✓
3	To renew rear windscreen for rear lid renewal.	S/N \$	480.00 ✓
4	To dismantle and renew rear bumper and rear lid. Reorganise rear crash management components. Reinstall all parts removed.	\$	2,100.00 1200 ✓
5	To respray rear bumper, rear lower spoiler, both rear wheel arc covers and rear lid.	\$	2,800.00 2600 ✓
6	To carry out diagnostic check	S/N \$	192.00 ✓
LABOUR CHARGES		:	<u>\$ 6,132.00</u>

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Deformed</i>	\$ 1,016.00	✓
2	FIXING PARTS FOR REAR BUMPER <i>new</i>	\$ 66.00	x
3	REAR BUMPER CENTRE COVER <i>Deformed</i>	\$ 671.00	✓ 670.50
4	TRIM WHEEL HOUSING LINER - LH/RH <i>new</i>	2 \$ 46.00	? x
5	REAR BUMPER LOWER SPOILER <i>Deformed</i>	\$ 502.00	✓ 501.50
6	COVER FOR REAR BUMPER TOWING EYE <i>new</i>	\$ 20.00	x
7	REAR LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$ 52.00	x
8	REAR BUMPER CARRIER <i>new</i>	\$ 480.00	? x
9	REAR END PANEL HOLDING STRAP - LH/RH <i>new</i>	2 \$ 22.00	x
10	GUIDE SECTION - LH/RH <i>new</i>	2 \$ 92.00	x
11	SENSOR - OUTER <i>new</i>	\$ 211.00	x
12	SENSOR - INNER <i>new</i>	2 \$ 421.00	x
13	REAR LID <i>Dented</i>	\$ 2,106.00	✓
14	ATTACHMENT PARTS FOR REAR LID <i>new</i>	\$ 103.00	? x
15	REAR BOOT LOCK STRIKER <i>new</i>	\$ 254.00	x
16	REAR BOOT LID WEATHERSTRIP SEAL <i>new</i>	\$ 101.00	x
17	REAR LID LOCK	\$ 188.00	x
18	REAR LID LOCK COVER	\$ 10.00	x
19	REAR LID PUSH BUTTON LOCK ACTUATOR	\$ 159.00	x
20	REAR BOOT LID LICENCE PLATE TRIM	\$ 204.00	x
SUB TOTAL SPARE PARTS		\$ 6,724.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR BOOT LID AUDI LOGO	\$	108.00 ✓ 107.50
22	Q2' EMBLEM	\$	83.00 ✓ 82.70
23	TFSI' EMBLEM	\$	83.00 ✓ 82.70
24	REAR WINDSCREEN	\$	679.00 ✓ 678.50
25	PRIMER	2 \$	38.00 ✓ 36.40
26	REAR WHEEL COVER - LH/RH	2 \$	794.00 ✓ 793
27	FIXING PARTS FOR REAR BUMPER SPOILER	\$	117.00 ? X
28	CAR PLATE - REAR	S/N \$	25.00 ✓ X
29	REAR WINDSCREEN SEALANT	S/N \$	200.00 ✓
30	SUNDRIES	\$	300.00 ? 2.80 ✓
TOTAL SPARE PARTS		:	\$ 9,151.00
TOTAL LABOUR CHARGES		:	\$ 6,132.00
GRAND TOTAL		:	\$ 15,283.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan hary
Surveyed Date : 13/09/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised 05 days


14/9/18

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1046/2018/PH
Date : 10-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SJQ 8291 R

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Hi Adrian,
5 days ok - Carrine

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Road
Singapore 159090
Telephone : HP +65 91592581
Type of Claim : Third party claims
Policy No. :
Vehicle No : **SLP 7242 X**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Jun-17
Engine No : CHZ 300978
Chassis No : WAUZZZGA6HA022118
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Sep-18
Place of Accident : ECP

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7242 X.

29

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid. Check function and renew according to damage	S/N	\$	280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$	280.00	\$ 280.00
3	To renew rear windscreen for rear lid renewal.	S/N	\$	480.00	\$ 480.00
4	To dismantle and renew rear bumper and rear lid. Reorganise rear crash management components. Reinstall all parts removed		\$	2,100.00	\$ 1,200.00
5	To respray rear bumper, rear lower spoiler, both rear wheel arc covers and rear		\$	2,800.00	\$ 2,600.00
6	To carry out diagnostic check	S/N	\$	192.00	\$ 192.00
7	Supplementary Estimate 1		\$	400.00	\$ 400.00
LABOUR CHARGES		:	\$	6,132.00	\$ 5,432.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (N) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,016.00	\$ 1,016.00
2	FIXING PARTS FOR REAR BUMPER	\$ 66.00	
3	REAR BUMPER CENTRE COVER	\$ 671.00	\$ 670.50
4	TRIM WHEEL HOUSING LINER - LH/RH	2 \$ 46.00	
5	REAR BUMPER LOWER SPOILER	\$ 502.00	\$ 501.50
6	COVER FOR REAR BUMPER TOWING EYE	\$ 20.00	
7	REAR LIGHT REFLECTOR - LH/RH	2 \$ 52.00	
8	REAR BUMPER CARRIER	\$ 480.00	
9	REAR END PANEL HOLDING STRAP - LH/RH	2 \$ 22.00	
10	GUIDE SECTION - LH/RH	2 \$ 92.00	
11	SENSOR - OUTER	\$ 211.00	
12	SENSOR - INNER	2 \$ 421.00	
13	REAR LID	\$ 2,106.00	\$ 2,106.00
14	ATTACHMENT PARTS FOR REAR LID	\$ 103.00	
15	REAR BOOT LOCK STRIKER	\$ 254.00	
16	REAR BOOT LID WEATHERSTRIP SEAL	\$ 101.00	
17	REAR LID LOCK	\$ 188.00	
18	REAR LID LOCK COVER	\$ 10.00	
19	REAR LID PUSH BUTTON LOCK ACTUATOR	\$ 159.00	
20	REAR BOOT LID LICENCE PLATE TRIM	\$ 204.00	
SUB TOTAL SPARE PARTS		\$ 6,724.00	\$ 4,294.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		b/f	\$ 4,294.00
21	REAR BOOT LID AUDI LOGO	\$ 108.00	\$ 107.50
22	Q2' EMBLEM	\$ 83.00	\$ 82.70
23	TFSI' EMBLEM	\$ 83.00	\$ 82.70
24	REAR WINDSCREEN	\$ 679.00	\$ 678.50
25	PRIMER	2 \$ 38.00	\$ 36.40
26	REAR WHEEL COVER - LH/RH	2 \$ 794.00	\$ 793.00
27	FIXING PARTS FOR REAR BUMPER SPOILER	\$ 117.00	
28	CAR PLATE - REAR	S/N \$ 25.00	
29	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
30	SUNDRIES	\$ 300.00	\$ 2.80
	TOTAL SPARE PARTS	: \$ 9,151.00	\$ 6,277.60
	TOTAL LABOUR CHARGES	: \$ 6,132.00	\$ 5,432.00
	GRAND TOTAL	: \$ 15,283.00	\$ 11,709.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1046/2018/PH 14-Sep-18 Jeffery Tan 1 SLP 7242 X Audi Q2 1.0 TFSI
Quantity	Description	Unit Price	Amount
LABORS			
1	To install rear solar film (Special Net) <i>See</i>	\$ 400.00	\$ 400.00
TOTAL		\$ 400.00	\$400.00

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016457/AQD3N2
Date: 25/02/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80457711QMX
Claimant Vehicle No :	SLP7242X	Insured Vehicle No :	SJQ8291R
Date of Loss:	05/09/2018	Nature of Claim:	TP
		Claim No:	569619

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7242X	Engine No:	CHZ300978
Make & Model:	AUDI Q2, 999cc TFSI S-TRONIC (A)	Chassis No:	WAUZZZGA6HA022118
Reg. Date:	15/06/2017 (Man. Year: 2017)	Odometer:	8048 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,551.00	6,677.60	2,873.40	30.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,132.00	5,032.00	1,100.00	17.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,683.00	11,709.60	3,973.40	25.34
+ GST 7.00/7.00% (S\$)	1,097.81	819.67	278.14	25.34
Nett Amount (S\$)	16,780.81	12,529.27	4,251.54	25.34

INSPECTION

Date of Assignment:	10/09/2018		
Date Inspected:	13/09/2018	Inspected At:	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Feb 2020)	
Parts:	N/A	AUDI Q2 999cc TFSI S-TRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7242X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,016.00 FS	*1,016.00 FS
2	1		*FIXING PARTS FOR REAR BUMPER	Not Necessary	66.00 FS	*- FS
3	1		*REAR BUMPER CENTRE COVER	Deformed	671.00 FS	*670.50 FS
4	2		*TRIM WHEEL HOUSING LINER-LH/RH	Not Necessary	46.00 FS	*- FS
5	1		*REAR BUMPER LOWER SPOILER	Deformed	502.00 FS	*501.50 FS
6	1		*COVER FOR REAR BUMPER TOWING EYE	Not Necessary	20.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	52.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	480.00 FS	*- FS
9	2		*REAR END PANEL HOLDING STRAP-LH/RH	Not Necessary	22.00 FS	*- FS
10	2		*GUIDE SECTION-LH/RH	Not Necessary	92.00 FS	*- FS
11	1		*SENSOR-OUTER	Not Necessary	211.00 FS	*- FS
12	2		*SENSOR-INNER	Not Necessary	421.00 FS	*- FS
13	1		*REAR LID	Dented	2,106.00 FS	*2,106.00 FS
14	1		*ATTACHMENT PARTS FOR REAR LID	Not Necessary	103.00 FS	*- FS
15	1		*REAR BOOT LOCK STRIKER	Not Necessary	254.00 FS	*- FS
16	1		*REAR BOOT LID WEATHERSTRIP SEAL	Not Necessary	101.00 FS	*- FS
17	1		*REAR LID LOCK	Not Necessary	188.00 FS	*- FS
18	1		*REAR LID LOCK COVER	Not Necessary	10.00 FS	*- FS
19	1		*REAR LID PUSH BUTTON LOCK ACTUATOR	Not Necessary	159.00 FS	*- FS
20	1		*REAR BOOT LID LICENCE PLATE TRIM	Not Necessary	204.00 FS	*- FS
21	1		*REAR BOOT LID AUDI LOGO	Necessary	108.00 FS	*107.50 FS
22	1		*Q2 EMBLEM	Necessary	83.00 FS	*82.70 FS
23	1		*TFSI EMBLEM	Necessary	83.00 FS	*82.70 FS
24	1		*REAR WINDSCREEN	Necessary	679.00 FS	*678.50 FS
25	2		*PRIMER	Necessary	38.00 FS	*36.40 FS
26	2		*REAR WHEEL COVER-LH/RH	Necessary	794.00 FS	*793.00 FS
27	1		*FIXING PARTS FOR REAR BUMPER SPOILER	Not Necessary	117.00 FS	*- FS
28	1		*CAR PLATE-REAR	Not Necessary	25.00 FS	*- FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
30	1		*SUNDRIES	Necessary	300.00 FS	*2.80 FS
31	1		*TO INSTALL REAR SOLAR FILM	Necessary	400.00 FS	*400.00 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$)	9,551.00	6,677.60
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN FOR REAR LID RENEWAL	New	480.00	480.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,200.00
5	TO RESPRAY REAR BUMPER,REAR LOWER SPOILER,BOTH REAR WHEEL ARC COVERS AND REAR LID	New	2,800.00	2,600.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,132.00	5,032.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >