

ASS. REC. BY:

REF: cslMSG18016457 / Aq d3 n2
Special Instruction:Survivor
Meimien

ASSIGNMENT (Office)

From (Person): Monica Chung of MSIG Date/Time: 10/9/18 9:45am

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 81P 7242X Insured: SJQ 8291R

at Workshop m/s Premium Automobile Tel: 6388 2223

of 281 Alexandra Level B2

Policy No: A80457711 QMX Claim No: 569619

Sum Insured: Excess:

Make of Veh: D.O.A. 05/09/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement:

Date/Time: 10:48 pm @ 10/9/18 Person Contacted: Kee Siang Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	81P 7242X - X
14/9/18 @ 3:14pm	revised to Monica Chung via meimien.
23/5/19	Submit pract. report.

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum. Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP7242X - Yr Regn: 2017 / JuneType: M. Cap / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2 C.C. 999.Colour: Grey. A/C: Insured / Std / NI / NASp. Reading: 8048. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ6A61HA 022118Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17.R: 215/55R17.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 13/09/18.Survey held at Premium.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

T7 ms16.

RECEIVED 23 MAY 2019

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$))

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS, St

) Photos

) Others

TOTAL

100

10

210

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 14 Sep 2018

Preliminary Advice

Insured Vehicle No	: SJQ8291R	Accident Date	: 05/09/2018
TP Vehicle No	: SLP7242X	Assignment Date	: 10/09/2018
Make	: AUDI Q2	Est. Duration of Repair	: 5.00
Date of Inspection	: 13/09/2018		
Inspection At	: PREMIUM AUTOMOBILES PTE LTD - ALEXANDRA (HQ) 281 ALEXANDRA PTE LTD, LEVEL B2 SINGAPORE 159938		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,283.00
Revised Amount	:S\$	11,337.00
Check Items (Estimated)	:S\$	1,046.00
Total	:S\$	12,383.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Sep 2018		10 Sep 2018 09:45 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SHI LINGXING, ID: G1315787T, Tel: +6585537302, Email: LING-XING.SHI@AGILENT.COM		
Main Claimant:	PREMIUM LEASING PTE LTD, Co. Reg. No.: 201009676M		
Vehicle Reg. No.:	SLP7242X	Date of Loss:	05/09/2018 08:00 - :59 [14 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569619	Policy/Cover Note No.:	A80457711QMX (Comprehensive) Coverage: 27/05/2018 - 26/05/2019
Vehicle Reg. No. (Insured):	SJQ8291R	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2, 159938 Alexandra - Tel: 63882233		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/09/2018]		
Driver/Custodian (Insured):	SHI LINGXING (28 / Female), NRIC: G1315787T, Tel: +6585537302		
Adj Asg. Remarks:	on WP. LIABILITY : 100% Please appoint LKK AUTO to conduct the survey . Kindly contact MR KEE SIANG @ 6388 2223 to arrange for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1046/2018/PH
Date : 10-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SJQ 8291 R

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Ms Anila Mawar Rahaedja
Address : 8 Scotts Road
: #13-02
Singapore 228238
Telephone : HP +65 91592581
Type of Claim : Third party claims
Policy No. :
Vehicle No : **SLP 7242 X**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Jun-17
Engine No : CHZ 300978
Chassis No : WAUZZZGA6HA022118
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Sep-18
Place of Accident : ECP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7242 X.

29

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓
3	To renew rear windscreen for rear lid renewal.	S/N \$ 480.00 ✓
4	To dismantle and renew rear bumper and rear lid. Reorganise rear crash management components. Reinstall all parts removed.	\$ 2,100.00 1200
5	To respray rear bumper, rear lower spoiler, both rear wheel arc covers and rear lid.	\$ 2,800.00 2600. 600 ✓ 600 ✓ 300 + 300 = 600 ✓ 800
6	To carry out diagnostic check	S/N \$ 192.00 ✓
LABOUR CHARGES		: \$ <u>6,132.00</u>

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Deformed</i>	\$ 1,016.00	✓
2	FIXING PARTS FOR REAR BUMPER <i>new</i>	\$ 66.00	x
3	REAR BUMPER CENTRE COVER <i>Deformed</i>	\$ 671.00	✓
4	TRIM WHEEL HOUSING LINER - LH/RH <i>new ?</i>	2 \$ 46.00	new ?
5	REAR BUMPER LOWER SPOILER <i>Deformed</i>	\$ 502.00	✓
6	COVER FOR REAR BUMPER TOWING EYE <i>new</i>	\$ 20.00	x
7	REAR LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$ 52.00	x.
8	REAR BUMPER CARRIER <i>new ?</i>	\$ 480.00	?
9	REAR END PANEL HOLDING STRAP - LH/RH <i>new</i>	2 \$ 22.00	x
10	GUIDE SECTION - LH/RH <i>new</i>	2 \$ 92.00	x
11	SENSOR - OUTER <i>new sec.</i>	\$ 211.00	x
12	SENSOR - INNER	2 \$ 421.00	x.
13	REAR LID <i>Dented.</i>	\$ 2,106.00	✓
14	ATTACHMENT PARTS FOR REAR LID <i>?</i>	\$ 103.00	?
15	REAR BOOT LOCK STRIKER <i>new</i>	\$ 254.00	x
16	REAR BOOT LID WEATHERSTRIP SEAL <i>new</i>	\$ 101.00	x
17	REAR LID LOCK	\$ 188.00	x
18	REAR LID LOCK COVER	\$ 10.00	x
19	REAR LID PUSH BUTTON LOCK ACTUATOR <i>new</i>	\$ 159.00	x
20	REAR BOOT LID LICENCE PLATE TRIM	\$ 204.00	x.
SUB TOTAL SPARE PARTS		\$ 6,724.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7242 X.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR BOOT LID AUDI LOGO	\$	108.00 ✓
22	Q2' EMBLEM	\$	83.00 ✓
23	TFSTI' EMBLEM	\$	83.00 ✓
24	REAR WINDSCREEN <i>new</i>	\$	679.00 ✓
25	PRIMER <i>new</i>	2 \$	38.00 ✓
26	REAR WHEEL COVER - LH/RH <i>new</i>	2 \$	794.00 ✓
27	FIXING PARTS FOR REAR BUMPER SPOILER ?	\$	117.00 ?
28	CAR PLATE - REAR <i>Dented</i>	S/N \$	25.00 ✓
29	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00 ✓
30	SUNDRIES ?	\$	300.00 ?
TOTAL SPARE PARTS		:	\$ 9,151.00
TOTAL LABOUR CHARGES		:	\$ 6,132.00
GRAND TOTAL		:	\$ 15,283.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Telefax

Name

: Adrian Heng

Surveyed Date

: 13/09/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised ASDays


14/9/18

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016457/AQD3N2

Date: 24/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80457711QMX
Claimant Vehicle No :	SLP7242X	Insured Vehicle No :	SJQ8291R
Date of Loss:	05/09/2018	Nature of Claim:	TP
		Claim No:	569619

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7242X	Engine No:	CHZ300978
Make & Model:	AUDI Q2, 999cc TFSI S-TRONIC (A)	Chassis No:	WAUZZZGA6HA022118
Reg. Date:	15/06/2017 (Man. Year: 2017)	Odometer:	8048 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,151.00	6,305.00	2,846.00	31.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,132.00	5,032.00	1,100.00	17.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,283.00	11,337.00	3,946.00	25.82
+ GST 7.00/7.00% (S\$)	1,069.81	793.59	276.22	25.82
Nett Amount (S\$)	16,352.81	12,130.59	4,222.22	25.82

INSPECTION

Date of Assignment: 10/09/2018

Date Inspected: 13/09/2018 Inspected At:

PREMIUM AUTOMOBILES PTE LTD
55 UBI ROAD 1
SINGAPORE 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,046.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2019)	
Parts:	N/A	AUDI Q2 999cc TFSI S-TRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7242X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,016.00 FS	*1,016.00 FS
2	1		*FIXING PARTS FOR REAR BUMPER	Not Necessary	66.00 FS	*- FS
3	1		*REAR BUMPER CENTRE COVER	Deformed	671.00 FS	*671.00 FS
4	2		*TRIM WHEEL HOUSING LINER-LH/RH	*Check	46.00 FS	*- FS
5	1		*REAR BUMPER LOWER SPOILER	Deformed	502.00 FS	*502.00 FS
6	1		*COVER FOR REAR BUMPER TOWING EYE	Not Necessary	20.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	52.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	*Check	480.00 FS	*- FS
9	2		*REAR END PANEL HOLDING STRAP-LH/RH	Not Necessary	22.00 FS	*- FS
10	2		*GUIDE SECTION-LH/RH	Not Necessary	92.00 FS	*- FS
11	1		*SENSOR-OUTER	Not Necessary	211.00 FS	*- FS
12	2		*SENSOR-INNER	Not Necessary	421.00 FS	*- FS
13	1		*REAR LID	Dented	2,106.00 FS	*2,106.00 FS
14	1		*ATTACHMENT PARTS FOR REAR LID	*Check	103.00 FS	*- FS
15	1		*REAR BOOT LOCK STRIKER	Not Necessary	254.00 FS	*- FS
16	1		*REAR BOOT LID WEATHERSTRIP SEAL	Not Necessary	101.00 FS	*- FS
17	1		*REAR LID LOCK	Not Necessary	188.00 FS	*- FS
18	1		*REAR LID LOCK COVER	Not Necessary	10.00 FS	*- FS
19	1		*REAR LID PUSH BUTTON LOCK ACTUATOR	Not Necessary	159.00 FS	*- FS
20	1		*REAR BOOT LID LICENCE PLATE TRIM	Not Necessary	204.00 FS	*- FS
21	1		*REAR BOOT LID AUDI LOGO	Necessary	108.00 FS	*108.00 FS
22	1		*Q2 EMBLEM	Necessary	83.00 FS	*83.00 FS
23	1		*TFSI EMBLEM	Necessary	83.00 FS	*83.00 FS
24	1		*REAR WINDSCREEN	Necessary	679.00 FS	*679.00 FS
25	2		*PRIMER	Necessary	38.00 FS	*38.00 FS
26	2		*REAR WHEEL COVER-LH/RH	Necessary	794.00 FS	*794.00 FS
27	1		*FIXING PARTS FOR REAR BUMPER SPOILER	*Check	117.00 FS	*- FS
28	1		*CAR PLATE-REAR	Dented	25.00 FS	*25.00 FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
30	1		*SUNDRIES	*Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,151.00	6,305.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN FOR REAR LID RENEWAL	New	480.00	480.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,200.00
5	TO RESPRAY REAR BUMPER,REAR LOWER SPOILER,BOTH REAR WHEEL ARC COVERS AND REAR LID	New	2,800.00	2,600.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,132.00	5,032.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >