

Dear Sir/Madam,


Refer to the letter dated 28/11/2018.




Front knuckle arm – damaged



Front knuckle arm bearing – necessary






Front knuckle arm bearing – necessary



Front lower arm – damaged




Front lower arm – damaged




Front door side mirror – damaged



Front sport rim (SN) - damaged



Front tyre (depreciation) (SN) – damaged



Rim out of alignment



Best Regards,


Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd


Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

photos (1) Pg 21.







Knuckle
Arm





Bearing.




photos (2) PG ~~15~~ (19)



lower
Arm





Mirror.






Photo (2) Pg 22



Rim




Tyre






→ Knuckle arm



Bearing



→ Bearing




lower arm




lower Arm





mirror







VVAH



100% POLYESTER

