

INS. CASE OWNER: Bernard | CC 6/AIG1801 Weto, Vtbb LKK IDAC

Surveyor: Marcus DOI: 25/9/2018 Date / Time: 10/10/18
Registered in Merimen: 10/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SUN X19P Claim No.: 090625982956
Name of Insured: ANDREW LUN KONG YAN LUN WONG YAN Policy No.:
Insured Tel No.: _____ HP: 8/11/18 Make / Model :
Excess Sec II :SS D.O.A.: 8/11/18 Place of Accident :
Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No.: _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SEC 88710



INSRS: Mark
WSP: Wah
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
<u>17/4/18</u>	<u>SEC 88710 - X</u>	Non-Reporting 1st (1st)	
<u>17/4/18</u>	<u>no oi gia, sev out 2st bottle</u>	Non-Reporting 1st (2nd)	
<u>17/4/18</u>		Non-Reporting 1st (Final)	
<u>17/4/18</u>		Notification 1st (if non-pickup)	
<u>17/4/18</u>		Call Of: <u>20/4/18</u>	
<u>17/4/18</u>		After call 1st to OI	
<u>17/4/18</u>	<u>Spoke to OI (Mr Low), OI just need come back business trip, confirmed to LA 17, Ask to lodge report ASAP.</u>	Documentation Check List: Handler Typist	
<u>17/4/18</u>	<u>pending oi GIA</u>	Notification 1st (if non-pickup)	
<u>17/4/18</u>	<u>TP convert OD, to submit WIP</u>	After call 1st to OI	
		Authorisation To Act	
		Release Voucher	
		Final Repair Bill	
		Car Rental Invoice	
		Towing Invoice	
		LTA / GIA	
		Medical Bill	
		PIR	
		Mandate/Reject Instruction	
		LOD	
		Payment Breakdown Form	
		Post-Repair Photos	
		Others	

PRELIMINARY ADVICE Date/Time: 26/9/18 Sent By: LSP

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
Repair Cost: \$5 1,700.00 (4 days) Reduction: 68.15 % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27
Repair Cost: \$5
Loss of Rental (LOR): \$5 (1 days)
Loss of Use (LOU): \$5 (\$ 1 x days)
Loss of Income (LOI): \$5 (\$ 1 x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)
GIA/LTA Search: \$5
Medical: \$5
Disbursement: \$5 (e.g. Tow/ Independent)
Legal Cost: \$5
Total: \$5 Global Sum \$5:
1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP
3) Survey fee: \$150.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐
Payee 1: \$5 Name 1: _____
Payee 2: (Strike if N.A.) \$5 Name 2: _____
Payee 3: (Strike if N.A.) \$5 Name 3: _____

(08/11/13) wef

ASS. REC. BY: M. Davis

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 8771at Workshop m/s WoodwardInsured: SLU 28199

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 10 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

L1A 38044

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKC 8771 Yr Regn: LO 11Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Nissan Teano c.c. 1997Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 54838 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IN13DUJ3280001667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/65R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

8/9/18

D.O.I.

25/9/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 28/9/18

451 \$1,700.00 (Redi \$ 3,631.49 / 68.15%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Invs

(\$

☐

Weekend

(\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18016470/fb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 10-09-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 2819P	Veh. Inspected	SKC 8871D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/09/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: SXXX2849F
P SATKUNARAJAH
BLK 72 ELIAS RIAD
#14-22
SINGAPORE 519944
TEL: FAX:
PH: 96301342
ATTN:

Not Affected
hwa
2/5
25/9/18
Chryslers Ats up

ESTIMATE BILL

Number: EB00004937
Date: 10/09/2018
Case No: AD00009954
Vehicle No: SKC8871D
Chassis: JN1BDUJ32Z0001667
Year of Mfr: 2010
Policy No: 5055571344-05
Model: NISSAN TEANA 2.0L
CVT ABS D/AIRBAG

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BUMPER	1.0	840.00	10	756.00
2	REAR BUMPER REINFORCEMENT	1.0	330.90	10	297.81
3	REAR BUMPER CLIP	3.0	4.40	10	11.88
4	REAR BUMPER SPONGE	1.0	139.00	10	125.10
5	REAR BUMPER MOULDING LH	1.0	145.50	10	130.95
6	REAR BUMPER MOULDING RH	1.0	145.50	10	130.95
7	REAR BUMPER RETAINER RH	1.0	36.30	10	32.67
8	REAR BUMPER RETAINER LH	1.0	36.30	10	32.67
9	END PANEL	1.0	550.20	10	495.18
10	END PANEL RUBBER	1.0	95.30	10	85.77
11	REAR FENDER LAMP LH	1.0	573.10	10	515.79
12	REAR FENDER LAMP INNER GARNISH LH	1.0	38.00	10	34.20
13	BOOTLID EMBLEM	1.0	56.70	10	51.03
14	BOOTLID LOGO - 200XL	1.0	80.90	10	72.81
15	BOOTLID LOGO - TEANA	1.0	105.20	10	94.68
Nett Price - Parts Sub Total					2,867.49
16	REVERSE SENSOR	1.0	280.00	0	280.00
17	BOOTLID - REPAIR	1.0			
18	REAR FENDER LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					280.00
Parts Total					3,147.49
19	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
20	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
21	ANTI-RUST COATING	1.0	300.00	0	300.00
22	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
23	WIRING	1.0	40.00	0	40.00
Labour 1 Sub Total					2,190.00
SINGAPORE DOLLARS : FIVE THOUSAND SEVEN HUNDRED ELEVEN AND CENTS ELEVEN ONLY					
Less Excess					0.00
SUBTOTAL					5,337.49
GST 7.00%					373.62
TOTAL					5,711.11

Date of accident : 08/09/2018 12:00 PM. Place : SLIP ROAD OF PIE TO TPE

E. & O. E.

LKK Auto Consultants hence notify

the Repairs of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

Acknowledged by Repairs

Signature:

Date:

AUTHORISED SIGNATURE

Page 1 of 1

* N = Item not subjected to GST

Issued by : Anyisia

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 2849F

Vehicle Details

Vehicle No.: SKC8871D

Vehicle to be Exported: No

Intended Deregistration Date: 25 Sep 2018

Vehicle Make: NISSAN

Vehicle Model: TEANA 2.0L CVT ABS D/AIRBAG 2WD

Primary Colour: Red

Manufacturing Year: 2010

Engine No.: MR20956478A

Chassis No.: JN1BDUJ32Z0001667

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$24,584.00

Original Registration Date: 12 Oct 2011

First Registration Date: 12 Oct 2011

Transfer Count: 0

Actual ARF Paid: \$24,584.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Oct 2021

PARF Rebate Amount: \$15,979.00

Intended COE Rebate Details

COE Expiry Date: 11 Oct 2021

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$74,490.00

COE Rebate Amount: \$22,065.00

Total Rebate Amount: \$38,044.00

The information contained herein is correct as at 25 Sep 2018

OK



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18016470/fb3

13 September, 2018

ANDREW (LIU QINGYAN LAW HENG YAN)
143 PASIR RIS STREET 11
#11-101
Singapore 510143

Dear Sirs,

**ACCIDENT INVOLVING SKC 8871D AND SLU 2819P ON 08/09/2018 ALONG/ AT SLIP
ROAD OF PIE TO TPE**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Poh Kin, Chong
Claims
Tel : 6841 2132
Fax: 6741 4108
Email : pohkin@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Wednesday, 12 December 2018 10:21 AM
To: 'Ler, Bernard-JQ'
Cc: Admin A
Subject: RE: Accident Involving SLU2819P & SKC8871D On 08/09/2018 | 0906259829SG-003

Importance: High

Your Ref: 0906259829SG-003
Our Ref: CC6/AIG18016470/Ufb3

Dear Bernard,

We refer to the above matter.

Apologies for late reply.

Please be informed that we have confirmed with TP Repairer that claimant convert to OD claim due OI late reporting (OI involved in overseas business trip) and let Insurance company the recovery claim later.

In view of above, we will submit W/P report to your office.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Ler, Bernard-JQ [mailto:Bernard-JQ.Ler@aig.com]
Sent: Wednesday, 5 December 2018 10:27 AM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Subject: Accident Involving SLU2819P & SKC8871D On 08/09/2018 | 0906259829SG-003

Dear Poh Kin,

As spoken, kindly assist to check with TP on whether they are still claiming under TP as we have received UIL claim from NTUC acting on behalf of the owner.

Thank you.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 10 January 2019 4:23 PM
To: 'Ler, Bernard-JQ'
Subject: RE: Accident Involving SLU2819P & SKC8871D On 08/09/2018 | 0906259829SG-003
Importance: High

Your Ref: 0906259829SG-003
Our Ref: CC6/AIG18016470/Ufb3

Dear Bernard,

We refer to the above matter and our tele conversation.

Apologies for late reply on this matter.

This is OI late reporting matter due to OI involved in oversea business trip. Please be informed that we managed to spoke to OI (Andrew Lau) and confirmed the nature of the accident (BOLA 27 against OI) and advise him to lodge report ASAP. But we yet to follow up the letter to OI.

Hope above information clarify.

We will submit W/P report to your good office ASAP.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Ler, Bernard-JQ [mailto:Bernard-JQ.Ler@aig.com]
Sent: Tuesday, 8 January 2019 11:10 AM
To: Poh Kin (LKKAuto) <pohkin@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident Involving SLU2819P & SKC8871D On 08/09/2018 | 0906259829SG-003

Hi Poh Kin,

Following up on this matter. Appreciate your advice ASAP.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2018 Edit Reg		25 Sep 2018 00:00 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LAW HENG YAN (LIU QINGYAN ANDREW), ID: 58323061D								
Main Claimant:	P SATKUNARAJAH, ID: 52192849F								
Vehicle Reg. No.:	SKC8871D	Date of Loss:	08/09/2018 12:00 - :59 [82 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0906259829SG	Policy/Cover Note No.:	1700078240 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLU2819P	Policy No. (Claimant):	5055571344-05						
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd - bedok (HQ) Blk 3011 Bedok North Avenue 4, #01-2008/2010/2012/2014, 489977 Bedok - Tel: 64415655								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (12/09/2018): Request To Upload TP GIA Report - AIG_SG (12/09/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKC8871D (09062598295G)**
[SLU2819P]
TP
P SATKUNARAJAH
Sep 8 2018 12:10PM
[LAW HENG YAN (LIU QINGYAN ANDREW)]
Hock Wah Motor Workshop Pte Ltd - bedok

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Assessment Reports						1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	08/10/18 14:46	Accident Statement From: SC - Reg. No: SLU2819P, Claimant: LAW HENG YAN, ANDREW (LIU QINGYAN, ANDREW)		 Load HTM			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	25/09/18 19:22	Chassis Number		 Load JPG	☒		
2	25/09/18 19:23	Odometer Reading		 Load JPG	☒		
3	25/09/18 19:23	General View		 Load JPG	☒		
4	25/09/18 19:23	General View		 Load JPG	☒		
5	25/09/18 19:23	General View		 Load JPG	☒		
6	25/09/18 19:23	General View		 Load JPG	☒		
7	25/09/18 19:23	General View		 Load JPG	☒		
8	25/09/18 19:23	General View		 Load JPG	☒		
9	25/09/18 19:23	General View		 Load JPG	☒		
10	25/09/18 19:23	General View		 Load JPG	☒		
11	25/09/18 19:23	General View		 Load JPG	☒		
12	25/09/18 19:23	General View		 Load JPG	☒		
13	25/09/18 19:23	General View		 Load JPG	☒		
14	25/09/18 19:23	General View		 Load JPG	☒		
15	25/09/18 19:23	General View		 Load JPG	☒		
16	25/09/18 19:23	General View		 Load JPG	☒		
17	25/09/18 19:23	General View		 Load JPG	☒		
18	25/09/18 19:23	General View		 Load JPG	☒		
19	25/09/18 19:23	General View		 Load JPG	☒		
20	25/09/18 19:23	General View		 Load JPG	☒		
21	25/09/18 19:23	General View		 Load JPG	☒		
22	25/09/18 19:23	General View		 Load JPG	☒		
23	25/09/18 19:23	General View		 Load JPG	☒		
24	25/09/18 19:23	General View		 Load JPG	☒		
25	25/09/18 19:23	General View		 Load JPG	☒		
26	25/09/18 19:23	General View		 Load JPG	☒		
27	25/09/18 19:23	General View		 Load JPG	☒		
28	25/09/18 19:23	General View		 Load JPG	☒		
29	25/09/18 19:23	General View		 Load JPG	☒		
30	25/09/18 19:23	General View		 Load JPG	☒		
31	25/09/18 19:23	General View		 Load JPG	☒		
32	25/09/18 19:23	General View		 Load JPG	☒		
33	25/09/18 19:23	General View		 Load JPG	☒		

Assessment Reports				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
34	25/09/18 19:23	General View		Load JPG	☒
35	25/09/18 19:23	General View		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/09/18 19:04	TP_GIA_REPORT		Load PDF	
2	13/09/18 19:18	Non reporting letter		Load PDF	
3	26/09/18 18:48	TP ESTIMATE- MARKED		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18016470/UFB3Q2

Date: 19/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1700078240

Claimant Vehicle No: SKC8871D

Insured Vehicle No: SLU2819P

Date of Loss: 08/09/2018

Nature of Claim: TP

Claim No: 0906259829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC8871D

Make & Model: NISSAN TEANA, 2.0 (A)

Engine No: MR20956478A

Reg. Date: 12/10/2011 (Man. Year: 2010)

Chassis No: JN1BDUJ32Z0001667

Colour: Maroon

Odometer: 54838 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,147.49	1,248.30	1,899.19	60.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	870.00	1,320.00	60.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,337.49	2,118.30	3,219.19	60.31
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	5,337.49	1,700.00	3,637.49	68.15
+ GST 7.00/7.00% (S\$)	373.62	119.00	254.62	68.15
Nett Amount (S\$)	5,711.11	1,819.00	3,892.11	68.15
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/09/2018

Date Inspected: 25/09/2018 Inspected At:

Hock Wah Motor Workshop Pte Ltd -
bedok (HQ)
Blk 3011 Bedok North Avenue 4, #01-
2008/2010/2012/2014
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	840.00 FL	*840.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	330.90 FL	*- FL
3	3		*REAR BUMPER CLIP	Necessary	13.20 FL	*13.20 FL
4	1		*REAR BUMPER SPONGE	Not Necessary	139.00 FL	*- FL
5	1		*REAR BUMPER MOULDING LH	Cracked	145.50 FL	*145.50 FL
6	1		*REAR BUMPER MOULDING RH	Cracked	145.50 FL	*145.50 FL
7	1		*REAR BUMPER RETAINER RH	Not Necessary	36.30 FL	*- FL
8	1		*REAR BUMPER RETAINER LH	Not Necessary	36.30 FL	*- FL
9	1		*END PANEL	Repair	550.20 FL	*- FL
10	1		*END PANEL RUBBER	Not Necessary	95.30 FL	*- FL
11	1		*REAR FENDER LAMP LH	Not Necessary	573.10 FL	*- FL
12	1		*REAR FENDER LAMP INNER GARNISH LH	Not Necessary	38.00 FL	*- FL
13	1		*BOOTLID EMBLEM	Necessary	56.70 FL	*56.70 FL
14	1		*BOOTLID LOGO -200XL	Necessary	80.90 FL	*80.90 FL
15	1		*BOOTLID LOGO -TEANA	Necessary	105.20 FL	*105.20 FL
16	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
17	1		*BOOTLID (NPA)	Repair	0.00 FS	*- FS
18	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	3,466.10	1,387.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	318.61	138.70

Total Parts (\$\$)	3,147.49	1,248.30
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINTING ON THE AFFECTED AREAS	New	900.00	400.00
3	ANTI -RUST COATING	New	300.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
5	WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			2,190.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >