

ASS. REC. BY:

REP: CS/MSG18016473/Rlgd302

Special Instruction:

Surveyor:
Meinert

ASSIGNMENT (Office)

From (Person): Katherine Wong of MS16 Date/Time: 10/9/18 @ 3:47pm

Estimated Cost: Bill to:

OD (IP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 77924 Insured: SLC 18332

at Workshop m/s Ding Auto Tel: 6265 2690

of 249 Jalan Bagan Lay

Policy No: MSD/NPCP 18-000756 Claim No: MSC/V/18-001209

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 08/09/2018

CA / REV / REP. / REV 24 HRS ^{1up} 11/09/2018 H.O.D. Endorsement:

Date/Time: 4:30pm @ 10/9/18 Person Contacted: Ah poh Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 77924 - X
	SLC 18332 -
13/9/18 @	Spn revised to Katherine Wong via Meinert.
17/9/18 @	9.38am Raoul finalised with Hong Bo LS to 2450, 5 days. (Red # 816, 77/0)

Surveyor: Passive

REF:

4597K

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLG 77924
 at Workshop m/s DINA AUTO
 of 249, JLN BROWN LAY
 Insured: MSLH
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLG 77924 Yr Regn: 2016 / 05
 Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MITSUBISHI ATTRAAGE 1.2 c.c. 1193
 Colour: GREEN A/C: Insured / Std / NI / NA
 Sp. Reading: 118533 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MMBSTA13AHH003153
 Gen. Cond: Good / (Fair) / Poor / Burnt
 Steering: In order / (Jammed) / Leaked / Burnt or _____
 Brake: In order / (Jammed) / Leaked / Burnt or _____
 Mod: Nil / (S) Rim / STD A/Rim or _____
 Tyre Size: F: 185/55 R15
 R: 1.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or ADTELI

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>08/09/18</u>	D.O.I. <u>11/09/18</u>

 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
RGAR N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 24 SEP 2018	
	<u>[Signature]</u> 21/9/2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Date/Time, File Return to?
 1) 24/9/2018
 2) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	200
Transportation:	
S + RS, SI	
Photos	
Others	10
TOTAL	210

Report Format : MER TR
 Lump Sum / I.B.I: (\$ 2450)

Shiau Chan (LKKAuto)

From: Duan Hongbo <duan.hongbo@dingauto.sg>
Sent: Monday, 17 September 2018 9:38 AM
To: Rasul (LKKAuto); SUR
Cc: CS A Team; Kenneth Ding; You jingfeng; Dd hashim; Accounts Ding Auto; Ding Auto Admin; Carlor Chan
Subject: Re: 85008606/SLG7792Y- FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear Rasul,

We accept the finalize amount \$ 2,450.00 / 5 days lump sum.

Many thanks.

BEST REGARDS

DING AUTO PTE LTD

DUAN HONG BO
TEL Office : 92394128
FAX : 62652690

ALL MAIL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW
- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST. SEC C SINGAPORE 5756

On Mon, Sep 17, 2018 at 9:23 AM, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Hongbo,

Finalised amount is \$ 2,450.00 / 5 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, [Ubi Avenue 1, #02-25](#) | S(408933)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 13 Sep 2018

Preliminary Advice

Insured Vehicle No	: SLC1833Z	Accident Date	: 08/09/2018
TP Vehicle No	: SLG7792Y	Assignment Date	: 10/09/2018
Make	: MITSUBISHI ATTRAGE	Est. Duration of Repair	: 5.00
Date of Inspection	: 11/09/2018		
Inspection At	: DING AUTO PTE LTD - BOON LAY (HQ) 249 JALAN BOON LAY SINGAPORE 619523 SINGAPORE 619523		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,566.00
Revised Amount	:S\$	3,082.90
Check Items (Estimated)	:S\$	266.40
Total	:S\$	3,349.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/09/2018 13:35
Date Of Accident	08/09/2018 11:05
Exact Location Of Accident	ALONG TPE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG7792Y
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	

Driver

Name of Driver	SIDQQI S/O MOHAMED
NRIC No	S7416766G
Date Of Birth	20/05/1974
Occupation	OUTDOOR
Date Of Driving Pass	17/04/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	249 JALAN BOON LAY
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNKNOWN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC1833Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: _____



 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: _____



 Reporting Centre Personnel's Signature
 Name: _____
 NRSC/FBI No.: _____

VEH A - SLG 7792 Y

VEH B - SLC 1833 Z



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 8 September 2018 at about 11:05 hrs, while entering TPE from Tampines Ave 12, I slowed down my vehicle due to congested TPE entrance. When my vehicle SLG 7792 Y came to a stop, I suddenly felt a bump from the back of the vehicle. I discovered that another vehicle numbered SLC 1833 Z driven by Mr. Neo Yong Kiah bearing IC no. S1725195C had hit my rear bumper and resulted it to be misaligned with dents.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: _____




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: _____


 Reporting Officer, Insurer's Signature
 Name: _____
 NRIC/PIN No.: _____

DING AUTO PTE LTD

Blk 10, #01-20
 Sin Ming Industrial Est. Sec C
 Singapore 575645
 Tel: 6452 1208
 Fax: 6452 0614

Vehicle:	SLG7792Y
Model:	MIT ATTRAGE
Chassis:	MMBSTA13AHH003153

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR BUMPER	1	\$ 708.00	10%	\$ 637.20	DE -
2	REAR BUMPER SIDE RETAINER LHS	1	\$ 26.00	10%	\$ 23.40	NA -
3	REAR BUMPER SIDE RETAINER RHS	1	\$ 26.00	10%	\$ 23.40	X SU
4	REAR BUMPER REFLECTOR LHS	1	\$ 20.00	10%	\$ 18.00	? X SU
5	REAR BUMPER REFLECTOR RHS	1	\$ 20.00	10%	\$ 18.00	X SU
6	BOOTLID	1	\$ 828.00	10%	\$ 745.20	PH -
7	BOOTLID 'MIT' LOGO	1	\$ 41.00	10%	\$ 36.90	NA -
8	BOOTLID 'E' EMBLEM	1	\$ 38.00	10%	\$ 34.20	NA -
9	BOOTLID 'ATTRAGE' EMBLEM	1	\$ 40.00	10%	\$ 36.00	NA -
10	BOOTLID HINGE LHS	1	\$ 192.00	10%	\$ 172.80	X
11	BOOTLID HINGE RHS	1	\$ 192.00	10%	\$ 172.80	X
12	BOOTLID LOCK	1	\$ 206.00	10%	\$ 185.40	X
13	BOOTLID OUTER CHROME GARNISH	1	\$ 318.00	10%	\$ 286.20	X
14	BOOTLID LICENSE PLATE LAMP LHS	1	\$ 48.00	10%	\$ 43.20	X SU
15	BOOTLID LICENSE PLATE LAMP RHS	1	\$ 48.00	10%	\$ 43.20	X
16	TAIL LAMP LHS	1	\$ 276.00	10%	\$ 248.40	X
17	TAIL LAMP RHS	1	\$ 276.00	10%	\$ 248.40	X
18	REAR END PANEL	1	\$ 402.00	10%	\$ 361.80	repair
19	REAR END PANEL TOP GARNISH	1	\$ 65.00	10%	\$ 58.50	X
20	REAR SPARE TYRE PANEL	1	\$ 906.00	10%	\$ 815.40	X
21	REAR SPARE TYRE PANEL FLOOR BOARD	1	\$ 185.00	10%	\$ 166.50	X
22	REAR END PANEL WEATHERSTRIP	1	\$ 148.00	10%	\$ 133.20	X
23	REAR FENDER LHS	1	\$ 723.00	10%	\$ 650.70	X
24	REAR FENDER RHS	1	\$ 723.00	10%	\$ 650.70	X
25	REAR FENDER INNER SHIELD LHS	1	\$ 38.00	10%	\$ 34.20	X
26	REAR FENDER INNER SHIELD RHS	1	\$ 38.00	10%	\$ 34.20	X
27	REAR FENDER INNER PANEL TRIM LHS	1	\$ 158.00	10%	\$ 142.20	X
28	REAR FENDER INNER PANEL TRIM RHS	1	\$ 158.00	10%	\$ 142.20	X
29	REAR END PANEL AIR DUCT	1	\$ 27.00	10%	\$ 24.30	X
30	REAR END PANEL AIR DUCT COVER LHS	1	\$ 36.00	10%	\$ 32.40	X
31	REAR FENDER MUDFLAP LH	1	\$ 40.00	10%	\$ 36.00	X
32	REAR FENDER MUDFLAP RH	1	\$ 40.00	10%	\$ 36.00	X
TOTAL:					\$ 6,291.00	

1512-90

NO	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	FRONT BUMPER CLIP	1	\$ 20 35.00	NA -
2	REAR REVERSE SENSOR	1	\$ 200 260.00	NA -
3	REAR END PANEL TOP GARNISH CLIP	1	\$ 35.00	X
4	REAR FENDER INNER SHIELD LHS CLIP	1	\$ 35.00	X
5	REAR FENDER INNER SHIELD RHS CLIP	1	\$ 35.00	X
6	REAR FENDER INNER PANEL TRIM LHS CLIP	1	\$ 35.00	X
7	REAR FENDER INNER PANEL TRIM RHS CLIP	1	\$ 35.00	X
8	REAR WINDSCREEN SEALANT	1	\$ 30.00	X
9	REAR END PANEL SEALANT	1	\$ 30.00	X
10	REAR SPARE TYRE PANEL SEALANT	1	\$ 40.00	X
11	REAR NUMBER PLATE & CASING	1	\$ 60.00	X
			\$ 195.00	(6.11)

3220

NO	LABOUR	PRICE	SURVEYOR MARKING
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	\$ 1,800.00	500
2	TO SPRAY REAR BUMPER	\$ 250.00	200
3	TO SPRAY REAR END PANEL	\$ 250.00	200
4	TO SPRAY REAR SPARE TYRE PANEL	\$ 250.00	X NA

5	TO SPRAY REAR BOOTLID	\$ 250.00	200
6	TO SPRAY REAR FENDER LHS	\$ 250.00	X17
7	TO SPRAY REAR FENDER RHS	\$ 250.00	X17
8	RUSH PROOFING	\$ 120.00	40
9	TO CHECK WIRING AND LIGHTING SYSTEM	\$ 120.00	30
10	REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER INNER PANEL TRIM LHS & RHS, SPARE TYRE PANEL FLOOR BOARD, CUSHION AND ETC.	\$ 160.00	60
11	R & R BOOTLID COMPONENTS	\$ 120.00	60
12	REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	\$ 130.00	60
13	REMOVE REAR WINDSCREEN	\$ 120.00	X17
14	REMOVE REAR SEAT & REMOVE REAR SPEAKER PANEL TRIM	\$ 120.00	X17
TOTAL:		\$ 4,080.00	1350

PARTS	\$ 6,291.00	
LABOUR	\$ 4,080.00	
SPECIAL NETT	\$ 195.00	
TOTAL	\$ 10,566.00	

Resul
Ap 50010068

5 days

4/3

11/09/18 @1645

Resurvey after repair

11121

[Signature]
13/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before ^{or} after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1512.90
220.00
1350.00

3082.90

20%
2466.92

45-21450

5 days

DING AUTO PTE LTD

Blk 10, #01-20
 Sin Ming Industrial Est. Sec C
 Singapore 575645
 Tel: 6452 1208
 Fax: 6452 0614

Vehicle:	SLG7792Y
Model:	MIT ATTRAGE
Chassis:	MMBSTA13AHH003153

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	REAR BUMPER	1	\$ 708.00	10%	\$ 637.20	DE ✓
2	REAR BUMPER SIDE RETAINER LHS	1	\$ 26.00	10%	\$ 23.40	NA ✓
3	REAR BUMPER SIDE RETAINER RHS	1	\$ 26.00	10%	\$ 23.40	X
4	REAR BUMPER REFLECTOR LHS	1	\$ 20.00	10%	\$ 18.00	?
5	REAR BUMPER REFLECTOR RHS	1	\$ 20.00	10%	\$ 18.00	X
6	BOOTLID	1	\$ 828.00	10%	\$ 745.20	PH ✓
7	BOOTLID 'MIT' LOGO	1	\$ 41.00	10%	\$ 36.90	NA ✓
8	BOOTLID 'E' EMBLEM	1	\$ 38.00	10%	\$ 34.20	NA ✓
9	BOOTLID 'ATTRAGE' EMBLEM	1	\$ 40.00	10%	\$ 36.00	NA ✓
10	BOOTLID HINGE LHS	1	\$ 192.00	10%	\$ 172.80	X
11	BOOTLID HINGE RHS	1	\$ 192.00	10%	\$ 172.80	X
12	BOOTLID LOCK	1	\$ 206.00	10%	\$ 185.40	X
13	BOOTLID OUTER CHROME GARNISH	1	\$ 318.00	10%	\$ 286.20	X
14	BOOTLID LICENSE PLATE LAMP LHS	1	\$ 48.00	10%	\$ 43.20	X
15	BOOTLID LICENSE PLATE LAMP RHS	1	\$ 48.00	10%	\$ 43.20	X
16	TAIL LAMP LHS	1	\$ 276.00	10%	\$ 248.40	X
17	TAIL LAMP RHS	1	\$ 276.00	10%	\$ 248.40	X
18	REAR END PANEL	1	\$ 402.00	10%	\$ 361.80	REAR ✓
19	REAR END PANEL TOP GARNISH	1	\$ 65.00	10%	\$ 58.50	X
20	REAR SPARE TYRE PANEL	1	\$ 906.00	10%	\$ 815.40	X
21	REAR SPARE TYRE PANEL FLOOR BOARD	1	\$ 185.00	10%	\$ 166.50	X
22	REAR END PANEL WEATHERSTRIP	1	\$ 148.00	10%	\$ 133.20	X
23	REAR FENDER LHS	1	\$ 723.00	10%	\$ 650.70	X
24	REAR FENDER RHS	1	\$ 723.00	10%	\$ 650.70	X
25	REAR FENDER INNER SHIELD LHS	1	\$ 38.00	10%	\$ 34.20	X
26	REAR FENDER INNER SHIELD RHS	1	\$ 38.00	10%	\$ 34.20	X
27	REAR FENDER INNER PANEL TRIM LHS	1	\$ 158.00	10%	\$ 142.20	X
28	REAR FENDER INNER PANEL TRIM RHS	1	\$ 158.00	10%	\$ 142.20	X
29	REAR END PANEL AIR DUCT	1	\$ 27.00	10%	\$ 24.30	X
30	REAR END PANEL AIR DUCT COVER LHS	1	\$ 36.00	10%	\$ 32.40	X
31	REAR FENDER MUDFLAP LH	1	\$ 40.00	10%	\$ 36.00	X
32	REAR FENDER MUDFLAP RH	1	\$ 40.00	10%	\$ 36.00	X
TOTAL:					\$ 6,291.00	

SPECIAL NETT		QTY	PRICE	SURVEYOR MARKING
1	FRONT BUMPER CLIP	1	\$ 20 / 35.00	NA ✓
2	REAR REVERSE SENSOR	1	\$ 200 / 260.00	AW ✓
3	REAR END PANEL TOP GARNISH CLIP	1	\$ 35.00	X
4	REAR FENDER INNER SHIELD LHS CLIP	1	\$ 35.00	X
5	REAR FENDER INNER SHIELD RHS CLIP	1	\$ 35.00	X
6	REAR FENDER INNER PANEL TRIM LHS CLIP	1	\$ 35.00	X
7	REAR FENDER INNER PANEL TRIM RHS CLIP	1	\$ 35.00	X
8	REAR WINDSCREEN SEALANT	1	\$ 30.00	X
9	REAR END PANEL SEALANT	1	\$ 30.00	X
10	REAR SPARE TYRE PANEL SEALANT	1	\$ 40.00	X
11	REAR NUMBER PLATE & CASING	1	\$ 60.00	X
			\$ 195.00	

LABOUR		PRICE	SURVEYOR MARKING
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	\$ 1,880.00	500 ✓
2	TO SPRAY REAR BUMPER	\$ 250.00	200 ✓
3	TO SPRAY REAR END PANEL	\$ 250.00	200 ✓
4	TO SPRAY REAR SPARE TYRE PANEL	\$ 250.00	X

5	TO SPRAY REAR BOOTLID	\$ 250.00	200
6	TO SPRAY REAR FENDER LHS	\$ 250.00	X
7	TO SPRAY REAR FENDER RHS	\$ 250.00	X
8	RUSH PROOFING	\$ 120.00	40
9	TO CHECK WIRING AND LIGHTING SYSTEM	\$ 120.00	30
10	REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER INNER PANEL TRIM LHS & RHS, SPARE TYRE PANEL FLOOR BOARD, CUSHION AND ETC.	\$ 160.00	60
11	R & R BOOTLID COMPONENTS	\$ 120.00	60
12	REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	\$ 130.00	60
13	REMOVE REAR WINDSCREEN	\$ 120.00	X
14	REMOVE REAR SEAT & REMOVE REAR SPEKER PANEL TRIM	\$ 120.00	X
TOTAL:		\$ 4,080.00	

PARTS	\$ 6,291.00	
LABOUR	\$ 4,080.00	
SPECIAL NETT	\$ 195.00	
TOTAL	\$ 10,566.00	

Resul
Ap 90010068

5 days

L/S

11/09/18 @1645

Resurvey after repair

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2018		10 Sep 2018 15:47 Edit Adj Rpt	S\$2,450.00 Edit Estimates	S\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: NA								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLG7792Y	Date of Loss:	08/09/2018 00:00 - :59 [22 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001209	Policy/Cover Note No.:	MSD/VPCP/18-000756 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019						
Vehicle Reg. No. (Insured):	SLC1833Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523, 619523 Boon Lay - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/10/2018]								
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey, vehicle SLG7792Y lying at 249 Jalan Boon Lay. Insured non-reporting Contact : Duan Hong Bo @ 6265 2690								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG7792Y (MSC/V/18-001209)**
[SLC1833Z]
TP
LCRF PTE LTD
Sep 8 2018 12:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Ding Auto Pte Ltd - Boon Lay

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/18 17:00	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/09/18 15:12	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	21/09/18 15:12	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
4	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
5	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
6	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
7	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
8	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
9	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
10	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
11	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
12	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
13	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
14	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
15	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
16	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
17	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
18	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
19	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
20	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
21	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
22	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
23	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
24	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
25	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
26	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
27	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
28	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
29	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
30	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
31	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
32	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
33	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
34	21/09/18 15:12	General View	Load JPG	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
36	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
37	21/09/18 15:12	General View	Load JPG	<input checked="" type="checkbox"/>
38	21/09/18 15:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	21/09/18 15:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	21/09/18 15:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	21/09/18 15:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	21/09/18 15:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	21/09/18 15:12	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/18 13:44	TP PRI	Load PDF	
2	10/09/18 13:45	TP ACCDT REPORT	Load PDF	
3	10/09/18 14:07	TP NOMINATED LKK TO BE SJE	Load PDF	
4	20/09/18 10:45	Status of Driving Licence <small>From:SC - Reg. No: SLC1833Z, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD</small>	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016473/R1QD3E2
Date: 27/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/18-000756
Claimant Vehicle No :	SLG7792Y	Insured Vehicle No :	SLC1833Z
Date of Loss:	08/09/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-001209

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG7792Y	Engine No:	3A92UDM8403
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH003153
Reg. Date:	13/10/2016 (Man. Year: 2016)	Odometer:	118553 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	AOTELI 5 mm	Rear Left Side:	AOTELI 5 mm
Front Right Side:	AOTELI 5 mm	Rear Right Side:	AOTELI 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,921.00	1,732.90	5,188.10	74.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,350.00	2,850.00	67.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,121.00	3,082.90	8,038.10	72.28
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	11,121.00	2,450.00	8,671.00	77.97
+ GST 7.00/7.00% (S\$)	778.47	171.50	606.97	77.97
Nett Amount (S\$)	11,899.47	2,621.50	9,277.97	77.97

INSPECTION

Date of Assignment:	10/09/2018	
Date Inspected:	11/09/2018 Inspected At:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523 Singapore 619523

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Sep 2018)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG7792Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	708.00 FL	*708.00 FL
2	1		*REAR BUMPER SIDE RETAINER LHS	Necessary	26.00 FL	*26.00 FL
3	1		*REAR BUMPER SIDE RETAINER RHS	Serviceable	26.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR LHS	Serviceable	20.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR RHS	Serviceable	20.00 FL	*- FL
6	1		*BOOTLID	Bent	828.00 FL	*828.00 FL
7	1		*BOOTLID MIT LOGO	Necessary	41.00 FL	*41.00 FL
8	1		*BOOTLID E EMBLEM	Necessary	38.00 FL	*38.00 FL
9	1		*BOOTLID ATTRAGE EMBLEM	Necessary	40.00 FL	*40.00 FL
10	1		*BOOTLID HINGE LHS	Serviceable	192.00 FL	*- FL
11	1		*BOOTLID HINGE RHS	Serviceable	192.00 FL	*- FL
12	1		*BOOTLID LOCK	Serviceable	206.00 FL	*- FL
13	1		*BOOTLID OUTER CHROME GARNISH	Serviceable	318.00 FL	*- FL
14	1		*BOOTLID LICENSE PLATE LAMP LHS	Serviceable	48.00 FL	*- FL
15	1		*BOOTLID LICENSE PLATE LAMP RHS	Serviceable	48.00 FL	*- FL
16	1		*TAIL LAMP LHS	Serviceable	276.00 FL	*- FL
17	1		*TAIL LAMP RHS	Serviceable	276.00 FL	*- FL
18	1		*REAR END PANEL	Repair	402.00 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	65.00 FL	*- FL
20	1		*REAR SPARE TYRE PANEL	Not Necessary	906.00 FL	*- FL
21	1		*REAR SPARE TYRE PANEL FLOOR BOARD	Not Necessary	185.00 FL	*- FL
22	1		*REAR END PANEL WEATHERSTRIP	Not Necessary	148.00 FL	*- FL
23	1		*REAR FENDER LHS	Not Necessary	723.00 FL	*- FL
24	1		*REAR FENDER RHS	Not Necessary	723.00 FL	*- FL
25	1		*REAR FENDER INNER SHIELD LHS	Not Necessary	38.00 FL	*- FL
26	1		*REAR FENDER INNER SHIELD RHS	Not Necessary	38.00 FL	*- FL
27	1		*REAR FENDER INNER PANEL TRIM LHS	Not Necessary	158.00 FL	*- FL
28	1		*REAR END PANEL AIR DUCT	Not Necessary	27.00 FL	*- FL
29	1		*REAR END PANEL AIR DUCT COVER LHS	Not Necessary	36.00 FL	*- FL
30	1		*REAR FENDER MUDFLAP LH	Not Necessary	40.00 FL	*- FL
31	1		*REAR FENDER MUDFLAP RH	Not Necessary	40.00 FL	*- FL
32	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*20.00 FS
33	1		*REAR REVERSE SENSOR	Not Working	260.00 FS	*200.00 FS
34	1		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	35.00 FS	*- FS
35	1		*REAR FENDER INNER SHIELD LHS CLIP	Not Necessary	35.00 FS	*- FS
36	1		*REAR FENDER INNER SHIELD RHS CLIP	Not Necessary	35.00 FS	*- FS
37	1		*REAR FENDER INNER PANEL TRIM LHS CLIP	Not Necessary	35.00 FS	*- FS
38	1		*REAR FENDER INNER PANEL TRIM RHS CLIP	Not Necessary	35.00 FS	*- FS
39	1		*REAR WINDSCREEN SEALANT	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
40	1		*REAR END PANEL SEALANT	Not Necessary	30.00 FS	*- FS	
41	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	40.00 FS	*- FS	
42	1		*REAR NUMBER PLATE & CASING	Not Necessary	60.00 FS	*- FS	
43	1		*REAR FENDER INNER PANEL TRIM RHS	Not Necessary	158.00 FL	*- FL	
					Sub Total (\$\$)	7,620.00	1,901.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	699.00	168.10
					Total Parts (\$\$)	6,921.00	1,732.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,800.00	500.00
2	TO SPRAY REAR BUMPER	New	250.00	200.00
3	TO SPRAY REAR END PANEL	New	250.00	200.00
4	TO SPRAY REAR SPARE TYRE PANEL	New	250.00	0.00
5	TO SPRAY REAR BOOTLID	New	250.00	200.00
6	TO SPRAY REAR FENDER LHS	New	250.00	0.00
7	TO SPRAY REAR FENDER RHS	New	250.00	0.00
8	RUSH PROOFING	New	120.00	40.00
9	TO CHECK WIRING AND LIGHTING SYSTEM	New	130.00	30.00
10	REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER INNER PANEL TRIM LHS & RHS, SPARE TYRE PANEL FLOOR BOARD, CUSHION AND ETC	New	160.00	60.00
11	R & R BOOTLID COMPONENTS	New	120.00	60.00
12	REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	New	130.00	60.00
13	REMOVE REAR WINDSCREEN	New	120.00	0.00
14	REMOVE REAR SEAT & REMOVE REAR SPEAKER PANEL TRIM	New	120.00	0.00
Gross Labour Cost (S\$)			4,200.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >