

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 13 Sep 2018

Preliminary Advice

Insured Vehicle No	: PA9958H	Accident Date	: 07/09/2018
TP Vehicle No	: SKN3948S	Assignment Date	: 10/09/2018
Make	: LEXUS ES250	Est. Duration of Repair	: 3
Date of Inspection	: 12/9/2018		
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,019.50
Revised Amount	:S\$	4,424.30
Check Items (Estimated)	:S\$	12,029.20
Total	:S\$	16,453.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle survey on "Without Prejudice" basis.