

NAZ

NS / INC 18016477 / Ncd302

TIR 1167 D Yr Regn: 2 AUG 2001  
Bus / Van / Lorry / Taxi / Prime Mover /

From: \_\_\_\_\_  
Estimated: \_\_\_\_\_  
OD / TIR: \_\_\_\_\_  
To Inspect: \_\_\_\_\_  
at Work: \_\_\_\_\_  
of \_\_\_\_\_  
Insured: **SMD 965R**  
Policy: **5096898757 31/07/2018**  
Claims: **MT/1009730-002**  
Sum Insured: \_\_\_\_\_  
(Client Receipt): \_\_\_\_\_  
Make of vehicle: \_\_\_\_\_

MB 04054 AUTO C.C. 11,967  
WHITE A/C: Insured / Std / NI / I  
273, 771 T/Radio: Insured / Std / NI / I

C/Nr WEB61232321098226  
Fair / Poor / Burnt  
In order / Damaged / Leaked / Burnt or  
In order / Damaged / Leaked / Burnt or  
/ STD A/Rim or  
275 / 70 R22.5  
71

(Police Report): \_\_\_\_\_  
Remarks: \_\_\_\_\_  
Bal. or Mileage: \_\_\_\_\_  
IDAC: \_\_\_\_\_  
GIA: \_\_\_\_\_  
Est. Rec: **2**  
Lum. S: \_\_\_\_\_  
CA / \_\_\_\_\_  
Date: \_\_\_\_\_  
Date: \_\_\_\_\_

FRY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
(CONTINENTALCE)  
FIRENZA (R) Rear  
R/Bal. 7 mm R/Bal. 7 / 6 mm  
L/Bal. 7 mm L/Bal. 7 / 6 mm  
D.O.A. 30/8/18 D.O.I. 5/9/18  
SMART WOODLANDS  
Res / OIS / NIS / UIC / Rooftop or  
FRT N/S  
Frame / Body Structure affected due to collision

10/4/19 FINALIZED LUMP SUM REPAIR \$1,300.00 / 2 DAYS  
(Red 875.15, 40%)

*[Signature]*  
10/4/2019

1) _____	Survey Fee:	160
Date/Time: _____	Transportation:	
2) _____	) S + RS: \$	
Report: _____	) Photos	
Lump S: _____	) Others	
	)	
	TOTAL	160



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18016477/Nrb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-09-2018

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 965R	Veh. Inspected	TIB 1167D
Policy No.	5096898757	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/09/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	30/08/2018	Inspection Date	05/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)
[Change Password](#)
[Log Out](#)

[My Desktop](#)  
[Notice of Loss](#)

**Policy Query**

Policy No.  Date of Accident   
 Vehicle No.(For Motor)  Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5096898757		BIS MOTORING PTE. LTD.	201735055D	GFT	drive PREMIUM	SMD965R	SMD965R	31/07/2018	

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	04/09/2018 09:27
Date Of Accident	30/08/2018 14:40
Exact Location Of Accident	ALONG EUNIS LINK (AFTER BS 17079) COMFORT DRIVING
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	TIB1167D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

#### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

#### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	DII027592MFBP
Cover Note Number	

#### Driver

Name of Driver	LYE SAN YOU
NRIC No	S2557818Z
Date Of Birth	03/12/1951
Occupation	OUTDOOR
Date Of Driving Pass	14/02/1977
Driving Experience	41 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 6 ANG MO KIO ST 62

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 15

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

WHILE TRAVELLING ALONG EUNOS LINK ON THE LEFT MOST LANE, A PRIVATE CAR, SMD965R THAT CAME OUT FROM THE SLIP ROAD OF AIRPORT ROAD FAILED TO STOP AT THE STOP LINE AND THE RIGHT FRONT PORTION OF THE SAID VEHICLE COLLIDED ONTO MY BUS LEFT FRONT PORTION. NO INJURY REPORTED. THAT'S ALL.

#### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMD865R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver POH WEE SIONG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claim process.
2. This Form must be completed by the **Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **But table regarding may be referred to the Police for investigations**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to my enquiries by me;
  - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover or envelope/final package); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms, which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to complete claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Director's Signature  
Date & Time:

Reporting Centre Personnel's Signature  
Name: BALQISH  
NIC/PIN No.: S834 03 252





## SMRT Accident Bus Repair Estimate

**Section A - To be completed by Claims Advisor/, KJ/AMK Duty Officer**

Reg. No. : TIB / SMB 1167D Ref. No. BUS/BPS 8 / 18 / 10 39

Make / Model : HABIT BENDY Reg. Date : \_\_\_\_\_

Name of Driver : BC 71 95 5

Date/Time of Accident : 30 / -8 / 70 18

Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / UAS / AIS / Others \_\_\_\_\_


Bus is Towed Back ? YES / NO

Accident reporting date : 31 -8 18

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any :  
LEFT FRONT PORTION

The damages on the Buses are as indicated in the following diagram :



Signed : \_\_\_\_\_ Date : \_\_\_\_\_

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Accident Repair Job Card No : \_\_\_\_\_ Chassis No : \_\_\_\_\_

Mileage : \_\_\_\_\_ Date Prepared : \_\_\_\_\_

Summary of Repair Estimates Repair Completed : \_\_\_\_\_

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>795</u>	\$ _____
Total Spray Painting Charges :	\$ <u>786</u>	\$ _____
Total Material Charges :	\$ <u>534.74</u>	\$ _____
Other Charges :	\$ <u>NA</u>	\$ _____
<b>TOTAL</b> :	<b>\$ <u>2115.74</u> 217515</b>	<b>\$ _____ ( )</b>
	Lump Sum Repair, if any :	\$ <u>2120.00</u>
No. of Repair Days :	[ <u>2</u> ] days	[ <u>2</u> ] days
Signature :	Prepared by: <u>Sunny Tan</u>	Adjusted by: _____

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

QN No. \_\_\_\_\_ Invoice No. \_\_\_\_\_ Invoice Date \_\_\_\_\_

Signed : \_\_\_\_\_ Date : \_\_\_\_\_

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$795 ±	530
<b>Total Labour</b>	\$	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786 ±	538
<b>Total Spray Painting &amp; Panel Beating</b>	\$	\$

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>	\$	\$

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (I)	Not given (X) Repair (R) Replace (I)
600 8196	FRONT LH BUMPER END	1	594.15	10%	534.74	/ CRA	
	NAZ LKK						
	5/9/18 1615						
	LIS						
	2 DAYS						
	AFTER REPAIR PHOTO						
					<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p>		
<b>TOTAL MATERIALS</b>					\$		

2125.15

NA2 LKIC

5/9/18 1615

LIS  
2 DAYS

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/04/2019  
User ID : CatherineLee

Section A - Accident Details	
Registration Number	TIB1167D
Case Reference Number	BUS/08/18/1047
Registration Date	2/8/2001
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MERCEDES 0405G
Name of Driver	Lye San You
Type of Accident	Side Swipe
Accident Date and Time	30/9/2018 2:41 PM
Accident Reported Date and Time	31/8/2018 9:55 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24097829
Special Instruction to ARC, if any	TIB1167D - LEFT FRONT PORTION SMD965R (TP) - INSURED WITH NTUC
Prepared Date and Time	8/4/2019 5:04 PM
Chassis Number	WEB61232321098226
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$786.00	\$538.00
Total Spare Part Cost	\$427.79	\$427.79
Total Other Cost	\$0.00	(\$213.60)
<b>TOTAL COST</b>	<b>\$2,008.79</b>	<b>\$1,282.19</b>
Lump Sum Total	\$2,000.00	\$1,300.00
Number of Repair Days	2.0	2.0
Prepared / Adjusted By	Kek Khoo Goh	
ARC / Surveyor Sign Off Date		
Signature		-
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/04/2019  
 User ID : CatherineLee

Section D - Details of Repair Estimates									
<b>Part 1 - Labour Works</b>									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$795.00			\$530.00				
Total Labour		\$795.00			\$530.00				
<b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b>									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$786.00			\$538.00				
Total Spray Painting & Panel Beating		\$786.00			\$538.00				
<b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b>									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
Lump Sum Adjustment by Surveyor		\$0.00			(\$213.60)				
Total Other Costs		\$0.00			(\$213.60)				
<b>Part 4 - Spare Parts / Material Usage</b>									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
8008196	BODY LH	4015751000	BUMPER_END.FRONT LH.FOR MB O405G HABIT	1.00	\$594.15	10.00	\$534.74	Replace	Replace <i>CRK</i>
Total					\$594.15		\$534.74		
<b>Added Spare Parts / Material Usage After Surveyor Signed off</b>									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

PARTS, \$ 534.74

LABOUR \$ 530

SPRAY \$ 538

\$1,602.74

LESS LIS 20% \$1,282.19

\$1,300.00 / 2 DAYS.

FINALIZED LUMP SUM REPAIR \$1,300 / 2 REPAIR DAYS

NAZUKK  
 H/d  
 10/4/19



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18016477/Ncd3e2			
73 BRAS BASAH ROAD		Date: 17-04-2019	
#05-01 NTUC TRADE UNION HOUSESINGAPORE			
189556			
Code: INC4			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMD 965R	Veh. Inspected	TIB 1167D
Policy No.	5096898757	Coverage (\$)	0.00
Claim No.	MT/1009730-002	Excess (\$)	0.00
Assign From		Assign Date	05/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ O405G AUTO	c.c	11967
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	WEB61232321098226	Colour	WHITE
Odometer	273771	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	7/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	7/6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	30/08/2018	Inspection Date	05/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. TIB 1167D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT LH BUMPER END LESS 10% DISCOUNT	CRACKED	594.15	594.15
			-	-59.42
			594.15	534.73
<b>LABOUR</b>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		795.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		786.00	538.00
			1,581.00	1,068.00
<b>GRAND TOTAL</b>			<b>2,175.15</b>	<b>1,602.73</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,300.00</b>

Report Ref No. NS/INC18016477/Ncd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.