



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:	SJT 6218 B
MAKE & MODEL:	BMW Z4
MILEAGE:	
TYRE:	
CHASSIS NUM:	WBA1M32040E355236

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT BONNET 11X	1	\$2,598.85
2	FRONT HEADLAMP LH 11X	1	\$2,437.65
3	FRONT BUMPER Deep cut ✓	1	\$1,408.05
4	FRONT BUMPER RETAINER L+R n/s 12 12 X nn	2	\$72.50
5	FRONT BUMPER BRACKET L+R 11X	2	\$72.50
6	FRONT BUMPER REINFORCEMENT 11X	1	\$658.05
8	FRONT BUMPER GRILLE L+R 11X	1	\$227.30
9	FRONT BUMPER LOWER GRILLE 11X	1	\$55.15
11	FRONT BUMPER FOG LAMP GRILLE LH 11X	1	\$55.50
12	FRONT BUMPER SENSOR LH 11X	2	\$473.70
13	FRONT BUMPER HEADLAMP NOZZLE LH 11X	1	\$159.85
14	FRONT KNUCKLE LH 11X	1	\$424.25
15	FRONT KNUCKLE BEARING LH 11X	1	\$476.25
16	FRONT BEARING HUB LH 11X	1	\$373.10
17	FRONT ABSORBER LH 11X	1	\$541.35
18	FRONT LOWER ARM LH 11X	1	\$268.75
	PARTS = \$1,408.05		
	LESS 8% = \$1,337.68		
	SUBTOTAL		\$ -
	LESS 10%		\$ -
	PARTS TOTAL		\$ -
	SPECIAL NETT	QTY	PRICE
1	FRONT NUMBER PLATE 11X	1	\$ 120.00
2	FRONT BUMPER CLIPS n/s ✓ \$50.00	10	\$ 100.00
3	FRONT RIM LH cut 6.505.2	1	\$ 1,000.00
4	FRONT TYRE LH SVC X	1	\$ 800.00
	SPECIAL NET = \$750		
	SPECIAL NETT TOTAL		\$ 2,020.00
	LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN 250	1	\$ 600.00
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA 400	1	\$ 600.00
2	TO RUST PROOF ACCIDENT AFFECTED AREA 11X	1	\$ 120.00
3	TO RNR UNDERCARRAIGE SYSTEM 11X	1	\$ 350.00
4	TO CHECK WHEEL ALIGNMENT 80	1	\$ 120.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS 20	1	\$ 120.00
7	TO RNR TYRE AND WHEEL BALANCING 11X	1	\$ 120.00
	LABOUR = \$750 not allowed		
	LABOUR TOTAL		\$ 2,030.00
	GROSS TOTAL \$2,837.65		
	LESS 20% = \$2,300.12		
	GRAND TOTAL COST		\$ 4,050.00

10/9/18
Whe ph. After repair.