

ASS. REC. BY:

REF:

CS/MSG18016519/Urbon2

Special Instruction:

Surveyor

MORRIS

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

msch

Date/Time: 11/09/2018 9:37am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

YN 924P

Insured:

YN 2167U

at Workshop m/s

Tim Lim mdr

Tel:

6858 5151

of

51 Defu Lane 10

Policy No:

A38800295MKC

Claim No:

569703

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS. wp

H.O.D. Endorsement:

Date/Time:

11/09/2018 10:14am

Person Contacted:

William

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

YN 924P - X

YN 2167U - NA / INC 12/02/27/cl

DA: 31/10/2012

12/9/18

Revert this morning

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / *FP* / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *YN 924P*at Workshop m/s *Tan Lim*of *11an.*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<i>[Signature]</i>	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *3* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS *LYA 2790*

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *YN 924P* Yr Regn: *210*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(M)*Make: *HINO* c.c. *7684*Colour: *white/red* A/C: Insured / Std / NI / NASp. Reading: *120299* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *FD 8JJK12.004*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Good* / Jammed / Leaked / Burnt orBrake: *Good* / Jammed / Leaked / Burnt orModi: *Nil* / 8/Rim / STD A/Rim orTyre Size: F: *8.25-16*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Magnum*Front *6* mm Rear *6/6* mmL/Bal. *6* mm L/Bal. *6/6* mmD.O.A. *7/9/18* D.O.I. *11/9/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>windscreen and dashboard need to disassemble because front inner part damage need to repair, need bealing weld straighten</i>
<i>18/9/18</i>	<i>confirmed 1/3 \$2400 with Caymen.</i>
	<i>Red: \$6254.00, 175%.</i>
RECEIVED 21 SEP 2018	

Date/Time, File Pass to?

1) *typist*

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: *3*Resurvey No. of Trip: *2*Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

10

160

Report Format : *TP*Lump Sum / LBH: (\$ *2400*)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Sep 2018

Preliminary Advice

Insured Vehicle No	: YN2167U	Accident Date	: 07/09/2018
TP Vehicle No	: YN924P	Assignment Date	: 11/09/2018
Make	: HINO FD8JLKA	Est. Duration of Repair	: 3.00
Date of Inspection	: 11/09/2018		
Inspection At	: TAN LIM MOTOR PTE LTD (DEFU) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,940.00 (Labour only)
Revised Amount	:S\$	1,170.00
Check Items (Estimated)	:S\$	320.00
Total	:S\$	1,490.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Sep 2018 19:47 Sendback Est	08 Sep 2018 15:15 S\$1,940.00	11 Sep 2018 09:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	Sinmah Poultry Processing (S) Pte Ltd, Co. Reg. No.: 199100209N		
Main Claimant:	MALAYSIA DAIRY INDUSTRIES PTE LTD, Co. Reg. No.: A00260/1963D		
Vehicle Reg. No.:	YN924P	Date of Loss:	07/09/2018 03:00 - :59 [102 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 569705	Policy/Cover Note No.:	A28800295MKC (Comprehensive) Coverage: 03/08/2018 - 02/08/2019
Vehicle Reg. No. (Insured):	YN2167U	Policy No. (Claimant):	2018-V0072146-VCV-R008
		Excess:	
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/09/2018]		
Driver/Custodian (Insured):	Lim Chuan Kek (), NRIC: S04878311, Tel: +6590118490		
Adj Asg. Remarks:	Liability 100%. TP agree to use Marcus Chua frm LKK as the SJE. Contact Person: William Lam / 6858 5151		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/09/2018 13:38
Date Of Accident	07/09/2018 03:00
Exact Location Of Accident	LOADING/UNLOADING BAY OF SELERAT MALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN924P
Insured/Policyholder	
Name Of Registered Owner	MALAYSIA DAIRY INDUSTRIES PTE LTD
Co Reg No	A00260/1963D
Email Address	JESSIECHAN@MDI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62886421

Vehicle Particulars

Manufacturer	HINO
Model	FD8JJKA
Exact Purpose for which vehicle was being used at time of accident	DELIVERY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2018-V0072146-VCV-R008
Cover Note Number	26.02.2018 TO 25.02.2019

Driver

Name of Driver	YANG PENG
Passport No/FIN	G8460637K
Date Of Birth	15/08/1986
Occupation	OUTDOOR
Date Of Driving Pass	24/02/2016
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94561162
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	2 DAVIDSON ROAD
Postcode	369941
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 07/09/2018 at about 0300hrs, I stopped my vehicle (A: YN924P) at parking lot loading/unloading Bay at Seletar Mall in order to unloading goods. My colleague with me at behind of the vehicle unloading goods, suddenly heard the bang sound from my vehicle's front portion. I immediately go in front and discovered that vehicle (B: YN2167U) which was came out from loading/unloading bay and hit onto my vehicle's front portion. Nobody was injured in this accident. My vehicle have no driver and passenger on board. Vehicle B have no passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2167U
Vehicle Make/Model/Colour	
Details Of Properties	LORRY
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM CHUAN KEK
NRIC/Passport Number	S0487831J
Contact Number	90118490
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT REAR PORTION
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature: 
Date & Time: 

Driver's Signature: 
(if driver is not the policyholder)
Date & Time: 07/09/18 01:40h

Reporting Centre Personnel's Signature: 
Name: Lim Mr Shu Ng
NRIC/FIN No.: 60664052R

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to CIA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Yany Peng
Driver's Signature
(if driver is not the policyholder)
Date & Time: 07/04/18 @ 1400h

Reporting Centre Personnel's Signature
Name: Lam Wai Hon
NRIC/EPN No.: 668640636

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	0260D

Vehicle Details

Vehicle No.:	YN924P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2018
Vehicle Make:	HINO
Vehicle Model:	FD8JJKA
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	J08EUC11556
Chassis No.:	FD8JJK12004
Maximum Power Output:	-
Open Market Value:	\$51,010.00
Original Registration Date:	26 Feb 2010
First Registration Date:	26 Feb 2010
Transfer Count:	0
Actual ARF Paid:	\$2,551.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 Feb 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$19,001.00
COE Rebate Amount:	\$2,790.00
Total Rebate Amount:	\$2,790.00

The information contained herein is correct as at 07 Sep 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
Sinmah Poultry Processing (S) Pte Ltd
27 Defu Lane 12
Singapore 539134

Claimant Insurer: Great Eastern General Insurance Limited

Not Authorized
HLH
11/9/18
Take photo before repair
3 day

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP009092018
Policy No:		Date of Loss:	07/09/2018
Vehicle Reg. No.:	YN924P	Driveable?	
Part At Fault:	UNKNOWN	Driver (Insured):	LIM CHUAN KEK
Driver (TP):	YANG PENG		
Make/Model:	HINO FD8JLKA, 7.7 D (M)	Vehicle Reg. Date:	26/02/2010
Vehicle Colour:	WHITE	Chassis No:	FD8JJK12004
Engine No:	J08EUC11556	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence not the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____</p> </div>	
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	<p>ON 07/09/2018 AT ABOUT 0300HRS, I STOPPED MY VEHICLE (A: YN924P) AT PARKING LOT LOADING/UNLOADING BAY AT SELETAR MALL IN ORDER TO UNLOADING GOODS. MY COLLEAGUE WITH ME AT BEHIND OF THE VEHICLE UNLOADING GOODS, SUDDENLY HEARD THE BANG SOUND FROM MY VEHICLE'S FRONT PORTION. I IMMEDIATELY GO IN FRONT AND DISCOVERED THAT VEHICLE (B: YN2167U) WHICH WAS CAME OUT FROM LOADING/UNLOADING BAY AND HIT ONTO MY VEHICLE'S FRONT PORTION. NOBODY WAS INJURED IN THIS ACCIDENT. MY VEHICLE HAVE NO DRIVER AND PASSENGER ON BOARD. VEHICLE B HAVE NO PASSENGER ON BOARD.</p>		
Present Location:	TAN LIM MOTOR PTE LTD (DEFU)		

COST OF CLAIMS

	Amount
Parts	380.00
Miscellaneous Items	0.00
Labour	710.00
Paintwork Labour	850.00
Towing	0.00
Gross Total (\$\$)	1,940.00
+ GST 7.00% (\$\$)	135.80
Nett Amount (\$\$)	2,075.80

Repairer Estimates

This claim is handled by: LAM WEI SHONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Repairer Estimates

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Sep 2018)
 Parts: N/A HINO FD8JLKA 7.7 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/YN924P/08/09/2018 15:15
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*wiper garnish <i>bro</i> ✓	10.00	0.00	-
2	1		*right wiper blade <i>AA</i> X	10.00	0.00	-
3	1		*right wiper arm <i>one</i> ✓	10.00	0.00	-
4	1		*right wiper arm cover <i>one</i> ✓	10.00	0.00	-
5	1		*right wiper arm cover washer nozzle <i>11</i> X	10.00	0.00	-
6	1		*right wiper arm cover washer nozzle hose <i>70.1</i> ✓	10.00	0.00	-
7	1		*right wiper arm nut <i>11</i> X	10.00	0.00	-
8	1		*right wiper motor <i>11</i> X	10.00	0.00	-
9	1		*right wiper linkage <i>11</i> X	10.00	0.00	-
10	1		*wiper garnish weatherstrip <i>11</i> ✓	10.00	0.00	-
11	1		*front bumper upper <i>11</i> X	10.00	0.00	-
12	1		*front bumper lower <i>11</i> X	10.00	0.00	-
13	1		*right front indication light <i>11</i> X	10.00	0.00	-
14	1		*front wing mirror - bracket assy <i>11</i> X	10.00	0.00	-
15	1		*front body panel corporate sticker <i>11</i> ✓ <i>1005-2</i>	0	0.00	*380.00 FS
Total Parts (S\$)						380.00

F=Franchise part. S=SpcNett.

Tan Lim Motor Pte Ltd/YN924P/08/09/2018 15:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Repairer Estimates

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New 600	850.00
Labour Items			
2	To check electrical lighting concerned.	New 20	60.00
3	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 450	650.00
Gross Labour Cost (\$\$)			1,560.00

Tan Lim Motor Pte Ltd/YN924P/08/09/2018 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

Supplementary bill

1) For windscreen glass w/strip

2) Labor to remove/replace front
windscreen glass to enable
to open

- \$250 120?

2) To remove and refit instrument.

decommissioning to facilitate repair \$450? 200?
Pah? phn



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1/5 \$2400

Not Authorized
11/9/18
take photo After repair
3 day.

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

Sinmah Poultry Processing (S) Pte Ltd

27 Defu Lane 12
Singapore 539134

Claimant Insurer: Great Eastern General Insurance Limited

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP009092018
Policy No:	A28800295MKC	Date of Loss:	07/09/2018
Vehicle Reg. No.:	YN924P	Driveable?	
Part At Fault:	UNKNOWN	Driver (Insured):	LIM CHUAN KEK
Driver (TP):	YANG PENG		

Make/Model: HINO FD8JLKA, 7.7 D (M)
Vehicle Colour: WHITE
Engine No: J08EUC11556
Odometer: 0 KM

Vehicle Reg. Date: 26/02/2010

Paint Type:
List Item Discount: 10.00 %
Total Loss? NO
Est. Duration of Repair (day) 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Chassis No: FD8JJK12004

Acknowledged by Repairer
Signature:
Date:

Description of Accident/Loss

ON 07/09/2018 AT ABOUT 0300HRS, I STOPPED MY VEHICLE (A: YN924P) AT PARKING LOT LOADING/UNLOADING BAY AT SELETAR MALL IN ORDER TO UNLOADING GOODS. MY COLLEAGUE WITH ME AT BEHIND OF THE VEHICLE UNLOADING GOODS, SUDDENLY HEARD THE BANG SOUND FROM MY VEHICLE'S FRONT PORTION. I IMMEDIATELY GO IN FRONT AND DISCOVERED THAT VEHICLE (B: YN2167U) WHICH WAS CAME OUT FROM LOADING/UNLOADING BAY AND HIT ONTO MY VEHICLE'S FRONT PORTION. NOBODY WAS INJURED IN THIS ACCIDENT. MY VEHICLE HAVE NO DRIVER AND PASSENGER ON BOARD. VEHICLE B HAVE NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

	Amount
Parts	6,394.00
Miscellaneous Items	0.00
Labour	1,410.00
Paintwork Labour	850.00
Towing	0.00
Gross Total (\$\$)	8,654.00
+ GST 7.00% (\$\$)	605.78
Nett Amount (\$\$)	9,259.78

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Sep 2018)
 Parts: N/A HINO FD8JLKA 7.7 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/YN924P/13/09/2018 17:27
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*wiper garnish 1320 / 745.50	10.00	0.00	*1,120.00 FL
2	1		*right wiper blade 11 X	10.00	0.00	*90.00 FLX
3	1		*right wiper arm 11 X 259.70	10.00	0.00	*280.00 FL
4	1		*right wiper arm cover 11 X	10.00	0.00	*60.00 FL
5	1		*right wiper arm cover washer nozzle 11 X	10.00	0.00	*150.00 FLX
6	1		*right wiper arm cover washer nozzle hose 10.1	10.00	0.00	*80.00 FL
7	1		*right wiper arm nut 11 X	10.00	0.00	*60.00 FLX
8	1		*right wiper motor 11 X	10.00	0.00	*980.00 FLX
9	1		*right wiper linkage 11 X	10.00	0.00	*80.00 FL
10	1		*wiper garnish weatherstrip 11 X	10.00	0.00	*30.00 FL
11	1		*front bumper upper 11 X	10.00	0.00	*1,500.00 FLX
12	1		*front bumper lower 11 X	10.00	0.00	*1,000.00 FLX
13	1		*right front indication light 11 X	10.00	0.00	*380.00 FLX
14	1		*front wing mirror - bracket assy 11 X	10.00	0.00	*150.00 FLX
15	1		*front body panel corporate sticker 11 X	0	0.00	*380.00 FS
16	1		*front windscreen glas weatherstrip 11 X 372.20 1005.2	0	0.00	*650.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,990.00
- List Item Discount on L Items (S\$)	596.00
Total Parts (S\$)	6,394.00

Tan Lim Motor Pte Ltd/YN924P/13/09/2018 17:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1627.40
 1464.66

3004.66
 2403.73

P-1627.4
 102
 1464.66

S.N-100
 1464.66
 3004.66
 202
 2403.72

Repairer Estimates

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New 600	850.00
<u>Labour Items</u>			
2	To check electrical lighting concerned.	New 20	60.00
3	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 450	650.00
4	To remove and refit front windscreen glass to enable repair.	New 120	250.00
5	To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	New 250	450.00
Gross Labour Cost (S\$)			2,260.00

Tan Lim Motor Pte Ltd/YN924P/13/09/2018 17:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1440

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016519/URBN2

Date: 25/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28800295MKC
Claimant Vehicle No :	YN924P	Insured Vehicle No :	YN2167U
Date of Loss:	07/09/2018	Nature of Claim:	TP
		Claim No:	569705

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN924P	Engine No:	J08EUC11556
Make & Model:	HINO FD8JLKA, 7.7 D (M)	Chassis No:	FD8JJK12004
Reg. Date:	26/02/2010 (Man. Year: 2009)	Odometer:	120299 km
Colour:	Red/White		
Engine Capacity:	7684 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	8.25-16	Rear Tyre Size:	8.25-16 (D)
Front Left Side:	Magnum 6 mm	Rear Left Side:	Magnum 6/6 mm
Front Right Side:	Magnum 6 mm	Rear Right Side:	Magnum 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,394.00	1,564.66	4,829.34	75.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	840.00	570.00	40.43
Paintwork Labour	850.00	600.00	250.00	29.41
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,654.00	3,004.66	5,649.34	65.28
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	8,654.00	2,400.00	6,254.00	72.27
+ GST 7.00/7.00% (S\$)	605.78	168.00	437.78	72.27
Nett Amount (S\$)	9,259.78	2,568.00	6,691.78	72.27

INSPECTION

Date of Assignment:	11/09/2018	Present Location:	Tan Lim Motor Pte Ltd (Defu)
Date Inspected:	11/09/2018	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10 Singapore 539216
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Sep 2018)	
Parts:	N/A	HINO FD8JLKA 7.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN924P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*wiper garnish	Broken	1,120.00 FL	*745.50 FL
2	1		*right wiper blade	Not Necessary	90.00 FL	*- FL
3	1		*right wiper arm	Cracked	280.00 FL	*259.70 FL
4	1		*right wiper arm cover	Cracked	60.00 FL	*60.00 FL
5	1		*right wiper arm cover washer nozzle	Not Necessary	150.00 FL	*- FL
6	1		*right wiper arm cover washer nozzle hose	Torn	80.00 FL	*80.00 FL
7	1		*right wiper arm nut	Not Necessary	60.00 FL	*- FL
8	1		*right wiper motor	Not Necessary	980.00 FL	*- FL
9	1		*right wiper linkage	Bent	80.00 FL	*80.00 FL
10	1		*wiper garnish weatherstrip	Twisted	30.00 FL	*30.00 FL
11	1		*front bumper upper	Repair	1,500.00 FL	*- FL
12	1		*front bumper lower	Repair	1,000.00 FL	*- FL
13	1		*right front indication light (Scratched)	Not Consistent With The Impact	380.00 FL	*- FL
14	1		*front wing mirror - bracket assy (Bent)	Not Consistent With The Impact	150.00 FL	*- FL
15	1		*front body panel corporate sticker	Necessary	380.00 FS	*100.00 FS
16	1		*front windscreen glas weatherstrip	Necessary	650.00 FS	*372.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,990.00	1,727.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	596.00	162.74
Total Parts (\$\$)	6,394.00	1,564.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Putty and spray painting of the affected portion.	New	850.00	600.00
<u>Labour Items</u>				
2	To check electrical lighting concerned.	New	60.00	20.00
3	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	650.00	450.00
4	To remove and refit front windscreen glass to enable repair.	New	250.00	120.00
5	To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	New	450.00	250.00
Gross Labour Cost (S\$)			2,260.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >