

ASS. REC. BY:

REF:

CS/MSCH18016521/Ksb

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Insured

From (Person):

Chhia Nyuk Pui

of

MSCH

Date/Time:

11/09/2018 935am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 7875U

Insured:

92 5715J

at Workshop m/s:

Optima Werkz

Tel:

6484 9919

of

SA Serampang North Ave 5

Policy No:

A29082055 AVW

Claim No:

569431

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

12.09.2018 @ 10am

H.O.D. Endorsement:

Date/Time:

11/09/2018

Person Contacted

Wly

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 7875U - NBN / UCI 18011914/Y

DUA: 05/09/2018

92 5715J - NBN / UPI 18011910/Y

DUA: 30/09/2018

13/09/18 @ 14:41 p.m. revised IA to Chhia Nyuk Pui via merimer.

16/10 82612-28 email & confirmed

Service:

REF: mslh

ASSIGNMENT

From: Date: 12092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKW 7875U

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess:


(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 7875U Tr Regn: 11 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Toy Sierra

Wagon

C.C

1496

Colour

M.D. white

A/C: Insured / Std / NI / NA

Sp. Reading

60524

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

N1P170 7001776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / Std A/Rim or

Tyre Size:

F:

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A

5/9/18

D.O.I

12/9/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/9 File pass to Customer

25/10/18 Confirmed r/p \$2,612.28 @ 4 days with Kenneth. (\$2,900.12 Red - 53%)

RECEIVED 25 OCT 2018

25/10/2018

Date/Time: File Pass to?

25/10/18

File

Typ. 24

Date/Time: File Return to?

25

☐

Prel. Report

☒

Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee

Transportation

3 + RE. SI

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$ 2,612.28 p/p)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Sep 2018		11 Sep 2018 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SAUMYA SHEKHAR JAMUAR, ID: 57979203I, Tel: +6581211796, Email: NOEMAIL								
Main Claimant:	TEO KAT SOON, ID: 56804568A								
Vehicle Reg. No.:	SKW7875U	Date of Loss:	05/09/2018 08:00 - :59 [33 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569431	Policy/Cover Note No.:	A29082055AVW (Comprehensive) Coverage: 09/05/2018 - 08/05/2019						
Vehicle Reg. No. (Insured):	SLZ5715J	Policy No. (Claimant):							
		Excess:	\$1,500.00						
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/09/2018]								
Driver/Custodian (Insured):	SAUMYA SHEKHAR JAMUAR (39 / Male), NRIC: 57979203I, Tel: +6581211796								
Adj Asg. Remarks:	Liability 100%. TP agree to use LKK as the SJE. Contact Person: Lily Loi / 6484 9919.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4568A

Vehicle Details

Vehicle No.: SKW7875U
Vehicle to be Exported: Yes
Intended Deregistration Date: 07 Sep 2018
Vehicle Make: TOYOTA
Vehicle Model: SIENTA HYBRID 1.5G A
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 1NZR313552
Chassis No.: NHP1707001776
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$24,681.00
Original Registration Date: 16 Nov 2015
First Registration Date: 16 Nov 2015
Transfer Count: 0
Actual ARF Paid: \$11,554.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Nov 2025
PARF Rebate Amount: \$8,665.00

Intended COE Rebate Details

COE Expiry Date: 15 Nov 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,001.00
COE Rebate Amount: \$40,258.00
Total Rebate Amount: \$48,923.00

The information contained herein is correct as at 07 Sep 2018

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 13 Sep 2018

Preliminary Advice

Insured Vehicle No	: SLZ5715J	Accident Date	: 05/09/2018
TP Vehicle No	: SKW7875U	Assignment Date	: 11/09/2018
Make	: TOYOTA SIENTA	Est. Duration of Repair	: 4 days
Date of Inspection	: 12/09/2018		
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,132.40
Revised Amount	:S\$	2,362.28
Check Items (Estimated)	:S\$	1,230.60
Total	:S\$	3,592.88

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/09/2018 12:15
Date Of Accident	05/09/2018 08:45
Exact Location Of Accident	ALONG DEPOT ROAD TOWARDS ALEXANDRA ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKW7875U
Insured/Policyholder	
Name Of Registered Owner	TEO KAT SOON
NRIC No	S6804568A
Email Address	GARRETT.TEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97359031
Alternative Phone No	OTHERS-97359031
Vehicle Particulars	
Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5075644473-02
Cover Note Number	
Driver	
Name of Driver	TEO KAT SOON
NRIC No	S6804568A
Date Of Birth	02/02/1968
Occupation	INDOOR
Date Of Driving Pass	20/02/1995
Driving Experience	23 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97359031
Fax Number	
Contact Number	OTHERS-97359031
EMail Address	GARRETT.TEO@GMAIL.COM

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:
5 SEP 2018
12:26 PM


Driver's Signature
(If driver is not the policyholder)

Date & Time:
5 SEP 2018
12:26 PM


Reporting Centre Personnel's Signature

Name:
NRIC/TIN No.:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 7 SEPTEMBER 2018

Third Party Insurer: MSIG

Vehicle No: SKW7875U

Third Party Veh No: SLZ5715J

Model: TOYOTA SIENTA

Date of Accident: 5 SEPTEMBER 2018

Chassis: NHP1707001776 - 2015

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE		<i>Rs</i> \$1,186.60
1	REAR TAILGATE WINDSCREEN MOULDING		<i>Rs</i> \$35.70
1	REAR TAILGATE EMBLEM LOGO		<i>Rs</i> \$65.60
1	REAR TAILGATE EMBLEM HYBRID SYNERGY DRIVE		<i>Rs</i> \$48.20
2	REAR TAILGATE HINGE RH/LH	\$78.60	<i>Rs</i> \$157.20
1	REAR TAILGATE MECHANISM LOCK		<i>Rs</i> \$452.70
1	REAR BUMPER		<i>Rs</i> \$1,178.60
1	REAR BUMPER PAD CENTRE		<i>Rs</i> \$285.60
1	REAR BUMPER INNER SPONGE		<i>Rs</i> \$105.00
8	REAR BUMPER CLIPS	\$6.00	<i>Rs</i> \$48.00
SUB TOTAL			\$3,563.20
Less 25%			-\$890.80
PARTS TOTAL			\$2,672.40

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		<i>Rs</i> \$100.00
1	REAR BUMPER REVERSE SENSOR		<i>Rs</i> \$280.00
S/N TOTAL			\$380.00

*Not Authorized
Resurvey Bk pain*

82612-28

4 days

13/9/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	7 SEPTEMBER 2018	Third Party Insurer:	MSIG
Vehicle No:	SKW7875U	Third Party Veh No:	SLZ5715J
Model:	TOYOTA SIENTA	Date of Accident:	5 SEPTEMBER 2018
Chassis:	NHP1707001776 – 2015		

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$800.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$600.00

TO TUFF KOTE / ANTI-RUST

\$60.00

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

~ \$150.00

TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA

\$80.00

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$60.00

TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST

\$150.00

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR

~ \$180.00

LABOUR TOTAL	\$2,080.00
--------------	------------

PEI TING	TOTAL	\$5,132.40
----------	-------	------------

5,512.40

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 7 SEPTEMBER 2018

Third Party Insurer: MSIG

Vehicle No: SKW7875U

Third Party Veh No: SLZ5715J

Model: TOYOTA SIENTA

Date of Accident: 5 SEPTEMBER 2018

Chassis: NHP1707001776 – 2015

SUPPLEMENTARY

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE COATING	<i>Per</i>	\$380.00
		S/N TOTAL	\$380.00
PEI TING		TOTAL	\$380.00

250/4

Optima Werkz Pte Ltd

6 Kung Chong Road, Singapore 159143.
TEL: +65 6472 1313 FAX: +65 6472 2112
Co. Reg & GST No. 201212455W

Tax Invoice

SKW7875U TOYOTA SIENTA HYBRID - MR TEO
Tel: 97359031

Inv No. : 02INV15120675
Invoice Date : 28 Dec 2015
Ref : 11185-02WJ1512494
Terms : COD
Veh. No. : SKW7875U
Advisor : Rick Lew
Current Mileage : 2201

#	Description	Qty	UOM	U/P	Disc	Amt
1	BRILA PREMIUM GLASS COATING SERVICES WITH GST	1.00	JOB	513.60	0.00	513.60
2	LESS BRILA VOUCHER - S\$50/	1.00	TIME	-50.00	0.00	-50.00

Name : _____

Includes GST 7.0% : S\$ 30.33
Total : S\$ 463.60

NRIC No. : _____

Signature : _____

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs. I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

New parts purchased/installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one(1)year or mileage up to 30,000km, whichever comes first, from date of invoice, with the exception to wear & tear items.

Recon parts and used parts purchased/installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six(6)months or mileage up to 10,000km, whichever comes first, from date of invoice, with the exception to wear & tear items.

Original invoice is only valid when the payment is acknowledge receipt by OPTIMA WERKZ PTE. LTD. Interest at 2% per month will be charged on any outstanding amount. Goods sold are not refundable/returnable.

*All Customer's information are solely used for the purposes of completing the sales transactions / legitimate purposes and will be strictly kept confidential. Should there be other purposes, we would seek prior approval from the customer.

For Optima Werkz Pte Ltd



(Authorised Signature)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Sep 2018		11 Sep 2018 09:35 Edit Adj Rpt	S\$2,612.27 Edit Estimates	S\$2,612.27 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	SAUMYA SHEKHAR JAMUAR, ID: S7979203I, Tel: +6581211796, Email: NOEMAIL								
Main Claimant:	TEO KAT SOON, ID: S6804568A								
Vehicle Reg. No.:	SKW7875U	Date of Loss:	05/09/2018 08:00 - :59 [33 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 569431	Policy/Cover Note No.:	A29082055AVW (Comprehensive) Coverage: 09/05/2018 - 08/05/2019						
Vehicle Reg. No. (Insured):	SLZ5715J	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/10/2018]								
Driver/Custodian (Insured):	SAUMYA SHEKHAR JAMUAR (39 / Male), NRIC: S7979203I, Tel: +6581211796								
Adj Asg. Remarks:	Liability 100%. TP agree to use LKK as the SJE. Contact Person: Lily Loi / 6484 9919.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW7875U (569431)
[SLZ5715J]
TP
TEO KAT SOON
Sep 5 2018 8:00AM
[SAUMYA SHEKHAR JAMUAR]
Optima Werkz Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/09/18 17:01	Accident Statement From: SC - Reg. No: SLZ5715J, Claimant: SAUMYA SHEKHAR JAMUAR	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/09/18 14:41	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/09/18 14:38	General View	1	Load JPG	☒
2	13/09/18 14:38	General View	1	Load JPG	☒
3	13/09/18 14:38	General View	1	Load JPG	☒
4	13/09/18 14:38	General View	1	Load JPG	☒
5	13/09/18 14:38	General View	1	Load JPG	☒
6	13/09/18 14:38	General View	1	Load JPG	☒
7	13/09/18 14:38	General View	1	Load JPG	☒
8	13/09/18 14:38	General View	1	Load JPG	☒
9	13/09/18 14:38	General View	1	Load JPG	☒
10	13/09/18 14:38	General View	1	Load JPG	☒
11	13/09/18 14:38	Odometer Reading	1	Load JPG	☒
12	13/09/18 14:38	General View	1	Load JPG	☒
13	13/09/18 14:38	General View	1	Load JPG	☒
14	13/09/18 14:38	Chassis Number	1	Load JPG	☒
15	25/10/18 10:06	Reinspection Photo	1	Load JPG	☒
16	25/10/18 10:06	Reinspection Photo	1	Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/09/18 11:06	Email - PRI	1	Load PDF	
2	10/09/18 17:01	SKW7875U TP E-FILE REPORT From: SC - Reg. No: SLZ5715J, Claimant: SAUMYA SHEKHAR JAMUAR	1	Load PDF	
3	10/09/18 17:03	TP agree to use LKK as the SJE	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/10/18 10:32	SUPPLEMENTARY PART	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18016521/KSBQ2

Date: 26/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29082055AVW

Claimant Vehicle No : SKW7875U

Insured Vehicle No : SLZ5715J

Date of Loss: 05/09/2018

Nature of Claim: TP

Claim No: 569431

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW7875U

Make & Model: TOYOTA SIENTA, 1.5 HYBRID (A)

Engine No: 1NZR313552

Reg. Date: 16/11/2015 (Man. Year: 2015)

Chassis No: NHP1707001776

Colour: Metallic Pearl White

Odometer: 60524 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,432.40	1,542.27	1,890.13	55.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,070.00	1,010.00	48.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,512.40	2,612.27	2,900.13	52.61
+ GST 7.00/7.00% (S\$)	385.87	182.86	203.01	52.61
Nett Amount (S\$)	5,898.27	2,795.13	3,103.14	52.61

INSPECTION

Date of Assignment: 11/09/2018

Date Inspected: 12/09/2018

Inspected At: Optima Werkz Pte Ltd (HQ)
9A Serangoon North Ave 5
Singapore 554500

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,612.28

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2018)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW7875U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,186.60 FL	*1,186.60 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	35.70 FL	*35.70 FL
3	1		*REAR TAILGATE EMBLEM LOGO	Necessary	65.60 FL	*65.60 FL
4	1		*REAR TAILGATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	48.20 FL	*48.20 FL
5	2		*REAR TAILGATE HINGE LH/RH	Repair	157.20 FL	*- FL
6	1		*REAR TAILGATE MECHANISM LOCK	Repair	452.70 FL	*- FL
7	1		*REAR BUMPER	Serviceable	1,178.60 FL	*- FL
8	1		*REAR BUMPER PAD CENTRE	Dented /Cut	285.60 FL	*285.60 FL
9	1		*REAR BUMPER INNER SPONGE	Serviceable	105.00 FL	*- FL
10	8		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
11	1		*REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*40.00 FS
12	1		*REAR BUMPER REVERSE SENSOR	Serviceable	280.00 FS	*- FS
13	1		*REAR TAILGATE COATING	Necessary	380.00 FS	*250.00 FS
					Sub Total (\$\$)	4,323.20 1,959.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	890.80 417.43
					Total Parts (\$\$)	3,432.40 1,542.27

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	800.00	400.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	600.00	440.00
3	TO TUFF KOTE/ANTI-RUST	New	60.00	30.00
4	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	New	150.00	0.00
5	TO DISMANTLE & REFIX REAR TAILGATE REVERSE CAMERA }	New	80.00	80.00
6	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR }	New	60.00	0.00
7	TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	New	150.00	120.00
8	TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR	New	180.00	0.00
Gross Labour Cost (\$\$)			2,080.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >