

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

10-Sep-18

Our ref : TP/4570/18

Hock Hua Tonic Pte Ltd

TPLCR
xiao Tony

RE : estimate cost for vehicle no : GBE 4238E

1 pc	rear lh door <i>Dented</i>	\$	1,164.70	nett ✓	
1 pc	NV 200 emblem <i>ny</i>		79.90	✓	
1 pc	rear bumper <i>dent</i>		624.80	✓	1857.7
1 pc	rear bumper lh retainer <i>zave</i>		33.30	✓	
1 pc	rear bumper lh reflector <i>scratched</i>		55.00	✓	1761.93
			1,957.70		
	less 10%		195.77		
			1,761.93		
1 pc	reverse sensor <i>Damaged</i>		250.00	nett	200 (sav)
1 pc	end panel <i>Repair</i>		471.00	✓	
1 pc	70km/h sticker?		10.00	✓	
1 pc	6 pax sticker <i>3 pax</i>		10.00	✓	
1 pc	Co logo <i>new</i>		250.00	155	
1 pc	rear w/creen gum <i>new</i>		50.00	✓	1340
	Panel beating		600.00	400	
	spray painting.		600.00	400	
	Remove & reft rear lh door glass.		80.00	60	
	Transfer door parts.		80.00	60	
			4,162.93		
	Plus 7% GST		291.41		
			4454.34		

SD : Four thousand four hundred fifty-four & cents thirty-four only.

Adrian Ling, Total: 3101.93
L/s 18/09/18
04 days
H/s: 2450.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: